




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19005712/Gpa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: PETER WANG			Date : 20-04-2020	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKR 2062H	Veh. Inspected	SJL 2826P	
Policy No.	GA283559/1	Coverage (\$)	0.00	
Claim No.	S9M01IKG	Excess (\$)	0.00	
Assign From	PETER WANG	Assign Date	01/04/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CIVIC 1.8G	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	FD11200656	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45ZR17	CST	6 mm	
L/H Front Tyre	225/45ZR17	CST	6 mm	
R/H Rear Tyre	225/45ZR17	CST	6 mm	
L/H Rear Tyre	225/45ZR17	CST	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/03/2019	Inspection Date	02/04/2019	
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>10 Working Days</b>		