

08/11/19

Surveyor

Star

REF: AIG

ASSIGNMENT

Front:

Date: 8/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKR 3133E

at Workshop m/s

performance

of

303 Alexander Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Inthiran

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKR 3133E

Yr Regn:

15/11/18

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520

c.c

1998

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

10740

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAJA 1290WE 69551

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firmi

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

27/3/19

D.O.I.

8/4/19

Survey held at

performance

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)