

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

	ACCIDENT RE	PAIR ESTIMATES	
Our Ref:			
Ins Company : III Excess :	TP	Vehicle No. : Make & Model : Year of Manufacture : Chassis No. : Engine No. : Policy No. : In-house Vehicle Assess Case Owner : Signature : Contact No Frt Counter Operation 63837466 - Patrick	YV3T7U52XJA192079
Total of Cost / List (b) Nett Price Items Less Total of Nett Item (c) Special Nett Items Total Parts Cost (Appendix A) Labour (Appendix B) Total Repair Cost The above total will be subjected in	\$ - \$ 1,422.00 \$ 1,960.00 \$ 3,382.00	63837730 - Brenda 63837890 — Rohani braddell cr@sparkcarecar. Back-end Operation 63837656 - Ngo 63837362 - Andrew 63838115 - William braddell_operation@sparkc	
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is a (b) Recommended Days of Re (c) Resurvey (d) Excess		day(s) of Required	
(e) Signature of surveyor	•	Date:	

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	:	PC7674D	Case Owner	:	0
Make & Model	:	VOLVO B8R	Year Manufacture	:	2018
Chassis No	:	YV3T7U52XJA192079	Engine No	:	0
Sales Order	:		Supplier	;	
Order By	:		Type of Claim	:	<u>TP</u>

S/No	Part Description	QTY		Cost Price	1	List Price	Nett Price	S/N	Disposition By Surveyor
1	RH REAR WHEEL PANEL	1	\$	1,580.00					
	0	1	Ť	1,000.00					
	0	1							
	0	1							
	0	1							
	0	1							
7	o	1	***************************************						
8	0	1							
9	0	1							
10	0	1							
11	o	1							
12	O	1							
13	0	1							
14	0	0							
15	0	0							
16	0	0							
17	0	0							
18	0	0							
19	0	0							
20	0	0							
21	0	0							
22	0	0							
23	0	0							
24	0	0							
25	0	0							
26	0	0							
27	0	0							
28	0	0							
29		0							
30		0							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

30/03/2019 11:13 AM

Spark Car Care
ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax: 62815767

<u>Labour</u>

Vehic	le No. :	PC7674D	Case Owner	:	0
Make	& Model:	VOLVO B8R	Year of Manufacture		2018
S/No		Labour De	escription	Esimated Price	Adjusted Price
	TO KNOCK, STF	RAIGHTEN AND REN	EW ACCIDENT AREA SUCH AS		
			SIDE ENGINE PANEL, RH REAR		
	BATTTERY PAN			\$960.00	
	TO PUTTY AND	RESPRAY ACCIDEN	T AREA SUCH AS RH REAR		
	WHEEL PANEL,	RH REAR SIDE ENG	SINE PANEL, RH REAR BATTERY		
	PANEL AND ETC)		\$1,000.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	15/02/2019 16:13
Date Of Accident	14/02/2019 18:10
Exact Location Of Accident	WOODLANDS AVE 12
Country/State of Loss	SINGAPORE

	D]=##_	1 2 3	o) [[0]'	U N NY		(6)	
		1520/65/69	07/57/8/59/0			\$155 SOM	1000	02 M/02

Vehicle Registration Number PC7674D

Insured/Policyholder

Name Of Registered Owner COMFORTDELGRO BUS PTE LTD

Co Reg No 199607256W **Email Address** NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-97808793

Vehicle Particulars

Manufacturer VOLVO Model B8R

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

BUS

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy YES

Policy Number

Cover Note Number 101117

Driver

Name of Driver WONG CHEE SENG

NRIC No S0746924A Date Of Birth 08/04/1954 Occupation OUTDOOR Date Of Driving Pass 14/02/1994

Driving Experience 25 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97808793

Fax Number Contact Number

EMail Address NOEMAIL Address

BLK 148 YISHUN ST 11 #10-113

Postcode

760148

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 32 YISHUN ST 81, POSTCODE: 768456, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-8522999 - FAX NO: 68522239

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBM4972B

Vehicle Make/Model/Colour

HONDA MOTORBIKE

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

ONG YIJUN S9134639G

Contact Number

NRIC/Passport Number

Address

Postcode

Insurance Company Name

AXA INSURANCE PTE LTD

Nature Of Damage

Page 2 of 33

DETAILS OF INJURED PERSON 1

Name

ONG YI JUN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBM4972B


Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode



SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Foliovincider and/or the Authorised Driver.
- 3. Information provided must be as arothful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputilize policy liability;
- a. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Antifalse reporting may be referred to the Police for investigation.
- 5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
- 7. By the lodgment of this report to the incurers, you hereby consent to the archiving of this report at the cantre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDFA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information satiout in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vahicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "ಗಾಗಾರ್ವತಿ")
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all incurers and/or any other third parties that essist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Driver's Signosure

Folic, holder's Stensture

Date & Time:

(If driver is not the policyholder)

Late & Time:

Reporting Centra Personnel's Signature

HAIC/FIN No.





Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456 Tel No: 1800-8522999

1 of 3 Report No. T/20190214/2167

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/02/2019 21:24			Vide Report No.: Station Dia			
Informani	's Partic	ulars				
Name of I			Address: APT BLK 148 YISHUN STREET 11 #10-113 SINGAPORE 760148			
ID Type / I NRIC NO	/ S074692	24A	Contact No.: Home/Office:	Mobile: 97808793		
Nationality: SINGAPORE CITIZEN			Email:			
Sex: Male	Age: 64	Date of Birth: 08/04/1954	Type of Informant: Driver	700000000000000000000000000000000000000		
Race: Chinese			Language:	Institution / School Name:		
Occupation: Bus driver			Driving Licence Information: Class: 2B,2A,2,3,4A,4,5 Date of Expiry:			

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/02/2019 18:05	Type of Location: Straight Road	
Location: Along Road 1 WOODLAND Towards SLE	S AVENUE 12				
Weather: Ro		Road Surface: Dry		Road Speed Limit:	
O . 101		Traffic Control: Traffic Light - Wor	rking	Traffic Volume: Heavy	
Type of Collis Between Mov	ion: ing Vehicles - Head	To Side		Anyone conveyed by ambulance:	

Details of Vo	ehicle involved	20,000 (10,000), 10,000 (10,000)			2863-020 co-46-060	
Vehicle No.		The state of the state of the second state of	Model	Color	Condition	No of Passenger
FBM4972B	Motorcycle				No	0
50507/5	B (2				Damage	
PC7674D	Bus/Coach/Mi				Slightly	0
	nibus				Damaged	

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing; NA





Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456 Tel No: 1800-8522999 2 of 3 Report No. T/20190214/2167

CONTINUATION OF REPORT

Rider				raci (takir)	ver Pretime (N 4760)	
Name	Ong Yi Jun			ID No	<i>.</i> •	S9134639G
Related Vehicle	FBM4972B (Motorcycle	e)	, willware.	Contact No.		81413676
Hospital/Clinic	NIL			Class Drivin Licend Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discl	<u> </u>	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	***************************************	Sligh	t
Driver				X033350175		
Name	WONG CHEE SENG			ID No		S0746924A
Related Vehicle	PC7674D (Bus/Coach/	Minibus)	··· ·····	Conta	ct No.	97808793
Hospital/Clinic	NIL			Class Driving Licence Expiry	3 e &	Class: 2B,2A,2,3,4A,4,5 Date of Expiry: NIL
Date Treatment	NIL		Date Disch		NIL	· · · · · · · · · · · · · · · · · · ·
No. of Days grant	ed Medical Leave	NIL	Degree of		NIL	

Brief Details.

On 14/12/2019 at about 1808hrs, While I was travelling along Woodlands Ave 12 heading towards SLE/CTE, as the traffic was heavy and the traffic was slow, Suddenly I heard sound coming from the rear, I made a check via my rear mirror and discover that there is one motorcycle fell on the road, After which I alighted from my company bus (PC7674D) to make check and discover that there is some scratches, dent and crack around my right rear wheels area. After which I made a check on the rider of FB4972B namely Ong Yi Jun H/P:81413676 S9134639G if he is alright and if he require any ambulance, as I observed that there is some abrasions on his hand he mentioned no, after which we exchange particulars and left the vicinity.

When the accident happen there is dash cam on board which is working however unsure if its able to capture the accident.

I am lodging this report for insurance claims and for comfort delgro actions.





Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456 Tel No: 1800-8522999 3 of 3 Report No. T/20190214/2167

CONTINUATION OF REPORT

Ot-	4-1-	D1-	
Ske	rrn	-	} { `

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Sgt 2 LUM JUN KAI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/02/2019 21:24
Officer In Charge Of Case: .TP./.AEIT./ SSI 2 YEO GEAK ENG CECILIA, Contact No.: 65476404	Classification Of Case:
Authentication Stamp NP168	

INDIA INTERNATIONAL INSURANCE PTE LTD GEORGAGIO MENGARCIO CO REC. NO. MATORIYOK 64 CECIL STREET #04/#05 IOB BUILDING SINGAPORE 049711 TEL: 6347 6100 FAX: 6224 4174 + 6225 7743 POSTAL ADDRESS: ROBINSON ROAD P. O. BOX NO. 738 SINGAPORE 901.			OPIGINAL				
			438 Motor Dept: 5th Levei				
This cover no	te is valid fo	or					
Singapore Registered Vehicles only.				Cover Note No	. 101117		
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1980 ROAD TRAISPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (MALAYSIA)						and the same I	
Cover note not valid if issued on or after 30/04/209 Date: 30/10/2019							
Comfort Dol Gro Bus Pte Ltd							
*****************	*******	************			having propose	d for Especial 24 E	
respect of the i	Motor Vehic	e described in the	e Schedule i	halour the	rick in horomy th	1 一人為 沙漠 (2)	
Policy applica	e Company's ble_thereio	or the periods	NEAVCE C		Markhon Sivie		
to midnight or	i	iz izvij unies	terceser b	e termin	a.m./p.m. ated by the Con and a proportion larged for the tim	Third 2019	
in writing in w	hich case	the insurand (%)	原则po	n cease	and a proportion	nate part of the	
has been on ri	n otherwise isk and pro	payable for said	iosurarice	will be of	narged for the time aforesaid liabilit	ne the Company	
effected with ot	on that pro	video that an ma	mismos con	ering the	aroresaid liabilit	y has not been	
		SC	HEDIJLE				
Make and Type of Body	Year of Manufacturer	Cubic Capacity/ Carrying Capacity/ Tonnage	Proposer's es present v including acc	ratue	TYPE	Petrol/Dissel Eng.	
Velvo	2018	6.61 ton	Martin	<u>.</u> †-	Private Car		
BBR	2019	, , , , , ,	vad	الألك	Commercial	Registration No.	
					Vehicle	13310000	
	Engine No:	as per att	er attached		Motor Cycle	787	
	Chassis No:	ar per attached					
Use negistration Authorised		l Driver		Excess			
of new ac per		policy		05 pm			
ven.ca		· · · · · · · · · · · · · · · · · · ·		Macheel			
		CERTIFICAT	te of insi	JRANCE			
IWE HEREB	Y CERTIFY	that this cover not	ie is issued i	n accord	ance with the prov	risions	
of the Wotor Vel	nicles (Thire	l-Party Risks and	Compens	ation) Ac	t (Chapter 189) a	and Part IV of	
the Road Transpo	ort Act, 198	(Malaysia).					
Hire Purchase:			Approved Insurers				
			for India International Insurance PTE LTD				
			ا ، حت	-	ے جے ا		
MPORTANT NOTE: Planse note that this Gover is soon as possible	Note should be rep	aced by a Certificate of inst	wance .		Authorised Signa	tory	

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S0746924A






WONG CHEE SENG @LYE THIAN SAN





SINGAPORE

4.00







VOCATIONAL LICENCE

Licence No : S0746924A Name: WONG CHEE SENG

Issue Date : 7/6/2011

Please visit www.lta.gov.sg to check the status of this vocational licence



#10-113 SINGAPORE 2776

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE . 11 May 1979 11 May 1979 11 May 1979 16 Apr 1985

Class 28 Class 2A Class 2 Class 3

Motorcycles not exceeding 200 cc Motorcycles between 201 cc and 400 cc Motorcycles exceeding 400 cc Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Omnibuses
Heavy Motor Cars and Motor Tractors the
weight of which unladen exceeds 2500 kilograms
Motor Vahicles which are not constructed
themselves to carry any load and the weight
of which unladen exceeds 7250 kilograms Omnibuses Class 5

17 Jun 1992 14 Feb 1994

12 Apr 1994

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type Description

NP 428A

BUS VL 03

Issue Date 05/07/1994