

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

*CY/TPI 905759/14d3n2*

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

*6* days

Res.: Yes or No

Lum Sum:

*20* %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

*LTA 69786*

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.A. (\$

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, \$ SI

) Photos

) Others

TOTAL

10x15 = 150

170 + 150

50

50 + 50

117

80

667

RECEIVED 15 APR 2019

*OAC QRm*  
*1/5 \$10,000 (Red \$10127.79, 50%)*

Ref. No :	C8/1819008759/Vqd3n2		Res. Date:	11/4/19	Date Received:	
Veh. No :	SKD25-167		SP:		WKSP:	Bent
C/No :						
<b>Action/Instruction:</b>						
1. File	2. Submit Photo?	YES / NO		Message:		
3. Indicate Res. Date On Photo Page?	YES / NO					
If No, due to	a) No authorisation	b) Days of repair				
others:						
Final Re-inspection or Progress Photos				Inspected By:		

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5528D
<b>Vehicle Details</b>	
Vehicle No.:	SKD2516P
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Apr 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLS 350
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	27695230049248
Chassis No.:	WDD2183592A026341
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$83,251.00
Original Registration Date:	14 Nov 2011
First Registration Date:	14 Nov 2011
Transfer Count:	0
Actual ARF Paid:	\$83,251.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Nov 2021
PARF Rebate Amount:	\$49,950.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	13 Nov 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$75,889.00
COE Rebate Amount:	\$19,836.00
<b>Total Rebate Amount:</b>	<b>\$69,786.00</b>

The information contained herein is correct as at 02 Apr 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/03/2019 15:40
Date Of Accident	27/03/2019 15:15
Exact Location Of Accident	PIE (TWDS BALESTIER RD)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD2516P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA JIA YING
NRIC No	S1615528D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82556162
Alternative Phone No	OFFICE-82556162
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	CLS350
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA409117
Cover Note Number	
<b>Driver</b>	
Name of Driver	PAK LIAN HUAT
NRIC No	S1541111B
Date Of Birth	08/04/1962
Occupation	INDOOR
Date Of Driving Pass	10/09/1979
Driving Experience	39 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82556162
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 7 PAVILION GREEN  
 Postcode 658292  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY  
 Other Information  
 Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of Intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

ON 27/03/2019 AT ABOUT 3.16PM, I WAS DRIVING ALONG PIE ON THE FIRST LANE. VEHICLE IN FRONT OF ME CAME TO A STOP, SO I FOLLOWED. SUDDENLY, CAR B CANNOT STOP IN TIME AND HIT THE REAR OF MY CAR.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLB2130S  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1


## SKETCH PLAN

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time: 28/3/19, 2:20 pm

  
Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/3/19, 2:20 pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/3/19 at about 3:16pm, I was driving along PIE on the 1st lane. Vehicle in front of me came to a stop so I followed. Suddenly Car B cannot stop in time and hit the rear of my car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 28/3/19, 2:20pm

Q:\A\AC SketchPlan\Forti\_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/3/19, 2:20pm

Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.:

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[F](#)

SUPREME

CLICK HERE OR CALL  
64**Post an Advertisement**

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**Coollest Lamborghini Gallardo LP 560-4 in town!**Open to negotiation! Low  
depreciation for a Supercar!  
Sanctuary Motor StarAd

ABWIN

ONE  
MOTORING



Browse by Category ▼

Sort by Date Posted

**2 vehicles**

Mercedes-Benz cls350

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
<b>Search Selection</b>	Mercedes-Benz cls350		Any	Any	2011	Any	Any	
	Mercedes-Benz CLS-Class	CLS350 Sunroof	\$88,000	\$17,950 /yr	02-Nov-2011	3,498 cc	130,000 km	
Owner Consignment Unit. Licence Plate 8989 To Go With Car. Regularly Serviced. Very Well Maintained. Sheltered Parking. Owner Upgrd Executive Saloon With A Very Sporty Feel. Call No To Enqu...								
Posted: 27-Mar-2019 Tags: 2011 Mercedes-Benz CLS350, 2011 mercedes-benz cls350, Mercedes-Benz CLS350, mercedes-benz cls350, Mercedes-Benz, CLS350, cls350, Used Mercedes-Benz								
	Mercedes-Benz CLS-Class	CLS350 Sunroof	\$88,800	\$18,780 /yr	14-Oct-2011	3,498 cc	120,500 km	
Genuine Mileage. Regularly Serviced. Very Well Maintained. Original Paint With Expensive Paint Protection Coating. Upgraded Sports Rin Performance Tyres. Sheltered Parking At All Times. Wear And...								
Posted: 24-Mar-2019 Tags: 2011 Mercedes-Benz CLS350, 2011 mercedes-benz cls350, Mercedes-Benz CLS350, mercedes-benz cls350, Mercedes-Benz, CLS350, cls350, Used Mercedes-Benz								

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
--	------	-------	-------	--------------	----------	---------	---------	---

For old advertisements, view [Expired ads](#)
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resour](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage car insurance. Find buy used Mercedes-Benz cls350, Mercedes-Benz cls350 Singapore, used Mercedes-Benz cls350 Singapore, used Mercedes-Benz cls350, used vel Mercedes-Benz cls350 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, for leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy.

**Follow sgCarMart.com**[Compare](#)
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

11355-64



# BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28  
(Unit C) #01-29-53/55 Singapore 417883  
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088  
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg  
Co. Reg. No.: 200704951N  
GST Reg. No.: 200704951N

SKD 2516P

To check wiring	S\$0.00	-30
To Dismantle & replacing Rear reverse sensor	S\$0.00	-50
To Dismantle & re-fix seat, cushion upholstery	S\$50.00	-100
To spray rust proofing	S\$0.00	-50
To Dismantle & replacing, reprogramme headrest	S\$80.00	-100
To transfer Bootlid mechanism	11 S\$50.00	-X
Labour for panel beating & replacing parts	S\$980.00	-800
To putty & spray painting	S\$1380.00	-1200

TOTAL \$20027.79

12/5/07

Insurance notice

The insured must notify the insurer immediately after the accident.

- The insured must provide a copy of the police report.
- The insured must provide a copy of the medical report.
- The insured must provide a copy of the repair estimate.
- The insured must provide a copy of the insurance policy.
- The insured must provide a copy of the insurance certificate.
- The insured must provide a copy of the insurance claim form.
- The insured must provide a copy of the insurance claim form.

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP19005759/Uqd3n2

BLK 1 KAKI BUKIT AVE 6  
#01-28/51/53/55(MAIN OFFICE)SINGAPORE  
417883

Date : 16-04-2019



ON BEHALF OF CHUA JIA YING

Code : TP149

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	Veh. Inspected	SKD 2516P
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	01/04/2019

**2. Vehicle Particulars & Condition**

Make & Model	MERCEDES BENZ CLS 350 (A)	c.c	3498
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2183592A026341	Colour	WHITE
Odometer	123402	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	255/40 R18	PIRELLI	6 mm
L/H Front Tyre	255/40 R18	PIRELLI	6 mm
R/H Rear Tyre	285/35 R18	PIRELLI	6 mm
L/H Rear Tyre	285/35 R18	PIRELLI	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	27/03/2019	Inspection Date	01/04/2019
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>6 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 2516P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOTLID	TO REPAIR SEE LABOUR	2,645.31	-
1	BOOTLID REAR LOGO	NECESSARY	75.00	75.00
1	BOOTLID "CLS" EMBLEM	NECESSARY	72.50	72.50
1	BOOTLID "350" EMBLEM	NECESSARY	78.00	78.00
1	BOOTLID "C&C" LOGO	NECESSARY	45.00	45.00
1	BOOTLID "TG TRONIC" EMBLEM	NECESSARY	72.80	72.80
1	BOOTLID INNER LOCK	SHORTED	439.50	439.50
1	BOOTLID WEATHERSTRIP	TWISTED / NECESSARY	288.62	288.62
1	BOOTLID CHROME MOULDING	NOT NECESSARY	350.00	-
1	REAR BUMPER	DENTED	2,466.21	2,466.21
1	REAR BUMPER CHROME MOULDING	NECESSARY	241.33	241.33
2	REAR BUMPER SIDE HOLDERS @\$171.00	NECESSARY	342.00	342.00
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
1	REAR BUMPER REINFORCEMENT	BENT	665.30	665.30
1	REAR BUMPER TOP RETAINER	CRACKED	188.20	188.20
4	REAR BUMPER PDC SENSORS @\$261.62	SHORTED (2 PCS ONLY)	1,046.48	523.24
1	REAR BUMPER LOWER COVER N/S	CRACKED	98.50	98.50
1	REAR BUMPER LOWER SKIRTING	DEFORMED	533.82	533.82
1	REAR BUMPER LOWER CENTRE LAMP	CRACKED	243.23	243.23
1	REAR BUMPER EXHAUST CHROME N/S	SERVICEABLE	450.00	-
2	TAILLAMPS @\$901.10	CRACKED	1,802.20	1,802.20
1	REAR END PANEL	DENTED	988.35	988.35
1	REAR END PANEL TOP GARNISH	TWISTED	266.20	266.20
2	FRONT HEADRESTS @\$932.82	CRACKED / ACTIVATED	1,865.64	1,865.64
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,018.30	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	605.30	-
	LESS 10% DISCOUNT		-	-1,135.56
			16,947.79	10,220.08
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		80.00	30.00

Report Ref No. CS/TP19005759/Uqd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REPLACING REAR REVERSE SENSOR.	NOT NECESSARY	80.00	50.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	100.00
	TO SPRAY RUST PROOFING.		80.00	50.00
	TO DISMANTLE & REPLACING,REPROGRAMME HEADREST.		180.00	100.00
	TO TRANSFER BOOTLID MECHANISM.		150.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR FLOOR PANEL.		980.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,380.00	1,200.00
			3,080.00	2,330.00
<b>GRAND TOTAL</b>			<b>20,027.79</b>	<b>12,550.08</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>10,000.00</b>

Report Ref No. CS/TP19005759/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.