

12/03/2011

ASS. REC. BY:

REF: CS/MSG19005763/ GCD312

Special Instruction:

Surveyor: GO
Munim

ASSIGNMENT (Office)

From (Person): Jawyn Tay ming of MSG

Date/Time: 1. Apr. 2017 18:09 PM

Estimated Cost: _____ Bill to: _____

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 8194 B

Insured: SKK 8181U

at Workshop m/s Team Auto pro

Tel: 62581955

of N038 Woodlands Industrial Park E1, #05-16 (Sin ming Auto City 01#14)

Policy No: 29114470 QMX

Claim No: 58 9139

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)

D.O.A. 29/3/2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 2.4.19 9.44 a.m

Person Contacted: Michelle

Vehicle IN OUT

Date/Time	Action/Instruction	Estimate (X)	Inspection At
	SLJ 8194B - X		Sin ming Auto City 01#14
	SKK 8181U - CS3/AIG14013734/CP92-1		D.O.A - 18/07/2014

PRS
Gd

REF: MS19

7907B

ASSIGNMENT

From: _____ Date: 2.4.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 8194 B

at Workshop m/s Team AutoPro

of Sin Ming Auto City of #14

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "w/r"

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLJ 8194 B Yr Regn: 02 Aug 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Merce C180 c.c 1796

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 81691 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2043492F838454

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/45R17 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm

D.O.A. _____ D.O.I. 02-04-19

Survey held at w/s _____ 3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$5000 - \$6000 <i>Amounts</i>
	3/4/2019.

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

Date/Time, File Return to? _____

2) _____

Report Format: PRE

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 7

Resurvey No. of Trip: -

Add Fee: : Site Insp (\$ _____) : Interview (\$ _____) : Tech. Invs (\$ _____) : Weekend (\$ _____)

Survey Fee:	120
Transportation:	
S + RS, SI	
Photos	
Others	10
TOTAL	130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Apr 2019		01 Apr 2019 18:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	Tay Hoan Jye, ID: S8029713J			
Main Claimant:	LOH PEI YAO KEVIN, ID: S8037907B			
Vehicle Reg. No.:	SLJ8194B	Date of Loss:	29/03/2019 17:00 - :59 [79 Months and 27 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 589139	Policy/Cover Note No.:	29114470QMX Coverage: 13/02/2019 - 12/02/2020	
Vehicle Reg. No. (Insured):	SKK8181U	Policy No. (Claimant):		
		Excess:		
Repairer:	Team Autopro Pte Ltd - Woodlands (HQ) NO.38 WOODLANDS INDUSTRIAL PARK E1, #05-16, 757700 Woodlands - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/04/2019]			
Driver/Custodian (Insured):	Tay Hoan Jye (), NRIC: S8029713J Email:			
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: DISPUTE CONTACT: ALAN KOH/ FREDERICK LIM 9092 7279/9674 6635. On WP.			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS											View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					
No results.														

62581956
michelle / Bell

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7907B
Vehicle Details	
Vehicle No.:	SLJ8194B
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	27182030418401
Chassis No.:	WDD2043492F838454
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$42,089.00
Original Registration Date:	02 Aug 2012
First Registration Date:	02 Aug 2012
Transfer Count:	1
Actual ARF Paid:	\$42,089.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Aug 2022
PARF Rebate Amount:	\$27,357.00
Intended COE Rebate Details	
COE Expiry Date:	01 Aug 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$90,501.00
COE Rebate Amount:	\$30,118.00
Total Rebate Amount:	\$57,475.00

The information contained herein is correct as at 03 Apr 2019

OK

▶ Mercedes-Benz c180 Used Vehicle List (3 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Mercedes-Benz C-Class C180 CGI Coupe	\$69,500	\$15,100 /yr	15-May-2012	1,796 cc	124,582 km		Availabl

Car Wrapped In Matte Satin Red! Full C63 Black Series AMG Body Kit Worth Up To \$15k! Rare Full Panoramic Sunroof! 100% Accident-Free! Price Negotiable For Serious Buyer Only! No Dealers/Consignment Ag...

Office No. - -

Donald - 97229369

Mercedes-Benz C-Class C180 Coupe	\$60,500	\$12,880 /yr	17-May-2012	1,796 cc	83,000 km	Carsmart Pte Ltd	Availabl
---	-----------------	--------------	-------------	----------	-----------	------------------	-----------------

Best Deal! High Rebate Amount Means Minimum Lost. Sporty Moon Roof Sport Unit With 3M White Vinyl Stickers. Sport Rim With New Tyres Accident Free. Welcome Trade In, Bank Loan And In House Loan Avail...

Office No. - 62006351

Tony - 88213020 | Vince - 86878866

Mercedes-Benz C-Class C180 CGI Coupe	\$61,388	\$12,650 /yr	02-Jul-2012	1,796 cc	112,000 km	Cars 88 Pte Ltd	Availabl
---	-----------------	--------------	-------------	----------	------------	-----------------	-----------------

Well Maintained Coupe! Prestigious Sports Seats With Automatic Front Movement. Higher Spec Model With GPS And Moonroof Options. Own Reluctant Sales As He Has Treated This Car With Lots Of Love And C...

Office No. - -

Alex - 92242194 | Marvin - 90094433

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 29/03/2019 (dd/mm/yy) Time of Accident: 17:50 (24-HR-FORMAT)
Vehicle No.: SLJ 8194 B Vehicle Make & Model: Mercedes C180
Exact location of Accident: PSA Building S(119963) L1 carpark of Arc.
Policyholder's Name / IC No.: Loh Pei Yao, Kevin S8037907B
Driver's Name / IC No.: Loh Pei Yao, Kevin S8037907B (As Above)
Driver's Contact No.: 9382 3035 Company Contact No.: _____
Driver's Address: Blk 192 Depot Road #14-24 S(109690)
Insurance Company: NTUC Income Email address (if any): _____

Relationship between Owner & Driver: Owner
Owner / Spouse / Children / Friend / Parent / Others specify: _____

What do you wish to claim? (Please TICK one only)

Own Insurance / Other Vehicle (The one you want to claim against) / Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

Occupation (nature of job) Indoor / Outdoor

Private use / Work purpose

No. of Passengers (Including Driver): 01

Passenger Name : _____
Passenger Name : _____

Gender : _____
Gender : _____

Weather condition & Road conditions? (On the day of accident)

Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? Yes / No

Any Injuries: Yes / No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: Yes / No (If YES) Which Police Station: Queenstown NPC

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: SKK 8181 U

Driver's Contact No: _____ Insurance Company (If any): MSIG Insurance

2. Driver's Name / IC No: _____ Vehicle No: _____

Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.



**SINGAPORE
POLICE FORCE**



D/20190329/2053

1 of 2

POLICE REPORT (NP299)

Report No. D/20190329/2053

Police Station Of Origin
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999


Date/Time Report Made 29/03/2019 21:12		Vide Report No.		Station Diary No. 102	
Name Of Informant LOH PEI YAO, KEVIN		Address APT BLK 192 DEPOT ROAD #14-24 SINGAPORE 109690			
ID Type / ID No. NRIC NO / S8037907B		Contact No. Home/Office 93823035		Mobile	
Nationality SINGAPORE CITIZEN		Email Address			
Occupation Security Operations		Sex Male	Age 38	Date of Birth 28/11/1980	Race Chinese
Institution/School Name		Language English			
Date/Time Of Incident 29/03/2019 17:50 - 29/03/2019 17:55		Location Of Incident 460 ALEXANDRA ROAD PSA BUILDING SINGAPORE 119963 Level 1 Carpark of Arc			

Brief details.

On the 29 Mar 2019, at about 1750hrs, I drove into the Level 1 carpark of Alexandra Retail Centre (ARC). I am the owner of Mercedes C180, vehicle number SLJ8194B. I was reversing my car into the right side of the carpark lot. Suddenly, a car bumped into my car from the left side. As a result of the bump, my vehicle suffered a severe dent on the left side. No one was injured. This happened at about 1751 hrs. The owner of the vehicle who bumped into my car is Tay Hoan Jye, vehicle number SKK8181U. I am

Signature Of Officer Recording The Report: D / Insp KIMBERLY LIM PEIXUAN 		Signature Of Informant: 	
Signature Of Interpreter: Not applicable		Date/Time: 29/03/2019 21:12	
Officer In-Charge Of Case: D / Clementi Police Divisional Investigation Branch / Insp ANG BENG HWA Contact No.: 68727683		Classification Of Case:	

Authentication Stamp



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2019 14:18
Date Of Accident	29/03/2019 17:50
Exact Location Of Accident	PSA BUILDING L1 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ8194B
Insured/Policyholder	
Name Of Registered Owner	LOH PEI YAO KEVIN
NRIC No	S8037907B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92833035
Alternative Phone No	Office-92833035

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093141457-01
Cover Note Number	

Driver

Name of Driver	LOH PEI YAO KEVIN
NRIC No	S8037907B
Date Of Birth	28/11/1980
Occupation	INDOOR
Date Of Driving Pass	14/04/2005
Driving Experience	13 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92833035

Fax Number	
Contact Number	OFFICE-92833035
EEmail Address	NOEMAIL
Address	APT BLK 192 DEPOT ROAD #14-24
Postcode	109690
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes,Please state which Police Station	
Police Station Name	QUEENSTOWN N.P.C
Police Station Address	ROAD: 3 QUEENSWAY #01-03 , POSTCODE: 149073 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4719999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK8181U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

10/10/2010 10:10:10

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report D/20190329/2053.


Would like to state that Vehicle B has 5 seconds to react to stop to prevent this accident but Vehicle B did not stay safety distance with my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



D/20190329/2053

1 of 2

POLICE REPORT (NP299)

Report No. D/20190329/2053

Police Station Of Origin
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999


Date/Time Report Made 29/03/2019 21:12	Vide Report No.	Station Diary No. 102
Name Of Informant LOH PEI YAO, KEVIN	Address APT BLK 192 DEPOT ROAD #14-24 SINGAPORE 109690	
ID Type / ID No. NRIC NO / S8037907B	Contact No. Home/Office 93823035	Mobile
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Security Operations	Sex Male	Age 38
Institution/School Name	Date of Birth 28/11/1980	Race Chinese
Date/Time Of Incident 29/03/2019 17:50 - 29/03/2019 17:55	Location Of Incident 460 ALEXANDRA ROAD PSA BUILDING SINGAPORE 119963 Level 1 Carpark of Arc	

Brief details.

On the 29 Mar 2019, at about 1750hrs, I drove into the Level 1 carpark of Alexandra Retail Centre (ARC). I am the owner of Mercedes C180, vehicle number SLJ8194B. I was reversing my car into the right side of the carpark lot. Suddenly, a car bumped into my car from the left side. As a result of the bump, my vehicle suffered a severe dent on the left side. No one was injured. This happened at about 1751 hrs. The owner of the vehicle who bumped into my car is Tay Hoan Jye, vehicle number SKK8181U. I am

Signature Of Officer Recording The Report: D / Insp KIMBERLY LIM PEIXUAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 29/03/2019 21:12
Officer In-Charge Of Case: D / Clementi Police Divisional Investigation Branch / Insp ANG BENG HWA Contact No.: 68727683	Classification Of Case:

Authentication Stamp



POLICE REPORT



**SINGAPORE
POLICE FORCE**



D/20190329/2053

2 of 2

POLICE REPORT (NP299)


CONTINUATION OF REPORT

Report No. D/20190329/2053

lodging this report so that it will help facilitate my insurance claims.

Signature Of Officer Recording The Report: D / Insp KIMBERLY LIM PEIXUAN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 29/03/2019 21:12
Officer In-Charge Of Case: D / Clementi Police Divisional Investigation Branch / Insp ANG BENG HWA Contact No.: 68727683	Classification Of Case:

Authentication Stamp



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Apr 2019		01 Apr 2019 18:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Tay Hoan Jye , ID: S8029713J								
Main Claimant:	LOH PEI YAO KEVIN , ID: S8037907B								
Vehicle Reg. No.:	SLJ8194B	Date of Loss:	29/03/2019 17:00 - :59 [79 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 589139	Policy/Cover Note No.:	29114470QMX Coverage: 13/02/2019 - 12/02/2020						
Vehicle Reg. No. (Insured):	SKK8181U	Policy No. (Claimant):							
		Excess:							
Repairer:	Team Autopro Pte Ltd - Woodlands (HQ) NO.38 WOODLANDS INDUSTRIAL PARK E1, #05-16, 757700 Woodlands - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 02/04/2019]								
Driver/Custodian (Insured):	Tay Hoan Jye (), NRIC: S8029713J Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: DISPUTE CONTACT: ALAN KOH/ FREDERICK LIM 9092 7279/9674 6635. On WP.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ8194B (589139)
[SKK8181U]
TP
LOH PEI YAO KEVIN
Mar 29 2019 5:00PM
[Tay Hoan Jye]
Team Autopro Pte Ltd - Woodlands

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
2	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
3	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
4	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
5	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
6	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
7	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
8	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
9	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
10	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
11	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
12	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
13	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
14	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
15	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
16	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
17	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
18	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
19	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
20	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
21	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
22	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
23	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
24	04/04/19 13:45	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/04/19 17:32	SLJ8194B E-FILE REPORT	Load PDF	
2	01/04/19 17:33	SLJ8194B GIA REPORT	Load PDF	
3	01/04/19 17:33	SKK8181U E-FILE REPORT	Load PDF	
4	01/04/19 17:42	SURVEY DISAGREE ON SJE - ASSIGN LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19005763/GCD3E2
Date: 04/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114470QMX
Claimant Vehicle No : SLJ8194B	Insured Vehicle No :	SKK8181U
Date of Loss: 29/03/2019	Nature of Claim:	TP
		Claim No: 589139

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ8194B	Engine No:	27182030418401
Make & Model:	MERCEDES-BENZ C180, 1.8 (A)	Chassis No:	WDD2043492F838454
Reg. Date:	02/08/2012 (Man. Year: 2011)	Odometer:	81691 km
Colour:	Silver		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/04/2019	
Date Inspected:	02/04/2019	Inspected At: SIN MING AUTO CITY 01#14 Repairer : Team Autopro Pte Ltd - Woodlands (HQ)
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
Parts: 143	MERCEDES-BENZ C180 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ8194B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >