

Hwee Jie

REF: HTUC NS/INC 19005781/J9d35

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No 508555065702 (11/10/2018 - )

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 0.5 days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SG5772K Yr Regn: 29 Jun 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Man A95 c.c. 10518Colour: Green A/C: Insured / Std / NI / NASp. Reading: 202689 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WMWA9522SG7003246Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 275/70R22.5

R: \_\_\_\_\_

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7/7 mmL/Bal. 7 mm L/Bal. 7/7 mmD.O.A. 28/3/19 D.O.I. 29/3/19Survey held at SumitDes. of Damages: Frt / Rear / D/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SG5772K - X
	PC 841A - X
	1961300, 0.5 day (red) \$ 162.40, 37.1%
	RECEIVED 02 MAY 2019

Date/Time. File Pass to? ☐ : Preli. Report1) 02/5/2019 ☐ : Final Report

Date/Time. File Return to?

Days Of Repair: 0.5Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + PG. \$

) Photos

) Other

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: TI

Lump Sum / L.B.C. (\$)

1300

**Income: Follow-Through Survey**Date : 29/04/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/1041561-002	COMFORT TRANSPORTATION PTE LTD	SHD 3952S	SKR 6508M	23/04/2019
2	MT/1041777-002	COMFORT TRANSPORTATION PTE LTD	SHC 2142A	FBG 376E	24/04/2019
3	MT/1038898-002	CITYCAB PTE LTD	SHC 956G	GBE 6770X	04/04/2019
4	MT/1041562-002	COMFORT TRANSPORTATION PTE LTD	SHA 2506U	SJC 2359T	23/04/2019
5	MT/1041551-002	CITYCAB PTE LTD	SHC 7042Y	SBR 7674R	24/04/2019
6	MT/1042257-001	SMRT BUSES LTD	SG 5772K	PC 8211A	28/03/2019

eBaoTech

General/Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)  
[Notice of Loss](#)

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="28/03/2019 13:39"/>							
Vehicle No.(For Motor)	<input type="text" value="PC8211A"/>	Certificate Number	<input type="text"/>							
<input type="button" value="Search"/>										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5085550657-02		COMFORTDELGRO BUS PTE LTD	199607256W	GFT	Comprehensive	PC8211A	PC8211A	11/10/2018	
<input type="button" value="Continue"/>										

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/03/2019 14:11
Date Of Accident	28/03/2019 08:15
Exact Location Of Accident	BOON LAY WAY BS 28341
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG5772K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81111111

### Vehicle Particulars

Manufacturer	MAN
Model	DOUBLE DECKER

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	

### Driver

Name of Driver	CHUA ENG ANN
NRIC No	S0221998J
Date Of Birth	06/04/1954
Occupation	OUTDOOR
Date Of Driving Pass	28/06/1997
Driving Experience	21 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 6 ANG MO KIO ST 62

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 65

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

My bus was stationary for pax activities at BS: 28341. A private bus PC8211A cut into my lane to pick up passengers at the front of the bus stop, and the left portion of the private bus hit my bus right side mirror. No injuries were reported.

#### Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: PEND DOWNLOAD  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC8211A  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category BUS  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

 67864

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name: **BALQISH**  
NRIC/FIN No.: **S8340325Z**

**Sketch Plan Pg. 2**

### SKETCH PLAN

Bus Stop  
ID 08341

Chinese 8  
Bus STOP

Chinese      good      station

8-15  
28 13

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO REPORT

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signat  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

G-864



Reporting Centre Personnel's Signature  
Name: BALQISH  
NRIC/FIN No.: S8340325Z



> [Back to OneMotoring](#)

## Enquire Transfer Fee

### Vehicle Details

Vehicle No. :	SG5772K
Vehicle Type :	H20 - Public Transport Bus/Coach/Minibus
Vehicle Attachment 1 :	Air-Conditioned
Vehicle Scheme :	OmniBus (LTA-ARF exempted)
Vehicle Make :	MAN
Vehicle Model :	A95
Chassis No. :	WMAA95ZZ5G7003246
Propellant :	Diesel
Engine No. :	50343392184343
Engine Capacity :	10518 cc
Maximum Power Output :	-
Maximum Laden Weight :	23100 kg
Unladen Weight :	14920 kg
Year Of Manufacture :	2015
Original Registration Date :	29 Jun 2016
Lifespan Expiry Date :	28 Jun 2033
Road Tax Expiry Date :	28 Jun 2019
Inspection Due Date :	28 Jun 2019
Intended Transfer Date :	06 May 2019
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 28 Jun 2019. You may renew the road tax from 29 Mar 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 28 Jun 2019, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable (From 29 Jun 2019 to 28 Dec 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	765.00	-	765.00
<b>Total Amount Payable :</b>			<b>790.00</b>

### Amount Payable (From 29 Jun 2019 to 28 Jun 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	1,530.00	-	1,530.00
<b>Total Amount Payable :</b>			<b>1,555.00</b>

You may print this page for reference.

[OK](#)

[Print](#)





## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 30/03/2019

User ID : JeongCH

### Section A - Accident Details

Registration Number	SG5772K
Case Reference Number	BUS/03/19/5056
Registration Date	8/18/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	CHUA ENG ANN
Type of Accident	Side Swipe
Accident Date and Time	3/28/2019 8:15 AM
Accident Reported Date and Time	3/28/2019 12:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100635
Special Instruction to ARC, if any	SG5772K - RIGHT SIDE MIRROR DAMAGED PC8211A - TP INSURED WITH NTUC - LEFT PORTION DAMAGED
Prepared Date and Time	3/30/2019 9:23 AM
Chassis Number	WMAA95ZZ5G7003246
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$1,379.16	\$1,379.16
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,909.16	\$1,644.16
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted By	Jeong Choon Hwee	Hwee Jie
ARC / Surveyor Sign Off Date	30/03/2019 9:42 AM	30/03/2019 11:21 AM
Signature		
Remarks	P repair. After repair photo. L/S	

 8/4/19

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63885582
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/03/2019

User ID : JeongCH

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL FRONT VIEW MIRROR RH	\$530.00	\$265.00
<b>Total Labour</b>	<b>\$530.00</b>	<b>\$265.00</b>

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161	BODY RH	4001M01-ACCE467	MIRROR,VIEW.FRONT,R H, FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	Replace
6010162	BODY RH	4001M01-ACCE46	ARM.MIRROR VIEW.FRONT,RH, FOR MAN	1.00	\$267.50	10.00	\$258.75	Replace	Replace
<b>Total</b>					<b>\$1,532.40</b>		<b>\$1,379.16</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## SMRT Accident Vehicle Repair Estimates

Shuan Chan

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63885502
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/04/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5772K
Case Reference Number	BUS/03/19/5056
Registration Date	18/8/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	CHUA ENG ANN
Type of Accident	Side Swipe
Accident Date and Time	28/3/2019 8:15 AM
Accident Reported Date and Time	28/3/2019 12:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100835
Special Instruction to ARC, if any	SG5772K - RIGHT SIDE MIRROR DAMAGED PC8211A - TP INSURED WITH NTUC - LEFT PORTION DAMAGED
Prepared Date and Time	30/3/2019 9:23 AM
Chassis Number	WMAA95ZZ5G7003246
Mileage	
Work Shop	
Repair Completion Date and Time	

L/S \$1300/- O.S. delay.

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$1,103.33	\$1,103.33
Total Other Cost	\$0.00	(\$53.00)
TOTAL COST	\$1,633.33	\$1,315.33
Lump Sum Total	\$1,650.00	\$1,300.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted By	Jeong Choon Hwee	Hwee Jie
ARC / Surveyor Sign Off Date	02/04/2019 10:25 AM	02/04/2019 10:46 AM
Signature		
Remarks	L/S repair. After repair photo.	

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/04/2019

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL FRONT VIEW MIRROR RH	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$53.00)
Total Other Costs	\$0.00	(\$53.00)

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161	BODY RH	4001M01-ACCE467	MIRROR,VIEW:FRONT,R H, FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	Replace
6010162	BODY RH	4001M01-ACCE46	ARM, MIRROR VIEW:FRONT,RH, FOR MAN	1.00	\$287.50	10.00	\$258.75	Replace	Replace
Total					\$1,532.40		\$1,379.16		

MIS  
CRA

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2052-40



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19005781/Jqd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 06-05-2019  
189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 8211A	Veh. Inspected	SG 5772K
Policy No.	5085550657-02	Coverage (\$)	0.00
Claim No.	MT/1042257-001	Excess (\$)	0.00
Assign From		Assign Date	29/03/2019

### 2. Vehicle Particulars & Condition

Make & Model	MAN A95	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WMAA95ZZ5G7003246	Colour	GREEN
Odometer	202689	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	7 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	7 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	7/7 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	7/7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	28/03/2019	Inspection Date	29/03/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	0.500 Working Days
-------------------------------------	--------------------



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5772K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	MIRROR, VIEW: FRONT, RH, FOR MAN	MISSING	1,244.90	1,244.90
1	ARM MIRROR VIEW: FRONT, RH FOR MAN		287.50	287.50
	LESS 10% DISCOUNT		-	-153.24
			1,532.40	1,379.16
	<b>LABOUR</b>			
	TO REMOVE & INSTALL VIEW MIRROR RH.		530.00	265.00
			530.00	265.00
	<b>GRAND TOTAL</b>		<b>2,062.40</b>	<b>1,644.16</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,300.00</b>

Report Ref No. NS/INC19005781/Jqd3s2

ONG HWEE JIE

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.