



Case Details

Case Reference Number : TAX/03/19/2146
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6356T

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6298-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 29/03/2019 06:50 PM
 Vehicle Age(In Months) : 41

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	* X N/A
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	* / BR
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	* / N/A
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Check	* X N/A
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Check	* X N/A
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Check	* X N/A
One Time Key In	Main			BUMPER SEAL, RR LH	1	66.90	66.90	25.00	50.18	Replace	1	66.68	Replace	* / CRU
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	* / BR
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	* X N/A
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check	* X N/A
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Check	* X N/A

Total Spare Part Cost 25,157.04

Surveyor Total 3,874.26

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 20,125.63

Final Sur Total 3,099.41

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0	Check * X	N/A
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0	Check * X	N/A
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace * /	DO
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace * /	N/C
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace * /	N/C
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace * /	N/C
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace * /	N/C
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace * /	BR
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace * /	N/C
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace * /	BR
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace * /	N/C
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check * X	N/A
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check * X	N/A
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check * X	N/A
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	0	0	Not Give * X	N/A
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give * X	N/A
Total Spare Part Cost									25,157.04	Surveyor Total 3,874.26				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									20,125.63	Final Sur Total 3,099.41				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check	* X N/A
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	* X N/A
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	* X N/A
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Check	* X N/A
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Check	* X N/A
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Check	* X N/A
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Check	* X N/A
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.60	1,436.60	10.00	1,292.94	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	146.10	146.10	10.00	131.49	Replace	0	0	Check	* X N/A
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace	* / N/A
One Time Key In	Main			LICENSE PLATE LAMP	2	35.70	71.40	10.00	64.26	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give	* X N/A

Total Spare Part Cost 25,157.04

Lump Sum Discount (%) 20.00

Final Spare Part Cost 20,125.63

Surveyor Total 3,874.26

Lump Sum Dis (%) 20

Final Sur Total 3,099.41

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	✓
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace	✓
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	✓
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	X N/A
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Check	X N/A
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ MC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ MC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	X N/A
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	X N/A
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check	X N/A
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check	X N/A
One Time Key In	Main		4006314	SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	X N/A
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	X N/A
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	X N/A
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	X N/A
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0	Check	X N/A
Total Spare Part Cost									25,157.04	Surveyor Total			3,874.26	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									20,125.63	Final Sur Total			3,099.41	

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0	Not Give	X N/A
One Time Key In	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0	Not Give	X N/A
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Check	X N/A
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Check	X N/A
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Check	X N/A
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Check	X N/A
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	0.00	307.00	Replace	0	0	Check	X N/A
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Not Give	X N/A
One Time Key In	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	X N/A
Total Spare Part Cost									25,157.04	Surveyor Total		3,874.26		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									20,125.63	Final Sur Total		3,099.41		

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	* X NAI
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	* X NAI
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	1	493.56	Replace	* Z / BR
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	* X NAI
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	* / DD
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	* / N/C
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	* / N/C
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check	* X NAI
One Time Key In	Main			LID ASSY, FUEL	1	102.00	102.00	25.00	76.50	Replace	1	0	Repair	* X R
One Time Key In	Main			CABLE SUB-ASSY, FUEL LID	1	63.90	63.90	25.00	47.92	Replace	0	0	Check	* X NAI
One Time Key In	Main			RETAINER, FUEL LID CABLE	1	5.90	5.90	25.00	4.43	Replace	0	0	Check	* X NAI
One Time Key In	Main			CAP ASSY, FUEL TANK	1	68.10	68.10	25.00	51.07	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			PIPE SUB-ASSY, FUEL NECK	1	230.80	230.80	25.00	173.10	Replace	0	0	Check	* X NAI
One Time Key In	Main			TUBE, FUEL TANK	1	36.10	36.10	25.00	27.08	Replace	0	0	Check	* X NAI
One Time Key In	Main			TANK SUB-ASSY, FUEL	1	745.10	745.10	25.00	558.83	Replace	0	0	Check	* X NAI
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	1	126.07	Replace	* / N/C
Total Spare Part Cost									25,157.04	Surveyor Total 3,874.26				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									20,125.63	Final Sur Total 3,099.41				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	* ✓ MC
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	* ✓ TN
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	1	0	Repair	* X R
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	* X NA
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Give	* X NA
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	* X NA
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	* X NA
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	* X NA
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	* X NA
One Time Key In	Main			DOOR RRLH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	* X R
One Time Key In	Main			DOOR LOCK RRLH	1	709.30	709.30	25.00	531.97	Replace	0	0	Check	* X NA
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Check	* X NA
One Time Key In	Main			DOOR HINGE UPPER RRLH	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give	* X NA
One Time Key In	Main			DOOR HINGE LOWER RRLH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	* X NA
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Check	* X NA
Total Spare Part Cost									25,157.04	Surveyor Total 3,874.26				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									20,125.63	Final Sur Total 3,099.41				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,690.00	1,000	
Total:			1,690.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY REAR SPOILER	180.00	0	
5	Main	TO RESPRAY REAR PANEL	180.00	0	
6	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
7	Main	TO RESPRAY REAR MEMBER,RH	180.00	0	
8	Main	TO RESPRAY REAR MEMBER,LH	180.00	0	
9	Main	TO RESPRAY REAR LH WHEEL HOUSE	180.00	0	
10	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0	
11	Main	TO RESPRAY RIM	240.00	50	
12	Main	TO RESPRAY FUEL LID COVER	180.00	20	
13	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
14	Main	TO RESPRAY REAR FENDER LH	378.00	200	
15	Main	TO RESPRAY REAR FENDER RH	378.00	0	
16	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
Total:			3,732.00	670.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	126.00	90	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
Total:			3,326.00	630.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	30	N/C
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE / REFIT SEAT	120.00	50	N/C
6	Main	TO ALIGN CHASSIS	350.00	0	
7	Main	TO REMOVE & REFIT FUEL TANK	120.00	0	
8	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
9	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	250	N/C
10	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	N/C
11	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	N/C
12	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50	N/C
13	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30	N/C
14	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	30	N/C
15	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
16	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	60	N/C
17	Main	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	40	N/C
18	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0	
19	Main	TO REPLACE SUNDRY PARTS	100.00	0	
20	Main	TO WASH AND VACUUM	60.00	0	
Total:			3,326.00	630.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	20,125.63	3,099.41
Total Labour Cost	1,690.00	1,000.00
Total Spray Painting	3,732.00	670.00
Other	3,326.00	630.00
Overall Total	28,873.63	5,399.41

4/1/2019

<https://vacswb.smrt.com.sg/Estimation.aspx>

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Lump Sum Repair Option		☒
Lump Sum Total	28,850.00	5,400.00
Surveyor Approved Amount		5,400.00
No of Repair Days*	12	8
Remarks		L/S REPAIR, PHOTO AFTER PAINT.
Surveyor Name		Hwee Jie
Signature		
Survey Date	01/04/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damage to list during resurvey
- Parts provided subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal methods are allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7DX / 03 / 19 / 2146	Date of Collection	2 / 4 / 19
Vehicle No	SHD 6356 T	Date of Request	5 / 4 / 19
Vehicle Model	76307A PRIUS	Number of Days to Extend	3 / 6 DAYS

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	8998, 99, 9000	Bumper Lip Cover RR LH		\$ 72.20 ✓
2	9001, 02, 103	Bumper Lip Cover RR RH		\$ 118.10 ✓
3	9004, 05, 06	Bumper Lip Rear		\$ 228.90 ✓
4	9007, 08, 09, 10	Bumper Side Retainer RR LH		\$ 94.50 ✓
5	9012, 13, 14	Under Cover Sub Assy RR Floor		\$ 514.50 ✓
6	9015, 16, 17, 25, 26	Bumper Reinforcement Rear		\$ 205.70 ✓
7	9021, 22, 27, 28	Arm Sub Assy RR Bumper LH	\$194.70	\$ 139.60 ✓
8	9023, 24, 29, 30	Arm Sub Assy RR Bumper RH		\$ 139.60 ✓

CUT \$54.11
 CRA \$88.51
 CUT \$171.6
 CRA \$71.16
 BUL \$385.6
 DD \$154.7
 BT \$130.58
 BT \$194.70

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

①

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	70X/03/19/2146	Date of Collection	2/4/19
Vehicle No	SHD 6356 T	Date of Request	5/4/19
Vehicle Model	70X07A PLUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price	
1	9018,19,20	Tail Gate Door Weatherstrip		\$353.40	✓ CUT \$265.01
2	9043,44,45	End Panel Cover Deck Trim Hole		\$46.10	✓ CRA \$34.58
3	9039,40,41,42	End Panel Cover Deck Trim RR		\$121.10	✓ SCR \$90.83
4	9054,60,61	Member Sub Assy RR LH		\$174.10	✓ BUC \$130.51
5	9046,47,48	Rear LH Floor Panel		\$185.90	✓ BUC \$76.50
6	9031,32,33,34,35	End Panel		\$602.10	✓ BUC \$451.51
7	9062,63,64,65,66,67	Spare Tyre Panel		\$667.70	✓ BUC \$500.71
8	9036,37,38	To Repair Tail Lamp Panel		\$150.00	✓ \$80

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) ADVISOR

I do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

CHIA

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(2)

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX/03/19/2146	Date of Collection	2/4/19
Vehicle No	SHD 6356T	Date of Request	5/4/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price	
1	9055,56,57	To Repair Rear LH wheel House		\$500.00	\$150
2		To Respray End Panel		\$180.00	\$100
3		To Respray Spare Tyre Panel		\$180.00	\$100
4		To Respray Rear Member LH		\$180.00	\$100
5		To Respray Rear LH wheel House		\$180.00	\$100
6		To Respray Rear RH Floor Panel		\$180.00	\$100
7		To Respray Rear LH Tail Lamp Panel		\$180.00	\$80
8					

<<<Please submit photographs for damaged parts>>>

2/4/19

I. (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Charles

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff

(2)