



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19005803/Eps3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 10-12-2020



ATTN:RICHARD

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGV 1362A	Veh. Inspected	SMG 4337L
Policy No.	GA360249	Coverage (\$)	0.00
Claim No.	S9M01IQZ	Excess (\$)	0.00
Assign From		Assign Date	02/04/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180K	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WDD2040452A317550	Colour	SILVER
Odometer	174786	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/03/2019	Inspection Date	02/04/2019
Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------