

DATE/TIME

Steve

REF:

ASSIGNMENT

From

Date:

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No:

Claims No

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SMG 4337L

Vt Regn.

5/10/09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz C180K

CC

1597.

Colour

Silver

A/C

Insured / Std / NI / NA

Sp. Reading

174 786

T/Ratio: Insured / Std / NI / NA

Eng/No:

Ci/No:

W00 2040452A 317550

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/3/19

D.O.I.

2/4/19

Survey held at

Xingya

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear RH

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV- 24.000

PV- 19.282

NV- 4.718

Date/Time, File Pass to?

☐

Prel. Report

4)

Date/Time, File Return to?

☐

Final Report

2)

Report Format:

Lump Sum / I.B.L (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

\$ + R5 \$

Photos

Other

TOTAL