

22/03/2019

ASS. REC. BY:

REF: CS/A1419005813/ VQd3n2 Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

Main

From (Person): Viniane Hor Yin Rul of

A14

Date/Time:

02/4/19

Estimated Cost:

Bill to:

OD-TP-WS-TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLG 2592R

Insured:

SPD 8008 J

at Workshop m/s Euro Success Services

Tel:

98289277

of 1 Kati Bukit Avenue 6 #02-03

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31.3.2019

3.4.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2.4.2019 4.01 p.m

Person Contacted:

Ah Huat

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SLG 2592R - CS/LPC 120196031 VQd3n2	D.O.A. - 25/10/2018
	SPD 8008 J - NA/msg 15004144 n4	D.O.A. - 02/03/2015

REF: A1G

## ASSIGNMENT

From:

Date: 3.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 2592R

at Workshop m/s Euro Success

of 1 Kaki Bukit Avenue 6 # 02-03

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

60

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

WP

LIA 47599

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG 2592R

Yr Regn:

9.16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Mazda 3

c.c 1496

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

156010

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BM42A8G0344068

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or other

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Campeon

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/3/19

D.O.I.

3/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/4/19

2/5 @ 6200 confirmed with AM Insur.  
(Ref to 9052.24, 59%)

RECEIVED 16 APR 2019

Date/Time, File Pass to?



Preli. Report

15/4/19



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

250  
10

260

Report Format:

MER-TP

Lump Sum / I.B.I. (\$)

6200

PRE-REPAIR INSPECTION REQUEST – SLG2592R vs SFD8008J (OI) on D.O.A.: 31/03/2019

From: Hor, Yinnul  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur  
Sent: 2/4/2019 3:06:56 PM

Hi,

Please refer to the enclosed request from **Hin Tat Augustine & Partners**.  
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Yin Rul, Hor (Viviane)  
AIG  
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
Shared Services – Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

Person: Ah Huat  
Time: 4.01 p.m  
Date: 2/4/19  
V: in.  
E: ✓

From: Ruby Ong [mailto:ruby@htapartners.com.sg]  
Sent: Tuesday, April 02, 2019 3:03 PM  
To: Hor, Yinnul  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur  
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFD8008J AND SLG2592R ON 31/03/2019 [HTAP Ref. TCL.MH.ro.50201.19.ess]  
Importance: High

Caution: External Email

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear Sirs

We refer to your email of even date.

Our clients are agreeable to appoint LKK Auto Consultants Pte Ltd from your list to conduct the joint pre-repair survey as a single joint expert for our clients' vehicle no. SLG 2592R.

Please make the necessary arrangements with the contact person. The details are as follows :

Venue : EURO SUCCESS SERVICES PTE LTD  
1 Kaki Bukit Avenue 6  
#02-03 Autobay  
Singapore 417883

Contact Person : Ah Huat (Tel. 9828 9277 / 6742 6231)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,  
Ruby Ong  
Secretary  
M/s Hin Tat Augustine & Partners  
20 Upper Circular Road  
#02-10/12 The Riverwalk  
Singapore 058416  
Tel : 6533 0212 ext 278  
Fax : 6338 3536 / 6533 0313  
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Hor, Yinnul <Yinnul.Hor@aig.com>  
Sent: Tuesday, April 02, 2019 1:14 PM  
To: Ruby Ong <rubby@htapartners.com.sg>  
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>  
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFD8008J AND SLG2592R ON 31/03/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัส เพื่ออ่านให้ชัดเจนโปรดพิมพ์

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부

파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-04-09 13:13 +08 to read your message.  
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul.Hor@aig.com  
To: ruby@htapartners.com.sg  
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baiji.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com  
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFD8008J AND SLG2592R ON 31/03/2019  
Date: Tue, 2 Apr 2019 05:13:41 +0000

Without Prejudice

Your Reference : TCL.MH.RO.50201.19.ESS  
Our Reference : SFD8008J

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations - Auto  
Shared Services - Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

**From:** Ruby Ong [mailto:ruby@htapartners.com.sg]

**Sent:** Tuesday, April 02, 2019 12:22 PM

**To:** Hor, Yinnul; Md Ishak, Mohd Imran; Abu Kassim, Noor Mariesa; Supramaniam, Darshene

**Subject:** [EXTERNAL] REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLG2592R [OUR REF. TCL.MH.RO.50201.19.ESS]

**Importance:** High

Caution: External Email

Your ref: SFD 8008J  
Our ref: TCL.GCN.ro.50201.19.ess

WITHOUT PREJUDICE

2 April 2019

AIG Asia Pacific Insurance Pte Ltd  
Motor Claims Department  
78 Shenton Way  
#08-16 AIG Building

By Email Only

Singapore 079120

**VERY URGENT**

Dear Sirs,

**CLAIMANT: AMV PTE LTD**

**ACCIDENT INVOLVING SLG 2592R & SFD 8008J AT BLOCK 638 ANG MO KIO AVENUE 6 CARPARK ON 31 MARCH 2019 @ 2135HRS**

We are instructed by AMV Pte Ltd to notify you of a road traffic accident on 31 March 2019 at about 2135hrs at Block 638 Ang Mo Avenue 6 carpark involving our clients' vehicle registration number SLG 2592R and vehicle registration number SFD 8008J driven by your insured/insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/04/2019 13:08
Date Of Accident	31/03/2019 21:35
Exact Location Of Accident	CARPARK AT BLK 638 ANG MO KIO AVENUE 6
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG2592R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	A&A CAPITAL SINGAPORE PTE. LTD.
Co Reg No	201727424G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98583956

### Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098713113-01 CLASSIC
Cover Note Number	

### Driver

Name of Driver	TEO BOK MING
NRIC No	S8707866C
Date Of Birth	04/03/1987
Occupation	OUTDOOR
Date Of Driving Pass	30/01/2012
Driving Experience	7 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91371191
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	368C LORONG CHUAN
Postcode	556789
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFD8008J
Vehicle Make/Model/Colour	TOYOTA COROLLA ALTIS 1.6L CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# **IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The insurer and insurance intermediaries, insurance companies and/or an admission of policy liability of the insurer or insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the SIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

Understand, acknowledge, agree and consent that:

- (1) The insurer, its employees and the General Insurance Association of Singapore (GIA) may use the information collected, disclosed and/or processed by vehicle data persons' information set out in the form and any other personal information provided by me or processed by my insurer collectively the "Personal Information" and disclose and transfer with business information to all insurers who make required records in the accident of persons who have injured vehicles involved in this accident and all other relevant information as the insurers' (the "insurers") and/or the Motor Insurance Association of Singapore (MIA) and/or the General Insurance Association of Singapore (GIA) for the purpose of:
- (a) processing, handling and/or dealing with my claim including the requirement to file a claim and/or to request for a settlement;
- (b) investigating the accident to determine fault;
- (c) for the purpose of dealing with my claim including the requirement to file a claim and/or to request for a settlement;
- (d) conducting the claims including the handling of my claim including the requirement to file a claim and/or to request for a settlement;
- (e) complying with applicable law in administering, processing, handling and/or dealing with my claim including the "Purposes";
- (f) if insurers who have injured vehicles involved in this accident and the insurers' law enforcement, insurance companies to collect, use, disclose and/or process my Personal Information for the purposes of the above Purposes; and
- (g) my Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.
- (2) My Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.
- (3) My Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.
- (4) My Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.
- (5) My Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.
- (6) My Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.
- (7) My Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.
- (8) My Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.
- (9) My Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.
- (10) My Personal Information may be disclosed by any of the insurers' to all other third party service providers for the purpose of processing my claim including the requirement to file a claim and/or to request for a settlement.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time: **2 APR 2019**

**IDAC KAKI BUKIT (VAC)**  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)  
Reporting Centre Personnel's Signature  
Name:  
NRIC/IN No:



# Sketch Plan #2 Pg. 1



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the stated date and time, I vehicle A was travelling along the stated venue as I was travelling straight, vehicle B drove out of the parking lot and collided to my front left portion of my vehicle.



### DECLARATION

We declare the following particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

- 2 APR 2019

VAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 7424G

**Vehicle Details**

Vehicle No.: SLG2592R

Vehicle to be Exported: No

Intended Deregistration Date: 05 Apr 2019

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: P520370319

Chassis No.: JM6BM42A8G0344068

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$16,359.00

Original Registration Date: 26 Sep 2016

First Registration Date: 26 Sep 2016

Transfer Count: 2

Actual ARF Paid: \$11,359.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Sep 2026

PARF Rebate Amount: \$8,519.00

**Intended COE Rebate Details**

COE Expiry Date: 25 Sep 2026

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$56,002.00

COE Rebate Amount: \$39,080.00

**Total Rebate Amount: \$47,599.00**

The information contained herein is correct as at 03 Apr 2019

OK

PHILIPS

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad


Advertiser Login

Ways of Selling

Low Mileage , 1 Owner, Low Depreciation For This Unit



Low Mileage , Low Depreciation  
For This Luxury Sedan,  
Panoramic Roof  
Absolute Wheels StarAd



Browse by Category

&lt; Back ( 1 2 ) Next &gt;

Sort by Date Posted 20 results/page

Advanced Search Submit

26 vehicles

mazda 3

	Make	Model	Price	Depreciation	Reg Date	Eng Cap.	Mileage	Veh Type	Status
<b>Search Selection</b>	mazda 3		Any	Any	2016	Any	Any	Any	Available
	Mazda	Mazda 3 1.5A Sunroof	\$62,800	\$7,610 /yr	16-Sep-2016	1,496 cc	34,000 km	Sedan	Available
Full Loan Available At \$1k+/ Month We Can Help To Conver To Z10 Usage If Needed. In House Loan / Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart ...									
88 Motor Trading									
Posted: 02-Apr-2019 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda	Mazda 3 1.5A Sunroof	\$59,988	\$7,690 /yr	29-Apr-2016	1,496 cc	36,701 km	Sedan	Available
Easy To Maintain Silvery Colour! Well Maintained By Previous Owner! Very Fuel Economical Skyactive Engine Fetching 15km/L On City Driving! Probably One Of The Lowest Depreciation Now! Low Mileage! Gre...									
Posted: 02-Apr-2019 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda	Mazda 3 1.5A Deluxe	\$59,800	\$7,810 /yr	29-Jan-2016	1,496 cc	60,000 km	Sedan	Available
Good Value, Full Agent Maintained, Flexible In House Loan, Please Feel Free To Call Our Friendly Sales Consultants Now For More Details.									
Car Lingual									
Posted: 01-Apr-2019 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda	Mazda 3 1.5A Sunroof	\$63,800	\$7,420 /yr	27-Dec-2016	1,496 cc	52,300 km	Sedan	Available
1.5 Sunroof Mazda 3, Downpayment Only 10%. Monthly \$ 830 x 84. Hi Paper Value \$50,000+, High Bank Loan/In House Loan And Trade In Available. Call Your Trusted Dealership And Drive Home Your Mazda 3 1.5A...									
Posted: 31-Mar-2019 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda	Mazda unveils 30th anniversary MX-5							
After 30 years and more than one million units sold, Mazda has made 3,000 anniversary editions of the MX-5, exclusively offered in Racing Orange.									
Read this article									
	Mazda	Mazda 3 1.5A	\$59,800	\$7,710 /yr	22-Apr-2016	1,496 cc	47,545 km	Sedan	Available
Ever Popular Sedan From Mazda! Comes With Upgraded Head Unit! Selling Cheap! In Excellent Condition! Bank Loan And Trade In Available! Call For A Viewing Appointment Today!									
Mayfair Motoring									
Posted: 30-Mar-2019 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda	Mazda 3 1.5A	\$62,800	\$7,940 /yr	18-Apr-2016	1,496 cc	56,173 km	Sedan	Available
Ever Popular Sedan From Mazda! High Specs Deluxe Unit Comes With Heads Up Display And Electric Seat! Selling Cheap! In Excellent Condition! Bank Loan And Trade In Available! Call For A Viewing Appoint...									
Mayfair Motoring									
Posted: 30-Mar-2019 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda	Mazda 3 1.5A Sunroof	\$60,800	\$7,630 /yr	20-Jun-2016	1,496 cc	-	Sedan	Available

Compare

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SLG2592R

Model: MAZDA 3

not allowed  
link  
2/5 6200  
Euphonia Aftercare  
5 day.

QTY	List Items	Price \$
1	FRONT BUMPER	1339.50
2	FRONT L-R BUMPER RETAINER @38.60	77.20
1	FRONT BUMPER TOP PAD	288.90
1	FRONT BUMPER L/H Chrome MOULDING	186.90
1	FRONT BUMPER TOP FRAME PAD	131.60
1	FRONT BUMPER TOP BEAM	145.00
1	FRONT BUMPER REFORMENT reinforcement	523.70
1	FRONT BUMPER REFORMENT PAD	161.20
1	FRONT BUMPER L/H BRACKETS	58.20
1	FRONT BUMPER LOWER GRILL	86.20
1	FRONT BUMPER L/H FOG LAMPS	155.60
1	FRONT BUMPER L/H FOG LAMPS COVERS	110.20
1	FRONT L/H SHOCK ABSORBER absorber	320.00
1	FRONT L/H LOWER ARM	260.00
1	FRONT L/H KNUCKLE ARM	436.20
1	FRONT L/H WHEEL BEARING	430.00
1	ELECTRICAL CAPACITOR ASSY	3926.00
1	FRONT L/H FENDER	333.90
1	FRONT L/H FENDER INNER SHIELD	129.50
1	FRONT GRILL	481.60
1	FRONT GRILL LOGO	58.60
1	FRONT L/H HEADLAMP	1889.00
1	FRONT SUPPORT PANEL	569.00
1	FRONT SUPPORT TOP PANEL	245.00
1	FRONT SUPPORT TOP GARNISH	335.00
1	AIR-CON CONDENSER	1063.00
1	AIR CLEANER INTAKE DUCT	98.60
1	FRONT BUMPER TOWING COVER	45.20

TOTAL \$13,884.80  
LESS 20% \$2,776.96  
TOTAL \$11,107.84

6767.3  
202  
5413.84

AIR-CON OIL  
FRONT BUMPER CLIP  
FRONT GRILL CLIP  
FRONT FENDER SHEILD CLIP  
FRONT L/H SPORT RIM

11	60.00	X
ru	45.00	✓
11	45.00	X
ru	45.00	✓
cus/bel	900.00	800

TOWING CHARGES  
TO REMOVE AND REFIX FRONT UNDERCARRIAGE  
TO REMOVE, REFIX ALC CONDENSOR AND GAS  
TO RESPARAY UNDERCOATING  
TO CHECK ELECTRICAL WIRING  
TO RESPRAY PAINTING AND ETC  
PANEL BEATING, CUT, WELD, REMOVE AND  
REPLACING ABOVE PARTS

17	100.00	X
	180.00	/ 20
11	120.00	X
	250.00	50
	100.00	30
	1000.00	600
	1300.00	650

**\$15,252.84**

7753.84

# COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: SIONG HAI MOTOR  
VIN: SLG 2592 R  
Date: 3.4.19 13:41



SLG 2592 R

MAZDA 3

Front : Left

Actual	Before	Specified Range
-1°54'	-1°54'	-1°20' 0°10'
2°27'	2°27'	2°15' 3°45'
0°08'	0°08'	-0°06' 0°06'
21°45'	21°45'	10°40' 12°10'
19°51'	19°51'	9°20' 12°20'

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°41'	-0°41'	-1°20' 0°10'
2°46'	2°46'	2°15' 3°45'
0°07'	0°07'	-0°06' 0°06'
19°44'	19°44'	10°40' 12°10'
19°03'	19°03'	9°20' 12°20'

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	Before	Specified Range
-1°13'	-1°13'	
-0°19'	-0°19'	
2°01'	2°01'	
0°14'	0°14'	-0°11' 0°11'

Rear : Left

Actual	Before	Specified Range
-1°44'	-1°44'	-2°15' -0°45'
0°10'	0°10'	0°00' 0°11'

Camber  
Toe

Rear : Right

Actual	Before	Specified Range
-1°38'	-1°38'	-2°15' -0°45'
0°02'	0°02'	0°00' 0°11'

Rear

Cross Camber  
Total Toe  
Thrust Angle  
Axle Offset

Actual	Before	Specified Range
-0°06'	-0°06'	
0°12'	0°12'	0°00' 0°22'
0°04'	0°04'	
0mm	0mm	

# COMPUTERISED 4 WHEEL ALIGNMENT

## HUNTER DSP700

Company: SIONG HAI MOTOR  
VIN: SLG 2592 R  
Date: 6.4.19 9:54



SLG 2592 R

MAZDA 3

Front : Left

Actual	Before	Specified Range
-0°31'	-0°31'	-1°20' 0°10'
2°27'	2°27'	2°15' 3°45'
-0°03'	-0°03'	-0°06' 0°06'
20°04'	20°04'	10°40' 12°10'
19°34'	19°34'	9°20' 12°20'

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°37'	-0°37'	-1°20' 0°10'
2°48'	2°48'	2°15' 3°45'
-0°02'	-0°02'	-0°06' 0°06'
19°24'	19°24'	10°40' 12°10'
18°47'	18°47'	9°20' 12°20'

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	Before	Specified Range
0°06'	0°06'	
-0°20'	-0°20'	
0°41'	0°41'	
-0°05'	-0°05'	-0°11' 0°11'

Rear : Left

Actual	Before	Specified Range
-1°44'	-1°44'	-2°15' -0°45'
0°06'	0°06'	0°00' 0°11'

Camber  
Toe

Rear : Right

Actual	Before	Specified Range
-1°25'	-1°25'	-2°15' -0°45'
0°05'	0°06'	0°00' 0°11'

Rear

Cross Camber  
Total Toe  
Thrust Angle  
Axle Offset

Actual	Before	Specified Range
-0°19'	-0°19'	
0°11'	0°11'	0°00' 0°22'
0°00'	0°00'	
0mm	0mm	

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19005813/UQD3N2  
Date: 23/04/2019

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLG2592R	Insured Vehicle No :	SFD8008J
Date of Loss:	31/03/2019	Nature of Claim:	TP
		Claim No:	N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG2592R	Engine No:	P520370319
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BM42A8G0344068
Reg. Date:	26/09/2016 (Man. Year: 2016)	Odometer:	156010 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Champeon 6 mm	Rear Left Side:	Champeon 6 mm
Front Right Side:	Champeon 6 mm	Rear Right Side:	Champeon 6 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,202.84	6,303.84	5,899.00	48.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,450.00	1,600.00	52.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,252.84</b>	<b>7,753.84</b>	<b>7,499.00</b>	<b>49.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,252.84</b>	<b>6,200.00</b>	<b>9,052.84</b>	<b>59.35</b>

### INSPECTION

Date of Assignment:	02/04/2019	
Date Inspected:	03/04/2019 Inspected At:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,339.50 FL	*1,339.50 FL
2	1		*FRONT BUMPER TOP PAD	Not Necessary	288.90 FL	*- FL
3	1		*FRONT BUMPER L/H CHROME MOULDING	Scratched/Cracked	186.90 FL	*186.90 FL
4	1		*FRONT BUMPER TOP FRAME PAD	Not Necessary	131.60 FL	*- FL
5	1		*FRONT BUMPER TOP BEAM	Not Necessary	145.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	523.70 FL	*523.70 FL
7	1		*FRONT BUMPER REINFORCEMENT PAD	Not Necessary	161.20 FL	*- FL
8	1		*FRONT BUMPER L/H BRACKETS	Not Necessary	58.20 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILL	Not Necessary	86.20 FL	*- FL
10	1		*FRONT BUMPER L/H FOG LAMPS	Cracked	155.60 FL	*155.60 FL
11	1		*FRONT BUMPER L/H FOG LAMPS COVERS	Grazed	110.20 FL	*110.20 FL
12	1		*FRONT L/H SHOCK ABSORBER	Bent	320.00 FL	*320.00 FL
13	1		*FRONT L/H LOWER ARM	Bent	260.00 FL	*260.00 FL
14	1		*FRONT L/H KNUCKLE ARM	Bent	436.20 FL	*436.20 FL
15	1		*FRONT L/H WHEEL BEARING	Necessary	430.00 FL	*430.00 FL
16	1		*ELECTRICAL CAPACITOR ASSY	Repair	3,926.00 FL	*- FL
17	1		*FRONT L/H FENDER	Buckled	333.90 FL	*333.90 FL
18	1		*FRONT L/H FENDER INNER SHIELD	Torn	129.50 FL	*129.50 FL
19	1		*FRONT GRILL	Not Necessary	481.60 FL	*- FL
20	1		*FRONT GRILL LOGO	Not Necessary	58.60 FL	*- FL
21	1		*FRONT L/H HEADLAMP	Scratched/Cracked	1,889.00 FL	*1,889.00 FL
22	1		*FRONT SUPPORT PANEL	Cracked	569.00 FL	*569.00 FL
23	1		*FRONT SUPPORT TOP PANEL	Not Necessary	245.00 FL	*- FL
24	1		*FRONT SUPPORT TOP GARNISH	Not Necessary	335.00 FL	*- FL
25	1		*AIR-CON CONDENSER	Not Necessary	1,063.00 FL	*- FL
26	1		*AIR CLEANER INTAKE DUCT	Not Necessary	98.60 FL	*- FL
27	1		*FRONT BUMPER COVER	Missing	45.20 FL	*45.20 FL
28	1		*AIR-CON OIL	Not Necessary	60.00 FS	*- FS
29	1		*FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
30	1		*FRONT GRILL CLIP	Not Necessary	45.00 FS	*- FS
31	1		*FRONT FENDER SHIELD CLIP	Necessary	45.00 FS	*45.00 FS
32	1		*FRONT L/H SPORT RIM	Cut/Bent	900.00 FS	*800.00 FS
33	1		*FRONT L-R BUMPER RETAINER	N/s Cracked	77.20 FL	*38.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,979.80**    **7,657.30**  
 - List Item Discount on L Items 20.00/20.00% (\$\$)    2,776.96    1,353.46

Total Parts (\$\$) **12,202.84**    **6,303.84**

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES.	New	100.00	0.00
2	TO REMOVE AND REFIX FRONT UNDERCARRIAGE.	New	180.00	120.00
3	TO REMOVE, REFIX AIR-CON CONDENSOR AND GAS.	New	120.00	0.00
4	TO RESPRAY UNDERCOATING.	New	250.00	50.00
5	TO CHECK ELECTRICAL WIRING.	New	100.00	30.00
6	TO RESPRAY PAINTING AND ETC.	New	1,000.00	600.00
7	PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS.	New	1,300.00	650.00
Gross Labour Cost (\$\$)			3,050.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >