

ASS. REC. BY:

REF: CS3/III 19005815/Gcd302

Special Instruction:

Surveyor: 99

ASSIGNMENT (Office)

From (Person): minimum Gabriel Wee

of III

Date/Time: 2/4/19 3.06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGG1880A

Insured: SH 6453V

at Workshop m/s HIMP L&K Automobile Trading
of 160 Sin Ming Drive #05-17

Tel: 64531743

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 29.3.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

3.4.2019

Date/Time: 2/4/19 4.05p.m.

Person Contacted:

Mr Ong

Vehicle IN/OUT

Date/Time	Action/Instruction	Fahmotl (X)
	SGG1880A - NS/INC 19005789/ NScd3	D.O.A. - 29/03/ 2019
	SH 64530 - NS/INC 19005789/ NScd3	D.O.A. - 29/03/ 2019
	Dismantle part: 05/04/ 2019 1235pm	

Surveys

PRS
GQ

REF: III

6380 G

ASSIGNMENT

(-2021)

From: Date: 3.4.2019

Veh No: SGG1880A Yr Regn: 04 May 2006

Estimated Cost:

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SGG 1880A

Make: Toyota Vios c.c 1497

at Workshop m/s Hiap Lek Automobile
of 160 sin ming Drive #05-17

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 204787 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: MK053HY 420 418 4508

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inoper / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inoper / Jammed / Leaked / Burnt or

Make of Veh:


Modi: Nil / SRM / STD A/Rim or

(Policy Condition)

Tyre Size: F: 185/60 R15

R: 11

Remark: The veh had commenced its
repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dayton

Bal. or Market Value: \$13k

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 5 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 5 mm

Est. Repairs: 4 days Res.: Yes or No

D.O.A. D.O.I. 03-04-19

Lump Sum: % 3 Val.: Yes or No

Survey held at W/S 11:45

CA / REV / REP. / 24 HRS "wp"

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Wt N/S, SA d/s

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 2000 - \$ 3000

[Signature]
4/4/2019

RECEIVED 08 APR 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee: 120

2)

Transportation:

Add Fee: ☐ : Site Insp (\$)

S + RS, SI

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

10

130

Report Format : PRS

Lump Sum / I.B.I. (\$))

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 2 April 2019 3:06 PM
To: 'mail@oraclelaw.sg'; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SGG1880A (Accident involving SGG1880A and SH6453U on 29.03.19
Attachments: sh6453u_20190402092413.pdf; sh6453u_20190402145712.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SGG1880A
III INSURED VEHICLE NO. : SH6453U
DATE OF LOSS : 29.03.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANT to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

P: Mr Ong
T: 4.05pm 24/19
E: X
V: in

From: Motor Claim - III
Sent: 02 April, 2019 9:40 AM
To: 'mail@oraclelaw.sg' <mail@oraclelaw.sg>
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SGG1880A (Accident involving SGG1880A and SH6453U on 29.03.19

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 2009045727

237 Alexandra Road #04-11
The Alexier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oraclelaw.sg



FACSIMILE TRANSMISSION NOTE

To :	India International Insurance Pte Ltd	Date :	2nd April 2019
Attention :	Motor Claims (Gabriel Wee)	From :	Mr Stanley Bay / Miss Pauline Ong
Your Ref. :	Insurer of SH 6453U	Our Ref. :	SB/PO/Acc/2019-8956
Facsimile :	6225-7743 / 6224-4174	No. of Pages :	1 (including this page)

IMMEDIATE ATTENTION

Dear Gabriel,

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SGG 1880A & SH 6453U ALONG CLEMENCEAU ROAD NORTH/CAVENAGH HOUSE ON 29-03-2019 @ 10.10 A.M.

1. We refer to your fax of even date and your list of motor surveyors.
2. We are instructed by our clients that they are not agreeable to the appointment of any one of the surveyors named in your said list. We append herewith our list of our clients' proposed motor surveyors for your kind consideration to conduct a joint pre-repair survey:-
 - a. Mr. B J Lol of PAR Automotive Consultancy
 - b. Mr. Marc of United Appraisal & Management Pte Ltd
 - c. Mr. Oh Han Cheong of Oh Appraisal Services
 - d. Mr. Kuma (S. Ku,aman) of SK Auto Consultants
 - e. Mr. Lee K W of Lee Automobile Appraisers Services
 - f. Mr. Ng Cheng Meng of CM Automotive Consultancy and
 - g. Mr. Zail Saldi of ISP Management Pte Ltd
3. Kindly let us know **within the two (2) working days** whether you agree to any of the said proposed motor surveyors failing which you are deemed to have agreed to the appointment of any of the motor surveyors named in our said list.

Yours faithfully


Mr Stanley Bay / Miss Pauline Ong
Enc

cc: Hlap Lek Automobile Trading
160 Sin Ming Drive
#05-17 Sin Ming Autoalty S(575722)
Tel No.: 6453-1743 Fax No.: 6457-6181

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	6380G
Vehicle No.:	SGG1880A
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Silver
Secondary Colour:	Black
Manufacturing Year:	2006
Engine No.:	1NZX418829
Chassis No.:	MR053HY4204184508
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,707.00
Original Registration Date:	04 May 2006
First Registration Date:	04 May 2006
Transfer Count:	1
Actual ARF Paid:	\$13,439.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	03 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,789.00
COE Rebate Amount:	\$9,495.00
Total Rebate Amount:	\$9,495.00
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Apr 2019

OK

► Vios Used Vehicle List (19 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Vios 1.5A G (COE till 02/2024)	\$26,800	\$5,490 /yr	19-Feb-2009	1,497 cc	-	GV Credit Pte Ltd	Available
Office No. - 63443344 Alvin - 93607619 2.88% Per Annum, Interest At \$468 Monthly For Toyota Vios. 2 Years Warranty For Engine And Gear Box. Add On Available.							
Toyota Vios 1.5M E (COE till 12/2019)	\$5,999	\$8,140 /yr	29-Dec-2004	1,497 cc	99,000 km	GV Credit Pte Ltd	Available
Very Rare 1 Ownership With Low Mileage Done. Manual Transmission. Very Well Maintained Unit. COE Rebate, Road Tax Refund, Body Value = \$5500. Viewing And Test Drive Is Available. Office No. - 63443344 KL - 97933333							
Toyota Vios 1.5A E (COE till 03/2020)	\$9,388	\$9,710 /yr	22-Mar-2005	1,497 cc	151,000 km	Juzt Carz Auto	Available
Current Paper \$6684! New Arrival! Owned By A Careful Lady Owner. Service Done Every 10k Km Without Fail. Accident Free, Original Paint And Beautiful Leather Seats. Suitable For All Ages, Idea For Shor... Office No. - 63383813 James Li - 88588866 Joey Lim - 97898277 Shawn Zheng - 97520620 Phillip Koh - 82338484							
Toyota Vios 1.5A E (COE till 01/2021)	\$12,800	\$7,080 /yr	23-Jan-2006	1,497 cc	-	88 Motor Trading	Available
Well Known For It's Fuel Economy, Reliable And Low On Maintenance, New Coat Of Paintwork And Free Servicing Will Be Given, STA Evaluation Can Be Arrange For Peace Of Mind Purchase, Easy Financing. Office No. - 62911187 Lek - 87555787 Ben - 90913551 Rayner Ho - 96811390 Nic - 81001945							
Toyota Vios 1.5A E (COE till 05/2021)	\$14,800	\$6,870 /yr	29-May-2006	1,497 cc	181,000 km	Ideal Automobile Pte Ltd	Available
100% Loan Options Available! \$600 Plus Per Month Installment. Low Mileage. Sell As It Is Condition. Good Fuel Efficiency! Trade In Welcome. Call Us For Viewing Now! Office No. - 64696733 Chris - 90229004 Vyn - 93637703							
Toyota Vios 1.5M E (COE till 05/2021)	\$12,999	\$6,010 /yr	01-Jun-2006	1,497 cc	165,307 km	Mutual Concept Motoring Pte Ltd	Available
New Arrival! Selling At Attractive Pricing And Major Wear And Tear Replacement Is Provided. High Loan Service Is Provided. Purchase Comes With Free Servicing. Viewing Available Till 9pm Daily. Office No. - - Benny - 82003243							
Toyota Vios 1.5A E (COE till 06/2021)	\$15,999	\$7,130 /yr	06-Jul-2006	1,497 cc	140,855 km	Trans Express	Available
Best For Short Term. Low Mileage Done. Good Engine, Regularly Maintained. Nice Plate. Clean And Neat Interior. Loan Avail. Sell As It Is Condition. Probably Most Practical, Reliable 1.5L Engine, With ... Office No. - 67473818 Adrian Chua - 98182884							
Toyota Vios 1.5A E (COE till 06/2021)	\$16,800	\$7,490 /yr	18-Jul-2006	1,497 cc	-	Car Search	Available
One Of The Popular Sedan Among Its Class. Smooth Drive With Very Good Fuel Consumption. Low Maintenance Cost. Consignment Unit. Flexible Loan Scheme Available. Trade In Welcome! Call Us Now! Office No. - 62620728 Rachel - 91126538 Justin - 91827511 Ken - 93388994 Athrun Lee - 87425361							
Toyota Vios 1.5M E (COE till 06/2021)	\$12,438	\$5,540 /yr	21-Jul-2006	1,497 cc	-	Phoenix Motor Trading Enterprise	Available
100% Loan COE 5 Years Or 10 Years View At Phoenix Motor Trading Enterprise. Office No. - 62766662							

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/03/2019 14:48
Date Of Accident	29/03/2019 10:10
Exact Location Of Accident	CLEMENCEAU ROAD NORTH / CAVENAGH HOUSE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG1880A
Insured/Policyholder	
Name Of Registered Owner	LIM LI CHING
NRIC No	S7806380G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98364880
Alternative Phone No	OFFICE-98364880

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104045333 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	LIM LI CHING
NRIC No	S7806380G
Date Of Birth	10/03/1978
Occupation	OUTDOOR
Date Of Driving Pass	14/04/1997
Driving Experience	21 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98364880
Fax Number	
Contact Number	OFFICE-98364880
Email Address	NOEMAIL

Address	3 BRISTOL ROAD
Postcode	219842
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNABLE TO UPLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH6453U
Vehicle Make/Model/Colour	HYUNDAI 140
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN KENG HOCK
NRIC/Passport Number	S1241475G
Contact Number	81269646
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

30 MAR 2019

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS coming out from Cavenagh House. I stopped to check for oncoming traffic. When it was clear, I moved turn left.


Suddenly a taxi SH64534 made a U-turn without checking and crashed onto the right front of my car. Upon the impact, my car mounted the kerb and the left.

I do not have any passenger at the time of accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

30 MAR 2019



Alli

Policyholder's Signature
Date & Time:

Alli

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Apr 2019 12:39 Edit Reg		02 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SGG1880A	Date of Loss:	29/03/2019 00:00 - :59 [154 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SH6453U	Policy No. (Claimant):							
		Excess:							
Repairer:	Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGG1880A

[SH6453U]






































TP



















































-





















Mar 29 2019 12:00AM

[-]

Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
2	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
3	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
15	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
17	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
19	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
20	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
22	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
23	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/04/19 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	08/04/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	08/04/19 11:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	03/04/19 09:03	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19005815/GCD3E2

Date: 22/04/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SGG1880A

Insured Vehicle No : SH6453U

Date of Loss: 29/03/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGG1880A

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX418829

Reg. Date: 04/05/2006 (Man. Year: 2006)

Chassis No: MR053HY4204184508

Colour: Grey

Odometer: 204787 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Dayton 5 mm

Rear Left Side: Dayton 5 mm

Front Right Side: Dayton 5 mm

Rear Right Side: Dayton 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/04/2019

Date Inspected: 03/04/2019 Inspected At:

160 SIN MING DRIVE #05-17

Repairer : Hiap Lek Automobile Trading

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2019)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG1880A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >