

22/03/2012

ASS. REC. BY:

REF: CS/CT19005820/K+d3et Special Instruction:

Surveyor: Penell

minim

ASSIGNMENT (Office)From (Person): Chong Boon Senof CTIDate/Time: 2 Apr 19 16:36 PM

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLS 8411C

Insured: _____

at Workshop m/s S & H Motor Pte LtdTel: 64534730of 160 Sin Ming Autoaty.Policy No: DMPCSW 3083051801Claim No: SNM19D201409

Sum Insured: _____

Excess: \$1250.00

Make of Veh: _____

(Client's Record)

D.O.A. 28.3.2019CA / (REV) / REP. / REV 24 HRS(3.4.2019 morning)Date/Time: 2.4.19 4.42p.m

H.O.D. Endorsement: _____

Person Contacted: miss wongVehicle (IN) / OUT

Date/Time	Action/Instruction Estimate (✓)
	<u>SLS 8411C - X</u>
<u>3/10 April</u>	<u>Rever uneconomical report</u>
	<u>Submit uneconomical total loss report</u>

REF: CT1 CS/CT119005820/Ktd3

ASSIGNMENT

From:

Date: 3.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL58411C

at Workshop n/s S 8 H Motor

of 160 sin ming Auto City

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: \$1250.00

(Client's Record)

Make of Veh: (Morning)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

812k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL58411C Yr Regn: 06 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis (A)

C.C.

1598

Colour:

M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading

107994

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRO 53 8EE 206114124

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / HOOTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

28/3/19

D.O.I.

314119

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S & etc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV: 12,000/-
LTA: 10,231/-
NV: 17,641/-

RECEIVED 26 APR 2019

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1) 26/4 Typist

Date/Time, File Return to?

2)

Report Format:

TL

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2019 Sendback Est	02 Apr 2019 09:59 S\$100.00	02 Apr 2019 16:36 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	PANG SIAW YEN, ID: S7972044E		
Vehicle Reg. No.:	SLS8411C	Date of Loss:	28/03/2019 00:00 - :59 [117 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D201409	Policy/Cover Note No.:	DMPCSN3083051801 (Comprehensive)
		Excess:	S\$1,250.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/04/2019]		
Driver/Custodian:	KAM BOON TIONG (/ Male) , NRIC: S8288145Z, Tel: +6596373075 Email:		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Denise Tay (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 26 April 2019 8:23 AM
To: Denise Tay (LKKAuto)
Subject: RE: OD / SNM19D201409 / SLS8411C

Proceed lo

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 25 April, 2019 1:22 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OD / SNM19D201409 / SLS8411C

Dear Boon Sen,

Can advise if I can submit my report?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 24 April 2019 3:12 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: OD / SNM19D201409 / SLS8411C

Dear Boon Sen,

Can advise if I can submit my report?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2044E
Vehicle Details	
Vehicle No.:	SLS8411C
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.8 AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1ZZ4897634
Chassis No.:	MR053ZEE206114124
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$20,071.00
Original Registration Date:	16 Jun 2009
First Registration Date:	16 Jun 2009
Transfer Count:	1
Actual ARF Paid:	\$20,071.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2019
PARF Rebate Amount:	\$10,035.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$10,046.00
COE Rebate Amount:	\$183.00
Total Rebate Amount:	\$10,218.00

The information contained herein is correct as at 03 Apr 2019

OK



INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
 Policy No: DMPCSN3083051801
 Vehicle Reg. No.: SLS8411C
 Driver Age/Info: / MALE
 TP Injury Involved? NO

Ref. No:
 Date of Loss: 28/03/2019
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? NO

Insured/Claimant: PANG SIAW YEN
 Driver: KAM BOON TIONG

Make/Model: TOYOTA COROLLA ALTIS, 1.8 (A) Vehicle Reg. Date: 16/06/2009

Vehicle Colour: WHITE
 Engine No: 1ZZ4897634
 Odometer: 0 KM

Chassis No: MR053ZEE206114124

Paint Type:
 Total Loss? YES
 Est. Duration of Repair (day) 21

Per old bulc

Not Authorized

Ex 8 1250h

7/loss

for 67586315

Present Location: S & H MOTOR PTE LTD (SIN MING)

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	100.00
Towing	

Gross Total (S\$)	100.00
+ GST 7.00% (S\$)	7.00
Nett Amount (S\$)	107.00

This claim is handled by: MYINT MYINT THAN

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2044E

Vehicle Details

Vehicle No.: 5LS8411C

Vehicle to be Exported: Yes

Intended Deregistration Date: 29 Mar 2019

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.8 AUTO

Primary Colour: White

Manufacturing Year: 2009

Engine No.: 1ZZ4897634

Chassis No.: MR053ZEE206114124

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$20,071.00

Original Registration Date: 16 Jun 2009

First Registration Date: 16 Jun 2009

Transfer Count: 1

Actual ARF Paid: \$20,071.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Jun 2019

PARF Rebate Amount: \$10,035.00

Intended COE Rebate Details

COE Expiry Date: 15 Jun 2019

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$10,046.00

COE Rebate Amount: \$196.00

Total Rebate Amount: \$10,231.00

The information contained herein is correct as at 29 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/03/2019 16:14
Date Of Accident	28/03/2019 23:45
Exact Location Of Accident	CLEMENTI AVE 3 TOWARDS COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS8411C
Insured/Policyholder	
Name Of Registered Owner	PANG SIAW YEN
NRIC No	S7972044E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96373075
Alternative Phone No	OFFICE-96373075

Vehicle Particulars

Manufacturer	TOYOTA
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3083051801
Cover Note Number	

Driver

Name of Driver	KAM BOON TIONG
NRIC No	S8288145Z
Date Of Birth	13/10/1982
Occupation	INDOOR
Date Of Driving Pass	09/09/2006
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96373075
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured FRIEND
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY
 Weather Conditions AFTER RAIN
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 1
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : PASSENGER
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name EUNOS NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4439999 - FAX NO: 62444376
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

refer attached police report.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 29/3/19
1:50pm

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per Police Report NO: T/20190329/2083

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 29/3/19
1:50 pm

1-50
GJ2525C SuperForm V3

Driver's Signature _____

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: _____
NRIC/FIN No.: _____



**SINGAPORE
POLICE FORCE**



T/20190329/2083

1 of 3

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

Report No. T/20190329/2083

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/03/2019 13:16	Vide Report No.:	Station Diary No.: 12
--	------------------	--------------------------

Informant's Particulars

Name of Informant: KAM BOON TIONG			Address: APT BLK 948 JURONG WEST STREET 91 #04-693 SINGAPORE 640948	
ID Type / ID No.: NRIC NO / S8288145Z			Contact No.: Home/Office: Mobile: 96373075	
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 36	Date of Birth: 13/10/1982	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: OPERATION COORDINATOR			Driving Licence Information: Class: 2B,3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 28/03/2019 23:45	Type of Location: Bend
Location: Along Road 1 CLEMENTI AVENUE 3				
Weather: Raining		Road Surface: Wet		Road Speed Limit: 60 Km/h
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLS8411C	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190329/2083

2 of 3

Police Station Of Origin:

Eunos NPP

629 Bedok Reservoir Road #01-1620

SINGAPORE 470629

Tel No: 1800-4439999

Report No. T/20190329/2083

CONTINUATION OF REPORT

Driver			
Name	KAM BOON TIONG		ID No. S8288145Z
Related Vehicle	SLS8411C (Car)		Contact No. 96373075
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On the 28/3/2019 at about 2345hours I was driving vehicle, a white Toyota Altis bearing plate number SLS8411C along Clementi Ave 3. The road was wet due to the rain, and I was driving towards a bend when I skidded and I hit on to the green colour centre railing. No other vehicle was at the location at the point of the accident, no one was injured. I was driving at 40km/hr as it was already night and the road was wet.

The car suffered a dent on the front right side of the car. The green coloured railing had toppled over.



**SINGAPORE
POLICE FORCE**



T/20190329/2083

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 3

Report No. T/20190329/2083

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 MUHAMMAD FIKRI BIN MOHD FADIL

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

29/03/2019 13:16

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt MOHAMAD ZULFAZDLI BIN
ABDULLAH

Contact No.: 65476204

Authentication Stamp

NP168

Classification Of Case:

SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2044E

Vehicle Details

Vehicle No.:	SL58411C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.8 AUTO
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1ZZ4897634
Chassis No.:	MR053ZEE206114124
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$20,071.00
Original Registration Date:	16 Jun 2009
First Registration Date:	16 Jun 2009
Transfer Count:	1
Actual ARF Paid:	\$20,071.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2019
PARF Rebate Amount:	\$10,035.00

Intended COE Rebate Details

COE Expiry Date:	15 Jun 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$10,046.00
COE Rebate Amount:	\$196.00
Total Rebate Amount:	\$10,231.00

The information contained herein is correct as at 29 Mar 2019

OK

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN3083051801	Date of Loss:	28/03/2019
Vehicle Reg. No.:	SLS8411C	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	NO
Insured/Claimant:	PANG SIAW YEN		
Driver:	KAM BOON TIONG		
Make/Model:	TOYOTA COROLLA ALTIS, 1.8 (A)	Vehicle Reg. Date:	16/06/2009
Vehicle Colour:	WHITE		
Engine No:	1ZZ4897634	Chassis No:	MR053ZEE206114124
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	21		
Present Location:	S & H MOTOR PTE LTD (SIN MING)		

Not Authorized
Ex \$ 1250/h
7/loss.
for 62584315

Pls & ulc

COST OF CLAIMS		Amount
Parts		0.00
Miscellaneous Items		0.00
Labour		0.00
Paintwork Labour		0.00
Towing		100.00
Gross Total (S\$)		100.00
+ GST 7.00% (S\$)		7.00
Nett Amount (S\$)		107.00

This claim is handled by: MYINT MYINT THAN

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 02 Apr 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: S & H Motor Pte Ltd/SLS8411C/02/04/2019 09:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

S & H Motor Pte Ltd/SLS8411C/02/04/2019 09:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

S & H Motor Pte Ltd/SLS8411C/02/04/2019 09:59. Not valid without Reference section.

Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

Date : 01/04/2019

The Motor Claims Department
China Taiping Insurance (S) Pte Ltd

RE : ACCIDENT ON SLS 8411 C ACCIDENT DATED : 28.03.2019


Refers to the above vehicle being towed to our workshop for repair, we hereby inform your that the vehicle is very badly damaged and the cost of repair is more that S\$9,500.00 for repair. Kindly arrange for surveyor to survey vehicle.

Towing Charge

S\$100.00

Shall you require any assistance pertaining this matter, please do not hesitate to contact undersigned.

Yours faithfully
S & H Motor Pte Ltd



Doris Ang

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2019 Sendback Est	02 Apr 2019 09:59 \$S\$100.00	02 Apr 2019 16:36 Edit Adj Rpt	\$S\$0.00 Edit Estimates	\$S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: PANG SIAW YEN , ID: S7972044E									
Vehicle Reg. No.: SLS8411C		Date of Loss: 28/03/2019 00:00 - :59 [117 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM19D201409		Policy/Cover Note No.: DMPCSN3083051801 (Comprehensive)							
		Excess: \$S\$1,250.00							
Repairer: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/04/2019]									
Driver/Custodian: KAM BOON TIONG (/ Male) , NRIC: S8288145Z, Tel: +6596373075 Email:									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (26/04/2019): Alert - Adj Mandate Maintained - SLS8411C - Claim Handler: Chong Boon Sen									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents






























SLS8411C (SNM19D201409)

OD

Mar 28 2019 12:00AM

[PANG SIAW YEN]

S & H Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	02/04/19 09:59	Repairer Estimates	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	03/04/19 15:28	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
2	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
3	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
4	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
5	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
6	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
7	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
8	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
9	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
10	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
11	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
12	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
13	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
14	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
15	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
16	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
17	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
18	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
19	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
20	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
21	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
22	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
23	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
24	10/04/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	02/04/19 10:02	Total loss letter	 Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	03/04/19 14:13	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	03/04/19 15:53	Log card (if available)	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19005820/KTD3E2

Date: 06/05/2019

REFERENCE

Insured/Claimant: PANG SIAW YEN Policy No: DMPCSN3083051801

Date of Loss: 28/03/2019 Nature of Claim: OD Claim No: SNM19D201409

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS8411C**
 Make & Model: TOYOTA COROLLA ALTIS, 1.8 (A) Engine No: 1ZZ4897634
 Reg. Date: 16/06/2009 (Man. Year: 2009) Chassis No: MR053ZEE206114124
 Colour: Metallic Pearl White Odometer: 107994 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: S\$12,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	100.00	0.00	100.00	100.00
Calculated Gross Total (S\$)	100.00	0.00	100.00	100.00
- Excess (S\$)	0.00	1,250.00	-1,250.00	
(S\$)	100.00	-1,250.00	1,350.00	1,350.00
+ GST 7.00/0.00% (S\$)	7.00	0.00	7.00	100.00
Nett Amount (S\$)	107.00	-1,250.00	1,357.00	1,268.22

INSPECTION

Date of Assignment: 02/04/2019 Present Location:

Date Inspected: 03/04/2019 Inspected At:

S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #07-02, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$12,000.00
OMV : \$20,071.00
PARF Rebate (1) : \$10,035.00
Quota Premium Paid : \$10,046.00
COE Rebate (2) : \$183.00
Total Rebate (1) + (2) = : \$10,218.00

The total amount incurred will be Market Value \$12,000.00 minus Total Rebate \$10,218.00 = \$1,782.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 06 May 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS8411C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >