

3

ASSIGNMENT

REF: CS/FCI 19005832/KHd3 ⁷²

Special Instruction

City/Region

From (Person)

Kalvin
Maychuan

ASSIGNMENT (Office)

of FCI

Date/Time: 11:18am @ 2/4/19

Estimated Cost

Bill to

OUT () WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle For

SHD 1611P

Insured

SH 66505

at Workshop on/

Premier Automotive

Tel

65446689

of

23 Changi South Ave 2 #03-02

Policy No

Claim No

D19002198MFST

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A. 30/3/2019

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement

Date/Time

11:57am @ 2/4/19

Person Contacted

Vincent

Vehicle (IN) (OUT)

(IN) (OUT)

Date/Time

Action/Instruction (✓) Estimate

SHD 1611P - CC6/11 1601274/uhb 392

D.O.A - 02107/2016

SH 66505 - CS/FCI 16011 085/ Avb m 2

D.O.A - 05106/2016

3/4 @ 5:38pm - remsd via email preli aduse

Surveyor: Kolvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspected Vehicle No: _____

at Workshop no/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD1611P Yr Regn: 24 Jan 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/ 6 / Prime Mover /

Truck / Trailer or

Make: Hyundai Zora cc 1580

Colour: Silver A/C: Ins / Std / Nil / NA

Sp. Reading: 27203 T/Radio: Ins / Std / Nil / NA

Eng/No: _____

C/No: KMHC851CVK0122438

Gen. Cond: Good / 6 / Poor / Burnt

Steering: Ins / Jammed / Leaked / Burnt or

Brake: Ins / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD 6 / Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / 6 / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 30/3/19 D.O.I. 2/4/19

Survey held at Premis

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|----------------------|---|
| 9/4/19 | Check PIP # 87820 / 262. (Red: 499.30, 36%) FCZ PIP |
| RECEIVED 09 APR 2019 | |

Date/Time, File Pass to? : Prell. Report

1) 9/4 Typist : Final Report

Date/Time, File Return to?

2) _____

Report Format: TP

Lump Sum / (\$ 878.20)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

| |
|-----|
| 100 |
| 50 |
| 50 |
| 23 |
| |
| 223 |



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002198MFSH

Date: 3/4/2019

Our Ref: CS/FCI19005832/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1611P

Please be informed that we had conducted the inspection of the abovementioned vehicle 2/4/2019 at the premises of M/s Premier have the following to report: -

| | | |
|--------------------------|-------|-------------------|
| Workshop Estimate Amount | : S\$ | <u>1,378.00</u> |
| Revised Estimate Amount | : S\$ | <u>705.00</u> |
| "Check" Items Amount | : S\$ | <u>00.00</u> |
| Market Value | : S\$ | <u> </u> |
| LTA Reimbursement Value | : S\$ | <u> </u> |
| Nett Value | : S\$ | <u> </u> |

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date 01-04-2019 **Our Ref No.** D19002198MFSH

Accident Date 30-03-2019 **Claim Type.** Third Party

Insured Vehicle SH6650S **Third Party Vehicle.** SHD1611P

Survey Location 23 CHANGI SOUTH AVENUE 2 #03-02

Contact Person. VINCENT CHUA

Contact No. 62148880/ 65446689 **Fax No.** 62141511

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop PREMIER AUTOMOTIVE SERVICES PTE LTD **Attention.** NIL

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge MAY CHUA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 3 April 2019 5:38 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002198MFSH/1
Attachments: PRELI ADVISED SHD 1611P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 1611P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 2 April 2019 12:12 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002198MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 2 April 2019 11:18 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002198MFSH/1

Dear Sir/Mdm,

Enquire Vehicle Registration Details

Owner Particulars

| | |
|----------------------------------|--|
| NRIC/Passport /Company Cert No.: | 200304975H |
| Owner ID Type: | Company |
| Owner Name: | PREMIER TAXIS PTE. LTD. |
| Registered Address: | 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443 |
| Mailing Address: | - |
| Birth Date: | - |

Vehicle Particulars

| | |
|--------------------------------|-----------------------------------|
| Vehicle No.: | SHD1611P |
| Previous Vehicle No.: | - |
| Effective Date of Ownership: | 24 Jan 2019 |
| Original Regn Date: | 24 Jan 2019 |
| Registration Date: | 24 Jan 2019 |
| Year of Manufacture: | 2018 |
| Vehicle Type: | Public Transport Taxi (Motor Car) |
| Vehicle Scheme: | Taxi (Company) |
| Vehicle Attachment 1: | Air-Con (Taxi) |
| Vehicle Attachment 2: | - |
| Vehicle Attachment 3: | - |
| Vehicle Make: | HYUNDAI |
| Vehicle Model: | AE IONIQ HEV 1.6 DCT |
| Primary Colour: | Silver |
| Secondary Colour: | - |
| Passenger Capacity: | 4 |
| Chassis No.: | KMHC851CVKU122438 |
| Engine No.: | G4LEJU134207 |
| Motor No.: | PM04JA2066DJ |
| Engine Capacity /Power Rating: | 1580 cc / 32.0 kW |
| Maximum Power Output: | 103.6 kW (138 bhp) |

| | |
|--|--|
| Propellant: | Petrol-Electric |
| Max Unladen Weight: | 1370 kg |
| Maximum Laden Weight: | 1870 kg |
| Open Market Value: | \$25,402.00 |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 23 Jan 2027 |
| Minimum PARF Benefit: | \$7,537.00 |
| No. of Transfers: | 0 |
| IU Label No.: | 1050452027 |
| COE No.: | 2019012401003977R |
| COE Expiry Date: | 23 Jan 2027 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Registration Category: | A - Car up to 1600cc & 97kW (130bhp) |
| Quota Premium (QP) / Prevailing Quota Premium: | - / \$26,047.00 |
| PQP Paid: | \$20,838.00 |
| QP (Regn Cat): | - |
| OPC Cash Rebate Eligibility: | No |
| QP during COE Bidding Exercise: | \$0.00 |
| Additional Registration Fee Rate: | First \$20,000.00 (100%), next \$5,402.00 (140%) |
| Actual ARF Paid: | \$12,563.00 |
| Vehicle Lifespan Expiry Date: | 23 Jan 2027 |
| CO2 Emission: | 86.00 (g/km) |
| CEV/VES Rebate Utilised Amount: | \$15,000.00 |
| CO Emission: | 0.109280 (g/km) |
| HC Emission: | 0.028670 (g/km) |
| NOx Emission: | 0.002060 (g/km) |
| PM Emission: | 0.052000 (mg/km) |
| Message: | This is a public service vehicle. |

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

2-Apr-19

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1611 P

| | | | |
|------|-----------------------|-----------------|-----------|
| 1 pc | Rear bumper | <i>x repair</i> | \$ 459.40 |
| 1 pc | Rear bumper cover | <i>- Rehub</i> | \$ 216.50 |
| 1 pc | Rear bumper lower lip | <i>x repair</i> | \$ |

less 20%

S/NETT

| | | | |
|-------|--|--------------|--------------------------|
| 1 set | Rear bumper clips | <i>x an</i> | \$ 48.00 |
| 1 set | Reverse sensor | <i>- sld</i> | \$ 280.00 200 |
| 1 pc | Rear bumper top protector | <i>- m</i> | \$ 80.00 50 |
| | <i>Rear Number plate</i> | <i>- cut</i> | \$ 25 |
| | Sundry | <i>net</i> | \$ 50.00 20 |
| | To dismantle / replace reverse sensor to new bumper and reset to the same | | \$ 120.00 50 |
| | To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the the rear bumper, etc | | \$ 600.00 200 |
| | To putty and spray painting on rear bumper | | \$ 200.00 180 |
| | | | <u>\$ 1,378.00</u> |

1943.72

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalin 10004
2/4/19 1700h
2 Pgs.
PIP
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action against is allowed
- Customer's consent must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Sig: _____
 Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|------------------------------|---|
| MS FIRST CAPITAL INSURANCE LTD | | Ref : CS/FCI19005832/K1td3n2 | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date : 10-04-2019 |  |
| | | Code : FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SH 6650S | Veh. Inspected | SHD 1611P |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | D19002198MFSH | Excess (\$) | 0.00 |
| Assign From | MAY CHUA | Assign Date | 02/04/2019 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | HYUNDAI IONIQ | c.c | 1580 |
| Engine No. | HIDDEN | Year of Reg. | 2019 |
| Chassis No. | KMHC851CVKU122438 | Colour | SILVER |
| Odometer | 27203 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195/65 R15 | MICHELIN | 8 mm |
| L/H Front Tyre | 195/65 R15 | MICHELIN | 8 mm |
| R/H Rear Tyre | 195/65 R15 | MICHELIN | 8 mm |
| L/H Rear Tyre | 195/65 R15 | MICHELIN | 8 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 30/03/2019 | Inspection Date | 02/04/2019 |
| Survey held at | PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 | | |
| 5a. Remarks | | | |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1611P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | REAR BUMPER | TO REPAIR SEE LABOUR | 459.40 | - |
| 1 | REAR BUMPER COVER | DEFORMED | 216.50 | 216.50 |
| 1 | REAR BUMPER LOWER LIP (NPA) | TO REPAIR SEE LABOUR | - | - |
| | LESS 20% DISCOUNT | | -135.18 | -43.30 |
| | | | 540.72 | 173.20 |
| SPECIAL NETT ITEMS | | | | |
| 1 | SET REAR BUMPER CLIPS (SN) | NOT NECESSARY | 48.00 | - |
| 1 | SET REVERSE SENSOR (SN) | SHORTED | 280.00 | 200.00 |
| 1 | REAR BUMPER TOP PROTECTOR (SN) | NECESSARY | 80.00 | 50.00 |
| 1 | REAR NUMBER PLATE (SN) | CUT | 25.00 | 25.00 |
| 1 | SUNDRY (SN) | NECESSARY | 50.00 | 20.00 |
| | | | 483.00 | 295.00 |
| LABOUR | | | | |
| | TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME. | | 120.00 | 30.00 |
| | TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE THE REAR BUMPER,ETC.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER LOWER LIP. | | 600.00 | 200.00 |
| | TO PUTTY AND SPRAY PAINTING ON REAR BUMPER. | | 200.00 | 180.00 |
| | | | 920.00 | 410.00 |
| GRAND TOTAL | | | 1,943.72 | 878.20 |
| RECOMMENDED COST OF REPAIRS | | | | 878.20 |

Report Ref No. CS/FCI19005832/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.