

2. Remarks:

ASSIGNMENT

REF: 3/SMO19005834/Gcd30r

Instruction

SA/VEH/IN  
Mehmen

Quo Qiang  
Thelma Choo

ASSIGNMENT (Office)

of SMO

Date/Time: 28/3/19 @ 2.57pm

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No

FBL 3526T

Insured

GBF 6446C

at Workshop m/s

Bike Image

Tel

69093770

of

10 Kalki Bukit Road 2 #01-06

Policy No

D19 MTPCV E000106

Claim No

CMTD1901475

Sum Insured

Excess

Make of Veh  
(Client's Record)

D.O.A. 20/03/2019

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time: 28/3/2019 @ 4:17pm

Person Contacted

Vehic

IN ☒ OUT

Date/Time	Action/Instruction (x) Estimate
	FBL 3526T - NS / NC 19005446 / Jsd 3
	GBF 6446C - X
	Dismantle: 4/4/2019

D.O.A. 20/3/2019



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2019		28 Mar 2019 14:57 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SING POH CHYE, ID: S1574770F, Tel: +6596887656, Email: NOEMAIL		
Main Claimant:	UNKNOWN RIDER		
Vehicle Reg. No.:	FBL3526T	Date of Loss:	20/03/2019 14:00 - :59
Claim Type:	TP / CMTD1901475	Policy/Cover Note No.:	D19MTPCVE000106 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF6446C	Policy No. (Claimant):	
		Excess:	
Repairer:	BIKE IMAGE MOTOR TRADING (KAKI BUKIT) 10 KAKI BUKIT ROAD 2, #01-06 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel: 69093770		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 08/04/2019]		
Driver/Custodian (Insured):	SING POH CHYE (55 / Male), NRIC: S1574770F, Tel: +6596887656 Email: NOEMAIL		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

151 Chin Swee Road  
#02-21 Manhattan House  
Singapore 169876  
Tel: 6235 0633  
Fax: 6235 6939

Your ref : GBF6446C

Our ref : CLLC.PD.055.2019 LI

27 MARCH 2019

**SOMPO INSURANCE SINGAPORE PTE LTD**

**BY FAX & HAND**

50 Raffles Place

#05-01/06 Singapore Land Tower

Singapore 048623

Attn: **Officer-In-Charge**

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2  
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION  
PROTOCOL FOR NIMA CASE**

We act for **NETTO DAMIAN GEORGE**, the owner of motor vehicle **FBL3526T**, who has appointed us to act on his behalf to claim against your insured's vehicle no: **GBF6446C** in regards to the road traffic accident on **20.03.2019**.

Please be informed that the said motor vehicle can be inspected at:-

**BIKE IMAGE MOTOR TRADING**

**FIRST EAST CENTRE**

**#01-06 10 KAKI BUKIT RD 2**

**Singapore 417868**

**Tel: 6909 3770 | Fax: 6909 3771**

**E-Mail: [bike\\_image@yahoo.com.sg](mailto:bike_image@yahoo.com.sg)**

Kindly contact **Mr Sam** Tel: **6909 3770 / 9762 9998**

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

**CENTRO-LEGAL LAW CORPORATION**

**Cc Mr Sam**

**FAX NO: 6909 3771**

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Enquire Road Tax Payable			
Vehicle Details			
Vehicle No. :	FBL3526T		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	CBF190WH		
Chassis No. :	LWBMC469XH1104013		
Propellant :	Petrol		
Engine No. :	MC46E5014587		
Engine Capacity :	184 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	310 kg		
Unladen Weight :	140 kg		
Year Of Manufacture :	2016		
Original Registration Date :	13 Sep 2016		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$6,452.00		
COE Expiry Date :	12 Sep 2026		
Road Tax Expiry Date :	12 Sep 2019		
Inspection Due Date :	12 Sep 2019		
Intended Transfer Date :	05 Apr 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1965G
<b>Vehicle Details</b>	
Vehicle No.:	FBL3526T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	CBF190WH
Primary Colour:	Orange
Manufacturing Year:	2016
Engine No.:	MC46E5014587
Chassis No.:	LWBMC469XH1104013
Maximum Power Output:	-
Open Market Value:	\$3,003.00
Original Registration Date:	13 Sep 2016
First Registration Date:	13 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$451.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Sep 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,452.00
COE Rebate Amount:	\$4,797.00
<b>Total Rebate Amount:</b>	<b>\$4,797.00</b>

The information contained herein is correct as at 05 Apr 2019

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2019		28 Mar 2019 14:57 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>SING POH CHYE</b> , ID: S1574770F, Tel: +6596887656, Email: NOEMAIL								
Main Claimant:	<b>NETTO DAMIAN GEORGE</b> , ID: S8741965G								
Vehicle Reg. No.:	<b>FBL3526T</b>	Date of Loss:	20/03/2019 14:00 - :59 [30 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / CMTD1901475</b>	Policy/Cover Note No.:	D19MTPCVE000106 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBF6446C</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>BIKE IMAGE MOTOR TRADING (KAKI BUKIT)</b> 10 KAKI BUKIT ROAD 2, #01-06 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel: 69093770								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>Thelma Choo</b> - 6322 4681]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 08/04/2019]								
Driver/Custodian (Insured):	SING POH CHYE (55 / Male), NRIC: S1574770F, Tel: +6596887656 Email: NOEMAIL								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBL3526T (CMTD1901475)

[GBF6446C]

TP

NETTO DAMIAN GEORGE

Mar 20 2019 2:00PM

[SING POH CHYE]

BIKE IMAGE MOTOR TRADING

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	04/04/19 13:02	General View	1	Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	04/04/19 13:02	General View		Load JPG <input checked="" type="checkbox"/>
39	04/04/19 13:02	General View		Load JPG <input checked="" type="checkbox"/>
40	04/04/19 13:02	General View		Load JPG <input checked="" type="checkbox"/>
41	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
42	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
43	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
44	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
45	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
46	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
47	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
48	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
49	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
50	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
51	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
52	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
53	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
54	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
55	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
56	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
57	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
58	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
59	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
60	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
61	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
62	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
63	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
64	05/04/19 12:42	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	27/03/19 13:48	Letter - Centro Legal Law		Load PDF <input type="checkbox"/>
2	28/03/19 14:56	PRI - LKK (No consensus)		Load HTM <input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19005834/GCD3E2

Date: 15/04/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPCVE000106
Claimant Vehicle No :	FBL3526T	Insured Vehicle No :	GBF6446C
Date of Loss:	20/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901475

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	FBL3526T	Engine No:	MC46E5014587
Make & Model:	HONDA CBF 190, 184cc	Chassis No:	LWBMC469XH1104013
Reg. Date:	13/09/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Orange		
Engine Capacity:	184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	CST 4 mm	Rear Left Side:	CST 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	28/03/2019	
Date Inspected:	02/04/2019 Inspected At:	BIKE IMAGE MOTOR TRADING (KAKI BUKIT) 10 KAKI BUKIT ROAD 2, #01-06 FIRST EAST CENTRE Singapore 417868
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 15 Apr 2019)
<b>Parts:</b>	N/A HONDA CBF 190 184cc (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL3526T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >