

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: QBE	DATE	: 01/04/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBH9612H		
MODEL	: NISSAN NV200	VM20128431	
CHASSIS NO		Joy	
<u>ACCIDENT DETAILS</u>	DATE : 30-Mar-19		
	TIME : 15:00HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET <i>Best Dented</i>	1	\$ 1,266.30	\$ 1,266.30 ✓ 858
2	FRONT BONNET HINGE <i>RH Best</i>	2	\$ 103.00	\$ 206.00 ✓ 103
3	FRONT BUMPER <i>torn</i>	1	\$ 820.00	\$ 820.00 ✓ 618
4	FRONT BUMPER SIDE RETAINER <i>RH cracked torn</i>	2	\$ 65.20	\$ 130.40 ✓ 65.20
5	FRONT BUMPER UPPER PROTECTOR RH	1	\$ 320.00	\$ 320.00 ✓
6	HEADLAMP RH <i>cracked</i>	1	\$ 620.00	\$ 620.00 ✓ 485
7	FRONT FENDER RH <i>Dislodged</i>	1	\$ 733.20	\$ 733.20 ✓ 544.80

2984

TOTAL PRICE \$ 4,095.90

2694.60

LESS 10% \$ 409.59

SUB TOTAL PRICE \$ 3,686.31

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET) <i>25</i>	1	\$ 25.00	\$ 25.00 ✓

25

TOTAL \$ 25.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	650	
3	TUFF COAT	\$ 250.00	x	
4	WIRING CHECK	\$ 80.00	30	

TOTAL

\$2,930.00

1280

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,711.31
TOTAL LABOUR COST : \$ 2,930.00
TOTAL REPAIR COST : \$ 6,641.31

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lj total: 3999.60
L/S 02/04/19 L/S: 32K
05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: