

Surveyor

NAZ

REF: II

5886 (N)

ASSIGNMENT

From: _____ Date: 22.5.2019

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 94 9392 U

at Workshop m/s Hua Hong

of 25 D Sungei Kadut Street 1

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: nothing

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	
N/S	O/S

Bal. or Market Value: 15K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "up"

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GY 9392U Yr Regn: 29 / SER 2005

Type: M.Car / M.Cycle / Bus / Van / (Lorry) Taxi / Prime Mover / Truck / Trailer or

Make: HYUNDAI HRLADECK c.c 2,476

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 31,708 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMF2CN7HRSU077805

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / (STD) / Rim or

Tyre Size: F: 195 R15C R: 155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or WELLAKE (6), HANKOOK

Front	Rear
R/Bal. 6 mm	R/Bal. 6,6 mm
L/Bal. 6 mm	L/Bal. 6,6 mm
D.O.A. 29/03/19	D.O.I. 22/5/19

Survey held at HUA HONG

Des. of Damages (Fr) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	COE EXP 28/9/20. Need to check MV 1 year left.
	Repair Limit 6K-7K.

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI _____

Photos _____

Others _____

TOTAL _____

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7100J
Vehicle Details	
Vehicle No.:	GY9392U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Apr 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HRL0WDECK2.5
Primary Colour:	Blue
Manufacturing Year:	2004
Engine No.:	D4BH4071706
Chassis No.:	KMFZCN7HR5U077805
Maximum Power Output:	-
Open Market Value:	\$16,248.00
Original Registration Date:	29 Sep 2005
First Registration Date:	29 Sep 2005
Transfer Count:	1
Actual ARF Paid:	\$813.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,768.00
COE Rebate Amount:	\$7,389.00
Total Rebate Amount:	\$7,389.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 01 Apr 2019

OK