



# HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## Estimate Repair List

07 May 2019

QUOT201905-000014  
HHTPCCLAIMS19-70

INDIA INTERNATIONAL INSURANCE PTE LTD  
64 CECIL STREET, #04-00 / #05-00  
IOB BUILDING  
SINGAPORE 049711

Attn: Motor Claims Department

### ACCIDENT INVOLVING GY9392U & SHA4974M ON 09/03/2019 JUNCTION OF BT BATOK ST 23 & BT-BATOK EAST AVE 3 AT ABOUT 2235 HOURS

Insured : EVERGREEN GENERAL CONTRACTORS  
Vehicle Registration No. : GY9392U  
Vehicle Make : HYUNDAI  
Vehicle Model : HRL0WDECK2.5  
Vehicle Chassis No. : KMFZCN7HR5U077805  
Policy No. : DMCG18003595  
Date of Accident : 09/03/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper		\$ 512.10 / CRK
2	2	Front Bumper Retainer (LH/RH)	\$ 38.00	\$ 76.00 ?
3	10	Front Bumper Clip	\$ 3.00	\$ 30.00 / NEC
4	1	Front Grille		\$ 43.50 / DEF
5	1	Emblem		\$ 40.80 / NEC
6	1	Front Panel		\$ 1,341.10 XR
7	1	Front Head Lamp (LH)		\$ 373.80 / SCR
8	1	Front Corner Panel (LH)		\$ 109.10 XR
9	1	Front Oil Cooler		\$ 495.00 / DEF
10	1	Front Reinforcement		\$ 303.10 ?
11	2	Front Reinforcement Bracket (LH/RH)	\$ 65.00	\$ 130.00 ?
				\$ 3,454.50
				Less 10% \$ 345.45
				\$ 3,109.05
12	1	Front Number Plate	NETT	\$ 35.00 / CRK
To dismantle, cut & weld front panel, front bumper, front grille, front LH head lamp, front reinforcement, knocking & pull straight front chassis frame and all area affected by accident.				\$ 800.00 450
To perform wire checking.				\$ 20.00 / NEC
To spray front panel, front grille, front bumper and front reinforcement.				\$ 800.00 500
				\$ 4,764.05
				7% GST \$ 333.48
				<b>Total \$ 5,097.53</b>

**to Consultants hence notify**  
 Resurvey before/after spray painting  
 To display damaged part(s) during resurvey  
 Parts prices are subject to confirmation  
 Third party survey is on a "Without Prejudice" basis  
 No illegal modification(s) is allowed  
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



*Handwritten signature*

221519 1130  
LIS  
3 days  
= CHECK ITEMS (PHOTOS)  
- AFTER REPAIR (PHOTOS)