

7/10/2010

ASS. REC. BY:

REF: CS/smo 19005858/R1+d3 Special Instruction:

Supervisor: Kasu

ASSIGNMENT (Office)

merimen

From (Person): Hwang Shiang Yi of SMO

Date/Time: 24 @ 19:39

Estimated Cost:

Bill to:

OD-TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 51M

Insured: SJX 50895

at Workshop m/s NOVA

Tel: 62723892 / 64763333

of Blk 1008 1# 01-04/06/08/94 Bukit Merah Lane 3

Policy No: D18MTPV01016690

Claim No: CMTD1901618

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 31.3.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 3.4.19 9:49 a.m

Person Contacted: Annie

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓)
	SJW 51M - X
	SJX 50895 - X
24/04 -	Revised via IA. merimen.
	Lump Sum \$2200/- (Red 2040, 48%)

Surveyor

Paul


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJW 51M
 at Workshop m/s MOVA
 of 15, Fanyuan RD
 Insured: Sompo
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJW 51M Yr Regn: 2015 / SGP
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Vezel 1.5X c.c. 1498
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 063089 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU11101830
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>31/03/19</u>		D.O.I. <u>22/04/19</u>

Survey held at MOVA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 03 MAY 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 215 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 2200)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

TOTAL

<u>250</u>
<u>15</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Apr 2019 Sendback Est	02 Apr 2019 15:38 S\$4,240.00	02 Apr 2019 17:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ANG CHEOW YONG , ID: S7627828H, Tel: +6592375102, Email: ANGVINVANG@GMAIL.COM									
Main Claimant: TEO WEI SENG , ID: S8619037J									
Vehicle Reg. No.:	SJW51M	Date of Loss:	31/03/2019 13:00 - :59 [42 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1901618	Policy/Cover Note No.:	D18MTPV01016690 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJX5089S	Policy No. (Claimant):							
		Excess:							
RepaIrer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/04/2019]								
Driver/Custodian (Insured):	ANG CHEOW YONG (42 / Male) , NRIC: S7627828H, Tel: +6592375102 Email: ANGVINVANG@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 24 Apr 2019

Preliminary Advice

Insured Vehicle No	: SJX5089S	Accident Date	: 31/03/2019
TP Vehicle No	: SJW51M	Assignment Date	: 02/04/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 5.00
Date of Inspection	: 22/04/2019		
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3 SINGAPORE 159722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,240.00
Revised Amount	:S\$	2,716.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,716.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on 'wp'

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2019 14:51
Date Of Accident	31/03/2019 13:10
Exact Location Of Accident	WEST COAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW51M
Insured/Policyholder	
Name Of Registered Owner	TEO WEI SENG
NRIC No	S8619037J
Email Address	GERALDTEO1986@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90704943
Alternative Phone No	OFFICE-90704943
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5074020791-03
Cover Note Number	
Driver	
Name of Driver	TEO WEI SENG
NRIC No	S8619037J
Date Of Birth	25/06/1986
Occupation	OUTDOOR
Date Of Driving Pass	18/07/2007
Driving Experience	11 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90704943
Fax Number	
Contact Number	OFFICE-90704943
EMail Address	GERALDTEO1986@GMAIL.COM

Address	338T WEST COAST ROAD SINGAPORE
Postcode	127410
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: NA (MOTHER IN-LAW) GENDER: FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX5089S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANG CHEOW YONG
NRIC/Passport Number	S7627828H
Contact Number	92375102
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident in respect of the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or furnishing of material facts may allow the insurer a right to repudiate policy liability.
4. The issue and acceptance of this Form by insureds (with policy) is not an admission of policy liability on the part of the insurer or its companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the G.A. General Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available to interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report in the G.A. and to cooperation in the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are entitled to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be deemed jointly referred to as the "Insurers", the Insurers, together with the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claim, including the settlement of the claim and/or necessary investigations relating to the claim;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my instructions in pending to any enquiries by me;
 - (iv) administering my claims (including the making of claim, attendance, statements, inquiries, reports, etc.) in claims, which could involve disclosure of certain personal data about me to bring about delivery of the claim as well as on the external cover of a vehicle/poll packet(s); and/or
 - (v) complying with a applicable law in administering, processing, handling and/or dealing with my claim (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/agents, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for use or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (c) above may be shared/disclosed:
 - (i) to all insurers and/or any other third parties, who assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulatory laws or court orders.

Policyholder's Signature
Date & Time:

31/8/19 10:15

Driver's Signature
If Driver is not the policyholder
Date & Time:

31/8/19 10:15

Reporting Centre Personnel's Signature
Name:
NR/C/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car stationary during traffic light. Car did not stop and bang behind of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

Driver's License No.:

Reporting Officer/Personnel's Signature

Rank:

[> Back to OneMotoring](#)

SJWSIM H/Vezel

TP Sompoo

Veh not in.

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:Singapore NRIC
9037J

SJW51M

Yes

01 Apr 2019

HONDA

VEZEL 1.5 X

Black

2015

L15B4021833

RU11101830

96.0 kW (128 bhp)

\$18,719.00

25 Sep 2015

25 Sep 2015

0

\$8,719.00

Yes

24 Sep 2025

\$6,539.00

24 Sep 2025

A - Car up to 1600cc & 97kW (130bhp)

10

\$57,498.00

\$37,261.00

\$43,800.00

The information contained herein is correct as at 01 Apr 2019

OK



Main Office : No. 22, Jalan Klang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (6 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0068854-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
ANG CHEOW YONG

Sompo Insurance Singapore Pte. Ltd. (HQ)

Alan 96869276

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D18MTPV01016690	Date of Loss:	31/03/2019
Vehicle Reg. No.:	SJW51M	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	ANG CHEOW YONG		
Make/Model:	HONDA VEZEL, 1.5 X (A)	Vehicle Reg. Date:	25/09/2015
Vehicle Colour:	BLACK	Chassis No:	RU11101830
Engine No:	L15B4021833		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	AT TRAFFIC JUNCTION, MY VEHICLE MOVING SLOWLY BUT NOT COMPLETELY STOPPED. HIT INTO THE CAR IN FRONT OF ME.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS

	Amount
Parts	2,340.00
Miscellaneous Items	0.00
Labour	1,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	4,240.00
+ GST 7.00% (\$\$)	296.80
Nett Amount (\$\$)	4,536.80

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Apr 2019)
Parts: M1-SUV HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJW51M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE <i>BT</i> ✓	20.00	0.00	*995.00 FL ✓
2	1		*TAILGATE (VEZEL) EMBLEM <i>nee</i> ✓	20.00	0.00	*60.00 FL ✓
3	1		*TAILGATE LOCK <i>X SUV</i>	20.00	0.00	*230.00 FL X
4	1		*REAR WINDSCREEN MOULDING (1 SET) <i>nee</i> ✓	20.00	0.00	*220.00 FL ✓
5	1		*REAR BUMPER <i>cut</i> ✓	20.00	0.00	*315.00 FL ✓
6	1		*END PANEL <i>repair</i> ✓	20.00	0.00	*445.00 FL X
7	10		*REAR BUMPER CLIPS <i>nee</i> ✓	20.00	0.00	*50.00 FL ✓
8	1		*TAILGATE RUBBER <i>nee</i> ✓	20.00	0.00	*230.00 FL ✓
9	1		*TAILGATE INNER TRIM <i>X SUV</i>	20.00	0.00	*330.00 FL X
10	1		*REAR WINDSCREEN SEALANT <i>nee</i> ✓	0	0.00	*40.00 FS ✓

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) **2,915.00**

- List Item Discount on L Items (\$\$) 575.00

Total Parts (\$\$) **2,340.00**

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & INSTALL REAR COMPARTMENT CARPET, GARNISHES ETC IN ORDER TO CUT OFF END PANEL	New	60 200.00 ✓
2	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00 ✓
3	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE	New	60 100.00 ✓
4	TO CUT OFF END PANEL & RENEW DAMAGED PARTS	New	500 700.00 ✓
5	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	X 40.00 ✓
6	TO APPLY RUST PROOF ON AFFECTED AREAS	New	40.00 ✓
7	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	400 700.00 ✓
Gross Labour Cost (S\$)			1,900.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

[Signature]
24/4/19

[Signature]

Hp 90010068

5 days

43

22/04/19 @ 1800

Ready after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Main Office: No. 22, Jalan Klang, Singapore 159410
Tel: 6476 3333 Fax: 6471 5491

Service Centre: Block 1000, Bukit Merah Lane 3,
#01-04/05/06/115 Singapore 159722
Tel: (65) 6476 3333 & Lincoln Fax: (65) 6470 8214
www.mova.com.sg
GST Reg. No: M2-0009064-2

Mova Spray Centre
PK Quick Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
ANG CHEOW YONG

Sompo Insurance Singapore Pte. Ltd. (HQ)

Alan 96869276

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D18MTPV01016690	Date of Loss:	31/03/2019
Vehicle Reg. No.:	SJW51M	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	ANG CHEOW YONG		
Make/Model:	HONDA VEZEL, 1.5 X (A)	Vehicle Reg. Date:	25/09/2015
Vehicle Colour:	BLACK	Chassis No:	RU11101830
Engine No:	L15B4021833		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	AT TRAFFIC JUNCTION, MY VEHICLE MOVING SLOWLY BUT NOT COMPLETELY STOPPED. HIT INTO THE CAR IN FRONT OF ME.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS

	Amount
Parts	2,340.00
Miscellaneous Items	0.00
Labour	1,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,240.00
+ GST 7.00% (S\$)	296.80
Nett Amount (S\$)	4,536.80

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & INSTALL REAR COMPARTMENT CARPET, GARNISHES ETC IN ORDER TO CUT OFF END PANEL	New	60 200.00
2	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00
3	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE	New	60 100.00
4	TO CUT OFF END PANEL & RENEW DAMAGED PARTS	New	500 700.00
5	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	X 40.00
6	TO APPLY RUST PROOF ON AFFECTED AREAS	New	40.00
7	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	900 700.00
Gross Labour Cost (S\$)			1,900.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Perman

Hp 90010068

5 days

4/3

22/04/19 @ 1800

Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to cost approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Apr 2019)
 Parts: M1-SUV HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJW51M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE <i>PI</i>	20.00	0.00	*995.00 FL
2	1		*TAILGATE (VEZEL) EMBLEM <i>rel</i>	20.00	0.00	*60.00 FL
3	1		*TAILGATE LOCK <i>X</i>	20.00	0.00	*230.00 FL
4	1		*REAR WINDSCREEN MOULDING (1 SET) <i>rel</i>	20.00	0.00	*220.00 FL
5	1		*REAR BUMPER <i>cut</i>	20.00	0.00	*315.00 FL
6	1		*END PANEL <i>repair</i>	20.00	0.00	*445.00 FL
7	10		*REAR BUMPER CLIPS <i>rel</i>	20.00	0.00	*50.00 FL
8	1		*TAILGATE RUBBER <i>rel</i>	20.00	0.00	*230.00 FL
9	1		*TAILGATE INNER TRIM <i>X</i>	20.00	0.00	*330.00 FL
10	1		*REAR WINDSCREEN SEALANT <i>rel</i>	0	0.00	*40.00 FS
Sub Total (\$\$)						2,915.00
- List Item Discount on L Items (\$\$)						575.00
Total Parts (\$\$)						2,340.00

P=Franchise part, S=SpcNett, L=ListitemDisc.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

P-1870
 -20%

P-1496
 SIN-140.00
 LC-1180

2716
 -20% 148

2172.80

2200

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Apr 2019 Sendback Est	02 Apr 2019 15:38 S\$4,240.00	02 Apr 2019 17:39 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ANG CHEOW YONG, ID: S7627828H, Tel: +6592375102, Email: ANGVINVANG@GMAIL.COM		
Main Claimant:	TEO WEI SENG, ID: S8619037J		
Vehicle Reg. No.:	SJW51M	Date of Loss:	31/03/2019 13:00 - :59 [42 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1901618	Policy/Cover Note No.:	D18MTPV01016690 (Comprehensive)
Vehicle Reg. No. (Insured):	SJX5089S	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/04/2019]		
Driver/Custodian (Insured):	ANG CHEOW YONG (42 / Male) , NRIC: S7627828H, Tel: +6592375102 Email: ANGVINVANG@GMAIL.COM		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

SJW51M (CMTD1901618)

[SJX5089S]

TP

TEO WEI SENG

Mar 31 2019 1:00PM

[ANG CHEOW YONG]

Mova Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On		Thumbnail	Print
1	02/04/19 17:39	Sompo Insurance Singapore Pte. Ltd. (HQ) Accident Statement From: SC - Reg. No: SJX5089S, Claimant: ANG CHEOW YONG	Load HTM	☐
1	02/04/19 15:38	Mova Automotive Pte Ltd (Bukit Merah) Repairer Estimates	Load HTM	☐
1	24/04/19 11:13	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	Load HTM	☐

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder		Thumbnail	Print
1	02/05/19 15:27	LKK Auto Consultants Pte Ltd (HQ) General View	Load JPG ☒	☒
2	02/05/19 15:27	General View	Load JPG ☒	☒
3	02/05/19 15:27	General View	Load JPG ☒	☒
4	02/05/19 15:27	General View	Load JPG ☒	☒
5	02/05/19 15:27	General View	Load JPG ☒	☒
6	02/05/19 15:27	General View	Load JPG ☒	☒
7	02/05/19 15:27	General View	Load JPG ☒	☒
8	02/05/19 15:27	General View	Load JPG ☒	☒
9	02/05/19 15:27	General View	Load JPG ☒	☒
10	02/05/19 15:27	General View	Load JPG ☒	☒
11	02/05/19 15:27	General View	Load JPG ☒	☒
12	02/05/19 15:27	General View	Load JPG ☒	☒
13	02/05/19 15:27	General View	Load JPG ☒	☒
14	02/05/19 15:27	General View	Load JPG ☒	☒
15	02/05/19 15:27	General View	Load JPG ☒	☒
16	02/05/19 15:27	General View	Load JPG ☒	☒
17	02/05/19 15:27	General View	Load JPG ☒	☒
18	02/05/19 15:27	General View	Load JPG ☒	☒
19	02/05/19 15:27	General View	Load JPG ☒	☒
20	02/05/19 15:27	General View	Load JPG ☒	☒
21	02/05/19 15:27	General View	Load JPG ☒	☒
22	02/05/19 15:27	General View	Load JPG ☒	☒
23	02/05/19 15:27	General View	Load JPG ☒	☒
24	02/05/19 15:27	General View	Load JPG ☒	☒
25	02/05/19 15:27	General View	Load JPG ☒	☒
26	02/05/19 15:27	General View	Load JPG ☒	☒
27	02/05/19 15:27	General View	Load JPG ☒	☒
28	02/05/19 15:27	Reinspection Photo	Load JPG ☒	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
29	02/05/19 15:27	Reinspection Photo	 Load JPG	✓
30	02/05/19 15:27	Reinspection Photo	 Load JPG	✓
31	02/05/19 15:27	Reinspection Photo	 Load JPG	✓
32	02/05/19 15:27	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	02/04/19 15:38	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19005858/R1TD3S2

Date: 06/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01016690
Claimant Vehicle No :	SJW51M	Insured Vehicle No :	SJX5089S
Date of Loss:	31/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901618

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW51M	Engine No:	L15B4021833
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11101830
Reg. Date:	25/09/2015 (Man. Year: 2015)	Odometer:	63089 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,340.00	1,536.00	804.00	34.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,180.00	720.00	37.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,240.00	2,716.00	1,524.00	35.94
Approved Total (Overridden) (\$\$)		2,200.00		
(\$\$)	4,240.00	2,200.00	2,040.00	48.11
+ GST 7.00/7.00% (\$\$)	296.80	154.00	142.80	48.11
Nett Amount (\$\$)	4,536.80	2,354.00	2,182.80	48.11

INSPECTION

Date of Assignment:	02/04/2019	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	22/04/2019	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW51M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	995.00 FL	*995.00 FL
2	1		*TAILGATE (VEZEL) EMBLEM	Necessary	60.00 FL	*60.00 FL
3	1		*TAILGATE LOCK	Serviceable	230.00 FL	*- FL
4	1		*REAR WINDSCREEN MOULDING (1 SET)	Necessary	220.00 FL	*220.00 FL
5	1		*REAR BUMPER	Cut	315.00 FL	*315.00 FL
6	1		*END PANEL	Repair	445.00 FL	*- FL
7	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
8	1		*TAILGATE RUBBER	Necessary	230.00 FL	*230.00 FL
9	1		*TAILGATE INNER TRIM	Not Necessary	330.00 FL	*- FL
10	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	2,915.00	1,910.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	575.00	374.00
Total Parts (\$\$)	2,340.00	1,536.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL REAR COMPARTMENT CARPET, GARNISHES ETC IN ORDER TO CUT OFF END PANEL	New	200.00	60.00
2	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00	120.00
3	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE	New	100.00	60.00
4	TO CUT OFF END PANEL & RENEW DAMAGED PARTS	New	700.00	500.00
5	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	40.00	0.00
6	TO APPLY RUST PROOF ON AFFECTED AREAS	New	40.00	40.00
7	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	700.00	400.00
Gross Labour Cost (S\$)			1,900.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >