



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19005902/Kwb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 02-07-2019



ATTN: YVONNE ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 5015U	Veh. Inspected	YN 9253H
Policy No.	P1867200	Coverage (\$)	0.00
Claim No.	S8M011F0	Excess (\$)	0.00
Assign From	YVONNE ANG	Assign Date	03/04/2019

2. Vehicle Particulars & Condition

Make & Model	HINO XZU7	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JHHUCS3H40K012191	Colour	WHITE
Odometer	38698	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	700 R16X12	BRIDGESTONE	7 mm
L/H Front Tyre	700 R16X12	BRIDGESTONE	7 mm
R/H Rear Tyre	700 R16X12 (D)	BRIDGESTONE	7/7 mm
L/H Rear Tyre	700 R16X12 (D)	BRIDGESTONE	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/10/2018	Inspection Date	09/04/2019
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------