

ASS. REC. BY:

REF: ALA

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s City Auto

of _____

Insured: 2018383984

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8526

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + R.S. \$ _____

Fees

Others

TOTAL

Veh No: YN 9253HYr Regn: 08, 15Type: M.Car / M.Cycle / Bus / Van / Corr / Taxi / Prime Mover /

Truck / Traller or

Make: 14no X2U7

c.c

4009Colour: W2Z

A/C: Insured / Std / NI / NA

Sp. Reading 38898

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH-14UCS3H40K012191Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M11 / S/Rlm / STD A/Rlm orTyre Size: F: 700R16 X12R: 107

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 29/10/18D.O.I. 9/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.