

Survivor: MARCUS

ASSIGNMENT (Office)

Date/Time: 3.4.19 16.26 p.m

Minimum

From (Person): Clara Li zi Rong of FWD

Bill to:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLP 6734A

Insured:

at Workshop m/s SME motor Pte LTD

Tel: 67476106

of 1 Kaki Bukit Ave 6 # 02-15

Policy No: PNPV2018-00007629

Claim No: 1201900008519

Sum Insured:

Excess: \$1000.00

Make of Veh:

D.O.A. 1.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.4.19 9.06 a.m

Person Contacted:

Ying

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 6734 A - X

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLP 6734A
 at Workshop m/s Sure
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 60k.
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR-Seen: _____ Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S

Veh No: SLP 6734A Yr Regn: 1, 15
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Volvo / 40 cross Country 1560
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 7/389 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: YVIM2845BF 2066212
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50 R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 1/4/19 D.O.I. 5/4/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
8/5/19 conf. final of 4320 with Adyans Jumanja
(5160.00 Red 4%)
LMA 48760 54% Subl by 96.

RECEIVED 08 MAY 2019

8/5/2019

Date/Time, File Pass to? 08/05/19
 1) Typist
 Date/Time, File Return to?
 2) _____
 Report Format : _____
 Lump Sum / I.B.I: (\$ 4,320/- p/p)

Days Of Repair: 3
 Resurvey No. of Trip: 2

Add Fee: Site Insp (\$ _____))
 Interview (\$ _____))
 Tech. Invs (\$ _____))
 Weekend (\$ _____))

Survey Fee:	<u>200</u>
Transportation:	<u>50</u>
	<u>50+50</u>
	<u>10</u>
TOTAL	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2019 Sendback Est	03 Apr 2019 16:06 S\$4,130.00	03 Apr 2019 16:26 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	GAIFIL HAIRI BIN ABDULLAH, ID: S8425047C		
Vehicle Reg. No.:	SLP6734A	Date of Loss:	01/04/2019 07:00 - :59 [50 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900008519	Policy/Cover Note No.:	PNPV2018-00007629 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/04/2019]		
Driver/Custodian:	GAIFIL HAIRI BIN ABDULLAH (/ Male), NRIC: S8425047C Email:		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 5 April 2019 5:22 PM
To: peiyong@smemotor.com.sg
Cc: SUR
Subject: SLP 6734A OD (FWD)

Dear Pei Ying,

As instructed by our client, please proceed to repair the insured vehicle **SLP 6734A (Excess \$ 1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SLP6734A (1201900008519)

OD

Apr 1 2019 7:00AM

[GAIFIL HAIRI BIN ABDULLAH]

SME Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on **08/05/2019 14:13 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4320.00) - SLP6734A - Claim Handler: Clara Li Zi Rong

Approved:4320.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SLP6734A (1201900008519)

OD

Apr 1 2019 7:00AM

[GAIFIL HAIRI BIN ABDULLAH]

SME Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 05/04/2019 16:53 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$3970.00) - SLP6734A - Claim Handler: Clara Li Zi Rong

Approved:3970.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 08 May 2019

Preliminary Advice

Vehicle No	: SLP6734A	Accident Date	: 01/04/2019
Make	: VOLVO V40	Policy No.	: PNPV2018-00007629
Assignment Date	: 03/04/2019	Excess	: S\$1,000.00
Date of Inspection	: 05/04/2019	Est. Duration of Repair	: 3 days
Inspection At	: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,480.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	4,320.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,320.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	48,760.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,240.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 350.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 05 Apr 2019

Preliminary Advice

Vehicle No	: SLP6734A	Accident Date	: 01/04/2019
Make	: VOLVO V40	Policy No.	: PNPV2018-00007629
Assignment Date	: 03/04/2019	Excess	: S\$1,000.00
Date of Inspection	: 05/04/2019	Est. Duration of Repair	: 3 days
Inspection At	: SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,130.00
Revised Amount	:S\$	3,970.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,970.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	48,760.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,240.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2019 13:41
Date Of Accident	01/04/2019 07:55
Exact Location Of Accident	TAMPINES STREET 34
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP6734A
Insured/Policyholder	
Name Of Registered Owner	GAIFIL HAIRI BIN ABDULLAH
NRIC No	S8425047C
Email Address	GAIFIL@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-87509161
Alternative Phone No	OTHERS-87509161

Vehicle Particulars

Manufacturer	VOLVO
Model	V40 CROSS COUNTRY D2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00007629
Cover Note Number	N.A

Driver

Name of Driver	GAIFIL HAIRI BIN ABDULLAH
NRIC No	S8425047C
Date Of Birth	26/08/1984
Occupation	INDOOR
Date Of Driving Pass	05/08/2003
Driving Experience	15 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87509161
Fax Number	
Contact Number	OTHERS-87509161
EEmail Address	GAIFIL@YAHOO.COM.SG

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

ACCIDENT STATEMENT (2000 characters)

I make a right turn from the carpark and stop along the yellow box As the traffic was heavy. Seconds later, a motor came and collided with my car. I came down to help him. Rider apologise and mention that he was unable to stop on time due to the wet weather.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SHARIL BIN SATAR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

1 April 2019 at 11:18 AM

Date/Time:

1 April 2019 at 11:18 AM

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5047C
Vehicle Details	
Vehicle No.:	SLP6734A
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Apr 2019
Vehicle Make:	VOLVO
Vehicle Model:	V40 CROSS COUNTRY D2
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	D4162T3051035
Chassis No.:	YV1MZ845BF2066212
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$26,601.00
Original Registration Date:	13 Jan 2015
First Registration Date:	13 Jan 2015
Transfer Count:	1
Actual ARF Paid:	\$14,242.00 <i>712</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jan 2025
PARF Rebate Amount:	\$10,681.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,010.00
COE Rebate Amount:	\$38,079.00
Total Rebate Amount:	\$48,760.00

The information contained herein is correct as at 05 Apr 2019

OK

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5A



2.88% P.A Low Interest@Gv
Finance.2 Years Warranty.
\$1500 Down Monthly From \$458
GV Credit Pte Ltd StarAd

HIN LUNG A
HoBee Group
One Stop Car
Finance, Insurance
New and Used Car

Browse by Category ▾

Sort by Date Posted

2 vehicles

Volvo V40

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	Volvo V40	Any	Any	2015	Any	Any
	Volvo V40 T2	\$69,800	\$9,020 /yr	15-Dec-2015	1,498 cc	53,150 km
Best Buy. This Car Outperforms Many In The Same Engine Capacity. Responsive And Comfortable. Internal Transfer Done Once - The R Extra Transfer Count. Authentic Low Mileage. Good Car With 220... Posted: 02-Apr-2019 Tags: 2015 Volvo V40, 2015 volvo v40, Volvo V40, volvo v40, Volvo, V40, v40, Used Volvo						
	Volvo V40 Cross Country D2	\$73,888	\$10,080 /yr	19-Aug-2015	1,560 cc	69,000 km
Fuel Type: Diesel (Euro 5 Engine and Above) Pristine Condition. Interior And Exterior As Good As New. Well Maintained. Consignment Unit, High Loan Assists And Trade Ins Are Avail To Make An Appointment To View This Car. Posted: 16-Feb-2019 Tags: 2015 Volvo V40, 2015 volvo v40, Volvo V40, volvo v40, Volvo, V40, v40, Used Volvo						

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage

For old advertisements, view [Expired ads](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage car insurance. Find buy used Volvo V40, Volvo V40 Singapore, used Volvo V40 Singapore, used Volvo V40, used vehicles Singapore or even buy used Volvo V40 Singapore comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy

Follow sgCarMart.com

Compare

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	19/FWD/OD-181 (04)
Policy No:	PNPV2018-00007629	Date of Loss:	01/04/2019
Vehicle Reg. No.:	SLP6734A	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GAIFIL HAIRI BIN ABDULLAH		
Driver:	GAIFIL HAIRI BIN ABDULLAH		

Make/Model:	VOLVO V40, 2.0 T2 CROSS COUNTRY (A)	Vehicle Reg. Date:	13/01/2015
Vehicle Colour:	GREY	Chassis No:	YV1MZ845BF2066212
Engine No:	D4162T3051035	Odometer:	0 KM
Paint Type:		<i>rest of body</i>	
Total Loss?	NO	<i>reborn</i>	
Est. Duration of Repair (day)	5	<i>Whole job. Below party. 3 dy excess \$1000</i>	

Remarks: VEHICLE NOT IN
 Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS	Amount
Parts	3,400.00
Miscellaneous Items	0.00
Labour	730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,130.00
+ GST 7.00% (S\$)	289.10
Nett Amount (S\$)	4,419.10

rest of body
reborn
Whole job. Below party.
3 dy excess \$1000
ST 4/19

This claim is handled by: CHIA PEI YING

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00
2	LABOUR CHARGE	New	350.00
3	SPRAY PAINTING	New	350.00
Gross Labour Cost (S\$)			730.00

20
✓
300

SME Motor Pte Ltd/SLP6734A/03/04/2019 16:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

$$\begin{array}{r}
 9 - 3550 \\
 1045 - 770 \\
 \hline
 4320.
 \end{array}$$

Estimates on Miscellaneous Items
There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	30.00 <i>20</i>
2	LABOUR CHARGE	New	350.00 <i>200 ✓</i>
3	SPRAY PAINTING	New	350.00 <i>300</i>
Gross Labour Cost (S\$)			730.00 <i>620 100 720</i>

SME Motor Pte Ltd/SLP6734A/03/04/2019 16:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

AIR VENT *one* - \$150.
REPAIR END PANEL - \$200 x
PAINT END PANEL - \$200 - 100

Total \$ 6320

07/05/2019

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

(SUPPLEMENTARY)

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	19/FWD/OD-181 (04)
Policy No:	PNPV2018-00007629	Date of Loss:	01/04/2019
Vehicle Reg. No.:	SLP6734A	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GAIFIL HAIRI BIN ABDULLAH		
Driver:	GAIFIL HAIRI BIN ABDULLAH		
Make/Model:	VOLVO V40, 2.0 T2 CROSS COUNTRY (A)	Vehicle Reg. Date:	13/01/2015
Vehicle Colour:	Grey		
Engine No:	D4162T3051035	Chassis No:	YV1MZ845BF2066212
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS	Amount
Parts	150.00
Miscellaneous Items	0.00
Labour	200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	350.00
+ GST 7.00% (\$\$)	24.50
Nett Amount (\$\$)	374.50
+ Previous Estimates (\$\$)	4,419.10
Claim Total (\$\$)	4,793.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 07 May 2019)**Parts:** 144 VOLVO V40 2.0 T2 CROSS COUNTRY (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** SME Motor Pte Ltd/SLP6734A/07/05/2019 09:29**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR VENT	0.00	0.00	CN *150.00 F
Total Parts (S\$)						150.00

F=Franchise part.

SME Motor Pte Ltd/SLP6734A/07/05/2019 09:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PAINT END PANEL	New	<u>100</u> 200.00
Gross Labour Cost (S\$)			<u>200.00</u>

SME Motor Pte Ltd/SLP6734A/07/05/2019 09:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



友興汽車零件私人有限公司
YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708

TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858

Email: yewheng@yewhengauto.sg

Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S : SME MOTOR PTE LTD

KAKI BUKIT AVE 6 #02-15/16/17/18 AUTOBAY@KAKI
BUKIT BLK-D
SINGAPORE 417883
TEL:67476106;FAX67442368;; 64844303

NO: YLI1221318
PAGE: 1
DATE: 13/04/2019
A/C CODE: LYSME001
TERMS: 60 DAYS
P/O NO: SLP6734A

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
1	99999	RR BUMPER TOP	YDS	1	1,480.00	1,480.00
2	99999	RR BUMPER SIDE RETAINER RH	YDS	1	100.00	100.00
3	99999	RR BUMPER CLIPS	YDS	10	5.00	50.00
4	99999	RR BUMPER LOWER	YDS	1	750.00	750.00
5	99999	RR BUMPER SPOILER	YDS	1	750.00	750.00
6	99999	RR FENDER INNER COWLING RH	YDS	1	230.00	230.00
7	99999	RR FENDER INNER COWLING CLIPS	YDS	8	5.00	40.00
8	99999	AIR VENT	YDS	1	150.00	150.00
			TOTAL QUANTITY:	24	TOTAL	SIN 3,550.00
					ADD GST @ 7%	248.50
					GRAND TOTAL	<u>SIN 3,798.50</u>

Print / KXM / 13/04/2019 11:06:32 AM

SALESMAN: KXM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2019 Sendback Est	03 Apr 2019 16:06 S\$4,130.00	03 Apr 2019 16:26 Edit Adj Rpt	S\$4,320.00 Edit Estimates	S\$4,320.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	07 May 2019 09:28	07 May 2019 09:29 S\$350.00	07 May 2019 09:29			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	GAIFIL HAIRI BIN ABDULLAH, ID: S8425047C		
Vehicle Reg. No.:	SLP6734A	Date of Loss:	01/04/2019 07:00 - :59 [50 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900008519	Policy/Cover Note No.:	PNPV2018-00007629 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 12/04/2019]		
Driver/Custodian:	GAIFIL HAIRI BIN ABDULLAH (/ Male) , NRIC: S8425047C Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (08/05/2019): Alert - Adj Mandate Approved (S\$4320.00) - SLP6734A - Claim Handler: Clara Li Zi...
- FWD_SG (05/04/2019): Alert - Adj Mandate Approved (S\$3970.00) - SLP6734A - Claim Handler: Clara Li Zi...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLP6734A (1201900008519)
OD
Apr 1 2019 7:00AM
[GAIFIL HAIRI BIN ABDULLAH]
SME Motor Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▾

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail Print
1	03/04/19 16:06	Repairer Estimates		Load HTM
2	07/05/19 09:29	Repairer Estimates Suppl. #1		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	05/04/19 15:57	Adjuster Immediate Advice		Load HTM
2	08/05/19 10:57	Adjuster Immediate Advice		Load HTM

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	05/04/19 16:00	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
2	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
3	05/04/19 16:00	Chassis Number		Load JPG <input checked="" type="checkbox"/>
4	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
5	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
6	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
7	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
8	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
9	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
10	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
11	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
12	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
13	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
14	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
15	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
16	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
17	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
18	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
19	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
20	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
21	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
22	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
23	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
24	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
25	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
26	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
27	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
28	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
29	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>
30	05/04/19 16:00	General View		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
31	05/04/19 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/04/19 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/04/19 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/04/19 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/04/19 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/04/19 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/04/19 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	08/05/19 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	03/04/19 16:09	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/19 15:58	SLP 6734A GIA.pdf	 Load PDF	
2	05/04/19 15:58	ESTIMATE.pdf	 Load PDF	
3	08/05/19 10:58	ESTIMATE & SUPPLEMENTARY MARKED.pdf	 Load PDF	
4	09/05/19 10:01	SUPPLEMENTARY	 Load PDF	
5	09/05/19 10:01	PARTS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19005947/USD3S2
Date: 09/05/2019

REFERENCE

Insured/Claimant: GAIFIL HAIRI BIN ABDULLAH Policy No: PNPV2018-00007629
Date of Loss: 01/04/2019 Nature of Claim: OD Claim No: 1201900008519

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP6734A**
Make & Model: VOLVO V40, 2.0 T2 CROSS COUNTRY (A) Engine No: D4162T3051035
Reg. Date: 13/01/2015 (Man. Year: 2014) Chassis No: YV1MZ845BF2066212
Colour: Grey Odometer: 71369 km
Engine Capacity: 1560 cc
Market Value/New Car Price: S\$60,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,550.00	3,550.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	770.00	160.00	17.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,480.00	4,320.00	160.00	3.57
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	4,480.00	3,320.00	1,160.00	25.89
+ GST 7.00/7.00% (S\$)	313.60	232.40	81.20	25.89
Nett Amount (S\$)	4,793.60	3,552.40	1,241.20	25.89

INSPECTION

Date of Assignment: 03/04/2019 Present Location: SME Motor Pte Ltd (Kaki Bukit)
SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 05/04/2019 Inspected At: 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 09 May 2019)**Parts:** 144 VOLVO V40 2.0 T2 CROSS COUNTRY (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLP6734A)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (TOP)	Distorted / Torn	1,480.00 F	*1,480.00 F
2	1		*REAR BUMPER RETAINER RH	Cracked	100.00 F	*100.00 F
3	10		*REAR BUMPER CLIP	Necessary	50.00 F	*50.00 F
4	1		*REAR BUMPER (LOWER)	Deformed / Torn	750.00 F	*750.00 F
5	1		*REAR BUMPER SPOILER	Torn	750.00 F	*750.00 F
6	1		*REAR RH FENDER INNER COWLING	Torn	230.00 F	*230.00 F
7	8		*REAR RH FENDER INNER COWLING CLIP	Necessary	40.00 F	*40.00 F
Supplementary #1						
8	1		*AIR VENT	Cracked	150.00 F	*150.00 F
Total Parts (S\$)					3,550.00	3,550.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	30.00	20.00
2	LABOUR CHARGE	New	350.00	350.00
3	SPRAY PAINTING	New	350.00	300.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
4	PAINT END PANEL	New	200.00	100.00
Gross Labour Cost (S\$)			930.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >