

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLL3609U Yr Regn: 2017 / Feb.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volkswagen Jetta c.c. 1390
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 33949 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: WWZ2216ZFM 096601
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45R17
 R: 225/45R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 08/06/17
 Survey held at Premium Carz
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>TPAXA</u>
	<u>MV : 20K</u>
	<u>PV : 57.1K</u>
	<u>Nett : 12.9K</u>

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:					
1)	2)	IN	OUT	Basic & Add.	<table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>					
3)	4)			__ S + RS, __ SI						
5)	6)			Photos						
				Others						
				TOTAL						

Prel. Report:
 Final Report: