

INVEST

INS. CASE OWNER

Vale

CC

KSM

AXA1900

5997

Ug

LKK

H3A1

Surveyor:

marcus

DOI

ASSIGNMENT

9/4/19

Date / Time

4/4/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

skk 31AT

Name of Insured

Insured Tel No.

HP

Excess Sec II :SS

D.O.A.

30/3/19

Is driver the owner?

(YES / NO)

Nature of Accident

Claim No.

SAM0212K/108720

Policy No.

99M81157

Make / Model

Place of Accident

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability :

Final ? Yes / No

SBV 61J



INSRS:

WSP:

Tel :

Liability :

RMKS:

KFS



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/Time

SBV 61J - X

SKK 31AT - Y

STAGE

DATE / PIC

Non-Reporting It (1st):

Non-Reporting It (2nd):

Non-Reporting It (Final):

Notification It (if non-pickup):

Call OI:

After call It to OI:

7 CPL 25/9/19

Documentation Check List: Handler Typist

Notification It (if non-pickup)

After call It to OI:

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice:

Towing Invoice

UTA / GIA :

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form:

Post-Repair Photos

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

ANALIZATION

Date/Time:

Confirm with:

Confirm by:

marcus

Repair Cost:

46

SS

4300.00

4

days

Reduction: \$2484.85 = 45

Email

Call

FINAL SETTLEMENT

Date/Time:

23/3/2020

Confirm with:

HILL

Email

Call

Final Liability:

9

100

(Agreed / Assessed)

BOLA S/N No. NIL

If NO or B 28, Ass. Lia :

Repair Cost:

(w/amt)

SS

4601.00

Loss of Rental (LOR):

SS

428.00

4

days

x \$107 (w/amt)

Loss of Use (LOU):

SS

-

(5

x days)

Loss of Income (LOI):

SS

-

(5

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

LOR + LO

LOR + LO

[Tick only one]

GIA/UTA Search

SS

29.00

Medical

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

5058.00

Global Sum SS:

5000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5000.00

Name 1:

Kam Fook Sing Motor Workshop

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 23/3/2020

IP 13501-

REF: ASM (AA)

ASSIGNMENT

From:

Date:

9.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SBV 613

at Workshop n/s Kan Fook Sing motor
of 61 Defu Lane 12

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

12.30pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

21k.

IDAC Accident Report:

Consistent? : Yes or No

CA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lump Sum:

20.

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

rwp

Vehicle: IN / OUT

Date:

Person Contacted:

3yrs 9m.

Veh No:

SBV 613

Yr Regd:

12, 07

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Daihatsu open cc 659

Colour:

silver

AC:

Insured / Std / NI / NA

Sp. Reading

35194

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

L880K0041622

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

165/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FAUKER

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

30/3/19

D.O.A:

9/4/19

Survey held at

Des. of Damages: Frl / Rear / O/S / N/S / WC / Rooftop or

The WC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

car 26/12/2022 LTA 1585 / AEP 5149

45 24300.00 (Red= 43484.25 / 45%)

MV: \$21K

Rebate: \$15,800

NV: \$5100

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, ...

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

4/s \$4300

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 04-04-2019

VEHICLE NO. : SBV61J
ACCIDENT DATE : 30-03-2019 15:00
THIRD PARTY REF. : SKK319T

L880

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SBV61J DAIHATSU COPEN

QTY PARTS DESCRIPTION

1	1	FRONT BONNET
2	1	FRONT BONNET EMBLEM
3	1	FRONT SUPPORT PANEL
4	1	FRONT BRACE PANEL
5	1	FRONT FENDER LH
6	10	FRONT FENDER SHIELD CLIP@8.00
7	1	FRONT GRILLE
8	1	FRONT HEADLAMP LH
9	1	FRONT BUMPER
10	1	FRONT BUMPER LAMP LH
11	10	FRONT BUMPER CLIP@8.00

AMOUNT (SG\$)

Sub	758.00	✓
rer	105.00	—
one	856.00	2
in	25.00	X
Sub	488.00	—
in	80.00	X
one	651.00	—
for	608.00	—
Defect	1288.00	—
in	468.00	X
in	80.00	—

LESS 152.50
TOTAL (A)

5,407.00
540.70
4,866.30

SPECIAL NETT ITEMS

1 1 FRONT NUMBER PLATE

TOTAL (C)

11 30.00 X
30.00

LABOUR CHARGES

1 1 TO CHECK WIRING SYSTEM

30.00

2 1 TO REMOVE/REFIT/REFILL AIR CON GAS

100.00 ✓

\$7784.85

P-5869
502
P-2934.50
106 1370.00
4304.50

1-5889
142
4588/65
1370.00
6388/65
5006



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SBV61J
ACCIDENT DATE : 30-03-2019 15:00
THIRD PARTY REF. : SKK319T

QTY PARTS DESCRIPTION

3 1 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FI-
TTING NEW PARTS
4 1 SPRAYPAINTING CHARGES

AMOUNT (SG\$)

680.00

650

750.00

600

TOTAL (D)

1,560.00

ESTIMATE TOTAL

6,456.30





簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD

DATE : 21-06-2019

8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : SBV61J

ACCIDENT DATE : 30-03-2019 15:00

THIRD PARTY REF. : SKK319T

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEICLE SBV61J DAIHATSU COPEN

QTY PARTS DESCRIPTION

1 AIR CON CONDENSER

1 AIR CON FAN BLADE

1 AIR CON FAN MOTOR

AMOUNT (SGS)

Part 1035.00

11 132.00

11 396.00

1,563.00

LESS 15 %

234.45

TOTAL (A)

1,328.55

SUPPLEMENTARY TOTAL

1,328.55



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : SBV61J
ACCIDENT DATE : 30-03-2019 15:00
THIRD PARTY REF. : SKK319T

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SBV61J DAIHATSU COPEN

QTY PARTS DESCRIPTION

1	1	FRONT BONNET
2	1	FRONT BONNET EMBLEM
3	1	FRONT SUPPORT PANEL
4	1	FRONT BRACE PANEL
5	1	FRONT FENDER LH
6	10	FRONT FENDER SHIELD CLIP@\$8.00
7	1	FRONT GRILLE
8	1	FRONT HEADLAMP LH
9	1	FRONT BUMPER
10	1	FRONT BUMPER LAMP LH
11	10	FRONT BUMPER CLIP@\$8.00

LESS 15% 50%
TOTAL (A)

SPECIAL NETT ITEMS

1	1	FRONT NUMBER PLATE
---	---	--------------------

TOTAL (C)

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM
2	1	TO REMOVE/REFIT/REFILL AIR CON GAS

DATE : 04-04-2019

Not Authorized
Hah
Marcus
1/5
Hah
Temple Ahong

AMOUNT (SG\$)

Bucc	758.00	✓
ner	105.00	✓
.	856.00	?
	25.00	?
Bucc	488.00	✓
an	80.00	X
one	651.00	✓
one	608.00	?
Defen	1288.00	✓
	468.00	?
ner	80.00	✓

5,407.00

540.70

4,866.30

an 30.00 X

30.00

30.00

100.00 ✓



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SBV61J
ACCIDENT DATE : 30-03-2019 15:00
THIRD PARTY REF. : SKK319T

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	680.00 520
4	1	SPRAYPAINTING CHARGES	750.00 600
TOTAL (D)			1,560.00
ESTIMATE TOTAL			6,456.30



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1238H
Vehicle Details	
Vehicle No.:	SBV61J
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2019
Vehicle Make:	DAIHATSU
Vehicle Model:	COPEN 660 A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	JB0372109
Chassis No.:	L880K0041622
Maximum Power Output:	47.0 kW (63 bhp)
Open Market Value:	\$14,234.00
Original Registration Date:	27 Dec 2007
First Registration Date:	27 Dec 2007
Transfer Count:	4
Actual ARF Paid:	\$11,200.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Dec 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,349.00
COE Rebate Amount:	\$15,851.00
Total Rebate Amount:	\$15,851.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Apr 2019

OK

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

500+ dealers competed to buy my car!

Sell ur Car for More Cash

Highest Price or Get \$100 Free

Get Paid Now, Handover Later

SELL YOUR CAR

THE CARMART QUOTZ

QUOTZ

Daihatsu Copen

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Ace Automobile > Daihatsu Copen (COE till 01/2023)

Daihatsu Copen (COE till 01/2023)

Overview	Financial	Insurance	Accessories	Similar	Research	Photos	Map
Price	\$23,800						
Depreciation	\$6,250 /yr		Reg Date	30-Jan-2008 (3yrs 9mths 20days COE left)			
Mileage	121,000 km (10.8k /yr)		Manufactured	2007			
Road Tax	\$359 /yr		Transmission	Auto			
Dereg Value	\$16,376 as of today (change)		OMV	\$14,833			
COE	\$21,485		ARF	\$16,317			
Engine Cap	659 cc		Power	47.0 kW (63 bhp)			
Curb Weight	840 kg		No. of Owners	4			
Type of Vehicle	Sports Car						



Shortlist

Compare

Add note

Report Error

More Actions

Features

View specs of the Daihatsu Copen (2002-2014)

Description

Nice Number Plate, Well Kept, No Repairs Needed, Seldom Available. An Affordable Convertible Without Burning A Big Hole In Your Pocket! Definitely A Head Turner. Don't Miss This Beauty! View Now!

Category

COE Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started

Posted on: 30-Mar-2019 | Last Updated on: 07-Apr-2019

Upfront Payment

> more Financial info

Transfer Fee	\$25	
Down Payment	\$7,140 (change)	Maximum 70% Loan
1st Instalment	\$422	Based on 3.75% Interest rate

Compare

Seller Information

Company	Ace Automobile - dealer's prcelist 3 vehs sold 11 vehs available
Address	1210 Upper Thomson Road Search cars nearby this location
Office No	64835115
Contact Person(s)	Darence Koo 97373572



« Service Request Details

- kps

S9M01JQR

None

30 March 2019

1 Apr 2019 12:00:00 AM

4 April 2019

4 April 2020

LKK AUTO CONSULTANTS PTE LTD (TP)

Third Party Vehicle Damage

Pending verification - Direct Settlement

Actions

Finish the work

10. <i>Staphylococcus aureus</i>	10. <i>Staphylococcus aureus</i>
----------------------------------	----------------------------------

Vehicle Information

5BV61J

TRVD DAIHATSU

COPEN-660C



CLAIMS SERVICE REQUESTS

Primary Contact/Insured

SINGAPORE TECHNOLOGIES ENGINEERING LTD
1 ANG MO KIO ELECTRONICS PARK, #07-01 ST ENGINEERING HUB, 567710, Singapore
67221818
DOCUPRINT@AXA.COM.SG

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg
Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes



TYPE

SENT4/4/19 12:12 PM

FROMLKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECTVNI

BODY



AUTHORIZATION LETTER

Date : 1/4/2019

To : Fixa Ins

Cc : Borneo Motors (S) Pte Ltd

Attn: To Whom It May Concern

Dear Sir / Madam,

RE: Authorization to Act on Behalf for Insurance Claims Documentation

I, (full name) Singapore Technologies Engineering Ltd. NRIC No. hereby authorized my (relationship) employee (full name) KW a Chong Beng, NRIC No. S0234614C to exercise and execute to sign all / any necessary transaction documentation pertaining to my registration vehicle number BKK 319T as I am currently having tight official business schedules / away from Singapore on duty oversea travel.

Please do not hesitate to contact me should you require any further clarification on the above.

Thank You

Yours truly,

Signature :

Name :

Contact No :



BT Engineering Ltd.
6914-5200



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26/09/2019

Survey Details:

Date of loss	30-Mar-19
Date of appointment	4-Apr-19
Date of survey	9-Apr-19
Location of survey	KAN FOOK SING MOTOR WORKSHOP

Vehicle Details:

Claim Type:	Third party
Vehicle number	SBV 61J
Make and Model	DAIHATSU COPEN 660A
Date of registration	27/12/2007
Excess	
Market Value	\$21,000
Parf Rebate	\$15,851
Nett Loss	\$5,149

Repair details:

Initial Estimate	\$ 6,456.30
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 2,934.50
Check items (estimate)	\$ -
Labour	\$ 1,370.00
Total	\$ 4,304.50
Lump Sum(if applicable)	\$ 4,300.00

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	4,601.00	W/GST
Loss of use	\$	-	
Loss of rental (W/GST)	\$	428.00	4days x \$107
Loss of income	\$	-	
LTA search fees	\$	29.00	
Others	\$	-	
Proposed Total	\$	5,058.00	



<MANDATE IA> S9M01IQR {ACCIDENT INVOLVING SKK 319T(OI) & SBV 61J(TP) ON 30/03/2019}

Type

🔗 Question

Message

LIABILITY: 100% OI REVERSE HIT TPV - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$5058.00 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply



Re:<MANDATE IA> S9M01IQR {ACCIDENT INVOLVING
SKK 319T(OI) & SBV 61J(TP) ON 30/03/2019}

Type

🔗 Question

Message

Hi Cecilia Did you check on the parts pricing? Anyway to reduce further on COR?-VO

Reply

check w marcus
on the parts pricing
& adjust if COR amt.

AUTHORIZATION LETTER

Date : 1/4/2019

To : Axa Ins

Cc : Borneo Motors (S) Pte Ltd

Attn: To Whom It May Concern

Dear Sir / Madam,

RE: Authorization to Act on Behalf for Insurance Claims Documentation

I, (full name) Singapore Technologies Engineering Ltd. NRIC No. hereby authorized my (relationship) employee (full name) Kwa Chong Beng, NRIC No. S0234644C to exercise and execute to sign all / any necessary transaction documentation pertaining to my registration vehicle number BKK 319T as I am currently having tight official business schedules / away from Singapore on duty overseas travel.

Please do not hesitate to contact me should you require any further clarification on the above.

Thank You

Yours truly,

Signature : 
Name : ST Engineering Ltd.
Contact No : 6914-5200





Re:RE: Re:<MANDATE IA> S9M01IQR {ACCIDENT INVOLVING SKK 319T(OI) & SBV 61J(TP) ON 30/03/2019}

Type

🔗 Question

Message

Hi Cecilia Pls proceed, tks-VO

Reply

(LKK)

THIRD PARTY CLAIM

WITHOUT PREJUDICE
TO PERSONAL INJURY CLAIMS

Date: 3/4/2019

Name & Address Of Claimant: FONG HOI YAN ANNA
C/O: KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147
Name & Address Of Third Party Insured: AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way #27-01 AXA Tower Singapore 068811

Dear Sir/Madam,

Accident involving vehicles SBV61J & SKK319T
on 30/3/2019 along/ at
CROSS STREET OUTSIDE CHINATOWN POINT

I am the owner of vehicle registration no: SBV61J which was involved in the
above mentioned vehicle registration no: SKK319T which I understand is insured
with you.

The accident was clearly caused by your insured's negligence and I am therefore claiming
compensation from you for all financial losses as itemized below:-

1 Repair Costs	SS <u>4,601.00</u>
2 Miscellaneous Items	SS <u>-</u>
3 Surveyor Fee	SS <u>-</u>
4 LTA/GIA Search Fee (<u>\$15 + \$14</u>)	SS <u>29.00</u>
5 Loss of Use /	
Rental for <u>4</u> days @ SS <u>160.50</u> per day	SS <u>642.00</u>
6 Excess	SS <u>-</u>
7 Medical Fee	SS <u>-</u>
TOTAL:	SS <u>5,272.00</u>

I enclosed the relevant copies of documents in support of my claims. Your prompt settlement of my claim
would be much appreciated. If you require any other information, please contact my workshop at **KAN
FOOK SING MOTOR WORKSHOP**, 61 Defu Lane 12 Singapore (539147), Tel: 6747 9560 Fax: 6748 1006,
Email: ryan@kanfs.net / patricia@kanfs.net. I have authorized the said workshop to deal with my repairs
& accept payment in relation to the claim for repairs/loss of use & execute documents on my behalf for
the purpose of my convenience.

Thank you.

Your faithfully





簡福星摩多工廠
KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12, Singapore 539147
Tel: (65) 6747 9560, 6743 5344, 6858 4361 • Fax: (65) 6746 1006, 6281 8428
E-mail: ryan@kanfs.net / patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883
Tel: (65) 6481 5150 • Fax: (65) 6481 8683

TAX INVOICE

No. 46932

Business Reg. No. 221488-00E
GST Reg. No. M9-0005333-E

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

INVOICE NO : 46932
DATE : 08-07-2019

VEHICLE NO. : SBV61J
ACCIDENT DATE : 30-03-2019 15:00
THIRD PARTY REF. : SKK319T

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SBV61J DAIHATSU COPEN

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
	LABOUR CHARGES	
1	LUMP SUM REPAIRS	4300.00
TOTAL (D)		4,300.00
TOTAL REPAIR COST		4,300.00
GST		301.00
INVOICE AMOUNT		4,601.00



IN PANEL-BEATING & BODY-WORK, OUR WORKSHOP IS WELL-EQUIPPED WITH THE LATEST TECHNOLOGY --- CELETTE BENCH PULLER SYSTEM WHICH ENABLE US TO MEASURE CORRECTLY & REPAIR MANY DIFFERENT KINDS OF DAMAGES, SERIOUS DAMAGES TO THE FLOOR-BOARD CHASSIS & WHEEL-HOUSING CAN BE RESTORED BACK TO THE ACCORDING MEASUREMENT. WE ARE ABLE TO REPAIR & RESTORE ANY BADLY DAMAGED VEHICLE BACK TO ITS ORIGINAL SPECIFICATIONS TO ENSURE SAFETY WHILE DRIVING.

在钣金修理業，本廠有最精良，先進的機械，來準確測量及修理，在規格尺寸圖內，本公司有能力回復原來相符的程度。



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19005997/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:VALE OH

Date : 30-03-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 319T	Veh. Inspected	SBV 61J
Policy No.		Coverage (\$)	0.00
Claim No.	S9M011ST	Excess (\$)	0.00
Assign From		Assign Date	04/04/2019

2. Vehicle Particulars & Condition

Make & Model	DAIHATSU COPEL (A)	c.c	659
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	L880K0041622	Colour	SILVER
Odometer	35194	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	165/50 R15	FALKEN	6 mm
L/H Front Tyre	165/50 R15	FALKEN	6 mm
R/H Rear Tyre	165/50 R15	FALKEN	6 mm
L/H Rear Tyre	165/50 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/03/2019	Inspection Date	09/04/2019
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBV 61J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET (CONSISTENT)	BUCKLED	758.00	758.00
1	FRONT BONNET EMBLEM (CONSISTENT)	NECESSARY	105.00	105.00
1	FRONT SUPPORT PANEL (CONSISTENT)	CRACKED	856.00	856.00
1	FRONT BRACE PANEL (CONSISTENT)	NOT NECESSARY	25.00	-
1	FRONT FENDER LH (CONSISTENT)	BUCKLED	488.00	488.00
10	FRONT FENDER SHIELD CLIP @\$8.00 (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT GRILLE (CONSISTENT)	CRACKED	651.00	651.00
1	FRONT HEADLAMP LH (CONSISTENT)	CRACKED	608.00	608.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED / TORN	1,288.00	1,288.00
1	FRONT BUMPER LAMP LH (CONSISTENT)	NOT NECESSARY	468.00	-
10	FRONT BUMPER CLIP @\$8.00 (CONSISTENT)	NECESSARY	80.00	80.00
1	AIR CON CONDENSER (CONSISTENT) (ADDITIONAL)	PUNCTURE	1,035.00	1,035.00
1	AIR CON FAN BLADE (CONSISTENT) (ADDITIONAL)	NOT NECESSARY	132.00	-
1	AIR CON FAN MOTOR (CONSISTENT) (ADDITIONAL)	NOT NECESSARY	396.00	-
	LESS 10% DISCOUNT		-697.00	-
	LESS 50% DISCOUNT		-	-2,934.50
			6,273.00	2,934.50
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			30.00	-
LABOUR				
	TO CHECK WIRING SYSTEM.		30.00	20.00
	TO REMOVE/REFIT/REFILL AIR CON GAS.		100.00	100.00
	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS.		680.00	650.00
	SPRAYPAINTING CHARGES.		750.00	600.00
			1,560.00	1,370.00
GRAND TOTAL			7,863.00	4,304.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CC4/ASM19005997/Uga3q2



Report Ref No. CC4/ASM19005997/Uga3q2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	594010QR
Reference	CC4/ASM19005997/Uja3a2
Loss Date	30 March 2019
Report Date	1 Apr 2019 12:00:00 AM
Request Date	31 March 2020
Due Date	
Vendor Name	LK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SRV61J
Make	TPVO DAIHATSU
Model	COPEN-660C
Service Address	
...	
Primary Contact/Insured	
SINGAPORE TECHNOLOGIES ENGINEERING LTD 1 ANG MO KIO ELECTRONICS PARK, #07-01 ST ENGINEERING HUB, 567710, Singapore 67221818 DOCUPRINT@AXA.COM.SG	
Claim Handler	

CH Vale
6568804897
vale.ch@axa.com.sg

Additional Instructions

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKInvoice1 (5).pdf	Invoice	Surveyor/ Assessor expense	LK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKK Inspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKK Adjustment 1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKK PHOTO-3.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKK PHOTO-2.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKK PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020