

ASS. REC. BY:

REF:

CS/SPF19006086/rqd3<sup>st</sup>

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF

Date/Time: 5.4.19 3.57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 8576K

Insured: QX 363A

at Workshop m/s Supreme Auto

Tel: 64528211

of 176 Sin Ming Dr #02-01

Policy No:

Claim No:

AEMD/105/009/2019/023

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4.4.2019

(Client's Record)

8.4.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 5.4.19 4.54p.m

Person Contacted:

Mr chen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 8576K - CC4/AIG18002917/kh3 DOA - 02/02/2018
	Submit LS @ 3750, 5 days.
	(COR range @ 3750 - @ 3800; Weekend = 0 day)

Do Not Finalise

REF: SPF

## ASSIGNMENT

From:

Date: 8/4/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKZ 8576K

at Workshop m/s

Supreme Auto

of

176 Simming Drive #02-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Mr. Chew @ 6452 8211

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14.5

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1up</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKZ 8576K

Yr Regn:

02, 16

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy

Axi

c.c

1496

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

222301

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NRE161

0010108

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Agenda

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

4/4/19

D.O.L.

8/4/19

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Do Not Finalise

RECEIVED 25 JUL 2019

Date/Time, File Pass to?



Preli. Report

1) 25/7/19 tyris



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Report Format:

70

Lump Sum / I.B.T. (\$)

3250

Survey Fee:

220

Transportation:

S + RS, SI

Photos

Others

TOTAL

## Nivitha (LKK Auto)

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Friday, 5 April 2019 3:57 PM  
**To:** Abdul Rahman MOHAMAD SALIM (SPF); SUR; assignments  
**Cc:** Rosalyn TAN (SPF); Olivia Lau (LKKAuto); Frankie THAY (SPF); Hafizul Farhan RAHMAT (SPF)  
**Subject:** RE: Pre-Repair Inspection for SKZ8576K

Dear Rahman,

Thank you for the email.

Dear Assignment Team,

FYNA

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Mr Chew  
E: in  
E: ✓

---

**From:** Abdul Rahman MOHAMAD SALIM (SPF) <Abdul\_Rahman\_Mohamad\_Salim@spf.gov.sg>  
**Sent:** Friday, 5 April 2019 3:52 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Cc:** Rosalyn TAN (SPF) <Rosalyn\_TAN@spf.gov.sg>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>; Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>  
**Subject:** Pre-Repair Inspection for SKZ8576K

Your Ref : SKZ8576K  
Our Ref : AEMD/105/009/2019/023

Veron,

Please conduct a Pre-Repair Inspection for Vehicle **SKZ8576K** at the following address:

**M/s Supreme Auto**

Please contact **Mr Chew** at **64528211** for appointment.

Thanks.

Abdul Rahman (Mr)  
Accident Claims Officer  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4840 | FAX: (65) 6478 4848



**WARNING** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	05/04/2019 17:06
Date Of Accident	04/04/2019 18:30
Exact Location Of Accident	BOON KENG ROAD TOWARDS UPPER BOON KENG
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKZ8576K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MCQUEEN RENTALS PTE LTD
Co Reg No	201600605G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91682811
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104716720-01
Cover Note Number	
<b>Driver</b>	
Name of Driver	ONG RONG HUA
NRIC No	S8509258H
Date Of Birth	01/04/1985
Occupation	OUTDOOR
Date Of Driving Pass	13/09/2013
Driving Experience	5 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91682811
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 625 SENJA ROAD #07-154 SINGAPORE
Postcode	670625
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 25 SIN MING ROAD , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4529999 - FAX NO: 6 5535740
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX363A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	YEO KAY XING VENISE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

ONG RONG HUA

Approximate Age

Injuries Sustain

REFER POLICE REPORT

Injured person in which vehicle?

SKZ8576K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 05/04/19, 14:35

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190405/2103

1 of 3

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

Report No. T/20190405/2103

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/04/2019 14:02	Vide Report No.: A/20190404/0139	Station Diary No.: 17
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: ONG RONG HUA			Address: APT BLK 625 SENJA ROAD #07-154 SINGAPORE 670625	
ID Type / ID No.: NRIC NO / S8509258H			Contact No.: Home/Office:	Mobile: 91682811
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 34	Date of Birth: 01/04/1985	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Grab driver			Driving Licence Information: Class: 3	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 04/04/2019 18:30	Type of Location: X-Junction
Location: Along Road 1 BOON KENG ROAD				
Boon Keng Road towards Upper Boon Keng Road, At the X-Junction of Boon Keng Road and Bendemeer Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
QX363A	Car					0
SKZ8576K	Car				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190405/2103

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

2 of 3

Report No. T/20190405/2103

## CONTINUATION OF REPORT

Name	YEO KAY XING VENISE		ID No.	T170105
Related Vehicle	QX363A (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
<b>Driver</b>				
Name	ONG RONG HUA		ID No.	S8509258H
Related Vehicle	SKZ8576K (Car)		Contact No.	91682811
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	05/04/2019		Date Discharge	05/04/2019
No. of Days granted Medical Leave	05		Degree of Injury	NIL

**Brief Details.**

On 04/04/2019 at about 1830hrs, I was traveling along first lane of Boon Keng Road towards Upper Boon Keng Road. While near the X-Junction of Boon Keng Road and Bendemeer Road, I slowed down and stopped my vehicle as the vehicle in front stopped. Suddenly, I felt an impact from behind after I has been stationary for sometimes. After I stepped out of my vehicle and realized that a Police vehicle hit onto my vehicle from behind. The driver of the police vehicle then called for traffic police. After traffic police arrived, the traffic police interviewed both me and the driver for the police vehicle. After the interview, traffic police provide me a incident number and the police driver's name with service number and advised me to lodge a police report.



**SINGAPORE  
POLICE FORCE**



T/20190405/2103

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

3 of 3

Report No. T/20190405/2103

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
E /  
Sgt 2 ZHU JIANBIN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
SSI 2 JUREMAH BINTE AHMAD  
Contact No.: 65472076



Signature Of Informant:

Date/Time:  
05/04/2019 14:02

Classification Of Case:

4 076

Authentication Stamp  
NP168

SIGNATURE

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

MCQUIRENS RENTAL PTE LTD

c/o 46 Lentor Plain  
Singapore 786548

*Not Notified*

*11 Bay @ 7*

*Resurvey After Paint*

*4-5 days*

Date: 05/04/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE : TOYOTA COROLLA AXIO/ SKZ 8576 K</b>		
1 pc	rear boot lid	Bu 975.30 ✓
1 pc	rear boot emblem logo	re 97.60 ✓
1 pc	rear boot emblem "G"	re 56.80 ✓
1 pc	rear boot emblem ' AXIO '	re 86.50 ✓
1 pc	rear boot emblem ' COROLLA '	re 75.80 ✓
2 pcs	rear boot hinge @ 192.40	re 384.80 X
1 pc	rear boot lock	re 397.80 ✓
1 pc	rear boot lock catch	re 68.30 X
1 pc	rear boot weatherstrip	nd/lt 296.80 506in
1 pc	rear boot lock sensor	286.90 ?
1 pc	rear bumper	Bu 836.70 ✓
2 pcs	rear bumper retainer @ 197.50	dis 395.00 ✓
2 pcs	rear bumper lamp @ 115.30	su 230.60 X
2 pcs	rear bumper bracket @ 89.40	cmf 178.80 2
1 pc	rear end panel	487.50 ?
1 pc	rear end panel garnish	309.70 ?
2 pcs	rear tail lamp assy @ 648.90	dis/lt 1,297.80 4
1 pc	spare tyre board	su 308.70 X
1 pc	exhaust silencer	re 612.50 ?
Sub-total		7,383.90
Less 25%		1,845.98
Sub-total		5,537.93
1 set	reverse sensor s.nett	250.00 7
Sub-total		5,787.93

LKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Balance brought forward	5,787.93	
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	800.00	600
To check wiring system.	50.00	200
To spray painting on affected areas.	800.00	600
To apply rust proofing on affected areas.	80.00	?
To apply waterproof sealant on affected areas.	80.00	?
To install reverse sensors	60.00	500
To carry our exhaust works	nn 80.00	X
<b>Total</b>	<b>7,737.93</b>	

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

MCQUIRENS RENTAL PTE LTD

c/o 46 Lenton Plain  
Singapore 786548

04/04/19

Not Withheld

11 Days @ 3150

Presuming After Paint

4-5 days

Date: 05/04/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE : TOYOTA COROLLA AXIO/ SKZ 8576 K</b>		
1 pc	rear boot lid 895.	Bu 975.30
1 pc	rear boot emblem logo 59.20	re 97.60
1 pc	rear boot emblem "G" 42	re 56.80
1 pc	rear boot emblem 'AXIO' 45	re 86.50
1 pc	rear boot emblem 'COROLLA' 59.10	re 75.80
2 pcs	rear boot hinge @ 192.40	re 384.80
1 pc	rear boot lock	re 397.80
1 pc	rear boot lock catch	re 68.30
1 pc	rear boot weatherstrip 187.10	re 296.80
1 pc	rear boot lock sensor 189.20	re 286.90
1 pc	rear bumper 590.20	Bu 836.70
2 pcs	rear bumper retainer @ 197.50	re 395.00
2 pcs	rear bumper lamp @ 115.30	re 230.60
2 pcs	rear bumper bracket @ 89.40	re 178.80
1 pc	rear end panel	re 487.50
1 pc	rear end panel garnish 278.10	re 309.70
2 pcs	rear tail lamp assy 548.40 @ 648.90	re 1,297.80
1 pc	spare tyre board	re 308.70
1 pc	exhaust silencer	re 612.50
Sub-total		7,383.90
Less 25%		1,845.98
Sub-total		5,537.93
1 set	reverse sensor s.nett	Shan 250.00
Sub-total		5,787.93

Balance brought forward	5,787.93	
To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	800.00	600
To check wiring system.	50.00	200
To spray painting on affected areas.	800.00	600
To apply rust proofing on affected areas.	80.00	300
To apply waterproof sealant on affected areas.	nn 80.00	X
To install reverse sensors	60.00	500
To carry our exhaust works	nn 80.00	X
<b>Total</b>	<b>7,737.93</b>	



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING &amp; MGT DIVISION Ref : CS/SPF19006086/Kqd3s2

ACCIDENT CLAIM SECTION (SPORE POLICE  
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD  
POLICE ACADEMYSINGAPORE 298333

Date : 25-07-2019



ATTN: ABDUL RAHMAN

Code : SPF

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	QX 363A	Veh. Inspected	SKZ 8576K
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/023	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	05/04/2019

**2. Vehicle Particulars & Condition**

Make & Model	TOYOTA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NRE1610010108	Colour	METALLIC PEARL WHITE
Odometer	222301	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	185/60R15	AGENDA	8 mm
L/H Front Tyre	185/60R15	AGENDA	8 mm
R/H Rear Tyre	185/60R15	AGENDA	8 mm
L/H Rear Tyre	185/60R15	AGENDA	8 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

Accident Date	04/04/2019	Inspection Date	08/04/2019
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 8576K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID	BUCKLED	975.30	895.00
1	REAR BOOT EMBLEM LOGO	NECESSARY	97.60	59.20
1	REAR BOOT EMBLEM "G"	NECESSARY	56.80	42.00
1	REAR BOOT EMBLEM "AXIO"	NECESSARY	86.50	45.00
1	REAR BOOT EMBLEM "COROLLA"	NECESSARY	75.80	59.10
2	REAR BOOT HINGE @ \$192.40	TO REPAIR SEE LABOUR	384.80	-
1	REAR BOOT LOCK	DENTED	397.80	397.80
1	REAR BOOT LOCK CATCH	TO REPAIR SEE LABOUR	68.30	-
1	REAR BOOT LOCK SENSOR	CRACKED	286.90	189.20
1	REAR BUMPER	BUCKLED	836.70	590.20
2	REAR BUMPER RETAINER @ \$197.50	DISTORTED	395.00	196.20
2	REAR BUMPER LAMP @ \$115.30	SERVICEABLE	230.60	-
2	REAR BUMPER BRACKET @ \$89.40	TO REPAIR SEE LABOUR	178.80	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	487.50	-
1	REAR END PANEL GARNISH	MTG CRACKED	309.70	278.10
2	REAR TAIL LAMP ASSY @ \$648.90	O/S CUT	1,297.80	548.40
1	SPARE TYRE BOARD	SERVICEABLE	308.70	-
1	EXHAUST SILENCER	TO REPAIR SEE LABOUR	612.50	-
	LESS 25% DISCOUNT		-1,771.77	-825.05
			5,315.33	2,475.15
1	REAR BOOT WEATHERSTRIP (@ \$187.10 DISC 50%) (SN)	DENTED / CUT	296.80	93.55
	LESS 25% DISCOUNT		-74.20	-
			222.60	93.55
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			250.00	200.00

Report Ref No. CS/SPF19006086/Kqd3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE, REAR BOOT LOCK CATCH, REAR BUMPER BRACKET, REAR END PANEL AND EXHAUST SILENCER.		800.00	600.00
	TO CHECK WIRING SYSTEM.		50.00	20.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		800.00	600.00
	TO APPLY RUST PROOFING AFFECTED AREAS.		80.00	30.00
	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
	TO INSTALL REVERSE SENSORS.		60.00	50.00
	TO CARRY OUT EXHAUST WORKS.	NOT NECESSARY	80.00	-
			1,950.00	1,300.00
	<b>GRAND TOTAL</b>		<b>7,737.93</b>	<b>4,068.70</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,250.00</b>

Report Ref No. CS/SPF19006086/Kqd3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,250.00 - \$3,800.00

RECOMMENDED REPAIR DAYS : 5

WEEKENDS : 0

TOTAL DAYS : 5

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.