* * * * * * * * * * * * * * * * * * *	in Camilana	19/11/A-(1/40) W	SUI()
NATIONAL Assessment Centr	Job description	Date &Time Completed	. Done by
Rer No: XVBP/WSG19006141V		15/ate (c.) time Completed	,
Veh No. Cod 9849K	SAS c-filing		
	E-mail (Spole this, Alexin)		
0.01:01104/2018 01.20	I-Motor Claim Form	<u> </u>	
OD The Reporting Only		1, TP (brs)	:-
	i-Photo Uploaded	14	
TP Insurer:	Assessment/Survey Report		
The state of the s	Ass't Report by Fax / Hand	COLUMN TELEFORM TO SERVICE AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON A	
Proforred Wksp / INC Assign Wksp / QW: (to conta		axt
re Punticulares Veli Noi S	Kt 6891.7 . INC		
Owner / Driver: (Tel:	
	rlod: ()	Cover Type: (
Confirmed by (· Datei,	Time:	1001/1
	Note-Est Status (WO): N: 0-2	0%; P: 21-79%. P: 80-1	100%)
	Warranty: YES()/NO()	
Exects: (\$ ') Londing: \$1,0	000 () / \$2,000 ()	ALTERNATION OF THE STATE OF THE	705 75 77
enconaciminataro, republikatentara	SACRETURE SERVICE SERV	ACMINING AND	Mary Print
) Walk-In Customer : Customers info		Incly NO rater of repailor.	
) Total Loss Case : to e-mail Insur		1 5 5	·
Drive-In ()/ Towed-In (); Invoice	e: YES() / NO();	rowing Cor (· , '	SPECIAL WEST
antinia de la compania del compania del compania de la compania del		加州经验制制产出的 包括	STATISTICAL PROPERTY.
		A LA	
The state of the s	Courtesy Car ()	*	ii.
QC Check / Post Repair Inspection	(·)		
QC Check / Post Repair Inspection	(·)		
QC Check / Post Repair Inspection) Upload Resurvey Photo [Repair Cost > \$	(·)		
QC Check / Post Repair Inspection	(·)		Alle The The Control of the Control
QC Check / Post Repair Inspection) Upload Resurvey Photo [Repair Cost > \$:	(·)		Augustic and a second of the s
QC Check / Post Repair Inspection) Upload Resurvey Photo [Repair Cost > \$	(·)		VICEOUTONE.
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$:	(·)		Vicencia de la companya de la compan
QC Check / Post Repair Inspection) Upload Resurvey Photo [Repair Cost > \$:	(·)		Altomorasses.
QC Check / Post Repair Inspection) Upload Resurvey Photo [Repair Cost > \$:	(·)		STEACH STANDARD STANDARD
) QC Check / Post Repair Inspection) Upload Resurvey Photo [Repair Cost > \$: Injury : **Taction*** **Taction** **Taction**	(·)		ALL SAME OF THE SA
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$ Injury:	(·) 3000] () : :	at Reporting (530);	AND MAINS W WARDIN
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > S. Injury : ALCOMOS ACCOMOS	(·) 3000] ()	Fis : S	150) 10743
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > S. Injury : ALCOMOS ACCOMOS	(·) 3000] ()	* Assessment (5100); INC (Fee . 3 Through Survey Through Survey (Resurvey)	\$50) \$0) \$0,545 \$120 \$30
OC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > S. Injury: ARECONDUCACIONES AND PROPERTY OF THE PROP	(·) 3000] () 10 AR; Acade 2) DA; Berne 3) TF; Tewlor 4) PT; Follow 5) PT; Follow Ferslaimin	Fig. 1NC (Fig. 5 Through Survey (Resurvey) Through Survey (Resurvey) against INC Only (Wal 10 Jin 20	\$300 \$120 \$300 \$300 \$300
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > 5] Injury: ACCOUNTY COST	(·) 3000] () 1) AR; Aside 2) DA; Dans 3) TV; Twins 4) PT; Voltow 5) PT; Voltow Ferslaindig 6) TR; Re-jar	Through Survey (Resurvey) Through Survey (Resurvey) (against INC Only (Well 10 Jin 20	\$50) \$0) \$0,545 \$120 \$30
OC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$: Injury : The injury Cost Cos	() 3000] () 3000] () 3000] () 3000] () 3000] () 3000] () 31) AR; Aside 32) DA; Dense 33) FT; Follow 43) FT; Follow 53) FT; Follow 54) TR; Re-lar 77) NI; Idao D 58) NTUC Add	Fig. 1NC (Fig. 5 Through Survey (Resurvey) Through Survey (Resurvey) against INC Only (Wal 10 Jin 20	\$50) \$0,545 \$110 \$30 \$73
OC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$: Injury : The input Cost State	(·) 3000] () 11 Vol. St. 1 12 Vol. St. 1 13 AR; Aside 23 DA; Dans 3) TF; Tewlin 4) FT; Vol. 1 5) FT; Vol. 1 6) TR; Re-lar 7) NI; Idao D 8) NTUC Add Only	A Histiment (\$100); INC (Fig. 5 Through Survey (Resurvey) Integral Survey (Resurvey) Integral Survey (Well Din 20 Decilon A + SMRT Survey Honel Services:	\$30) \$0545 \$120 \$30 \$73 \$160
OC Checked by (Engr-In-Charge):	() 3000] () 1) AR; Acade 2) DA; Dema 3) TV; Tewin 4) PT; Vellow 5) PT; iVoltow Forslaimful 6) TR; Re-lar 7) NI; Idao D 2) NI; Cauch NS; Cauch NS; Cauch NS; Cauch	A Histiment (\$100); INC (Pre	\$120 \$30 \$75 \$160
Checked by (Engr-In-Charge):	() 3000] () 1) AR: Asside 2) DA: Deme 3) TF: Follow 4) PT: Follow 5) FT: Pollow Farslaimin 6) TR: Re-law 7) NI: Idao D a) NTUC Add OIN! NS: Cauch NS:	A Assessment (\$100); INC (Fig. 5 Through Survey (Resurvey) stellast INC Only (Well ID In 20 seellon A + SMRT Survey Idenal Services: If Cif Trpr Allowence Co-ordination / FOR ORG Antir Inspection Collect Uncers Consideration	310 310 310 310 310 310 310 310
OC Check / Post Repair Inspection Outlook Resurvey Photo [Repair Cost > 5: Injury: Outlook Resurvey Photo	() 3000] () 1) AR: Asside 2) DA: Deme 3) TF: Follow 4) PT: Follow 5) FT: Pollow Farslaimin 6) TR: Re-law 7) NI: Idao D a) NTUC Add OIN! NS: Cauch NS:	A Histiment (\$100); INC (Pre	130 130 130 130 130 130 130 130

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	08/04/2019 13:00
Date Of Accident	07/04/2019 09:30
Exact Location Of Accident	JUNCTION OF CLEMENTI AVE 3/COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE
ALES DE CARROL D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SGL9359K
Insured/Policyholder	
Name Of Registered Owner	LIU GE
NRIC No	S8383034D
Email Address	LUYOU83@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98719628
Alternative Phone No	OTHERS-97698316
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC-1.8 L (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 39120728 QMX
Cover Note Number	
Driver	
Name of Driver	LU YOU
NRIC No	S8480602A
Date Of Birth	05/10/1984
Occupation	INDOOR
Date Of Driving Pass	23/10/2013
Driving Experience	5 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98719628
Fax Number	
Contact Number	OTHERS-97698316

LUYOU83@GMAIL.COM

Address

BLK 163 STIRLING ROAD

#11-1234

Postcode

140163

Was driver an employee of the Insured's Company NO

SPOUSE

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKF6891T

Vehicle Make/Model/Colour

SUZUKI

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

PRISCILLA MON LIAN PHENG

NRIC/Passport Number

S7503774J

Contact Number

91391022

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

Veh A: SGL 9359 K Veh B: SKF 6891T

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

"I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY I WILL CHECK MY POLICY FOR MORE DETAILS

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is now the policyhalder)


Date & Time:

NRIC/FIN No.:

Porting Centre Personnel's Signature

colorbous

SKETCH PLAN Veh A: SGL 9359k Ven B: SEF 68917



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While i	turning	Out	from	Clementi	Ave 3	s to	wards	(padestrian	h Ave	₩.
1 was	stationari	4	at th	e traffic	June	tion	due	to	padestrian	Crossi	ng.
Suddenly	Vehicle	В	Collida	d with	my	Vehic	le.		<i>h</i>		
)											

DECLARATION

I/We der are the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Oriver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature In Name:

9:30Am

Accord Auto Services Pte Ltd Tel: 6271 7433 / 9274 0999 Fax: 6274 5715 Email: avclaims@mycarworkshop.com Particular Of Insured/Driver & Details Of The Accident Motor Accident Report *Time of Accident: *Date of Accident: _ *Accident Location: Vehicle Details * Make & Model: *Vehicle Number: ____ Insured / Policyholder LILL GE *Owner Name: *Address: BIK 163 Stirting (Indoor / Outdoor) * Tel /H /Other: *Occupation: _ Driver () same as above *Driver Name: *Date of Birth: 05-10-184 *Driving Pass Date: 2014 *Gender, Male / Female *Email: Luyou83 @ marc. Com (Indoor (Outdoor) * Tel /H /Other:_ *Driver an employee: Yes / No (*If no, what is relationship with the policyholder :_ Passengers Details (Male/Female) (Male/Female) * P/Name: * P/Name: (Male/Female) (Male/Female) * P/Name: _ * P/Name: Insurance Company M516 *Coverage: C/TPFT / TPO *Policy No: ___ *Insurer: Detail of other vehicle / Property 2 Detail of other vehicle / Property 1 SKF 6891 Vehicle No.: Vehicle No.: SUZUKI Make & Model: Make & Model: Vehicle Category: Vehicle Category: Name of Driver: Name of Driver: 575037741 NRIC NRIC : HP 91391022 No. of Passengers (Including Driver): No. of Passengers (Including Driver): For Official Use Only *Claiming against Own Ins.: Yes / (If No, Reporting Only / TPCD ms) General Information of the accident

*Type of accident: Head-Rear / Side Swipe / others: *Weather conditions: Clar / Raining / others:		*Any video cam: Yes 🕬
*Road Surface: Ry / Wet / others:		
*Witness: Yes / 🐼 (Name:	NRIC :	HP:

*Injured party: Yes / NO	*No. of passengers (include driver):					
-I/Name:	*Fasten seat belt: Yes / No *Conveyed by Ambulance: Yes / No					
I/Nama	*Fasten seat helt: Yes / No. *Conveyed by Ambulance: Yes / No.					





IDENTITY CARD NO \$8480602A





LU YOU

陆 游

CHINESE 05-10-1984

CHINA

10/10/06/02 3

4889219

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive 23 Oct 2013 of the driver; and other motor vehicles =< 2500kg

NP 478A

26-09-2012 APT BLK 163 STIRLING ROAD #11-1234 SINGAPORE 140163

BIE No. S8480602A

BUSHP

REPUBLIC OF SINGAPORE





/comw

LIU GE

刘 歌 CHINESE

Onto or horm See 05-12-1983 F Country of hirth CHINA

FERRIONAL

OWNER



##E N S8383034D



26-09-2012

APT BLK 163 STIRLING ROAD #11-1234 SINGAPORE 140163



MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807 Tel +65 6827 7888, Fax +65 6827 7800 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1

Individual Ownership

MOTOR MAX Comprehensive

Certificate No. A 29120728 QMX

Excess: SGD500

Windscreen Excess: SGD100

 Index Mark and Registration Number of Vehicle SGL9359K

2. Name of Policyholder

Liu Ge

 Effective Date of the Commencement of Insurance for the purposes of the Act 01/04/2019

4. Date of Expiry of Insurance

01/04/2020

5. Persons or Classes of Persons entitled to drive*

Liu Ge

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer