COMFORTDELGRO ENGINEERING

Our Ref : $\frac{30.5285(60)}{30.5285(60)}$

Date: 08/4/19

Time of Fax : _____

-> AXA

Attn: Motor Claims Dept.

Dear Sirs

vietax: Email

Your Insured : SKA 1955

Date of Acc:

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimílie +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshop

Loyang 59 Loyang Drive Singapore 508969

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHB6688X

1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.

- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore:508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
- ... I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng. Tel no. 62148355 or Hp no. 98240811

Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305

Lim Tien Siong

Tel no. 62148398 or Hp no. 96358546

Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006 Fauzy Bin Mokhtar Tel no: 62148319 or Hp no : 81259176

· Larry Ng ·

Tel: 6214 8316

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

for Vice President

Crash Repairs & Claims Recovery

A member of

COMFORTDELGRO











COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHB 6688X

DATE 8/4/2019 10:43

MAKE MODEL

.

: HYUNDAI SONATA

Like

AXA

Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	Front Bumper Cover			\$ 538.80
	Front Bumper Bracket Top (LH)			\$ 22.40
	Front Bumper Protector (LH)			\$ 29.20
	Headlamp (LH)			\$ 797.90
	Front Fender (LH)			\$ 593.00
	Front Fender Shield (LH)			\$ 86.00
	Front Fender Retainer			\$ 9.20
				·
	SUB TOTAL			\$ 2,076.50
	LESS 20%		ļ	\$ 415.30
	DISCOUNTED TOTAL			\$ 1,661.20
				,
	Labour Charge			
	Panel Beating		1	\$ 400.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 1,100.00
Ì				1,
	ESTIMATE TOTAL			\$ 2,761.20
		1		
	This is an initial estimate based on a visual inspection of the	ie above ve	ehicle. The final renair	quantum will
	be prepared after the vehicle is surveyed by a motor Surve			
	100 properties arter and ventere is surveyed by a motor barve	, or appoin	inca by the insurance co	p

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	06/04/2019 12:19
Date Of Accident	05/04/2019 11:40
Exact Location Of Accident	MAXWELL RD TWDS ANSON RD
Country/State of Loss	SINGAPORE

	Country/State of Loss	SINGAPORE			
		DETAILS OF OWN VEHICLE			
(Vehicle Registration Number	SHB6688X			
	Insured/Policyholder		-		
	Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD			
	Co Reg No	199303821R			
	Email Address	FLEETSAFETY@CDGTAXI.COM.SG			
	Mobile Phone No				
	Alternative Phone No	OFFICE-65508768			
	Vehicle Particulars				
	Manufacturer	HYUNDAI			
	Model	SONATA-2.0 (A)			

Exact Purpose for which vehicle was being used at time of accident

....

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Yehicle Category

TAXI

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number D-18088936MFSH

Cover Note Number

Driver

Name of Driver TAN SOEK HWEE

NRIC No S2596614G
Date Of Birth 12/01/1966
Occupation OUTDOOR
Date Of Driving Pass 16/06/1999

Driving Experience 19 YEARS AND 9 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-91091977

Fax Number

Contact Number

EMail Address JASMINETAN76@HOTMAIL.COM

Address BLK 707 CHOA CHU KANG STREET 53

#08-114

2

NO

NO

2

NO

NO

Postcode 680707

Was driver an employee of the Insured's Company NO

ICM DIEGO II OF DAY AND I AND A OTHE

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

- 4

Passenger 1 NAME:

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Remarks/ Reasons:

Was there any audio recorded?

YES

YES

-

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKA1955C

Vehicle Make/Model/Colour

MAZDA

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver VIJAYAKUMAR VENUGOPALAN

NRIC/Passport Number S7760134A

Contact Number

Address Postcode

Insurance Company Name

Page 2 of 15

Nature Of Damage

Postcode

RH FRONT

No. Of Passenger (Including Driver)

	DETAILS OF INJURED PERSON 1
Name	TAN SOEK HWEE
Approximate Age	
Injuries Sustain	SPRAIN ON NECK, SHOULDER, BACK AND NUMBNESS ON LEFT HAND
Injured person in which vehicle?	SHB6688X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	

Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

) understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTE

CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Loke Wai Yiang

Reporting Centre Personnel's Signature

Name: V

NRIC/FIN No.:

GIARMC SketchPlanForm_V3

4

600

SKETCH PLAN Maxwell-DESCRIBE CIRCUMSTANCES OF THE ACCIDENT at about Wers above with 10 cottin driving at Suddeniv Rido encwachea into ane nand **Vollisian** avoid 8UMA Veh onec Shoulder hand doctor alven bade and numbres on 2 daus **DECLARATION** I/We declare the foregoing particulars are true in every respect. COMFORT TRANSPORTATION PTELTO CO. REG. NO. 199303821R Loke Vvei Yierig Driver's Signature Reporting Centre Personnel's Signature Policyholder's Signature (If driver is not the policyholder) Name: Date & Time:

Date & Time:

GIARMC SketchPlanForm_V3

NRIC/FIN No.: