

INS CASE OWNER

CC 4 / Nov 1900

6138 / Plea 3 / LKK: 609176  
IDAC: 814/2019

Surveyor

DOI: 8/11/19

Date / Time

Registered in Jurisdiction

Pre-assign / CCU / FTE



Insured Vehicle No. : SKA 1955C

Name of Insured : Kaman Mohd

Insured Tel No. : HP: 514/2019

Excess Sec II : SS

Is driver the owner? ( YES (NO) )

If NO, Driver Name / Age:

Driver Tel No. : 514 6688 X

Nature of Accident :

(V/L: YES NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No



INSRS:

WSP: employers

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

Email: 16-04-19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: AMK

Repair Cost: \$5,150

( 3 days)

Reduction:

37 %

Email

Call

FINAL SETTLEMENT

Date/Time: 04-06-19

Confirm with: WILLIAM

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 15

If NO or B 28, Ass. Lia :

Repair Cost:

\$5,182.50

NO CHARGED WARE H11 TP

Loss of Rental (LOR):

\$5,365.65

( 3.5 days ) x = 104.41

Loss of Use (LOU):

\$5 -

( 3 x days)

Loss of Income (LOI):

\$5,115.10

( \$ 50 x 3.5 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☒

[Tick only one]

GIA/LTA Search

\$5,141

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$550

Total:

\$5,240.64

Global Sum SS: 2,430.10

FINAL PAYMENT

Date/Time: 04-06-19

Confirm with: WILLIAM

Email

Call

Payee 1:

\$5,240.64

Name 1:

CONFIDENTIAL ENGINEERS PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

Surveyor: Kalvin

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / INS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB 6688x Yr Regn: 28 Feb, 2013

Type: M. Car / M. Cycle / Bus / Van / Lorry / T / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe cc 1991

Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading: 692647 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/Nr: KMHETKIVADA 833675

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or  Hankook

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 5/4/19 D.O.I. 8/4/19

Survey held at CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1) \_\_\_\_\_

☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

☐ : \_\_\_\_\_ (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S - RS \$ \_\_\_\_\_

Phone:

CD41:

TC1M:


Report Final

Comp. Rep. & Val.

JG NO: 305285100

AXA

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



CKED & PASSED OUT BY:

### SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedgelement Slis

Exit Pass

MS: SHB6688X LKE

Vehicle No.: SHB6688X

If Service Advisor

Signature \_\_\_\_\_ Date \_\_\_\_\_

Name of Service Advisor

Data

Returned to Service Reception upon collection

To be kept by Security Guard

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHB 6688X

DATE 8/4/2019 10:43

MAKE :

MODEL : HYUNDAI SONATA

Like

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓ <i>cut</i>			\$ 538.80
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Protector (LH) ?			\$ 29.20
	Headlamp (LH) ✓			\$ 797.90
	Front Fender (LH) ✓			\$ 593.00
	Front Fender Shield (LH) X			\$ 86.00
	Front Fender Retainer X			\$ 9.20
	<b>SUB TOTAL</b>			<b>\$ 2,076.50</b>
	<b>LESS 20%</b>			<b>\$ 415.30</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,661.20</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			\$ <del>400.00</del>
	Spray Painting Charge			\$ <del>600.00</del>
	Wiring Charge			\$ <del>50.00</del>
	Tuff Kote			\$ <del>50.00</del>
	<b>TOTAL LABOUR</b>			<b>\$ 1,100.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,761.20</b>
<p><i>Kalin 16RM</i></p> <p><i>8/4/19 1415hr</i></p> <p><i>3 Days</i></p> <p><i>4/5</i></p> <p><i>After Repair photo</i></p> <div data-bbox="909 1500 1426 1926"> <p>By _____</p> <p>For _____</p> <p>• To inspect and repair damaged parts</p> <p>• To inspect and repair damaged parts</p> <p>• Part prices are subject to our quotation</p> <p>• Third party survey is on a "Without Prejudice" basis</p> <p>• No illegal modifications is allowed</p> <p>• Supplementary (any) must be resurveyed and is subject to final approval from Insurance Company</p> <p>Authorised by Repairer</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



REPAIR ESTIMATE\*

VEHICLE NO : SHB 6688X

DATE 8/4/2019 10:43

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover — <i>cut</i>			\$ 538.80
	Front Bumper Bracket Top (LH) <i>Xm</i>			\$ 22.40
	Front Bumper Protector (LH) <i>Xm</i>			\$ 29.20
	Headlamp (LH) — <i>housed</i>			\$ 797.90
	Front Fender (LH) — <i>housed</i>			\$ 593.00
	Front Fender Shield (LH) <i>X</i> <i>sm</i>			\$ 86.00
	Front Fender Retainer <i>X</i> <i>sm</i>			\$ 9.20
	<b>SUB TOTAL</b>			<b>\$ 2,076.50</b>
	<b>LESS 20%</b>			<b>\$ 415.30</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,661.20</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			\$ <del>400.00</del>
	Spray Painting Charge			\$ <del>600.00</del> <i>400</i>
	Wiring Charge			\$ <del>50.00</del> <i>20</i>
	Tuff Kote			\$ <del>50.00</del> <i>30</i>
	<b>TOTAL LABOUR</b>			<b>\$ 1,100.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,761.20</b>
<p><i>Kalin 16RM</i></p> <p><i>8/4/19 1415hr</i></p> <p><i>3 Days</i></p> <p><i>4/5</i></p> <p><i>After Repair photo</i></p> <div data-bbox="838 1355 1356 1758" data-label="Text"> <p>             • This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.              • The repair is subject to the insurance policy.              • Parts prices are subject to market price.              • Third party survey is on a "no prejudice" basis.              • No illegal modification(s) is allowed.              • Supplementary work(s) must be reviewed and approved by the insurance company.              Acknowledged by Repairer:              Signature:              Date:           </p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Our Ref : T 0419/ SHB6688X /WT(st)

**Your Ref :**

Date : 23-Apr-19

**AXA Insurance Pte Ltd**  
**8 Shenton Way**  
**#24-01, AXA Tower**  
**Singapore 068811**

Attn : Motor Claims Department

CDGE Taxi Claims Dept  
59 Loyang Drive 4th Flr  
Singapore 508969

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

## Workshops

**Braddell**  
205 Braddell Road  
Singapore 579701

Loyang  
59 Loyang Drive  
Singapore 508989

Sin Ming  
383 Sin Ming Drive  
Singapore 575717

**Pandan**  
45 Pandan Road  
Singapore 609286

Senoko  
24 Senoko Loop  
Singapore 758158

Sungei Kadut  
7 Sungei Kadut Way  
Singapore 728713

**Defu**  
6 Defu Avenue 1  
Singapore 539537

Yishun  
Non Industrial Park A  
Singapore 768722

Dear Sir

WITHOUT PREJUDICE

ACCIDENT INVOLVING OUR TAXI SHB6688X YOUR INSURED SKA1955C  
AND OTHER ON 05.04.19

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor vehicle No : **SHB6688X** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : **SKA1955C**  
we are submitting these claim for your consideration on behalf of the claimants

#### TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 1,872.50
2	<u>4</u> days Loss of Rental @ <u>\$ 104.47</u> per day	\$ 417.88
3	Survey Report Fees <i>(Surveyed by M/s LKK)</i>	\$ -
4	GIA / LTA Search Fee	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing Fees	\$ -
	<b>Sub Total :</b>	<b>\$ 2,297.87</b>

### HIRER'S CLAIM

7	<u>4</u>	days Loss of Income @	<u>\$ 80.00</u>	per days	<u>\$ 320.00</u>
<b>Total Claims:</b>					<b>\$ 2,617.87</b>

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs 7 pcs
- b) LTA search slip/s of: SKA1955C
- c) GIA / Police report/s of: SHB6688X
- d) Letter of authority from owner / hirer / operator

( X ) Photocopies of Accident Scene Photo/s      ( ) Towing receipts  
( ) Witness statement/s    ( x ) Rental Rate letter    ( x ) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: [williamtan@cdge.com.sg](mailto:williamtan@cdge.com.sg)

This is a computer generated letter. No signature is required.

**Asher Sng (LKKAUTO)**

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Tuesday, 16 April 2019 12:09 PM  
**To:** "Vijay Venugopalan"  
**Subject:** ACCIDENT INVOLVING SKA 1955C AND SHB 6688X ALONG SHENTON WAY TWDS ROBINSON ON 05/04/2019

16 APRIL 2019

**INDU KANNAN / VIJAYAKUMAR VENUGOPALAN**

Dear Sir/ Mdm

**OUR REF : CC4/ASM19006138/K1ea3**

**YOUR REF : SKA 1955C**

**ACCIDENT INVOLVING SKA 1955C AND SHB 6688X ALONG SHENTON WAY TWDS ROBINSON ON 05/04/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s COMFORTDELGRO ENGINEERING PTE LTD acting on behalf of the owner of SHB 6688X against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle filter into Third party lane and collided with Third Party vehicle SHB 6688X. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.



Your full co-operation in the handling of the claim is required and kindly submit the following to [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher

*Case Handler*

DID: 6841 6051

FAX: 6741 4108

Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)

*(Motor Claims Dept)*

## LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING  
ALONGSONATA SHB6688X , SKA1955C  
MAXWELL RD TWDS ANSON RD

ON 05-Apr-19 11:40

I / We

NG JIT KWAN EDMUND

(Hirer) NRIC No.: S7713594D

and/or

TAN SOEK HWEE

(Relief) NRIC No.: S2596614G

Taxi Number

SHB6688X

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

06-Apr-2019

Name of Hirer

NG JIT KWAN EDMUND

Hirer NRIC

S7713594D

Signature :



Address

812A CHOA CHU KANG AVENUE 7 #...  
681812

Contact No.

92783825

Name of Relief

TAN SOEK HWEE

Relief NRIC

S2596614G

Signature :



Address

707 CHOA CHU KANG STREET 53 08-114  
680707

Contact No.

91091977



## AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SKA 1955C	(Insd veh)	Model: HYUNDAI SONATA - 2.0 (A)
	SHB 6688X	(TP veh)	
Date of Accident/ Time:	05/04/2019 / 11:40		

Repair Estimate	S	2,754.48	
Final Repair Cost	S		
Loss of Use	S		days at \$ per day
Rental (if any)	S		days at \$ per day
LTA / GIA Search Fee	S		
Others	S		
Final Settlement Sum	S	2,420.00	Global Sum (All In)
Payee Name : COMFORTDELGRO ENGINEERING PTE LTD			
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)	
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ <del>No</del> BOLA Scenario No: 15	
	BOLA Liability: 100 (%)	Assessed Liability (*) _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

## NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp  
Name of Representative:  
Date:

Signature of Witness / Workshop stamp (if applicable)  
Name of Witness:  
Date: 15-5-19

Signature of AXA's surveyor/representative:  
Name of AXA's surveyor/Representative:  
Date: 13/6/2019

Please forward your cheque made payable to:  
COMFORTDELGRO ENGINEERING PTE LTD

The contents of this document apply to vehicle damages only  
All personal injuries and damages arising therefrom are excluded  
from the ambit and application of this document\*

Our Ref: CT19040153



Date: 17 April 2019

## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	05/04/2019 @ 11:40 hrs
ALONG	MAXWELL RD TWDS ANSON RD
INVOLVING	SKA1955C

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHB6688X** (the "Taxi"). The Taxi was hired to **NG JIT KWAN EDMUND IC NO S7713594D** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$104.47** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

[illegible]

## Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SKA1955C	05 Apr 2019 / 11:40:00	Successful	A12	AXA INSURANCE PTE LTD

[Previous](#)[OK](#)

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKA 1955C (Insd veh)	Model:	HYUNDAI SONATA
	SHB 6688X (TP veh)		
Date of Accident:	05/04/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$		2,954.48
Final Repair Cost	:	\$		1,872.50
Loss of Token Sum	:	\$		175.00
				3.5 days at \$50.00 per day
Rental (if any)	:	\$		365.65
				3.5 days
LTA / GIA Search Fee	:	\$		7.49

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum (Global Sum)	:	\$	2,420.00

Is Third Party Workshop GIA Registered?	[ X ]	YES	[ ]	NO	(Kindly indicate below)
<b>A) For Non GIA Registered Workshop:</b> Agreed Liability _____ (%)					
<b>B) For GIA Registered Workshop:</b> BOLA Applicable: Yes/ No BOLA Scenario No: _____					
BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)					
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	COMFORTDELGRO ENGINEERING PTE LTD	:	\$ 2,420.00

JOANNE LEE KHANG MIN  
 LKK Auto Consultants Pte Ltd

20/06/2019  
 Date

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19006138/K1ea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY		Date : 20-06-2019	
		Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKA 1955C	Veh. Inspected	SHB 6688X
Policy No.	GA436100	Coverage (\$)	0.00
Claim No.	S9M01JGQ	Excess (\$)	0.00
Assign From		Assign Date	08/04/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KMHET41VMDA833635	Colour	BLUE
Odometer	692647	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	HANKOOK	6 mm
L/H Front Tyre	215/60 R16	HANKOOK	6 mm
R/H Rear Tyre	215/60 R16	HANKOOK	6 mm
L/H Rear Tyre	215/60 R16	HANKOOK	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS			
<b>5. General Information</b>			
Accident Date	05/04/2019	Inspection Date	08/04/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6688X**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER COVER (CONSISTENT)	CUT	538.80	538.80
1	FRONT BUMPER BRACKET TOP (LH) (CONSISTENT)	SERVICEABLE	22.40	-
1	FRONT BUMPER PROTECTOR (LH) (CONSISTENT)	SERVICEABLE	29.20	-
1	HEADLAMP (LH) (CONSISTENT)	GRAZED	797.90	797.90
1	FRONT FENDER (LH) (CONSISTENT)	BUCKLED	593.00	593.00
1	FRONT FENDER SHIELD (LH) (CONSISTENT)	SERVICEABLE	86.00	-
1	FRONT FENDER RETAINER (CONSISTENT)	SERVICEABLE	9.20	-
	LESS 20% DISCOUNT		-415.30	-385.94
			1,661.20	1,543.76
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		400.00	200.00
	SPRAY PAINTING CHARGE.		600.00	400.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	30.00
			1,100.00	650.00
	<b>GRAND TOTAL</b>		<b>2,761.20</b>	<b>2,193.76</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,750.00</b>

Report Ref No. CC4/ASM19006138/K1ea3q2

**KALVIN ANG WEI KUN**

Automotive Assessor / Investigator

**HO LEONG CHUAN**


Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## Service Request Details

Claim	SYN4013CQ	Actions	
Reference	CC4/ADM19006136/K1na3q2 	Next Step	Wait for: Approve Invoice
Loss Date	5 April 2019		<div>Add Evidence</div>
Report Date	8 Apr 2019 4:24:05 PM		

Vehicle Information	
Incident Vehicle Registration #	SHB668BX
Make	TPVD HYUNDAI
Model	SONATA 2.0 I/A
Service Address	
...	
Primary Contact/Insured	
INDU KANNAN BLOCK 32, TANAH MERAH KECHIL ROAD, 02-20, 465559, Singapore	
PEIHUAMBPI@GMAIL.COM	
Claim Handler	
NG Stacey 6568804351 stacey.ng@aia.com.sg	















Additional Instructions  
INSURED NOT REPORTED

Messages	Indices	History	Documents	Assessment	Metrics	Notes
----------	---------	---------	-----------	------------	---------	-------

Document Type	Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Merimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 RENTAL_RECEIPT.pdf	Forms / Claim Documents	Others	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 RENTAL_MILEAGE.pdf	Forms / Claim Documents	Others	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 PAYMENT_BREAKDOWN_LK1.pdf	Forms / Claim Documents	Others	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 LTA_SEARCH.pdf	Forms / Claim Documents	Others	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 LK1inspection.pdf	Forms / Claim Documents	Others	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 LK1Adjustment1a.pdf	Forms / Claim Documents	Others	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 PAYMENT_BREAKDOWN_EXPRESS_SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 AUTHORISATION TO ACT /FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 WORKSHOP_INVOICE.pdf	Invoice	Repairer	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 LETTER TO Q1.pdf	Letters and Correspondence	Policy Holders / Insured	LK AUTO CONSULTANTS PTE LTD (TP)	25 June 2019
 TP_ESTIMATE - MAIBED.pdf	Reports & Statement	Estimate / Quotation	LK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 IA1.pdf	Forms / Claim Documents	Assessment	LK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019
 LK1 SURVEY PHOTO.pdf	Forms / Claim Documents	Assessment	LK AUTO CONSULTANTS PTE LTD (TP)	16 April 2019

