

25/03/2019

ASS. REC. BY:

REF:

CS3 III 19006140 / Tied 307

Special Instruction:

Surveyor: Tau 8KH

ASSIGNMENT (Office)

From (Person): Munmen Gabriel Nee

of

III

Date/Time:

4/4/2019 @ 10:45am

Estimated Cost:

Bill to:

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC1665U

Insured:

SHD 6713X

at Workshop m/s

Auto Gear

Tel:

94599091

of

23 Kelci Bulkit Rd 4 # 01-22

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/03/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:43pm @ 4/4/19

Person Contacted:

Pierre

Vehicle IN /

OUT

Date/Time	Action/Instruction (X) Estimate Insp: w. Hotel way @ 21 ocean way
	PC1665U - CC3/BEI 1602 3347 / H1 hb392
	SHD 6713X - CC4 / III 19003848 / U1b3
	12.4.19 - VNI - Pierre
	Dismantle: 22/4/2019 03:53pm
	After repair: 24/4/2019 03:03am

DOA: 3/12/2016

DOA: 17/2/2019

Garage

Taufhi

REF: II

ASSIGNMENT

From: Date: 22.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC1665 U

at Workshop m/s Auto Gear

of 23 Kati Bukit Road 4 #01-22

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"wp" PRB

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

PC1665 U

Yr Regn: Dec / 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi

C.C

4899

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

BE63DJF10055

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim or

Tyre Size:

F:

7.00 RLL

R:

7.00

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Condor

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

22/4/19 @ 3pm

Survey held at

Auto Gear

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No Key
	\$2000 - \$3000, 3 days
	Range + Days
	25/4/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

)

TOTAL

Report Format :

PRB

Lump Sum / I.B.I. (\$

120

10

130

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 4 April 2019 10:45 AM
To: Kuru & Co; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: Our Ref: L.19.0419.at//Your Ref: SHD 6713X//PRS
Attachments: img-403163708.pdf; AG.PDF

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : PC1665U
III INSURED VEHICLE NO. : SHD6713X
DATE OF LOSS : 27.03.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Sundari.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: 04 April, 2019 10:26 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Our Ref: L.19.0419.at//Your Ref: SHD 6713X//PRS

Hi Gabriel

Our client is objecting to your list of surveyors. Attached is our client's list of proposed surveyors for your consideration.

Please state the surveyor you will be appointing to be the single joint expert or that you are objecting to our client's proposed list of surveyors.

If we do not hear from you within 2 working days, it shall be deemed that you have agreed to the appointment of any of the surveyors listed by our client.

Best regards
Anne

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

On Thursday, 4 April 2019, 9:22:02 am SGT, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: 03 April, 2019 5:34 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Our Ref: L.19.0419.at//Your Ref: SHD 6713X//PRS

Dear Sirs

ACCIDENT INVOLVING PC 1665U & SHD 6713X ON 27.03.2019
ALONG BLANGAH ROAD NEAR HARBOURFRONT MRT
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **EZ Buzz Pte Ltd**, whose vehicle registration number **PC 1665U** was damaged in the above accident.

A copy of the Accident report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Anne

Kuruj & Co

150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 4 April 2019 1:36 PM
To: 'sur@lkkauto.com'; Admin-D (LKKAuto)
Subject: FW: Our Ref: L.19.0419.at//Your Ref: SHD 6713X//PRS

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: 04 April, 2019 10:57 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Our Ref: L.19.0419.at//Your Ref: SHD 6713X//PRS

Hi Gabriel

We confirm that you have objected to our client's list of surveyors. Our client's vehicle is at the following address:

AUTO GEAR PTE LTD

23 Kaki Bukit Rd 4

**# #01-22 Synergy @ KB
Singapore 417801**

Tel: Pierre Tok/ 94599091

Please inform your surveyor to conduct the pre-repair survey within 2 working days, failing which our client will have no alternative but to proceed with the repair of his vehicle.

Best regards

Anne

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

On Thursday, 4 April 2019, 10:45:45 am SGT, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : PC1665U

> [Back to OneMotoring](#)

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	PC1665U		
Vehicle Type :	Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus		
Vehicle Attachment 1 :	Air-Conditioned		
Vehicle Scheme :	Public Service Vehicle (Others)		
Vehicle Make :	MITSUBISHI		
Vehicle Model :	ROSA 4.9L MT 2WD 6T TURBO 4DR 24 SEATER		
Chassis No. :	BE63DJF10055		
Propellant :	Diesel		
Engine No. :	4M50D67882		
Engine Capacity :	4899 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	6020 kg		
Unladen Weight :	4120 kg		
Year Of Manufacture :	2011		
Original Registration Date :	03 Dec 2012		
Lifespan Expiry Date :	02 Dec 2032		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$60,235.00		
COE Expiry Date :	02 Dec 2022		
Road Tax Expiry Date :	02 Jun 2019		
Inspection Due Date :	02 Dec 2019		
Intended Transfer Date :	02 May 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 02 Jun 2019. You may renew the road tax from 03 Mar 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 02 Jun 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 03 Jun 2019 to 02 Dec 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	110.00	-	110.00
Total Amount Payable :			135.00
Amount Payable (From 03 Jun 2019 to 02 Jun 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	356.00	-	356.00
Total Amount Payable :			381.00
Message			
This vehicle has a road tax Over Payment of \$84.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7597D
Vehicle Details	
Vehicle No.:	PC1665U
Vehicle to be Exported:	No
Intended Deregistration Date:	02 May 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	ROSA 4.9L MT 2WD 6T TURBO 4DR 24 SEATER
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	4M50D67882
Chassis No.:	BE63DJF10055
Maximum Power Output:	-
Open Market Value:	\$88,086.00
Original Registration Date:	03 Dec 2012
First Registration Date:	03 Dec 2012
Transfer Count:	0
Actual ARF Paid:	\$4,405.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Dec 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$60,235.00
COE Rebate Amount:	\$21,584.00
Total Rebate Amount:	\$21,584.00

The information contained herein is correct as at 02 May 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI
































CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 May 2019 11:16 Edit Reg		04 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	PC1665U	Date of Loss:	27/03/2019 00:00 - :59 [75 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHD6713X	Policy No. (Claimant):							
		Excess:							
Repairer:	Auto Gear Pte Ltd (HQ) 23 KAKI BUKIT ROAD 4 #01-22 SYNERGY@KB, 400325 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC1665U
[SHD6713X]
TP
-
Mar 27 2019 12:00AM
[-]
Auto Gear Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View In Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
2	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
3	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
4	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
5	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
6	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
7	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
8	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
9	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
10	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
11	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
12	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
13	26/04/19 14:47	General View						 Load JPG	<input checked="" type="checkbox"/>	
14	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
15	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
16	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
17	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
18	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
19	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
20	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
21	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
22	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
23	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
24	26/04/19 14:47	Photographs of Damaged Parts						 Load JPG	<input checked="" type="checkbox"/>	
25	26/04/19 14:48	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
26	26/04/19 14:48	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
27	26/04/19 14:48	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
28	26/04/19 14:48	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
29	26/04/19 14:48	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
30	26/04/19 14:48	Photo After Spray						 Load JPG	<input checked="" type="checkbox"/>	
Documentation								1 per page		<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)						Thumbnail	Print	
1	09/04/19 09:19	Singapore Accident Statement						 Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19006140/T1CD3E2

Date: 14/05/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No: PC1665U

Insured Vehicle No: SHD6713X

Date of Loss: 27/03/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC1665U

Make & Model: MITSUBISHI ROSA, 4.9 D L MT (M)

Engine No: 4M50D67882

Reg. Date: 03/12/2012 (Man. Year: 2011)

Chassis No: BE63DJF10055

Colour: White

Odometer: 0 km

Engine Capacity: 4899 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16

Rear Tyre Size: 7.00 R16

Front Left Side: Condor 6 mm

Rear Left Side: Condor 6 mm

Front Right Side: Condor 6 mm

Rear Right Side: Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/04/2019

Date Inspected: 22/04/2019 Inspected At:

Auto Gear Pte Ltd (HQ)
23 KAKI BUKIT ROAD 4 #01-22
SYNERGY@KB
Singapore 400325

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 May 2019)

Parts: N/A MITSUBISHI ROSA 4.9 D L MT (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC1665U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >