




SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/04/2019

User ID : GohKK2

Section A - Accident Details		
Registration Number	SG6073M	
Case Reference Number	BUS/04/19/7002	
Registration Date	14/1/2019	
Company Type	SMRT Buses Ltd	
Make	MAN	
Model	A95	
Name of Driver	V Theagarajan	
Type of Accident	Side Swipe	
Accident Date and Time	3/4/2019 8:35 AM	
Accident Reported Date and Time	4/4/2019 3:34 PM	
Is Surveyor Required?	No	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time		
Replacement Vehicle issued?	No	
Job Card Number		
Special Instruction to ARC, if any	SG6073M - RIGHT FRONT PORTION XB6260G (TP) - INSURED WITH CHINA TAIPING	
Prepared Date and Time	5/4/2019 11:10 AM	
Chassis Number	WMAA95ZZ3KF008640	
Mileage		
Work Shop		
Repair Completion Date and Time		

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$728.00	\$0.00
Total Spare Part Cost	\$3,123.51	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,971.51	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	05/04/2019 11:28 AM	
Signature		<input type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/04/2019

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00 1590	
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$728.00 616	
Total Spray Painting & Panel Beating	\$728.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
124-4-2-001-025			DRIVER WINDOW	1.00	\$1,579.00	10.00	\$1,421.10	Replace	
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	
4006314			SEALANT SIKAFLEX	6.00	\$37.00	0.00	\$222.00	Replace	
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	
6010161	BODY RH	4001M01-ACCE467	MIRROR VIEW: FRONT, R H, FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	
Total					\$3,220.90		\$3,123.51		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Hwee Jie - lkk

5/4/19

P/P 4 days