



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63665592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2019

User ID : CatherineLee

Cecilia

P/P \$5329.51 / 4 days.

Section A - Accident Details	
Registration Number	SG6073M
Case Reference Number	BUS/04/19/7002
Registration Date	14/1/2019
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	V Theagarajan
Type of Accident	Side Swipe
Accident Date and Time	3/4/2019 8:35 AM
Accident Reported Date and Time	4/4/2019 3:34 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100920
Special Instruction to ARC, if any	SG6073M - RIGHT FRONT PORTION XB6260G (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	5/4/2019 11:10 AM
Chassis Number	WMAA95ZZ3KF008640
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,590.00
Total Spray Cost	\$728.00	\$616.00
Total Spare Part Cost	\$3,123.51	\$3,123.51
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,971.51	\$5,329.51
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Kok Khoo Goh	Hwee Jie
ARC / Surveyor Sign Off Date	05/04/2019 11:28 AM	05/04/2019 2:26 PM
Signature	<i>[Signature]</i>	<i>[Signature]</i>
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$2,120.00	\$1,590.00
Total Labour	\$2,120.00	\$1,590.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$728.00	\$616.00
Total Spray Painting & Panel Beating	\$728.00	\$616.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		124-4-2-001-025	DRIVER WINDOW	1.00	\$1,579.00	10.00	\$1,421.10	Replace	Replace <i>CRA</i>
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace <i>nel</i>
4006314			SEALANT SIKAFLEX	6.00	\$37.00	0.00	\$222.00	Replace	Replace <i>nel</i>
4006313	CONSUMABLE	SIKA8 Primer-208 G+P	PRIMER (SIKA 208 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace <i>nel</i>
8010161	BODY RH	4001M01-ACCE487	MIRROR, VIEW, FRONT, R H, FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	Replace <i>CRA</i>
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	Replace <i>nel</i>
Total					\$3,220.90		\$3,123.51		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: