

CS/AG19006156/Kvd3n2  
ASSIGNMENT (Office)  
Kenneth  
Hor, Yinnul  
of AG  
Date/Time: 5/4/19 @ 4:32pm

Estimated Cost: Bill to:  
OD: TP/WSTP RES / OD RES / EVA / INV / MV7CS  
To Inspect Vehicle No: SFT 8199G Insured: SFT 2187J  
at Workshop n/a: Chuen Motor Tel: 6453 6111  
of: 176 Sin Ming Drive #02-03  
Policy No: Claim No: 1302474942 SG  
Sum Insured: Excess:  
Make of Veh: D.O.A. 03/04/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS  
Date/Time: 1:40pm @ 8/4/19 Person Contacted: Ah Heng Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	D.O.A.
	SFT 8199G - CS3 / NK11014343 / Avc1-1	19/07/2011
	SFT 2187J - X	

18/4/19	6/1/19 @ 6:30pm email confirmed with Ah Heng (Ref 5759.20, 488)
---------	---

ASS. REC. BY:

REF:

AIG-1

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: £20k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SFT 8199G Yr Regn: 08, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Proton Exora c.c. 1597Colour: White A/C: Insured / Std / NI / NASp. Reading 342481 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: PL11786YRRBF041899Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: 205/55ZR16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal. 3 mmR/Bal. 4 mmL/Bal. 3 mmL/Bal. 4 mmD.O.A. 3/4/19D.O.I. 8/4/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ File pass to  
To/you jamm

RECEIVED 2-2 APR 2019

Date/Time, File Pass to?

☐ : Prell. ReportDays Of Repair: 7

1)

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2) 22/4 - typistAdd Fee: ☐ : Site Insp (\$

Transportation:

250

S + R.S. \$

10

Fees

Others

Report Format:

merimen

Lump Sum / I.B.I. (\$

6300☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

TOTAL

260

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Apr 2019 <a href="#">Edit Reg</a>		08 Apr 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	WINN PAUL TIN MOUNG MOUNG @PAUL MOUNG, ID: S26495671		
Main Claimant:	MUHAMMAD JAMIL BIN HAMDAN, ID: S7622039E		
Vehicle Reg. No.:	SFT8199G	Date of Loss:	03/04/2019 00:00 - :59
Claim Type:	TP / 1302474942SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLT2187J	Policy No. (Claimant):	
		Excess:	
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/04/2019]		
Claimant's Solicitor:	CK TEO & CO - Tel: 65354788		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG\_SG (09/04/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION REQUEST – SFT8199G vs SLT2187J (OI) on D.O.A.: 03/04/2019

From: Hor, Yinnul  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur  
Sent: 5/4/2019 4:32:17 PM  
Attachments:  tmp1A26.tif  tmp1A26.tif

Hi,

Please refer to the enclosed request from CK TEO & CO.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **KENNETH KONG** as Single Joint Expert as requested.

Thanks & Regards,

Yin Rul, Hor (Viviano)  
AIG  
Claim Adjuster II, Singapore FNQL, Claims Operations – Auto  
Shared Services – Malaysia | Global Business Services

[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Willow Tuang [mailto:wtuang@gmail.com]  
**Sent:** Friday, April 05, 2019 4:26 PM  
**To:** Hor, Yinnul  
**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT2187J AND SFT8199G ON 03/04/2019

Caution: External Email

Dear Sir

We refer to your email of even date.

We are agreeable of appointing KENNETH KONG (LKK AUTO CONSULTANTS PTE LTD) as a Single Joint Expert.

Our client's vehicle is available for pre-repair survey at:

Venue	:	Guan Motor Works 176 Sin Ming Drive #02-03 Sin Ming AutoCare Singapore 575721 Tel: 6453 6111 (AH HENG)
-------	---	--

Error! Filename not specified.Regards

Tuang Willow  
CK TEO & CO  
Tel: 65354788  
Fax: 65354245

On Fri, Apr 5, 2019 at 4:04 PM Hor, Yinnul <[Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com)> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านไฟล์โปรดคลิกที่นี่

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-04-12 16:04 +08 to read your message.  
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul Hor@aig.com  
To: wtuang@gmail.com  
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baijt Kaur@aig.com, NoorMariesa AbuKassim@aig.com, Syazairdina Azlan@aig.com, yokeshi.chan@aig.com, ShengYang Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com  
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLT2187J AND SFT8199G ON 03/04/2019  
Date: Fri, 5 Apr 2019 08:04:41 +0000  
Without Prejudice

Your Reference : SFT8199G  
Our Reference : SLT2187J

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Ruli, Hor (Viviane)  
AIG  
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
Shared Services – Malaysia | Global Business Services

Yinrul Hor@aig.com | www.aig.sg

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2039E
<b>Vehicle Details</b>	
Vehicle No.:	SFT8199G
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Apr 2019
Vehicle Make:	PROTON
Vehicle Model:	EXORA 1.6L AT (M-LINE) ABS D/AB 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	S4PHQQ4256
Chassis No.:	PL1FZ6YRRBF041899
Maximum Power Output:	93.0 kW (124 bhp)
Open Market Value:	\$14,124.00
Original Registration Date:	02 Aug 2010
First Registration Date:	02 Aug 2010
Transfer Count:	1
Actual ARF Paid:	\$14,124.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Aug 2020
PARF Rebate Amount:	\$7,768.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	01 Aug 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$31,510.00
COE Rebate Amount:	\$4,057.00
<b>Total Rebate Amount:</b>	<b>\$11,825.00</b>

The information contained herein is correct as at 18 Apr 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/04/2019 12:53
Date Of Accident	03/04/2019 10:00
Exact Location Of Accident	PASIR PANJANG ROAD & JALAN PELEPAH
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFT8199G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MUHAMMAD JAMIL BIN HAMDAN
NRIC No	S7622039E
Email Address	CT.JEMZ@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96819375
Alternative Phone No	OTHERS-96819375

### Vehicle Particulars

Manufacturer	PROTON
Model	EXORA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	19-MU001193-R02
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD JAMIL BIN HAMDAN
NRIC No	S7622039E
Date Of Birth	23/07/1976
Occupation	INDOOR
Date Of Driving Pass	18/03/2002
Driving Experience	17 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96819375
Fax Number	
Contact Number	OTHERS-96819375
Email Address	CT.JEMZ@GMAIL.COM

Address	BLK 809 TAMPINES AVE 4 #04-165 SINGAPORE
Postcode	520809
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT2187J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WINN PAUL TIN MOUNG MOUNG @ PAUL MOUNG
NRIC/Passport Number	S2649567I
Contact Number	98166808
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMA4923B
-----------------------------	----------



Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

KANG KIAN SIN (JIANG JIANXIN)

NRIC/Passport Number

S7143048J

Contact Number

91835796

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name

MUHAMMAD JAMIL BIN HAMDAN

Approximate Age

Injuries Sustain

NECK & BACK PAIN

Injured person in which vehicle?

SFT8199G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time: 3/4/2018 12:00 PM

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 3/4/2018 12:00 PM

Reporting Centre Personnel's Signature  
Name: [Signature]  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



A - SET 8199G  
I - SET 2877  
2 - SPWA 4623R

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At about 10:45am on 3/4/19, while I was driving SET 8199G along Pasir Panjang Road by the Pagar on lane 1, vehicle number SET 2877 hit my car from multiple impact. It takes a while for me to get out from my car because of the hard impact and shocked. Some time from my car I noticed it was a chain collision involving 3 vehicles (As shown in the sketch plan). Eventually, police and ambulance came and the police call made by the driver of SET 2877.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 3/4/19 11:30am

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 3/4/19 11:30am

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorized  
L1 Reg B 300f  
Resony After Paint  
7 days

**REPAIR ESTIMATE FOR SFT8199G**

No.	Qty	List Items			
1	1	Rear bumper	612.00	\$ Bu	660.00 —
2	2	Rear bumper reflector		\$ Sn	70.00 X
3	1	Rear bumper tow cover		\$ Sn	45.00 X
4	1 set	Rear bumper clips		\$ ne	30.00 —
5	2	Rear bumper side retainer		\$ cm	134.00 —
6	1	Rear bumper inner reinforcement	385.00	\$ B	450.00 —
7	2	Rear bumper inner reinforcement bracket		\$ nif	130.00 X
8	1	Rear tailgate		\$ B	1,350.00 —
9	1	Rear tailgate centre "PROTON" logo		\$ ne	66.00 —
10	1	Rear tailgate "EXORA" emblem		\$ ne	45.00 —
11	1	Rear tailgate outer handle/garnish		\$ Sn	280.00 X
12	1	Rear tailgate inner trim board	285.00	\$ cm	380.00 —
13	1 set	Rear tailgate inner trim board clips		\$ ne	60.00 —
14	1	Rear tailgate top lock		\$ Tn	260.00 —
15	1	Rear tailgate lower lock catch		\$ n	45.00 X
16	1	Rear tailgate weatherstrip		\$ cm	138.00 — 800sn
17	2	Rear fender under shield		\$ cm	600.00 —
18	1 set	Rear fender under shield clips		\$ ne	40.00 —
19	1	Rear end panel		\$ B	520.00 —
20	1	Rear end panel top garnish		\$ mgat	165.00 —
21	1	Rear lower axle beam		\$ Sn	1,550.00 X
22	1	Rear lower exhaust silencer		\$ B	620.00 —
				\$	7,638.00
			Less 10%	\$	763.80
			Total :	\$	6,874.20

**Special Nett Items**

23	1	Rear bumper lower skirting		\$ cm	1,250.00 — 800sn
24	1	Rear number plate		\$ Sn	45.00 X
25	1 set	Rear windscreen sealant		\$ ne	50.00 — 40sn
26	1 set	Rear end panel sealant		\$ ne	50.00 — 30sn
27	1 set	Reverse sensors		\$ shat	250.00 — 200sn
			Total :	\$	1,645.00

**Labour**

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,300.00	800f
2	To putty and spray Spray Paintings charges.	\$	1,500.00	1000f
3	To remove, refix rear windscreen glass.	\$	140.00	120f
4	To check wirings and lightings.	\$	40.00	20f
5	To remove, refix reverse sensors.	\$	80.00	50f
6	To remove, refit rear tailgate fittings.	\$	80.00	60f
7	To remove, refix rear lower axle beam	\$	240.00	X

- 8 To remove, refit rear exhaust silencer.  
9 To supply and apply anti rust treatment

\$	80.00	X
\$	80.00	606
Total :	\$ 3,540.00	

**Total Parts and Labour : \$ 12,059.20**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair work to be done without
- Repairer must acknowledge resurvey and is subject to the instructions from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19006156/KVD3N2

Date: 03/05/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
 Claimant Vehicle No: SFT8199G Insured Vehicle No: SLT2187J  
 Date of Loss: 03/04/2019 Nature of Claim: TP Claim No: 1302474942SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFT8199G  
 Make & Model: PROTON EXORA, 1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A) Engine No: S4PHQQ4256  
 Reg. Date: 02/08/2010 (Man. Year: 2010) Chassis No: PL1FZ6YRRBF041899  
 Colour: White Odometer: 342481 km  
 Engine Capacity: 1597 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 205/55ZR16 Rear Tyre Size: 205/55ZR16  
 Front Left Side: Kumho 3 mm Rear Left Side: Kumho 4 mm  
 Front Right Side: Kumho 3 mm Rear Right Side: Kumho 4 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,519.20	5,893.80	2,625.40	30.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	2,110.00	1,430.00	40.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>12,059.20</b>	<b>8,003.80</b>	<b>4,055.40</b>	<b>33.63</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,300.00</b>		
<b>Nett Amount (\$\$)</b>	<b>12,059.20</b>	<b>6,300.00</b>	<b>5,759.20</b>	<b>47.76</b>

## INSPECTION

Date of Assignment: 05/04/2019  
 Date Inspected: 08/04/2019 Inspected At: Guan Motor Works (HQ)  
 176 Sin Ming Drive #02-03 Sin Ming  
 Autocare  
 Singapore 575721

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Buckled	660.00 FL	*612.00 FL
2	2	*REAR BUMPER REFLECTOR	Serviceable	70.00 FL	*- FL
3	1	*REAR BUMPER TOW COVER	Serviceable	45.00 FL	*- FL
4	1	*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
5	2	*REAR BUMPER SIDE RETAINER	Cracked	134.00 FL	*134.00 FL
6	1	*REAR BUMPER INNER REINFORCEMENT	Bent	450.00 FL	*385.00 FL
7	2	*REAR BUMPER INNER REINFORCEMENT BRACKET	No such part	130.00 FL	*- FL
8	1	*REAR TAILGATE	Bent	1,350.00 FL	*1,350.00 FL
9	1	*REAR TAILGATE CENTRE PROTON LOGO	Necessary	66.00 FL	*66.00 FL
10	1	*REAR TAILGATE EXORA EMBLEM	Necessary	45.00 FL	*45.00 FL
11	1	*REAR TAILGATE OUTER HANDLE/GARNISH	Serviceable	280.00 FL	*- FL
12	1	*REAR TAILGATE INNER TRIM BOARD	Cracked	380.00 FL	*285.00 FL
13	1	*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FL	*60.00 FL
14	1	*REAR TAILGATE TOP LOCK	Jammed	260.00 FL	*260.00 FL
15	1	*REAR TAILGATE LOWER LOCK CATCH	Repair	45.00 FL	*- FL
16	2	*REAR FENDER UNDER SHIELD	Cracked	600.00 FL	*600.00 FL
17	1	*SET REAR FENDER UNDER SHIELD CLIPS	Necessary	40.00 FL	*40.00 FL
18	1	*REAR END PANEL	Bent	520.00 FL	*520.00 FL
19	1	*REAR END PANEL TOP GARNISH	Mtg Cracked	165.00 FL	*165.00 FL
20	1	*REAR LOWER AXLE BEAM	Serviceable	1,550.00 FL	*- FL
21	1	*REAR LOWER EXHAUST SILENCER	Bent	620.00 FL	*620.00 FL
22	1	*REAR TAILGATE WEATHERSTRIP (50%)	Cut	124.20 FS	*69.00 FS
23	1	*REAR BUMPER LOWER SKIRTING	Cracked	1,250.00 FS	*900.00 FS
24	1	*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
25	1	*SET REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
26	1	*SET REAR END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS
27	1	*SET REVERSE SENSORS	Shorted	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>9,269.20</b>	<b>6,411.00</b>
- List Item Discount on L Items 10.00/10.00% (S\$)	750.00	517.20
<b>Total Parts (S\$)</b>	<b>8,519.20</b>	<b>5,893.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES FOR REMOVE/REFIT,PANEL BEATING,CUTTING WELDING AND REPLACEMENT OF DAMAGES	New	1,300.00	800.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	1,500.00	1,000.00
3	TO REMOVE,REFIX REAR WINDSCREEN GLASS	New	140.00	120.00
4	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
5	TO REMOVE,REFIX REVERSE SENSORS	New	80.00	50.00
6	TO REMOVE,REFIX REAR LOWER AXLE BEAM	New	240.00	0.00
7	TO REMOVE,REFIT REAR TAILGATE FITTINGS	New	80.00	60.00
8	TO REMOVE,REFIT REAR EXHAUST SILENCER	New	80.00	0.00
9	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,540.00</b>	<b>2,110.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;