

INS. CASE OWNER:

CC 3, CT 1900 6158, K1ea3

IDAC:

Surveyor:

Ank

DOI:

ASSIGNMENT

51419


Date / Time:

51419

Registered in Merimen:

Pre-assign / CCU / FTE

SPW 629K



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 41419

Place of Accident:

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final ? Yes / No

5140 6818 C



INSRS:

WSP:

Tel:

Liability:

RMKS:

cont/5419



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	☐ ☐
After call ltr to OI:	☐ ☐
Authorisation To Act:	☐ ☐
Release Voucher:	☐ ☐
Final Repair Bill:	☐ ☐
Car Rental Invoice:	☐ ☐
Towing Invoice:	☐ ☐
LTA / GIA :	☐ ☐
Medical Bill:	☐ ☐
PIR:	☐ ☐
Mandate/Reject Instruction:	☐ ☐
LOD	☐ ☐
Payment Breakdown Form:	☐ ☐
Post-Repair Photos:	☐ ☐
Others:	☐ ☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305284524

CUSTOMER

COMFORT TRANSPORTATION PTE LTD
7010045

MS

CUSTOMER NO.

ADDRESS

383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(R)

(O)

(P)

COUNT CARD NO.

REGN NO.: SHD6818C

MILEAGE

MAKE : HYUNDAI

FUEL

E.....1/2.....F

MODEL I-40

DATE/TIME IN
04.04.2019 15:30

YR OF MANU 23.04.2015

TARGET DATE

CHASSIS CODE
KMHLB41UMFU068770

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 04.04.2019
NATURE: 3P 04.04.19

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

K:

D:

File No.:

SHD6818C

JU CHINA

Vehicle No.:

SHD6818C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6818C

DATE 5/4/2019 9:50

MAKE :


MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 553.00	
	Rear Bumper Clip 10 pcs			\$ 22.00	
	Rear Bumper Under Cover			\$ 228.00	
	Rear Bumper Reflector Lamp (LH) X			\$ 30.60	
	SUB TOTAL			\$ 833.60	
	LESS 20%			\$ 166.72	
	DISCOUNTED TOTAL			\$ 666.88	
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
				\$ 300.00	
	Labour Charge				
	Panel Beating			\$ 400.00 ²⁰⁰	
	Spray Painting Charge			\$ 300.00 ²⁰⁰	
	Wiring Charge			\$ 30.00 X	
	Remove/Refix Reverse Sensor			\$ 80.00 ²⁰⁰	
	TOTAL LABOUR			\$ 810.00	
	ESTIMATE TOTAL			\$ 1,776.88	

1/Calvin 1/11/19

5/4/19 11:16am

2 By,

4/5
After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our Job Ref No 305284524
Date : 06/04/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
: SHD6818C

Fax :

Date of Accident : 04/04/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SKW 629K
###
2. The finalized amount shall be:

(a) Spare Parts after List discount			
(b) Labour Charges	###		
Total for Part-By-Part Repair Cost			
NI			
(c) Lumpsum Repair (if applicable)			
Total for Lumpsum repair cost after Less: <u>20%</u>			<u>\$1,100.00</u>
Final Lumpsum Repair cost			
3. Estimated normal period for repairs: 2 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : KALVIN
Date : 8/4/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: