





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/04/2019

User ID : JeongCH

Section A - Accident Details	
Registration Number	SG1745R
Case Reference Number	BUS/03/19/5013
Registration Date	3/1/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	GOH JOO NIE
Type of Accident	Side Swipe
Accident Date and Time	3/11/2019 5:18 AM
Accident Reported Date and Time	3/11/2019 7:45 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SG1745R - LEFT FRONT PORTION SHC2324S (TP) - COMFORT TAXI (BLUE). INSURED WITH III. RIGHT FRONT PORTION
Prepared Date and Time	4/5/2019 3:44 PM
Chassis Number	WMAA22ZZXF7002868
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$1,744.90	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,212.90	\$0.00
Lump Sum Total	\$4,200.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	05/04/2019 4:05 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/04/2019

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL REPLACE ITEM & REPAIR LEFT SIDE PORTION			\$1,590.00						
Total Labour			\$1,590.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO PUTTY & RESPRAY			\$878.00						
Total Spray Painting & Panel Beating			\$878.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Replace	
6009999	BODY LH	A01001-CW555	PANEL,SIDE:L5,FOR MAN A22 BUS	1.00	\$1,776.80	10.00	\$1,599.12	Replace	
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE:DIRECT GLAZING	6.00	\$37.00	0.00	\$222.00	Replace	
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	
4006313	CONSUMABLE	SIKA® Primer- 206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	
Total					\$2,173.80		\$2,181.12		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									