

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

: GohKK2

Date Generated: 08/04/2019

User ID

× Section A - Accident Details SMB1437C Registration Number Case Reference Number BUS/04/19/7004 24/7/2014 Registration Date Company Type SMRT Buses Ltd MAN Make Model MAN NL320F(A22) Name of Driver Wang Yongjiang Type of Accident Head to Rear 5/4/2019 8:57 AM Accident Date and Time Accident Reported Date and Time 5/4/2019 10:15 AM Is Surveyor Required? Yes Survey by Vehicle is Towed Back? No Towed Back Date and Time Replacement Vehicle issued? No Job Card Number SMB1437C - FRONT PORTION GBJ2555B (TP) - NO DAMAGES. INSURED WITH CHINA TAIPING Special Instruction to ARC, if any Prepared Date and Time 8/4/2019 2:09 PM WMAA22ZZ6E7002154 Chassis Number Mileage Work Shop Repair Completion Date and Time Section B - Summary of Repair Estimates Summary of Repair Estimates Adjusted by Surveyor, if applicable Quotation from ARC \$0.00 \$1 325 00 Total Labour Cost Total Spray Cost \$616.00 \$0.00 \$0.00 \$3,208,61 Total Spare Part Cost \$200.00 \$0.00 Total Other Cost \$0.00 TOTAL COST \$3,208.61 \$3,200.00 \$0.00 Lump Sum Total Number of Repair Days 4.0 Prepared / Adjusted By Kok Khoon Goh ARC / Surveyor Sign Off Date LKKA 08/04/2019 2:16 PM × Signature 10 T 8 20 6 Remarks 0 F 3 15 D ty survey is un a "Wattout II" result on "basis abodi e Section C - Quotation and Accident Invoice Details **Quotation Number** Invoice Number ACKIDIN Quotation Date Invoice Date Prepared Date Invoice Amount



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated : 08/04/2019 User ID : GohKK2

			Sect	ion D - Det	ails of Repair I	Estimates			
Part 1 - Labo	ur Works			on b - bet	ans of Repair L	-sumates			
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$1,329.00 795					
Total Labour				\$1,325.00					
Part 2 - Spra	y Painting & F	Panel Beating Rela	ated Works			N TOUTE		P SUNANCE	
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$616.00 52.8					
Total Spray Painting & Panel Beating				\$616.00					
Part 3 - Othe	Costs - Acci	dent and Acciden	t Repair Related Expens	se	4 14 14	A TOUR			
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
TOWING CHARGE				\$200.00					
Total Other Costs				\$200.00					
Part 4 - Spare	Parts / Mater	rial Usage			n skin si s		A PARTIE	I will be the	STATE OF THE STATE OF
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010159	BODY LH	4001M01- ACCE466	MIRROR, VIEW: FRONT, L H, FOR MAN	1.00	\$1,903.30	10.00	\$1,712.97	Replace	
5010160	BODY LH	4001M01- ACCE468	ARM,MIRROR VIEW:FRONT,LH,FOR MAN	1.00	\$684.30	10.00	\$615.87	Replace	
6010151			BUMPER FRONT	1.00	\$1,868.80	100.00	\$0.00	Repair	
3010154	Body	F01001-CW263	FLAP,FRONT:FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	
5010153	Body	F01001-CW264	COVER,HEADLAMP:FRT ,LH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	
Total					\$7,299.90		\$4,010.76		
Added Spare	Parts / Materi	al Usage After Su	rveyor Signed off				HATE STATE		
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

LKK Auto Consultants hence notify

- the Repairer of the following:
 To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hose die - LKK 8/4/19 L/s 3days.