



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/05/2019

User ID : CatherineLee

lic

L/s \$4750/- 3 days.

Section A - Accident Details

Registration Number	SMB1437C
Case Reference Number	BUS/04/19/7004
Registration Date	24/7/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Wang Yongjiang
Type of Accident	Head to Rear
Accident Date and Time	5/4/2019 8:57 AM
Accident Reported Date and Time	5/4/2019 10:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100963
Special Instruction to ARC, if any	SMB1437C - FRONT PORTION GBJ2555B (TP) - NO DAMAGES. INSURED WITH CHINA TAIPING
Prepared Date and Time	8/4/2019 2:09 PM
Chassis Number	WMAA22ZZ6E7002154
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$795.00
Total Spray Cost	\$616.00	\$526.00
Total Spare Part Cost	\$3,208.61	\$3,208.61
Total Other Cost	\$200.00	\$200.00
TOTAL COST	\$5,349.61	\$4,731.61
Lump Sum Total	\$5,350.00	\$4,750.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kok Khoo Goh	Hwee Jie
ARC / Surveyor Sign Off Date	08/04/2019 2:15 PM	08/04/2019 2:30 PM
Signature		Lirk
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/05/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	\$795.00
Total Labour	\$1,325.00	\$795.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	\$528.00
Total Spray Painting & Panel Beating	\$616.00	\$528.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	\$200.00
Total Other Costs	\$200.00	\$200.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010159	BODY LH	4001M01-ACCE468	MIRROR VIEW:FRONT,L H, FOR MAN	1.00	\$1,903.30	10.00	\$1,712.97	Replace	Replace
6010160	BODY LH	4001M01-ACCE468	ARM.MIRROR VIEW:FRONT,LH, FOR MAN	1.00	\$684.30	10.00	\$615.87	Replace	Replace
6010151			BUMPER FRONT	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair
6010154	Body	FD1001-CW263	FLAP.FRONT.FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	Replace
6010153	Body	FD1001-CW264	COVER,HEADLAMP.FRT LH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair
Total					\$7,299.90		\$4,010.76		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									