

ASS. REC. BY:

REF: CS3/III 19006235/EC d302 Special Instruction:

Survivor: Steve

ASSIGNMENT (Office)

MUSMAN

From (Person): Gabriel Wee of TH Date/Time: 9.4.2019 11469.m

Estimated Cost: Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKG 4215D Insured: SHA 7631H

at Workshop m/s Xinyi Auto Tel: 97882224

of Blk 1002 Bukit Merah Lane 3 #01-75

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 6.4.2019
(Client's Record) 10.4.2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 9.4.19 208p.m Person Contacted: Sharon Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	SKG 4215D - CS/MSG 15015205/Frb52	D.O.A - 21/08/2019
	SHA 7631H - NS/INC 12023894/412n	D.O.A - 10/12/2012

Surveyor **Steve**

REF: **TH**

ASSIGNMENT

From: _____ Date: **11.4.2019**

Estimated Cost: _____

OD / **(TP)** / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKG 4215 D**

at Workshop n/s **Xing A Auto**

of **BLK 100~ Bukit Morah Lam 37101-75**

Insured: **86685757 boss**


Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) _____

Make of Veh: _____



(Policy Condition) _____

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **"wp"**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SKG 4215 D** Yr Regn: **31/08/12**

Type: **(M)** Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Volvo** **560** C.C. **1596**

Colour: **Red** A/C: Insured / Std / NI / NA

Sp. Reading **N/A** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **YV 1F548HBC 2143615**

Gen. Cond: Good / **(Fair)** / Poor / Burnt

Steering: **(Inorder)** / Jammed / Leaked / Burnt or

Brake: **(Inorder)** / Jammed / Leaked / Burnt or

Modi: Nil / **(S/Rim)** / STD A/Rim or

Tyre Size: F: **215/59R17**

R: **" "**

BS / DUN / EXNOVA / **(GY)** / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	6/4/19	D.O.I.	10/4/19

Survey held at **Xing A** **1101 AM**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear LH, Interior

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - SIK

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: **-**

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

) **S + RS** **SI**

) Photos

) Others

TOTAL

120

10

130

Report Format : **PRS**

Lump Sum / I.B.I. (\$) _____

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 9 April 2019 11:40 AM
To: Yvonne; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Zuhaidah Samsuri
Subject: RE: India Insured SHA7631H [EAL.2019.6266.MK.ya - SKG4215D]
Attachments: 190409-GIA report of SKG4215D(new).pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SKG4215D
III INSURED VEHICLE NO. : SHA7631H
DATE OF LOSS : 06.04.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Aida**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Yvonne [mailto:yvonne@ealc.com.sg]
Sent: 09 April, 2019 9:52 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: India Insured SHA7631H [EAL.2019.6266.MK.ya - SKG4215D]

Our ref : 2019.6266.MK.ya - **SKG4215D**
Your ref : **SHA7631H**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

India International Insurance Pte Ltd
64 Cecil Street,
#04/#05 IOB Building,
Singapore 049711
Attn: Motor Claims Department
NOTICE OF ACCIDENT

For your information only
Owner of **SHA7631H**
Comfort Transporation Pte Ltd
383 Sin Ming Drive
GAS Building
Singapore 575717

Dear Sir/Madam,

CLAIMANT: QUALITY LEASING PRIVATE LIMITED

ACCIDENT INVOLVING SKG4215D & SHA7631H ON 06 APRIL 2019 ALONG DUNEARN ROAD INTO LINDEN DRIVE AT ABOUT 0220 HOURS

We are instructed by **QUALITY LEASING PRIVATE LIMITED** to notify you (the insurer of **SHA7631H**) of a road traffic accident on **06 APRIL 2019 ALONG DUNEARN ROAD INTO LINDEN DRIVE AT ABOUT 0220 HOURS** involving our client's vehicle registration number **SKG4215D** and vehicle registration number **SHA7631H** driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle **SKG4215D** has been damaged. Before our client proceed to repair the damaged vehicle:

1. Please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle; and
2. Please forward a copy of your insured's report.

Our client proposes to use one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

3. Dennis Yap Teck Wee - Pal's Appraiser Pte Ltd

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.
India International Insurance Pte Ltd.
Registration No. 198703792-K

Nivitha (LKK Auto)

From: Yvonne <yvonne@ealc.com.sg>
Sent: Tuesday, 9 April 2019 11:46 AM
To: Motor Claim - III; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Zuhaidah Samsuri
Subject: PRI: India Insured SHA7631H [EAL.2019.6266.MK.ya - SKG4215D]

Our ref : 2019.6266.MK.ya - **SKG4215D**
Your ref : **SHA7631H**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

India International Insurance Pte Ltd
64 Cecil Street,
#04/#05 IOB Building,
Singapore 049711
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s India International Insurance Pte Ltd

Vehicle **SKG4215D** inspected as follows by Name:

Before repair	Parts removed	After repair
---------------	---------------	--------------

Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: QUALITY LEASING PRIVATE LIMITED

ACCIDENT INVOLVING SKG4215D & SHA7631H ON 06 APRIL 2019 ALONG DUNEARN ROAD INTO LINDEN DRIVE AT ABOUT 0220 HOURS

We refer to the above matter wherein we are instructed to act for **QUALITY LEASING PRIVATE LIMITED**, the owner of vehicle no. **SKG4215D**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SKG4215D** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Xinya Auto Services Pte Ltd
Blk 1002 Bukit Merah Lane 3
#01-75
Singapore 159719
Contact: Sharon - 9788 2224

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2796G
Vehicle Details	
Vehicle No.:	SKG4215D
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Apr 2019
Vehicle Make:	VOLVO
Vehicle Model:	S60 T4 1.6 AT ABS D/AB 2WD 4DR TC
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	B4164T1092548
Chassis No.:	YV1FS48HBC2143615
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$35,461.00
Original Registration Date:	31 Aug 2012
First Registration Date:	31 Aug 2012
Transfer Count:	2
Actual ARF Paid:	\$35,461.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2022
PARF Rebate Amount:	\$23,049.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$66,889.00
COE Rebate Amount:	\$22,637.00
Total Rebate Amount:	\$45,686.00

The information contained herein is correct as at 11 Apr 2019

OK



ANNOUNCING 88 Motor Trading

as sgCarMart Premium Dealer for the 5th Consecutive Year

88 汽车贸易

MOTOR TRADING

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Are
Welcome. 100% Deposit Refund
For Unapproved Loan.
Classic Credit Stand

HIN LUNG AUTO
Ho Bee Group

30 years
of car sale

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

7 vehicles

Volvo S60

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volvo S60	Any	Any	2012	Any	Any	Any	Available
	Volvo S60 T4	\$41,800	\$8,800 /yr	12-Jan-2012	1,596 cc	139,000 km	Luxury	Available
Low Mileage. Good Condition. Nice Car Plate Number(112). High Scarp Value + Car Body = \$37k, Low Interest Rate. Call/SMS For More Details.								
Posted: 25-Mar-2019 Tags: 2012 Volvo S60, 2012 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo								
	Volvo S60 T4	\$46,800	\$10,140 /yr	28-Feb-2012	1,596 cc	-	Luxury	Available
Elegant Volvo S60, Renowned For Safety, Serviced By Agent, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.								
Prime Motor & Leasing								
Posted: 06-Apr-2019 Tags: 2012 Volvo S60, 2012 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo								
	Volvo S60 T4	\$46,800	\$10,060 /yr	28-Feb-2012	1,596 cc	85,000 km	Luxury	Available
No Repair Needed, Perfect Engine Condition, Clean And Pristine Interior, Low Mileage Done At 85,000km, Price Negotiable, View The Car At Our Showroom.								
Motor Universe Credit Pte Ltd								
Posted: 28-Feb-2019 Tags: 2012 Volvo S60, 2012 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo								
	Volvo S60 T4	\$53,800	\$12,180 /yr	28-Mar-2012	1,596 cc	108,000 km	Luxury	Available
Only 1 Owner, Low Mileage, Immaculate Condition And In Showroom Condition. Buy With Extra Peace Of Mind! High Paper Value, Selling Near Export Price, High Trade In Welcome, In House And Bank Loan Avail...								
Posted: 29-Mar-2019 Tags: 2012 Volvo S60, 2012 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo								

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



	Volvo S60 T4	\$50,900	\$10,220 /yr	10-Jul-2012	1,596 cc	76,500 km	Luxury	Available
One Owner, Loan Available. Extremely Well Maintained, Genuine Mileage With Service Record. Whatsapp For Consignment Unit.								
Prem Roy Motoring								
Posted: 01-Apr-2019 Tags: 2012 Volvo S60, 2012 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo								
	Volvo S60 T4	\$58,800	\$12,040 /yr	31-Oct-2012	1,596 cc	105,000 km	Luxury	Available
No Repair Needed, Perfect Engine Condition, Clean And Pristine Interior, Price Negotiable, View The Car At Our Showroom.								
Motor Universe Credit Pte Ltd								
Posted: 14-Mar-2019 Tags: 2012 Volvo S60, 2012 volvo s60, Volvo S60, volvo s60, Volvo, S60, s60, Used Volvo								

Compare

Volvo S60 T4	\$54,800	\$10,570 /yr	12-Dec-2012	1,596 cc	102,000 km	Luxury	Available
---------------------	-----------------	---------------------	--------------------	-----------------	-------------------	---------------	------------------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	08/04/2019 11:55
Date Of Accident	06/04/2019 02:20
Exact Location Of Accident	ALONG DUNEARN RD INTO LINDEN DRIVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKG4215D
Insured/Policyholder	
Name Of Registered Owner	QUALITY LEASING PRIVATE LIMITED
Co Reg No	201312796G
Email Address	SHARONSOON5404@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	VOLVO
Model	S60 T4 1.6 AT ABS D/AB 2WD 4DR TC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MJ000980-R00
Cover Note Number	
Driver	
Name of Driver	ON SI YUAN, JOAB
NRIC No	S9020041J
Date Of Birth	12/06/1990
Occupation	INDOOR
Date Of Driving Pass	24/07/2015
Driving Experience	3 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81791484
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 292A BUKIT BATOK EAST AVENUE 6 #08-208
Postcode	651292
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7631H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

A: SKG 4215 D
B: SHA 7631 H



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SKG 4215 D	ACCIDENT DATE & TIME: 28/04/2019 02:20 AM
CONTACT NUMBER: 8179 1484	E-MAIL ADDRESS: jank-on@hotmail.com
LOCATION: Along Duneen Road Turning into Linden Drive	
I was driving along Duneen Road turning into Linden Drive suddenly this taxi SHA 7631 H came from behind at a very high speed and knock on to the rear of my vehicle.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy <input type="checkbox"/> Claim Third Party <input checked="" type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:






































...CLAIM SUBFOLDER...(Pending for Survey Report)


CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Apr 2019 12:18 Edit Reg		09 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: QUALITY LEASING PRIVATE LIMITED , Co. Reg. No.: 201312796G									
Vehicle Reg. No.: SKG4215D		Date of Loss: 06/04/2019 11:00 - :59 [79 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SHA7631H		Policy No. (Claimant):							
		Excess:							
Repairer: Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3, 159719 Bukit Merah - Tel: 6270 3481									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 18/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKG4215D
[SHA7631H]
TP
QUALITY LEASING PRIVATE LIMITED
Apr 6 2019 11:00AM
[-]
Xinya Auto Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
2	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
3	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
4	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
5	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
6	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
7	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
8	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
9	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
10	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
11	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
12	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
13	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
14	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
15	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
16	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
17	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
18	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
19	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
20	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
21	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
22	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
23	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
24	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
25	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
26	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
27	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
28	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
29	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
30	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
31	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
32	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
33	10/04/19 16:09	Odometer Reading						 Load JPG	<input checked="" type="checkbox"/>	
34	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
35	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
36	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	
37	10/04/19 16:09	General View						 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/04/19 16:09	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
48	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/04/19 16:09	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/04/19 08:56	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19006235/ECD3E2

Date: 22/04/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SKG4215D

Insured Vehicle No : SHA7631H

Date of Loss: 06/04/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKG4215D

Make & Model: VOLVO S60, 1.6 T4 (A)

Reg. Date: 31/08/2012 (Man. Year: 2012)

Colour: Red

Engine Capacity: 1596 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: B4164T1092548

Chassis No: YV1FS48HBC2143615

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size: 215/50 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/04/2019

Date Inspected: 10/04/2019 Inspected At:

Xinya Auto Services Pte Ltd (HQ)
Blk 1002, #01-75, Bukit Merah Lane 3
Singapore 159719

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2019)
Parts: 143	VOLVO S60 1.6 T4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKG4215D)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >