

ASS. REC. BY:

REF: CS/CTI 19006248/US d3 | n2
Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

Mimin

From (Person): Elaine Chong

of CTI

Date/Time: 8.4.19 17:20 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SG M 7975P

Insured: SL M 1798P

at Workshop m/s Autolution Industrial

Tel: 96450079

of 19 ubi Road 4

Policy No: DmpcsN3034741801

Claim No: SNM19D201418102

Sum Insured:

Excess:

Make of Veh:

D.O.A. 29-3-19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"rup"

10.4.19 (9.30A.M)

H.O.D. Endorsement:

Date/Time: 9.4.19 9.47A.M

Person Contacted: Hamzah

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SG M 7975P - X
	SL M 1798P - CS3 / LCR 17011365 / Sbr2
	D.O.A - 7/6/2017

REF: CTE

ASSIGNMENT

From: Date: 10/04/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGM 7975P

at Workshop m/s

of

AutoNation
19 ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

9:30am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

14%

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS / up

LTA 48107

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGM 7975P

Yr Regn:

6.18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Nissan

Sydney

C.C.

1598

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

8241

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MNTBBAB1720031933

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

2

mm

R/Bal:

2

mm

L/Bal:

2

mm

L/Bal:

2

mm

D.O.A.

29/3/19

D.O.I.

10/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

21/5/19 Confirmed final R \$ 1471.44 with handler.
(4350/- Red - 19%)

RECEIVED 24 MAY 2019

24/5/2019

Date/Time, File Pass to?

24/05/19

1)

Type: F

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$) 1,471.44 P/A

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Apr 2019		08 Apr 2019 17:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant:

Vehicle Reg. No.:

Claim Type:

Vehicle Reg. No. (Insured):

Repairer:

Handling Insurer:

Claimant's Insurer:

Adjuster:

CHIANG HAI ENG, ID: S0008530H

SGM7975P

TP / SNM19D201418C02

SLM1798P

Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4, 408623 Ubi - Tel:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]

AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/04/2019]

Date of Loss:

Policy/Cover Note No.:

Policy No. (Claimant):

Excess:

29/03/2019 21:00 - :59

DMPCSN3034741801

1800072573

S\$750.00

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8530H

Vehicle Details

Vehicle No.: SGM7975P

Vehicle to be Exported: No

Intended Deregistration Date: 10 Apr 2019

Vehicle Make: NISSAN

Vehicle Model: SYLPHY 1.6 CVT

Primary Colour: Silver

Manufacturing Year: 2018

Engine No.: HR16926148C

Chassis No.: MNTBBAB17Z0031933

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$16,419.00

Original Registration Date: 20 Jun 2018

First Registration Date: 20 Jun 2018

Transfer Count: 0

Actual ARF Paid: \$16,419.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Jun 2028

PARF Rebate Amount: \$12,314.00

Intended COE Rebate Details

COE Expiry Date: 19 Jun 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$38,941.00

COE Rebate Amount: \$35,793.00

Total Rebate Amount: \$48,107.00

The information contained herein is correct as at 10 Apr 2019

OK

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE. LTD.
301 ROAD 4
SINGAPORE 408623
TEL: 6490 9566 FAX: 6346 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0182/19
DATE : 30-MAR-2019

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR. CHIANG HAI ENG
ADDRESS : 19 HENDRY CLOSE

S(549274)
TELEPHONE NO : 96343356/94508070

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SGM7975P
MODEL CODE : BDTARCZB17EWA---K
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2017
ENGINE NO : HR16926148C
CHASSIS NO : MNTBBAB17Z0031933
MILEAGE : 7949 KM
DATE IN : 30/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH - 96450079
ACCIDENT DATE : 29/03/2019

Not Authorized
LHR
The photo taken party.
10/4/19
Z Ly.

Link to General Insurance notify
the following:
• Temporary repair spray painting
• Temporary repair during resurvey
• Permanent repair to confirmation
• The repair work is on a "without Prejudice" basis
• The repair work is allowed
• Signature must be authorized and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO 5GM7975P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO RENEW LH FRONT DOOR.	450.00	250
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	350.00	250
3	ZZ/003	REMOVE AND INSTALL LH FRONT DOOR MECHANISM.	80.00	✓
4	ZZ/004	APPLY SEALANT TO LH FRONT DOOR.	100.00	✓
TOTAL LABOUR CHARGES.			980.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO 56M7925P

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN		11	50.00	X
2	L/F DOOR TAPE	80817-3580A	29.30	✓		
3	L/F DOOR TAPE	80819-3580A	22.60	✓		
4	FRONT DOOR LH	H010A-35BMA	937.40	✓		
SUB TOTAL			989.30	0.00	50.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			197.86	0.00	0.00	
GRAND TOTAL			791.44	0.00	50.00	
OVERALL TOTAL			841.44			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SQM7975P

TOTAL LABOUR CHARGES	980.00
TOTAL SPARE PARTS CHARGES	841.44
GRAND TOTAL	1821.44 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Manchu
UKIC
AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9090 FAX: 6346 7483

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0182/19
DATE : 30-MAR-2019

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

3 days

OWNER'S NAME : MR CHIANG HAI ENG
ADDRESS : 19 HENDRY CLOSE

S(549274)
TELEPHONE NO : 96343356/94508070

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SGM7975P
MODEL CODE : BOTARC2B17EWA---K
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2017
ENGINE NO : HR16926148C
CHASSIS NO : MNTBBAB1720031933
MILEAGE : 7949 KM
DATE IN : 30/03/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 29/03/2019

-96450079

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGM7975P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO RENEW LH FRONT DOOR.	450.00	250.00
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	350.00	250.00
3	ZZ/003	REMOVE AND INSTALL LH FRONT DOOR MECHANISM.	80.00	80.00
4	ZZ/004	APPLY SEALANT TO LH FRONT DOOR.	100.00	100.00
TOTAL LABOUR CHARGES			980.00	680.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGM7975P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	L1ST	S/NETT REMARKS
1	SUNDRIES	NPN			50.00 X
2	L/F DOOR TAPE	B0B17-3S80A	29.30		OK
3	L/F DOOR TAPE	B0B19-3S80A	22.60		OK
4	FRONT DOOR LH	H010A-3S8MA	937.40		OK
SUB TOTAL			989.30	0.00	0.00
LESS DISCOUNT (NETT-20.00%, L1ST-30.00%, S/NETT-.00%)			197.86	0.00	0.00
GRAND TOTAL			791.44	0.00	0.00
OVERALL TOTAL			791.44		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SGM7975P

NETT ITEM	989.30
LESS 20.00%	-197.86
NETT AMOUNT	791.44
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	680.00
TOTAL SPARE PARTS CHARGES	791.44

TOTAL CHARGES	1471.44
ADD 7 % GST	103.00

GRAND TOTAL	1574.44

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006248/USD3N2

Date: 27/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3034741801	
Claimant Vehicle No :	SGM7975P	Insured Vehicle No :	SLM1798P	
Date of Loss:	29/03/2019	Nature of Claim:	TP	Claim No: SNM19D201418C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM7975P	Engine No:	HR16926148C
Make & Model:	NISSAN SYLPHY, 1.6 (A)	Chassis No:	MNTBBAB17Z0031933
Reg. Date:	20/06/2018 (Man. Year: 2018)	Odometer:	8241 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R16	Rear Tyre Size:	195/60R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	841.44	791.44	50.00	5.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	680.00	300.00	30.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,821.44	1,471.44	350.00	19.22
+ GST 7.00/7.00% (S\$)	127.50	103.00	24.50	19.22
Nett Amount (S\$)	1,948.94	1,574.44	374.50	19.22

INSPECTION

Date of Assignment:	08/04/2019		
Date Inspected:	10/04/2019	Inspected At:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4 Singapore 408623

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2019)
Parts: 143	NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM7975P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/F DOOR TAPE	Necessary	29.30 FN	*29.30 FN
2	1		*L/F DOOR TAPE	Necessary	22.60 FN	*22.60 FN
3	1		*FRONT DOOR LH	Dented	937.40 FN	*937.40 FN
4	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (\$\$)					1,039.30	989.30
- Nett Item Discount on N Items 20.00/20.00% (\$\$)					197.86	197.86
Total Parts (\$\$)					841.44	791.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO RENEW LH FRONT DOOR	New	450.00	250.00
2	CHARGES TO SPRAY PAINTING SAME	New	350.00	250.00
3	REMOVE AND INSTALL LH FRONT DOOR MECHANISM	New	80.00	80.00
4	APPLY SEALANT TO LH FRONT DOOR	New	100.00	100.00
Gross Labour Cost (\$\$)			980.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >