

2/03/2002

ASS. REC. BY:

REF: CS3/smo 19006251 / T1cd3p

Special Instruction:

Surveyor: Tau S K Y

ASSIGNMENT (Office)

minim

From (Person): Agnus Chanof SmoDate/Time: 9.4.19 13.08 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJH 545 2KInsured: YP 6254Pat Workshop m/s Ama AutocareTel: 87783636of 36 Toh Guan Road East # 01-36Policy No: D18MTPCV6 001573Claim No: CMTD1901722

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7.4.201910.4.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 9.4.19 2.12 p.mPerson Contacted: MelvinVehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate
	SJH 5452K - CS / INC 12007876 / Afn
	YP 6254P - X
	Dismantle: 10/4/2019

D.O.A. - 18/4/12

0010 +  
Curren  
Taufm

REF: SMO

# ASSIGNMENT

OPC

COF 2023 Aug

From: Date: 11.4.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJH 5452K

at Workshop m/s Ama Autocare

of 36 Toh Guan Road East # 01-36

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$20K \$32K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

"rup"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SJH 5452K

Yr Regn: 2008, Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish 1.8X A

C.C

1794

Colour

Black

A/C:

Insured / Std / NI / NA

Sp.Reading

121 666

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ENE 100414400.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

145/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Viking

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

10/4/19C/pu

Survey held at

Ama Toh Guan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt b/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair range \$5,000 - \$6,000

Rebate \$15,172

RECEIVED 20 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

PRS

Lump Sum / I.B.I. (\$

100

60

11

171

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Apr 2019		09 Apr 2019 13:08 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	LIM SIANG HUAT PTE LTD, Co. Reg. No.: 199803003N	
Main Claimant:	ANUAR BIN ATAN, ID: S0224687B	
Vehicle Reg. No.:	SJH5452K	Date of Loss: 07/04/2019 11:00 - :59
Claim Type:	TP / CMTD1901722	Policy/Cover Note No.: D18MTPCVE001573 (Comprehensive)
Vehicle Reg. No. (Insured):	YP6254P	Policy No. (Claimant):
		Excess:
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:	
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/04/2019]	
Driver/Custodian (Insured):	VEERAPATHIRAN MUTHIRULAN (), NRIC: G5290919N, Tel: +6591334821 Email:	
Adj Asg. Remarks:	WS: MELVIN 8778 3636	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4687B
<b>Vehicle Details</b>	
Vehicle No.:	SJH5452K
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	1ZZ3126414
Chassis No.:	ZNE100414400
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,611.00
Original Registration Date:	13 Aug 2008
First Registration Date:	13 Aug 2008
Transfer Count:	0
Actual ARF Paid:	\$13,846.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Aug 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$17,496.00
COE Rebate Amount:	\$15,059.00
<b>Total Rebate Amount:</b>	<b>\$15,059.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Apr 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	08/04/2019 09:04
Date Of Accident	07/04/2019 12:05
Exact Location Of Accident	62 TEBAN GARDENS (LOADING / UNLOADING BAY)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJH5452K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ANUAR BIN ATAN
NRIC No	S0224687B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85227006
Alternative Phone No	OFFICE-85227006
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5030359324-10 (CLASSIC)
Cover Note Number	
<b>Driver</b>	
Name of Driver	ANUAR BIN ATAN
NRIC No	S0224687B
Date Of Birth	18/09/1952
Occupation	OUTDOOR
Date Of Driving Pass	22/05/2008
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85227006
Fax Number	
Contact Number	OFFICE-85227006
EEmail Address	NOEMAIL

Address	21 TEBAN GARDENS ROAD #08-125
Postcode	S600021
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY VEHICLE WAS PARKED AT 62 TEBAN GARDENS UNLOADING AND LOADING BA, I ALIGHTED FROM MY VEHICLE CAUSED MY SON-IN-LAW WILL TAKING OVER THE DRIVING, AT THE POINT OF TIME MY WIFE WAS SEATED INSIDE THE VEHICLE AND MY FAMILY MEMBERS WERE STANDING BEHIND MY VEHICLE AT THE POINT OF TIME. THERE WAS A TRUCK WHICH WAS PARKED BESIDE MY VEHICLE, DRIVER TO THE TRUCK WAS TURNING OUT FROM THE CARPARK, AS THE DRIVER MAKE HIS LEFT TURN OUT, THE LEFT SIDE PORTION OF THE TRUCK HIT ONTO THE FRONT RIGHT PORTION OF MY STATIONED VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6254P
Vehicle Make/Model/Colour	TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	VEERAPATHIRAN MUTHIRULAN
NRIC/Passport Number	G5290919N
Contact Number	82280334
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time:

- 8 APR 2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


IDAC BUKIT BATOK (VAC)  
511 Bukit Batok Street 23  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**Sketch Plan #2 Pg. 1**



### SKETCH PLAN



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

**Date & Time:**

一、

Driver's Signature

(If driver is not the policyholder)

**Date & Time:**

**IDAC BUKIT BATOK (VAC)**  
511 Bukit Batok Street 23  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: [vacbb@singnet.com.sg](mailto:vacbb@singnet.com.sg)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



































### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Apr 2019		09 Apr 2019 13:08 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>LIM SIANG HUAT PTE LTD</b> , Co. Reg. No.: 199803003N								
Main Claimant:	<b>ANUAR BIN ATAN</b> , ID: S0224687B								
Vehicle Reg. No.:	<b>SJH5452K</b>	Date of Loss:	07/04/2019 11:00 - :59 [127 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / CMTD1901722</b>	Policy/Cover Note No.:	D18MTPCVE001573 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>YP6254P</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Ama Autocare Pte Ltd (HQ)</b> 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>CHAN SHU HUI AGNES</b> - 6329 5327]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 18/04/2019]								
Driver/Custodian (Insured):	VEERAPATHIRAN MUTHIRULAN (), NRIC: G5290919N, Tel: +6591334821 Email:								
Adj Asg. Remarks:	WS: MELVIN 8778 3636								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJH5452K (CMTD1901722)  
[YP6254P]  
TP  
ANUAR BIN ATAN  
Apr 7 2019 11:00AM  
[LIM SIANG HUAT PTE LTD]  
Ama Autocare Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	09/04/19 13:06	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> <b>Accident Statement</b> From: SC - Reg. No: YP6254P, Claimant: LIM SIANG HUAT PTE LTD	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	23/04/19 14:02	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
23	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
24	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
25	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
26	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
27	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
28	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
29	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
30	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
31	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
32	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
33	23/04/19 14:03	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/04/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	08/04/19 16:10	Pre-Repair Survey	 Load PDF	
2	09/04/19 13:07	Third Party E-filed GIA report(M)	 Load PDF	
3	09/04/19 13:07	Pre-Repair Survey - ASSIGN LKK	 Load PDF	
4	29/05/19 12:09	PD LOD FROM CHIA S ARUL - SJH5452K	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19006251/T1CD3E2

Date: 21/06/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001573
Claimant Vehicle No :	SJH5452K	Insured Vehicle No :	YP6254P
Date of Loss:	07/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1901722

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SJH5452K</b>	Engine No:	1ZZ3126414
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100414400
Reg. Date:	13/08/2008 (Man. Year: 2008)	Odometer:	121666 km
Colour:	Black		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Viking 6 mm	Rear Left Side:	Viking 6 mm
Front Right Side:	Viking 6 mm	Rear Right Side:	Viking 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	09/04/2019		
Date Inspected:	10/04/2019	Inspected At:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36 Singapore 608580
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJH5452K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >