

22/03/2002

ASS. REC. BY:

REF: CSB / SMO19006266 / Bcd322

Special Instruction:

Supervisor: Mr Lim

ASSIGNMENT (Office)

minim

From (Person): Hwang Shiang Yi

of SMO

Date/Time: 9.4.19 9.09am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKA 8935P

Insured: FBP 2085J

at Workshop m/s Team Autopro

Tel: 90 927279

of 160 Sin Ming Drive, #01-14

Policy No: D19MTMC 01001435

Claim No: CMTD1901728

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8.4.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"w.p."

H.O.D. Endorsement:

Date/Time: 2:02pm @ 9/4/19

Person Contacted: Alan

Vehicle IN OUT

Date/Time	Action/Instruction (LT) Estimate
	SKA 8935 P - X
	FBP 2085 J - X
	Dismantle: 9/4/2019
	After repair: 15/4/2019

REF: SMO

ASSIGNMENT

From: _____ Date: **9/4/19**

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SKA 8935P**

at Workshop m/s: **Team Autopro**

of: **160 SIA MING Drive #01-14**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **(UP)**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SKA 8935P** Yr Regn: **12/4/2011**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Mazda 8** C.C. **2261**

Colour: **Black** A/C: Insured / Std / NI / NA

Sp. Reading: **98500** T/Radio: Insured / Std / NI / NA

Eng/No: **L30518011**

C/No: **JM6LY103200201099**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / STD A/Rim / STD A/Rim or _____

Tyre Size: F: **215/65/16**
R: **215/65/16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /


TOYO / YOKO or **Kumho**

Front		Rear	
R/Bal. 7 mm		R/Bal. 7 mm	
L/Bal. 7 mm		L/Bal. 7 mm	
D.O.A. 8/4/19		D.O.I. 9/4/19	

Survey held at **Team Autopro**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
	Range 6,000/2 - 7,000/2
	Team Autopro
	15/4/2019
	MV 4,452/2
	PV 29,885/2
	NV 11,567/2

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : **PRS.**

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: **5**

Resurvey No. of Trip: **2**

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: **100**

Transportation: **60**

S + RS, SI: **60**

Photos: **10**

Others: _____

TOTAL: **230**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Apr 2019		09 Apr 2019 09:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	THIRUGNANA SURIYAN KARTHIK, ID: G1662443N			
Main Claimant:	STEPHEN JOHN FISHER, ID: S2742697B			
Vehicle Reg. No.:	SKA8935P	Date of Loss:	08/04/2019 09:00 - :59	
Claim Type:	TP / CMTD1901728	Policy/Cover Note No.:	D19MTMC01001435 (TP, Fire & Theft)	
Vehicle Reg. No. (Insured):	FBP2085J	Policy No. (Claimant):		
		Excess:		
Repairer:	Team Autopro Pte Ltd (sin Ming) (HQ) 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/04/2019]			
Adj Asg. Remarks:	WS: ALAN 90927279/ FREDERICK 96746635 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT			

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2697B
Vehicle Details	
Vehicle No.:	SKA8935P
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Apr 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA8 2.3L 5EAT
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	L310518011
Chassis No.:	JM6LY103200201099
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$34,356.00
Original Registration Date:	12 Apr 2011
First Registration Date:	12 Apr 2011
Transfer Count:	0
Actual ARF Paid:	\$34,356.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Apr 2021
PARF Rebate Amount:	\$18,895.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$55,001.00
COE Rebate Amount:	\$10,990.00
Total Rebate Amount:	\$29,885.00

The information contained herein is correct as at 12 Apr 2019

OK

dep 12,140/yr
1012/mth

39,000
MV ~~41,152~~/2
PV 29,885/2
NV ~~41,567~~
9,115

kin
12/4/19

500+ dealers competed to buy my car!



- ▶ **Sell ur Car for More Cash**
- ▶ **Highest Price or Get \$100 Free**
- ▶ **Get Paid Now, Handover Later**

SELL YOUR CAR



Post an Advertisement
 Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A RSZ



2.88%P.A Low Interest @ Gv Finance 7 Years Warranty. \$2500 Down Monthly Term \$738 GV Credit Pte Ltd [Search](#)

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

1 vehicles

Mazda 8

Advanced Search 

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mazda 8	Any	Any	2011	Any	Any	Any	All



Mazda 8 2.3A

\$45,500

\$12,180 /yr

23-Aug-2011

2,261 cc

116,222 km

MPV

Available

Spacious 7 Seater MPV. Auto Tailgate Closure. Low Depreciation. Flexible Loan. Trade In Welcome. Please Contact Our Sales Person For All Enquires.

Henly Enterprises Co

Posted: 11-Apr-2019 Tags: 2011 Mazda 8, 2011 mazda 8, Mazda 8, mazda 8, Mazda, 8, Used Mazda

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mazda, Mazda Singapore, used Mazda Singapore, used Mazda, used vehicles Singapore or even buy used Mazda Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Accident Report – Data Collection - TP/OD/

Insurance Co : *Sompo*

Vehicle No. : *SKA 893SP*

Policy Holder Name :

Model : *mazda 8*

Nric No.

Date Of Accident : *8/4/2019*

Relation :

Time Of Accident : *9.00 am*

Location : *CTE towards city before Amk Ave 1*

HP No. *9829 9919*

Email :

Weather : Clear/Dry - Drizzling / Wet - Raining / Wet

Occupation : *Indoor or Outdoor*

Driver & Passenger : *1* pax

Video Footage : Yes / No

1) Passenger Name :

Gender : *Male / Female*

Injury : Yes / No

2) Passenger Name :

Gender : *Male / Female*

3) Passenger Name :

Gender : *Male / Female*

Third Party's Particulars :

Vehicle No. : *F8P2085J*

Vehicle No. :

Name :

Name :

Nric :


Nric :

HP No. :

HP No. :

Date of accident: 8/4/2019 Time: 0900 Location: CTE towards City before Amk Ave 1
 My Vehicle A: SKA 893SP Vehicle B: FBP 2085J Vehicle C: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, i vehicle 'A' was travelling along my designated lane along CTE towards city before Amk Ave 1. The vehicle in front of me braked as such i followed suit. As i came to a stop i suddenly felt a huge impact hitting me from the rear. I got down from my vehicle to realized that vehicle 'B' couldn't stop in time and hence collided into me. That is all.

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop :
 Email address :
 & myself :
 Email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature


 Driver's Signature

 Reporting Centre Personnel's Signature

Date & Time:

(If driver is not the policyholder)

Name:

Date & Time:

NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/04/2019 15:48
Date Of Accident	08/04/2019 09:00
Exact Location Of Accident	CTE TWDS CITY B4 ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA8935P
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	STEPHEN JOHN FISHER
NRIC No	S2742697B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98299919
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	8
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01006292
Cover Note Number	12/04/2018 TO 11/04/2019

Driver

Name of Driver	LIM KIM CHIN
NRIC No	S2616514H
Date Of Birth	03/06/1963
Occupation	OUTDOOR
Date Of Driving Pass	25/05/1984
Driving Experience	34 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98299919
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 988B BUANGKOK GREEN #12-67
Postcode	532988
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBP2085J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

Sompo
Vehicle: -
SKA
8935P

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


8/4/19
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: Helen
 NRIC/FIN No.: 814/19

Sketch Plan Pg. 2

Date of accident: 8/4/2019 Time: 0900 Location: CTE towards City before Amk Ave
 My Vehicle A: SKA 8935P Vehicle B: FBP 2085J Vehicle C: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, i vehicle 'A' was travelling along my designated lane along CTE towards city before Amk Ave. The vehicle in front of me braked as such i followed suit. As i came to a stop i suddenly felt a huge impact hitting me from the rear. I got down from my vehicle to realized that vehicle 'B' couldn't stop in time and hence collided into me. That is all.

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop : Team auto Pro PTE LTD
 Email address : Teamautopl@gmail.com
 & myself :
 Email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own polly. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Driver's Particulars Pg. 1



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Tel: 6461 6955 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 196905490E | GST Reg. No.: M200603196

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D18MTPV01006292
Insured : STEPHEN JOHN FISHER
Motor Car (Registration No.) : SKA8935P
Cover : Comprehensive - ExcelDrive Prestige Plan
Policy Commencement Date : 12 APRIL 2018 00:00
Policy Expiry Date : 11 APRIL 2019 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : S\$800 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N.A
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule
* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 29 MARCH 2018 23:57

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 1102001 & IPP FINANCIAL ADVISERS PTE LTD CI Code: 22A_ODPPL4J4KTYVPAJ

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Apr 2019		09 Apr 2019 09:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	THIRUGNANA SURIYAN KARTHIK, ID: G1662443N			
Main Claimant:	STEPHEN JOHN FISHER, ID: S2742697B			
Vehicle Reg. No.:	SKA8935P	Date of Loss:	08/04/2019 09:00 - :59 [95 Months and 27 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / CMTD1901728	Policy/Cover Note No.:	D19MTMC01001435 (TP, Fire & Theft)	
Vehicle Reg. No. (Insured):	FBP2085J	Policy No. (Claimant):		
		Excess:		
Repairer:	Team Autopro Pte Ltd (sin Ming) (HQ) 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 18/04/2019]			
Adj Asg. Remarks:	WS: ALAN 90927279/ FREDERICK 96746635 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS											View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					
No results.														

Claim Documents

*SKA8935P (CMTD1901728)

[FBP2085J]

TP

STEPHEN JOHN FISHER

Apr 8 2019 9:00AM

[THIRUGNANA SURIYAN KARTHIK]

Team Autopro Pte Ltd (sin Ming)

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/04/19 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	18/04/19 14:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	18/04/19 14:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	18/04/19 14:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	18/04/19 14:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	18/04/19 14:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	09/04/19 08:59	Pre-Repair Survey	 Load PDF	
2	09/04/19 08:59	Pre-Repair Survey - AR	 Load PDF	
3	09/04/19 09:08	Pre-Repair Survey - AGREED LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19006266/BCD3E2
Date: 23/04/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTMC01001435
Claimant Vehicle No : SKA8935P **Insured Vehicle No :** FBP2085J
 Date of Loss: 08/04/2019 Nature of Claim: TP Claim No: CMTD1901728

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA8935P**
 Make & Model: MAZDA 8, 2.3 (A) Engine No: L310518011
 Reg. Date: 12/04/2011 (Man. Year: 2010) Chassis No: JM6LY103200201099
 Colour: Black Odometer: 98500 km
 Engine Capacity: 2261 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16
 Front Left Side: Kumho 7 mm Rear Left Side: Kumho 7 mm
 Front Right Side: Kumho 7 mm Rear Right Side: Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/04/2019
 Date Inspected: 09/04/2019 Inspected At: Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING
 AUTOCITY
 Singapore 575722
 Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2019)
Parts: M1-MPV	MAZDA 8 2.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA8935P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >