

ASS. REC. BY:

REF: CS/FWD19006269/K9D3⁵²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

MUMU

From (Person): Clara Li Zi Rong of FWD

Date/Time: 9.4.19 9.56a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 2996m

Insured:

at Workshop m/s Ah Lim Motor

Tel: 64831244

of 10 Ang Mo Kio Industrial Park Rd, #01-09

Policy No: PNPV2019-00000119

Claim No: 1201900009757

Sum Insured:

Excess: TBA 3300

Make of Veh:

D.O.A. 7.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.4.19 11.53a.m

Person Contacted: Zila

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 2996m - CC4 / FWD19006253/013

D.O.A. - 07/04/2019

10/4/19 @ 3.28pm report to Clara Li Zi Rong.

11/4/19 Submit Extensive Total Loss Report.

ASS. REC. BY:

REF: FWP/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Falken 245/40R18
R: HankookBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooflop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to
7/6/19

RECEIVED 11 APR 2019

Data/Time, File Pass to?

☐

: Prel. Report

1) 4/4 11/11/19

☐

: Final Report

Data/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Report Format:

MER-00/TL/E

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Apr 2019 17:42 Sendback Est	08 Apr 2019 17:43 S\$0.00	09 Apr 2019 09:56 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TAN CHU HIANG, ID: S1646971H, Tel: +6596319019		
Vehicle Reg. No.:	SLK2996M	Date of Loss:	07/04/2019 12:00 - :59 [76 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	PNPV2019-00000119 (Comprehensive)
		Excess:	
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/04/2019]		
Driver/Custodian:	TAN-MIN (CHEN MIN) (24 / Female), NRIC: S9422348B, Tel: +6591828859 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 10 Apr 2019

Preliminary Advice

Vehicle No	: SLK2996M	Accident Date	: 07/04/2019
Make	: MERCEDES-BENZ E250	Policy No.	: PNPV2019-00000119
Assignment Date	: 09/04/2019	Excess	: S\$3,300.00
Date of Inspection	: 09/04/2019	Est. Duration of Repair	: 0.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	67,123.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,877.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/04/2019 17:01
Date Of Accident	07/04/2019 12:15
Exact Location Of Accident	BUKIT CHERMIN RD / TELOK BLANGAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK2996M
Insured/Policyholder	
Name Of Registered Owner	TAN CHU HIANG
NRIC No	S1646971H
Email Address	OO32866@YMAIL.COM
Mobile Phone No	(LOCAL) +65-96319019
Alternative Phone No	OTHERS-91828859

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00000119
Cover Note Number	13/01/2019 - 12/01/2019

Driver

Name of Driver	TAN-MIN (CHEN MIN)
NRIC No	S9422348B
Date Of Birth	27/06/1994
Occupation	INDOOR
Date Of Driving Pass	30/09/2014
Driving Experience	4 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91828859
Fax Number	
Contact Number	OTHERS-96319019
EMail Address	NOEMAIL

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


DETAILS OF INJURED PERSON 1

Name	TAN-MIN
Approximate Age	
Injuries Sustain	LEFT KNEE
Injured person in which vehicle?	SLK2996M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 2

Date of accident: 7 April 2019 Time: About 12-1pm Location: Bukit Chini Road / Teluk Bimbang Road
My Vehicle A: SLK 2996M Vehicle B: SHC1028D Vehicle C: NA

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

7 April 2019 . about 12-15 pm.

I was driving vehicle SLK ~~299~~ 2976M turning from Teluk Bagan Road to Bukit Chermin Road, when my vehicle was rammed by Comfort Delgro taxi SHC 1028D from the left. I was in the traffic junction box slowly moving towards Bukit Chermin Road when the accident happened. At the junction box, 3 lanes of vehicles had stopped for me to proceed with my turn. As I was blocked by the 3 lanes of vehicles, I moved slowly further into the junction box to get a view of traffic coming from the left in the last lane of the 4 lanes. As my vehicle moved forward, the Comfort taxi speeding along the last lane, rammed into the forward left front of my vehicle. The impact pushed both vehicles across the road and the taxi onto the pedestrian walkway. The occupants in my vehicle, including my parents and myself, sustained minor injuries.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Center Personnel's Signature
Name:
NRIC/FIN No.:





YOUR CLASSIC CAR INSURANCE SUMMARY

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.
All accidents must be reported within 24 hours or the next working day of the incident
regardless of whether it will lead to a claim.

POLICY NUMBER : PNPV2019-00000119

About this policy

Premium paid	: S\$789.38	Coverage start date	: 13/01/2019
(Inclusive of GST)		Coverage end date	: 12/01/2020
Who is insured to drive:	: You and any Authorised Driver		
Policy Type	: CLASSIC		

About you (As the policyholder)

Your name	: Tan Chu Hiang		
Address	: 76 Tai Hwan Heights Tai Hwan Garden Singapore 555421		
Email	: oo32866@ymail.com		
NRIC/FIN	: S1646971H	Date of birth	: 21/11/1964
Marital status	: Married	Gender	: Male
Current no claims discount	: 50%	Mobile Number	: 96319019
Years of driving experience	: Three or more	Certificate of merit	: No

About your car

Car make and model	: MERCEDES BENZ E250 1.8
Year of first registration	: 2012
Car plate number	: SLK2996M
Issued on:	: 17/11/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please refer to contract for specific terms, conditions and exclusions of this policy.

Please immediately inform us at +65-6820-8888 or email us to contact.sg@fwd.com if any details in this Car Insurance Summary need to be changed.

Sketch Plan Pg. 6

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9422348B



Name

TAN-MIN
(CHEN MIN)

陈敏

Race

CHINESE

Date of birth

27-06-1994

Sex

F

Country of birth

SINGAPORE

S9422348B

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S9422348B

Name:

TAN-MIN
(CHEN MIN)

Birth Date: 27 Jun 1994

Valid Date: 30 Sep 2014



Q132959.

Dlc

Injury - driver left knee
NO camera

3pts.

Tan Chu Heng (Father)
Koh Ai Kim (Mother)



4378071

NRIC No: S9422348B



Date of issue

07-01-2009

Address

76 TAI HWAN HEIGHTS
SINGAPORE 555421

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 30 Sep 2014



License No: S9422348B

NP 428A

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

6971H

Vehicle Details

Vehicle No.:

SLK2996M

Vehicle to be Exported:

No

Intended Deregistration Date:

08 Apr 2019

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

E250 A

Primary Colour:

White

Manufacturing Year:

2012

Engine No.:

27186030468472

Chassis No.:

WDD2120472A619466

Maximum Power Output:

150.0 kW (201 bhp)

Open Market Value:

\$51,983.00

Original Registration Date:

22 Nov 2012

First Registration Date:

22 Nov 2012

Transfer Count:

1

Actual ARF Paid:

\$51,983.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

21 Nov 2022

PARF Rebate Amount:

\$33,788.00

Intended COE Rebate Details

COE Expiry Date:

21 Nov 2022

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$92,100.00

COE Rebate Amount:

\$33,335.00

Total Rebate Amount:

\$67,123.00

The information contained herein is correct as at 08 Apr 2019

OK

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg

GST Reg No: M9-0009639-E

INSURER: FWD Singapore Pte. Ltd. (HQ)

SURVEYOR COPY

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2019-00000119	Date of Loss:	07/04/2019
Vehicle Reg. No.:	SLK2996M	Driveable?	
Driver Age/Info:	24 / FEMALE LK	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	TAN CHU HIANG	Contact No:	+6596319019
Driver:	TAN-MIN (CHEN MIN)		
Make/Model:	MERCEDES-BENZ E250, 1.8 (A)	Vehicle Reg. Date:	22/11/2012
Vehicle Colour:	WHITE		
Engine No:	27186030468472	Chassis No:	WDD2120472A619466
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR TOW IN @ ALM AMK AUTOPOINT WORKSHOP		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

Not Authorised
Loss

9/4/19

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (\$\$)	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification of car
- Supplemental report must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Apr 2019)
Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Ah Lim Motor Company/SLK2996M/08/04/2019 17:43
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

Ah Lim Motor Company/SLK2996M/08/04/2019 17:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Ah Lim Motor Company/SLK2996M/08/04/2019 17:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

AH LIM MOTOR COMPANY

NO 10, ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT SINGAPORE 568047
TEL: 6483 1244 FAX: 64836170
GST REG NO: M9-000773-A

SURVEYOR COPY

Your Ref:

Date: 08/04/2019

Our Ref: VEHICLE NO. SLK2996M
MODEL: MERCEDES BENZ E250 A

M/S FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-04 SUNTEC TOWER FOUR
SINGAPORE 038986

ATTENTION: MOTOR CLAIMS DEPARTMENT
OWN DAMAGE

Dear Sirs

Accident involving Your Insured Vehicle No SLK2996M accident on 07/04/2019

We refer to the above matter.

Vehicle sustained extensive damage & car was registered in 22 Nov 2012.

We are not putting up the estimate for the time being & kindly arrange for survey soonest possible. After the survey if there is a need, we will furnish the estimate accordingly.

Thank You.
Yours faithfully,



Zila
Ah Lim Motor Company

AH LIM MOTOR COMPANY

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	08 Apr 2019	08 Apr 2019 17:43 S\$0.00	09 Apr 2019 09:56 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt	Pending for Survey Report

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TAN CHU HIANG, ID: S1646971H, Tel: +6596319019		
Vehicle Reg. No.:	SLK2996M	Date of Loss:	07/04/2019 12:00 - :59 [76 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900009257	Policy/Cover Note No.:	PNPV2019-00000119 (Comprehensive)
		Excess:	S\$3,300.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/04/2019]		
Driver/Custodian:	TAN-MIN (CHEN MIN) (24 / Female) , NRIC: S9422348B, Tel: +6591828859 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (10/04/2019): Alert - Adj Mandate Revoked - SLK2996M - Claim Handler: Clara Li Zi Rong

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLK2996M (1201900009257)

OD

Apr 7 2019 12:00PM

[TAN CHU HIANG]

Ah Lim Motor Company

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	08/04/19 17:43	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/04/19 15:27	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/04/19 15:20	General View	Load JPG	☒
2	10/04/19 15:20	General View	Load JPG	☒
3	10/04/19 15:20	General View	Load JPG	☒
4	10/04/19 15:20	General View	Load JPG	☒
5	10/04/19 15:20	General View	Load JPG	☒
6	10/04/19 15:20	General View	Load JPG	☒
7	10/04/19 15:20	General View	Load JPG	☒
8	10/04/19 15:20	General View	Load JPG	☒
9	10/04/19 15:20	General View	Load JPG	☒
10	10/04/19 15:20	General View	Load JPG	☒
11	10/04/19 15:20	General View	Load JPG	☒
12	10/04/19 15:20	General View	Load JPG	☒
13	10/04/19 15:20	General View	Load JPG	☒
14	10/04/19 15:20	General View	Load JPG	☒
15	10/04/19 15:20	General View	Load JPG	☒
16	10/04/19 15:20	General View	Load JPG	☒
17	10/04/19 15:20	General View	Load JPG	☒
18	10/04/19 15:20	General View	Load JPG	☒
19	10/04/19 15:20	General View	Load JPG	☒
20	10/04/19 15:20	General View	Load JPG	☒
21	10/04/19 15:20	General View	Load JPG	☒
22	10/04/19 15:20	Chassis Number	Load JPG	☒
23	10/04/19 15:20	General View	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/04/19 15:22	Log card (if available)	Load PDF	

Linked Accident Report Documents

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	☒
--------------------	--	--	------------	-------------------------------------

Assessment Reports		Ah Lim Motor Company (AMK)	1 per page	Thumbnail	Print
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	08/04/19 17:20	Accident Statement	1	Load HTM	
Photos/Images			3 per page		☒
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	08/04/19 17:19	Accident Photo	1	Load JPG	☒
2	08/04/19 17:19	Accident Photo	1	Load JPG	☒
3	08/04/19 17:19	Accident Photo	1	Load JPG	☒
4	08/04/19 17:19	Accident Photo	1	Load JPG	☒
5	08/04/19 17:19	Accident Photo	1	Load JPG	☒
6	08/04/19 17:19	Accident Photo	1	Load JPG	☒
7	08/04/19 17:19	Accident Photo	1	Load JPG	☒
8	08/04/19 17:19	Accident Photo	1	Load JPG	☒
9	08/04/19 17:19	Accident Photo	1	Load JPG	☒
10	08/04/19 17:19	Accident Photo	1	Load JPG	☒
11	08/04/19 17:19	Driving License	1	Load JPG	☒
12	08/04/19 17:19	Accident Photo	1	Load JPG	☒
13	08/04/19 17:19	Accident Photo	1	Load JPG	☒
14	08/04/19 17:19	Accident Photo	1	Load JPG	☒
15	08/04/19 17:19	Accident Photo	1	Load JPG	☒
16	08/04/19 17:19	Accident Photo	1	Load JPG	☒
17	08/04/19 17:19	Accident Photo	1	Load JPG	☒
18	08/04/19 17:19	Accident Photo	1	Load JPG	☒
19	08/04/19 17:19	Accident Photo	1	Load JPG	☒
20	08/04/19 17:19	Accident Photo	1	Load JPG	☒
21	08/04/19 17:19	Accident Photo	1	Load JPG	☒
22	08/04/19 17:19	Accident Photo	1	Load JPG	☒
23	08/04/19 17:19	Accident Photo	1	Load JPG	☒
24	08/04/19 17:19	Driving License	1	Load JPG	☒
Documentation			1 per page		☒
No	Finalized On	Ah Lim Motor Company (AMK)		Thumbnail	Print
1	08/04/19 17:20	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19006269/KQD3S2

Date: 11/04/2019

REFERENCE

Insured/Claimant: TAN CHU HIANG Policy No: PNPV2019-00000119
Date of Loss: 07/04/2019 Nature of Claim: OD Claim No: 1201900009257

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK2996M**
Make & Model: MERCEDES-BENZ E250, 1.8 (A) Engine No: 27186030468472
Reg. Date: 22/11/2012 (Man. Year: 2012) Chassis No: WDD2120472A619466
Colour: Metallic Pearl White Odometer: 0 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$79,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Falken 4 mm Rear Left Side: Hankook 7 mm
Front Right Side: Falken 4 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	3,300.00	-3,300.00	
(S\$)	0.00	-3,300.00	3,300.00	
+ GST 7.00/7.00% (S\$)	0.00	-231.00	231.00	
Nett Amount (S\$)	0.00	-3,531.00	3,531.00	

INSPECTION

Date of Assignment: 09/04/2019 Present Location: Ah Lim Motor Company (AMK)
Ah Lim Motor Company (AMK)
Date Inspected: 09/04/2019 Inspected At: 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
Autopoint
Singapore 568047
Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$79,000.00
OMV :	\$51,983.00
PARF Rebate (1) :	\$33,788.00
Quota Premium Paid :	\$92,100.00
COE Rebate (2) :	\$33,335.00
Total Rebate (1) + (2) = :	\$67,123.00

The total amount incurred will be Market Value \$79,000.00 minus Total Rebate \$67,123.00 = \$11,877.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2019)

Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK2996M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >