

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

ASSIGNMENT

REP

CS3/AIG19006276/Ecd3er

Special Instruction

ASSIGNMENT (Office)

of

AIG

Date/Time

9/4/19 @ 11:43am

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

FBE 7203K

Insured

SCF 3438J

at Workshop m/o

Motoplex

Tel.

of

10 kaki Bukit Rd 3 # 01-24

Policy No

Claim No

Sum Insured

Excess

Make of Veh

D.O.A

27/03/2019

(Client's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time

12:37pm @ 9/4/19

Person Contacted

Donald

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

FBE 7203K-X

SCF 3438J - NBA / NOI 16068174 / Y

D.O.A 3/5/2016

Dismantle: 11/4/2019

After repair: 16/4/2019

Vehicle

Steve

REF:

ASSIGNMENT

From
Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

at Workshop m/s

of

Insured

Policy No

Claims No

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time : Action / Instruction

Veh No **FBE 7203K**

Yr Regn. **Aug 10**

Type: M.Car / **M.Cycle** / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Suzuki Hayabusa**

CC **1340**

Colour **White**

A/C Insured / Std / NI / NA

Sp.Reading **58880**

T/Radio: Insured / Std / NI / NA

Eng/No:

CtNo: **JSICK 111100107805**

Gen. Cond: Good **Fair** / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: **Nil** / S(Rim) / STD A/Rim or

Tyre Size: F:

120/702R17

R:

190/552R17

BS / DUN / EXNOVA / GY / FS / LIZA **MIC** / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **7** mm

R/Bal. **7** mm

L/Bal. mm

L/Bal. mm

D.O.A.


D.O.A. **9/4/19**

Survey held at

Motorplex, Ubi Rd 2 First East Centre

Des. of Damages: Frt **Rear** O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Days: 2 days

RECEIVED 17 APR 2019

Date/Time, File Pass to?

☐

: Proll. Report

4)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: **2**

Resurvey No. of Trip: **2**

Survey Fee:

Transportation

) S + R + CI

) Photos

) Other

)

FOOT

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Report Format: **DAR**

Lump Sum / I.B.I. (\$

180

10

190

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 9/4/2019 11:43:36 AM
Attachments:  19.0428 PR.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Monday, April 08, 2019 4:22 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur

Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SCF3438J AND FBE7203K ON 27/03/2019 // Our ref: L.19.0428.It(jt)

Caution: External Email

Dear Sirs,

We confirm that you have **objected** to our client's list of surveyors. Our client's vehicle is at the following address:

M/s Motoplex Pte Ltd

10 Kaki Bukit Road 2

#01-24 First East Centre

Singapore 417868

Tel: 67476774

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBE7203K		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	SUZUKI		
Vehicle Model :	GSX1300RLO		
Chassis No. :	JS1CK111100107805		
Propellant :	Petrol		
Engine No. :	X704131309		
Engine Capacity :	1340 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	-		
Unladen Weight :	220 kg		
Year Of Manufacture :	2010		
Original Registration Date :	06 Aug 2010		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,301.00		
COE Expiry Date :	05 Aug 2020		
Road Tax Expiry Date :	05 Aug 2019		
Inspection Due Date :	05 Aug 2019		
Intended Transfer Date :	17 Apr 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1382I
Vehicle Details	
Vehicle No.:	FBE7203K
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Apr 2019
Vehicle Make:	SUZUKI
Vehicle Model:	GSX1300RL0
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	X704131309
Chassis No.:	JS1CK111100107805
Maximum Power Output:	-
Open Market Value:	\$16,558.00
Original Registration Date:	06 Aug 2010
First Registration Date:	06 Aug 2010
Transfer Count:	3
Actual ARF Paid:	\$2,484.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Aug 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,301.00
COE Rebate Amount:	\$169.00
Total Rebate Amount:	\$169.00

The information contained herein is correct as at 17 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/03/2019 16:23
Date Of Accident	27/03/2019 21:30
Exact Location Of Accident	JURONG TOWN HALL RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBE7203K
Insured/Policyholder	
Name Of Registered Owner	TAN LIAN ZHEN
NRIC No	S8811382I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91076837
Alternative Phone No	OFFICE-91076837
Vehicle Particulars	
Manufacturer	SUZUKI
Model	GSX1300
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	PNMC2019-00000668
Cover Note Number	
Driver	
Name of Driver	TAN LIAN ZHEN
NRIC No	S8811382I
Date Of Birth	12/04/1988
Occupation	INDOOR
Date Of Driving Pass	06/10/2009
Driving Experience	9 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91076837
Fax Number	
Contact Number	OFFICE-91076837
EEmail Address	NOEMAIL

Address	BLK 330 JURONG EAST AVE 1 #05-1708
Postcode	600330
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCF3438J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JEFFREY TAN YONG HENG
NRIC/Passport Number	S7225524J
Contact Number	97959809
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Refer to police report

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

→ PIE change

Traffic junction
Turn right on green





CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Motorcycle breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNMC2019-00000668

Plan Name: Third Party Fire & Theft

Motorcycle plate number: FBE7203K

Your name (As the policyholder): Tan Lian Zhen

Coverage start date: 06/02/2019

Coverage end date: 05/02/2020

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is Insured to ride: You Only

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Motorcycle Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Motorcycle understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Motorcycle is being used for personal use in accordance with Your contract.

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 26/01/2019

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

IDENTITY CARD NO. S88113821



nama

TAN LIAN ZHEN

陳 联 禎

Race

CHINESE

Date of birth

12-04-1988

Sex

M

Country of birth

SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S88113821

Name:

TAN LIAN ZHEN

Birth Date: 12 Apr 1988

Issue Date: 28 Apr 2008



NRIC No. S88113821



Date of issue

28-04-2008

Address

APT BLK 330 JURONG EAST AVENUE 1
#05-1708
SINGAPORE 600330

4219528

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(E)


PASS DATE

Class 3B	Motorcycles <= 300 CC	12 Nov 2007
Class 2A	Motorcycles between 301 CC and 400 CC	06 Oct 2009
Class 2	Motorcycles > 400 CC	18 Jul 2011
Class 3	Motor cars <= 3000 kg with <= 7 passengers, exclusive of the delivery and motor traders/vehicles <= 2500 kg	13 Mar 2018

S / No. 9000313341

S88113821

Licence No: S88113821



NP 428A

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190328/7013

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190328/7013

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/03/2019 14:38		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN LIAN ZHEN			Address: APT BLK 330 JURONG EAST AVENUE 1 #05-1708 SINGAPORE 600330		
ID Type / ID No.: NRIC NO / S88113821			Contact No.: Home/Office: Mobile: 91076837		
Nationality: SINGAPORE CITIZEN			Email: lianzhen88@hotmail.com		
Sex: Male	Age: 30	Date of Birth: 12/04/1988	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Others			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 27/03/2019 21:30	Type of Location: Traffic light
Location: JURONG TOWN HALL ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 50 Km/h
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBE7203K	Motorcycle	SUZUKI	GSX1300RL 0	White		0
SCF3438J	Car			Silver	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBE7203K	FWD Singapore Pte. Ltd	PNMC2019- 00000688	06/02/2019	05/02/2020

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190328/7013

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20190328/7013

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TAN LIAN ZHEN	ID No.	S8811382I
Related Vehicle	FBE7203K (Motorcycle)	Contact No.	91076837
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	27/03/2019	Date Discharge	28/03/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	Jeffrey Tan Yong Heng	ID No.	S7225524J
Related Vehicle	SCF3438J (Car)	Contact No.	97959809
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I, vehicle No. FBE7203K, was at the traffic light waiting to turn right with 2 cars ahead of me with right signal on. When the "turn right on green" arrow lighted from red to green, the car, vehicle No. SCF3438J, behind me knocked onto the rear of my motorcycle immediately. The cars in front of me have not moved off yet. My motorcycle was damaged. TP arrived on site. Driving particulars were exchanged. I have sought medical attention at Ng Teng Fong Hospital myself after the incident and given 5 days of MC.

Videos/pictures exceeding 2MB: YES

Any landmarks (e.g. opposite CPF building)?: NO

Location: Jurong Town Hall Road before turning into PIE towards Changi.

Did the accident take place at a pedestrian crossing?: NO



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190328/7013

3 of 3

Report No. T/20190328/7013

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 28/03/2019 14:38
Officer In Charge Of Case: TP / TPHQ / MUHAMMAD KHAIRIL BIN KAMAL Contact No.: 65476131	Classification Of Case:
Authentication Stamp NP168	

Motorcycle

Vehicle No: FRE 7293 K

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard			
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror			
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
3023	991019	ERP Bracket			
3024	991020	ERP Unit			
3025	992446	Ignition Switch			
3026	992442	Ignition Key Assy			
3027	990706	Cowling Stay			
3028	994470	Steering Stem			
3029	994427	Steering Cone			
3030	992299	Handle Bar			
3031	992312	Handle Bar Switch			
3032	992310	Handle Bar Grip			
3033	995184	Handle Bar Balancer LH			
3034	992300	Handle Bar Balancer RH			
3035	992179	Fuel Tank			
3036	990438	Brake Reservoir			
3037	990621	Clutch Lever			
3038	992293	Hand Brake Lever			
3039	991119	Side Fairing			
3040	994220	Side Fairing Top Garnish			
3041	994219	Side Fairing Inner Garnish			
3042	991118	Fairing Shield			
3043	992047	Front Top Fairing Inner Garnish			
3044	991123	Fairing Top Garnish			
3045	990538	Center Fairing			
	993378	Rear Fairing			
	991121	Fairing Stopper			
	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1057	990219	Battery			
1058	990224	Battery Cover			
1059	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest			
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield			
3061	991058	Exhaust Muffler Assy			
1405	993719	Rear LH Shock Absorber			
1415	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard	CRU	✓	
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1422	993626	Rear Number Plate	BT	✓	
3076	994192	Side Box			
3077	992927	Rear Box			
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1436	990247	Sticker			

No of Items:

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Apr 2019 09:44 Edit Reg		09 Apr 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

CHUA MONG HENG, ID: S6843016Z

Main Claimant:

UNKNOWN

Vehicle Reg. No.:

FBE7203K

Claim Type:

TP / 9048655895SG

Vehicle Reg. No. (Insured):

SCF3438J

Repairster:

Motoplex Pte Ltd (HQ) 10 KAKI BUKIT ROAD 2, # 01-24 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel: 67476774

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 18/04/2019]

Claimant's Solicitor:

KURU & CO - Tel: 65322009

Date of Loss:

27/03/2019 00:00 - :59
[103 Months and 21 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

(Comprehensive)

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (10/04/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)






Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBE7203K (9048655895SG)
[SCF3438J]**

**TP
UNKNOWN
Mar 27 2019 12:00AM
[CHUA MONG HENG]
Motoplex Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			▼		
Photos/Images															3 per page			▼			☑		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print						
1	17/04/19 09:57	General View													1	Load JPG	☑						
2	17/04/19 09:57	General View													1	Load JPG	☑						
3	17/04/19 09:57	General View													1	Load JPG	☑						
4	17/04/19 09:57	General View													1	Load JPG	☑						
5	17/04/19 09:57	General View													1	Load JPG	☑						
6	17/04/19 09:57	General View													1	Load JPG	☑						
7	17/04/19 09:57	General View													1	Load JPG	☑						
8	17/04/19 09:57	General View													1	Load JPG	☑						
9	17/04/19 09:57	General View													1	Load JPG	☑						
10	17/04/19 09:57	General View													1	Load JPG	☑						
11	17/04/19 09:57	General View													1	Load JPG	☑						
12	17/04/19 09:57	General View													1	Load JPG	☑						
13	17/04/19 09:57	General View													1	Load JPG	☑						
14	17/04/19 09:57	General View													1	Load JPG	☑						
15	17/04/19 09:57	General View													1	Load JPG	☑						
16	17/04/19 09:57	General View													1	Load JPG	☑						
17	17/04/19 09:57	General View													1	Load JPG	☑						
18	17/04/19 09:57	General View													1	Load JPG	☑						
19	17/04/19 09:57	General View													1	Load JPG	☑						
20	17/04/19 09:57	General View													1	Load JPG	☑						
21	17/04/19 09:57	General View													1	Load JPG	☑						
22	17/04/19 09:57	General View													1	Load JPG	☑						
23	17/04/19 09:57	General View													1	Load JPG	☑						
24	17/04/19 09:57	General View													1	Load JPG	☑						
25	17/04/19 09:57	General View													1	Load JPG	☑						
26	17/04/19 09:57	General View													1	Load JPG	☑						
27	17/04/19 09:57	General View													1	Load JPG	☑						
28	17/04/19 09:57	General View													1	Load JPG	☑						
29	17/04/19 09:57	Photographs of Damaged Parts													1	Load JPG	☑						
30	17/04/19 09:57	Photographs of Damaged Parts													1	Load JPG	☑						
31	17/04/19 09:57	Photographs of Damaged Parts													1	Load JPG	☑						
32	17/04/19 09:57	Photographs of Damaged Parts													1	Load JPG	☑						
33	17/04/19 09:57	Photographs of Damaged Parts													1	Load JPG	☑						
34	17/04/19 09:57	Photographs of Damaged Parts													1	Load JPG	☑						
35	17/04/19 09:57	Photographs of Damaged Parts													1	Load JPG	☑						
36	17/04/19 09:57	Photographs of Damaged Parts													1	Load JPG	☑						
37	17/04/19 09:57	Photographs of Damaged Parts													1	Load JPG	☑						

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/04/19 09:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	17/04/19 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/04/19 10:14	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19006276/ECD3E2

Date: 25/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBE7203K

Insured Vehicle No : SCF3438J

Date of Loss: 27/03/2019

Nature of Claim: TP

Claim No: 9048655895SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBE7203K

Make & Model: SUZUKI GSX1300RLO, 1.3

Engine No: X704131309

Reg. Date: 06/08/2010 (Man. Year: 2010)

Chassis No: JS1CK111100107805

Colour: White

Odometer: 58880 km

Engine Capacity: 1340 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17

Rear Tyre Size: 190/55Z R17

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/04/2019

Date Inspected: 09/04/2019 Inspected At:

Motoplex Pte Ltd (HQ)
10 KAKI BUKIT ROAD 2, # 01-24 FIRST
EAST CENTRE
Singapore 417868

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER WHEEL GUARD	Crushed	0.00 F	*- F
2	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >