

22/03/2002

ASS. REC. BY:

REF: (S/CTI 19006281 / Eq d301) Special Instruction:

Surveyor: STVR
MurienASSIGNMENT (Office)From (Person): Elaine Cheong of CTI Date/Time: 8.4.19 15.42pm

Estimated Cost: _____ Bill to: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLV 7032D Insured: GBC 355Lat Workshop m/s Bornio motor Tel: 93366875of 2 Pandan CrescentPolicy No: DMCVSN3045971800 Claim No: SNM 19D 201343 C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19.3.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 9.4.19 9.58am Person Contacted: Shashi Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 7032D - X
	GBC 355L - (S/AIG/6004090/TIV bc2) D.O.A. - 10/8/2019
<u>25/4/19 @ 2.07pm</u>	<u>confirmed with Shashi for final fig @ 7268.80, 7 days.</u>
	<u>Check @ 5718.30, 4477</u>

3. MYCALLID *Steve*


REF:

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured _____
 Policy No. _____
 Claims No _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *7* days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No *SLV 70320* Yt Regn. *11/1/18*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: *Toyota Wish* C.C. *1798*
 Colour *Grey* A/C Insured / Std / NI / NA
 Sp. Reading *22419* T/Rdnr: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *JT066 20W 30J00 8632*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rlm / STD A/Rlm or
 Tyre Size: F: *195/65R15*
 R: _____
 BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. *7* mm R/Bal. *7* mm
 L/Bal. *7* mm L/Bal. *7* mm
 D.O.A. *19/3/19* D.O.I. *16/4/19*
 Survey held at *Borneo*
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

RECEIVED 2-5-APR 2019

Date/Time, File Pass to?

4) *7/4/19* *Steve*

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) *7768.80*

☐ : Procl. Report
☐ : Final Report

Days Of Repair: *7*

Resurvey No. of Trip: *2*

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation

) \$ - R.S. 31

) Photos

) Other

70320

220
220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2019		08 Apr 2019 15:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:																								
Main Claimant:		HO CHENG MUN, EUGENE, ID: S8422602E																						
Vehicle Reg. No.:		SLV7032D	Date of Loss:	19/03/2019 12:00 - :59																				
Claim Type:		TP / SNM19D201343C02	Policy/Cover Note No.:	DMCVSN3045971800																				
Vehicle Reg. No. (Insured):		GBC355L	Policy No. (Claimant):	VA1/GA312526																				
			Excess:	S\$500.00																				
Repairer:		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857																						
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]																						
Claimant's Insurer:		AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288																						
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/04/2019]																						
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
<div> </div> ALL ASSOCIATED TASKS <div> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Monday, 8 April 2019 3:39 PM
To: Suraidah B Saidi PTCBC; 'assignments'
Subject: FW: OUR REF: SNM19D2001343C02-5 - GBC355L - Direct Settlement (ST) - Accident Involving SLV7032D & GBC355L DOA 19.03.2019
Attachments: SLV7032D_Video - Accident.MP4; SLV7032D_GIA Rpt_Damaged Photos.pdf; SLV7032D_Est Inv.pdf

WITHOUT PREJUDICE

Dear Suraidah,

We refer to your email of 03.04.19.

We propose direct settlement subject to the following:-

- Consistency of damages
- LKK Auto's recommendation / findings
- Quantum to be agreed
- Provide supporting documents

Aside to LKK,

Please refer to the email below and liaise with the third party workshop on the survey.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Angie Foo
Sent: Wednesday, 3 April, 2019 3:37 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; SuraidahB.Saidi@inchcape.com.sg
Subject: OUR REF: SNM19D2001343- GBC355L - Direct Settlement (ST) - Accident Involving SLV7032D & GBC355L DOA 19.03.2019

Dear Elaine,

Please conduct PRS –SLV7032D urgently –(SNM19D201343- GBC355L –FILE WILL PASS TO ELAINE)

Officer In Charge –Elaine Cheong –DID 6389 6530.

Regards
Angie Foo

From: Suraidah B Saidi PTCBC [<mailto:SuraidahB.Saidi@inchcape.com.sg>]
Sent: Wednesday, April 03, 2019 3:25 PM
To: Angie Foo
Subject: FW: Direct Settlement (ST) - Accident Involving SLV7032D & GBC355L DOA 19.03.2019

From: Suraidah B Saidi PTCBC
Sent: Wednesday, 3 April 2019 3:23 PM
To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>
Subject: FW: Direct Settlement (ST) - Accident Involving SLV7032D & GBC355L DOA 19.03.2019

resend

Warmest Regards,
SURAIDAH
TPR TEAM, CLAIMS DEPT
D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg
Inchcape Centre
Level 4, Bodycare Centre
2 Pandan Crescent
Singapore 128462
www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

From: Suraidah B Saidi PTCBC
Sent: Thursday, 21 March 2019 9:14 AM
To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>
Subject: Direct Settlement (ST) - Accident Involving SLV7032D & GBC355L DOA 19.03.2019

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured GBC355L thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$130 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Shashi @ 9336 6875 / 6631 1864** located at **2 Pandan Crescent – Level 4** for an appointment to inspect our client's vehicle soonest.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you

Warmest Regards,
SURAIDAH
TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 25 April 2019 2:02 PM
To: Shashi PTCBC; SUR
Subject: RE: SLV7032D FINAL BILL

Dear Shashi,

WITHOUT PREJUDICE

Confirm final fig \$7,268.80 before GST and 7 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shashi PTCBC <Shashitharan@borneomotors.com.sg>
Sent: Thursday, 25 April 2019 9:00 AM
To: SUR <sur@lkkauto.com>
Subject: FW: SLV7032D FINAL BILL

-----Original Message-----

From: Shashitharan@borneomotors.com.sg [<mailto:Shashitharan@borneomotors.com.sg>]
Sent: Thursday, April 25, 2019 8:07 AM
To: Shashi PTCBC
Subject: SLV7032D FINAL BILL

Sent by: [Shashitharan@borneomotors.com.sg]

Number of Images: 2

Attachment File Type: PDF

Device Name: ApeosPort-VI C3371

Device Location:

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2602E
Vehicle Details	
Vehicle No.:	SLV7032D
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2ZR0A46070
Chassis No.:	JTDGG20W30J008632
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	11 Jan 2018
First Registration Date:	11 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2028
PARF Rebate Amount:	\$14,966.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$39,554.00
Total Rebate Amount:	\$54,520.00

The information contained herein is correct as at 16 Apr 2019

OK

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA: Shashi

MOTOR ACCIDENT REPORT

Date Of Report: 20 Mar 19 Time: 1050 Date Of Accident: 19 Mar 19 Time: 1205
Exact Location Of Accident: Slip Road at the junction of Jln Besar Road & Boon Lay Way
Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SLV7032D Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: S8422602E
Name Of Registered Owner: Ho Cheng Mun Eugene
Mobile Number: 91838622 Alternative No: Email Address: EugeneHo84@gmail.com

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: 1.8L Wish
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒
Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: AXA
Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: GA312526

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: Ho Cheng Mun Eugene NRIC/Passport / FIN No: S8422602E
Date Of Birth: 30/07/1984 Occupation: Indoor ☒ Outdoor ☐
Date Of Driving Pass: 05/04/2007 Gender: Male ☒ Female ☐
Mobile Number: 91838622 Fax No: Alternative No:
Address: Blk 574 Hougang St 51 #11-01 Postal Code: 530574
Email Address: EugeneHo84@gmail.com
Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured:

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Rear collision
Number of Passengers in the above vehicle (Including Driver): 5 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Ho Cheng Mun Eugene Gender: Male ☒ Female ☐
Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):
Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):
Was any body injured in the Accident? No ☒ Yes ☐
Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐
Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
Number of vehicles involved in the accident: 2
Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below
Witness Name: | Contact No.: | Email:
Was there any other vehicle or property damaged? No ☐ Yes ☒
Was there any video captured by Car Camera? No ☐ Yes ☒ Are accident scene photos available for attachment? No ☐ Yes ☒
Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: GBC355L Vehicle Make/Model/Colour: Hyundai
Details Of Properties Damage in Accident:
Vehicle Category: Goods Van
Name of Driver: Muhammad Nurafiyah Bin Mohamed Sani
NRIC/Passport/FIN Number: S9306974I Contact Number: 87421464
Address: Postal Code:
Insurance Company Name:
Nature Of Damage: No. Of Passenger (Including Driver):

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was on the way to JEM with my family for lunch. Was travelling northeast towards ~~to~~ along Toh Guan Road and made a left turn ~~is~~ into the slip road at the junction of Toh Guan Road and Boon Lay Way. Was waiting at the slip road for traffic to clear before the left turn to Boon Lay Way. At about 1205pm there was ~~and~~ a sudden impact to the rear of my car. The vehicle that hit my car was a Yellow DHL delivery van (GA312526) driven by ~~the~~ Mr Muhammad Nurafyan Bin Mohamed Sami. He acknowledged that it was his mistake and explained that his vehicle jerked ~~to~~ forward as he was releasing his clutch. We subsequently took ~~p~~ pictures of the vehicle damages and exchanged contact detail.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

00000050212202

NRIC No / Colour
S8422602E / PINK

Race
CHINESE

Date Of Birth
30/07/1984

Service Status
REGULAR


Address
**Blk 574 HOUGANG STREET 51
#11-01 SINGAPORE 530574**

Blood Group
O (+)

Country Of Birth
SINGAPORE

Military Rank Status
SENIOR MILITARY EXPERT

Sex
M




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)


PASS DATE

Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg 05 Apr 2007

NP 428A


Licence No: S8422602E



 **SINGAPORE ARMED FORCES**
IDENTITY CARD

Name
**HO CHENG MUN,
EUGENE**

NRIC No
S8422602E



This card is the property of the Singapore Armed Forces. Any person finding this card is requested to forward it without delay to Central Mailroom Base or any Police Station.

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number **S8422602E**

Name
HO CHENG MUN, EUGENE

Birth Date **30 Jul 1984**

Issue Date **05 Apr 2007**





redefining / insurance

AXA Insurance Pte Ltd
☎ 1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
📠 (65) 6880 4740
✉ customer.care@axa.com.sg
🌐 www.axa.com.sg

date
16/01/2018

policy number
VA1 / GA312526

account number / sub-code
14885 / BSTL048

Certificate of Insurance

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189)-Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960-Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	HO CHENG MUN, EUGENE	Certificate number	GA312526 / 1
Cover	Comprehensive	Chassis number	JTDGG20W30J008632
Plan name	Toyota Prestige	Engine number	2ZR0A46070
NCD applicable	50%		
Vehicle registration number	SLV7032D		
Period of Insurance	from 11/01/2018 to 10/01/2020 (both dates inclusive)		
Finance loan company	HONG LEONG FINANCE LIMITED		

Authorized Drivers

- (a) The Policyholder
(b) Any Named Driver as stated in the Policy
(c) Any person who is driving on the Policyholder's order or with their permission
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

Limitation as to use*

- Use of the motor vehicle is connected to the Policyholder's business
- Use for the carriage of passengers (besides commercial hire or reward) in connection with the Policyholder's business
- Use for social, domestic, and personal purposes

The Policy does not cover:

- Use for commercial hire or reward, or for racing, pace-making, reliability trial, or speed testing
- Use while drawing a trailer, except for the towing of a disabled person's mechanically propelled vehicle

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 600.00
	Windscreen Excess	Not Applicable

Young/Inexperienced driver excess

An additional excess of \$2500 (to be added to any excess imposed under the Policy) whilst the Insured MotorCar is being driven by any driver aged below 23 years old and/or has been issued a valid driving license to drive in Singapore for the relevant class of vehicle for less than one year

Young and/or inexperienced driver shall mean any person who:

- Is less than 23 years old, and/or
- Has been issued with a valid driving license to drive in Singapore for the relevant class of vehicle for less than 1 year

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

AXA Insurance Pte Ltd

AXA Insurance Pte Ltd (199903512M)
8 Shenton Way, #24-01, AXA Tower,
Singapore 068811
Customer Centre, #B1-01



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sgCo Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Ho Cheng Mun Eugene 574 Hougang Street 51 #11-01 Singapore 530574 Mobile: 91838622
	Document No	
	Document Date	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	11/01/2018	SLV7032D	0	42725 :6TP/SLV7032D/20031!
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTDGG20W30J008632	2ZROA46070	60	Shashitharan	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH NO.:GBC355L ACC DATE:19/03/19 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 / 100.00
2	C	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				180.00
3	C	BP-LAB2 TRANSFER BOOT LID MECHAINS AND REVERSE CAMERA				540.00
4	C	BP-LAB2 R/I INTERIOR TRIMMING TO FAC REPAIR				360.00
5	C	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR				180.00
6	C	BP-WS2 R/I REAR WINDSCREEN				538.00
7	C	BP-LAB2 REPL ACC AFF PARTS AND PANEL 254 days - 729				3600.00
8	C	BP-RES2 STRAIGHTEN AND REALIGN ACC AFF AREA				1770 / 2950.00
9	1	T52155-68030 R/RR BUMPER SUPPORT, ALK	1.00	95.90		95.90
10	2	T52575-68020 R/R SIDE BPR RETAINER, ALK	1.00	45.30		45.30
11	3	T52159-68907 REAR BUMPER COVER, DR	1.00	584.70		584.70
12	4	S52161-OK040 PIECE, RR BUMPER ALK	4.00	4.00		16.00
13	5	T58307-68031 REAR LOWER FLR PANEL, R	1.00	529.60		529.60
14	6	T52181-68010 REAR BUMPER ARM, ? (RH)	1.00	53.10		53.10 / 106.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
Steve (LKK) 8322 8813	Please acknowledge receipt of vehicle w/ R/RR 16/4/19 1.45pm 5-6 days P/P	Parts Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3940048

3940048

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 20/03/2019
TIME 14:31

VEHICLE NO

SLV7032D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Tel no.: 6631 1188 Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Ho Cheng Mun Eugene 574 Hougang Street 51 #11-01 Singapore 530574 Mobile: 91838622
	Document No	
	0	
	Document Date	
	20/03/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	11/01/2018	SLV7032D	0	42725 :6TP/SLV7032D/20031!
Chassis No		Engine No	Terms		Service Engineer	Vehicle In	Collected On

JTDGG20W30J008632	2ZROA46070	60	Shashitharan	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	--------------	------------	------	------------	------

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
15	7	T68105-68071	REAR BACK DOOR GLASS, X	1.00	1029.40		1029.40X
16	8	T67881-68030	RR BACK DOOR W/STRIP, X	1.00	331.50		331.50✓
17	9	T67005-68041	PANEL ASSY, BACK DOOR X	1.00	1456.20		1456.20X
18	0	T90975-02086	TOYOTA SYMBOL EMBLEM, X	1.00	72.20		72.20✓
19	1	T75444-68010	LUGGAGE "VALVE MATIC " X	1.00	40.50		40.50✓
20	2	SPZ061-12010 24	1G3 SENSOR X	1.00	151.60		151.60X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
<hr/>	Please acknowledge receipt of vehicle <hr/>	Parts	12,907.10
		Labour 4,459.10	GST 7.00% 903.50
		Materials 8,448.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
		0.00	
		Amount Due	13,810.60

PLEASE TEAR ALONG PERFORATED LINE

3940049

TO SECURITY GUARD

3940049

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 20/03/2019
TIME 14:31

VEHICLE NO

SLV7032D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462

Tel no.: 6631 1188
Customer Detail

ESTIMATE

Account Detail	Account No	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	
	Document No	0
	Document Date	25/04/2019
		Mr Ho Cheng Mun Eugene 574 Hougang Street 51 #11-01 Singapore 530574 Mobile: 91838622

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP S6	ZGE20R	11/01/2018	SLV7032D	0	42725	6TP/SLV7032D/20031
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

JTDGG20W30J008632 2ZROA46070 60 Shashitharan 16/04/2019 8.00 24/04/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH NO.: GBC355L ACC DATE: 19/03/19 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: 7 days BY: STEVE LKK AUTHORIZED ON: 16/04/19				50.00
2	C	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST *				180.00
3	C	BP-LAB2 R/I INTERIOR TRIMMING TO FAC REPAIR *				360.00
4	C	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR *				180.00
5	C	BP-LAB2 REPL ACC AFF PARTS AND PANEL *				2880.00
6	C	BP-RES2 STRAIGHTEN AND REALIGN ACC AFF AREA *				1770.00
7	Z	BP-SLANT RESRPAY ACC AFF AREA				80.00
8	1	T52155-68030 SUPPLY SEALANT (NETT) END PANEL / NEC	1.00	95.90		95.90
9	2	T52575-68020 R/REAR BUMPER SUPPORT	1.00	45.30		45.30
10	3	T52159-68907 R/REAR BUMPER RETAINER	1.00	584.70		584.70
11	4	S52161-0K040 COVER RR BUMPER	4.00	4.00		16.00
12	5	T90975-02086 PIECE, RR BUMPER	1.00	72.20		72.20
13	6	T75444-68010 "TOYOTA" EMBLEM, SYMBOL	1.00	40.50		40.50
14	7	T58307-68031 PLATE, LUGGAGE COMPT	1.00	529.60		529.60
15	8	T52181-68010 PANEL LAMP LOWER	1.00	53.10		53.10
		ARM, RR BUMPER				

For & on behalf of
Borneo Motors

Customer's Signature

Change Summary

Total

Please acknowledge receipt of vehicle

Parts

Labour

Materials

Lubrication/Fluid

Others

Less

Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3941308

TO SECURITY GUARD

3941308

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME 25/04/2019
08:04

VEHICLE NO

SLV7032D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account & more!

Borneo Motors (Singapore) Pte Lt

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462

Tel no.: 6631 1188
Customer Detail

ESTIMATE

Account Detail	Account No	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ho Cheng Mun Eugene 574 Hougang Street 51 #11-01 Singapore 530574 Mobile: 91838622
	Document No	0
	Document Date	25/04/2019

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	11/01/2018	SLV7032D	0	42725 6TP/SLV7032D/20031
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

JTDGG20W30J008632 2ZROA46070 60 Shashitharan 16/04/2019 8.00 24/04/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	9	T67881-68030 WEATHERSTRIP, BACK	1.00	331.50		331.50
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour 1,768.80 Materials 5,500.00 Lubrication/Fluid 0.00 Others 0.00	7,268.80 GST 7.00% 508.82 Less 0.00 Amount Due 7,777.62

PLEASE TEAR ALONG PERFORATED LINE

3941309

TO SECURITY GUARD

3941309

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/04/2019
TIME 08:04

VEHICLE NO

SLV7032D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2019		08 Apr 2019 15:42 Edit Adj Rpt	S\$7,268.80 Edit Estimates	S\$7,268.80 View Rpt		Pending for Survey Report Cancel Case





























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: HO CHENG MUN, EUGENE , ID: S8422602E									
Vehicle Reg. No.: SLV7032D		Date of Loss: 19/03/2019 12:00 - :59 [14 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D201343C02		Policy/Cover Note No.: DMCVSN3045971800							
Vehicle Reg. No. (Insured): GBC355L		Policy No. (Claimant): VA1/GA312526							
		Excess: S\$500.00							
Repairer: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 17/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents







***SLV7032D (SNM19D201343C02)**
[GBC355L]

TP
HO CHENG MUN, EUGENE
Mar 19 2019 12:00PM
 [-]
Borneo Motors (S) Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Video						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)					Thumbnail	Print	
1	20/03/19 15:29	Video - Accident [Linked Accident Report Documents]					Load MP4		
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)					Thumbnail	Print	
1	20/03/19 15:31	Accident Statement					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)					Thumbnail	Print	
1	20/03/19 15:26	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
2	20/03/19 15:26	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
3	20/03/19 15:26	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
4	20/03/19 15:26	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
5	20/03/19 15:26	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
6	20/03/19 15:26	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
7	20/03/19 15:26	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
8	20/03/19 15:26	Accident Scene Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
9	20/03/19 15:26	Accident Scene Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
2	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
3	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
4	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
5	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
6	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
7	16/04/19 19:51	Odometer Reading					Load JPG	<input checked="" type="checkbox"/>	
8	16/04/19 19:51	Chassis Number					Load JPG	<input checked="" type="checkbox"/>	
9	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
10	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
11	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
12	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
13	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
14	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
15	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
16	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	
17	16/04/19 19:51	General View					Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
18	16/04/19 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
19	16/04/19 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
20	16/04/19 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
21	16/04/19 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
22	16/04/19 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
23	16/04/19 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
24	16/04/19 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
25	16/04/19 19:51	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	25/04/19 08:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	25/04/19 10:17	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	25/04/19 10:17	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/04/19 15:46	PRI - SJV7032D	 Load PDF	
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	20/03/19 15:27	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	20/03/19 15:27	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	20/03/19 15:27	CI [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	20/03/19 15:27	Nric And Driving Licence [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	20/03/19 15:27	Third Party Nric [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/19 10:30	Supplementary	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	20/03/19 15:29	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	20/03/19 15:31	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	20/03/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	20/03/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	20/03/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	20/03/19 15:26	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)		Thumbnail Print
5	20/03/19 15:26	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	20/03/19 15:26	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	20/03/19 15:26	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	20/03/19 15:26	Accident Scene Photo		Load JPG <input checked="" type="checkbox"/>
9	20/03/19 15:26	Accident Scene Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)		Thumbnail Print
1	20/03/19 15:27	Accident Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	20/03/19 15:27	Common Statement		Load JPG <input checked="" type="checkbox"/>
3	20/03/19 15:27	CI		Load JPG <input checked="" type="checkbox"/>
4	20/03/19 15:27	Nric And Driving Licence		Load JPG <input checked="" type="checkbox"/>
5	20/03/19 15:27	Third Party Nric		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119006281/EQD3E2

Date: 07/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3045971800
Claimant Vehicle No :	SLV7032D	Insured Vehicle No :	GBC355L
Date of Loss:	19/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201343C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV7032D	Engine No:	2ZR0A46070
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W30J008632
Reg. Date:	11/01/2018 (Man. Year: 2017)	Odometer:	22419 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,639.10	1,898.80	2,740.30	59.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,348.00	5,370.00	2,978.00	35.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,987.10	7,268.80	5,718.30	44.03
+ GST 7.00/7.00% (S\$)	909.10	508.82	400.28	44.03
Nett Amount (S\$)	13,896.20	7,777.62	6,118.58	44.03

INSPECTION

Date of Assignment:	08/04/2019	
Date Inspected:	16/04/2019	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV7032D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*R/RR BUMPER SUPPORT	Necessary	95.90 FS	*95.90 FS
3	1		*R/R SIDE BPR RETAINER	Necessary	45.30 FS	*45.30 FS
4	1		*REAR BUMPER COVER	Broken	584.70 FS	*584.70 FS
5	4		*PIECE, RR BUMPER	Necessary	16.00 FS	*16.00 FS
6	1		*REAR LOWER FLR PANEL	Dented	529.60 FS	*529.60 FS
7	1		*REAR BUMPER ARM	O/S Dented	106.20 FS	*53.10 FS
8	1		*REAR BACK DOOR GLASS	Not Necessary	1,029.40 FS	*- FS
9	1		*RR BACK DOOR W/STRIP	Crushed	331.50 FS	*331.50 FS
10	1		*PANEL ASSY, BACK DOOR	Repair	1,456.20 FS	*- FS
11	1		*TOYOTA SYMBOL EMBLEM	Necessary	72.20 FS	*72.20 FS
12	1		*LUGGAGE VALVE MATIC	Necessary	40.50 FS	*40.50 FS
13	1		*IG3 SENSOR	Not Necessary	151.60 FS	*- FS
14	1		*SEALANT END PANEL	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	4,639.10	1,898.80
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND CONDUCT LEAK TEST	New	180.00	180.00
2	TRANSFER BOOT LID MECHANISM AND REVERSE CAMERA	New	540.00	0.00
3	R/I INTERIOR TRIMMING TO FAC REPAIR	New	360.00	360.00
4	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
5	R/I REAR WINDSCREEN	New	538.00	0.00
6	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	3,600.00	2,880.00
7	RESPRAY ACC AFF AREA	New	2,950.00	1,770.00
Gross Labour Cost (S\$)			8,348.00	5,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >