

ASSN REC. BY:

REF: CS3/CT119006291/Gcds<sup>2</sup> Special Instruction:

Surveyor

90

ASSIGNMENT (Office)

From (Person):

chongy Beersan

of

CTI

Date/Time:

9/4/19 @ 1:53pm

Estimated Cost:

Bill to:

OD / ☒ TP WS / TP RES / OD RES / EYA / INV / MY / CS

To Inspect Vehicle No:

SMG 7215K

Insured:

GBC 8186E

at Workshop m/s

Blumel Automotive

Tel:

6745 2088

of

1 kcali Blt Ave 6 # 01-28

Policy No:

DMC8N30339518000

Claim No:

SNM19D201577002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8/4/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

5:00pm 9/4/19

Person Contacted:

Sally

Vehicle IN

☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SMG 7215K -
	Disassemble: 15/4/2019
	Before paint: 15/4/2019
	After paint: 16/4/2019

REF: C71

## ASSIGNMENT

From: PRS Date: 11/04/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMG7215K  
at Workshop m/s: Bluwel Automotive  
of 1 Kaki Bukit Ave 6 #01-28

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMG7215K Yr Reg: Dec / 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 1.5 c.c. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 4282 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6BN22A8J0236571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2000 - \$3000

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 3

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: PRE

Lump Sum / I.B.I. (\$) )

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2019		12 Jun 2019 17:44 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	GOLDEN MOUNT INTERNATIONAL PTE LTD, Co. Reg. No.: 201300803D		
Vehicle Reg. No.:	SMG7215K	Date of Loss:	06/04/2019 12:00 - :59
Claim Type:	TP / SNM19D201577C02	Policy/Cover Note No.:	DMCVSN30339518000
Vehicle Reg. No. (Insured):	GBC8186E	Policy No. (Claimant):	3100030771
		Excess:	S\$0.00
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 21/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 9 April 2019 1:53 PM  
**To:** Serene Tan  
**Cc:** Igene Lim; 'assignments'  
**Subject:** RE: PRE-REPAIR SURVEY / YOUR REF: SNM19d201577

Without Prejudice

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Serene Tan [mailto:serene.tan@mneduco.com.sg]  
**Sent:** Tuesday, 9 April, 2019 1:50 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** Igene Lim <igene.lim@mneduco.com.sg>; Angie Foo <angie.foo@sg.cntaiping.com>  
**Subject:** RE: PRE-REPAIR SURVEY / YOUR REF: SNM19d201577

Our Ref : MN.IG.B1.1913008.st

WITHOUT PREJUDICE  
SAVE AS TO COSTS

**NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS  
PROVIDED WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2.6 OF THE  
STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**

Hi Boon Sen,

1. We refer to your email below.
2. We are instructed by **GOLDEN MOUNT INTERNATIONAL PTE LTD**, the claimant and/or **BLUWEL AUTOMOTIVE SERVICE PTE LTD**, the motor workshop for **SMG 7215K** that they are not agreeable to the appointment of the motor surveyors as stated in your said email.
3. **In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016)**, we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

1. NICKY SEAH (Absolute Appraisal Services)	6. ANDREW HOW (Prominent Appraiser Services)
2. MICHAEL YAP TECK CHYE (MC-COY Appraiser Pte Ltd)	7. LOI BOON JUAN (PAR Automotive)
3. DIXON YEO (Treasure Appraisal Services)	8. ANANDA KUMAR BISWAS S/O B N BISWAS (United Appraisal & Management Pte Ltd)
4. LAWRENCE NG (PRIORITY Services)	9. DENNIS YAP TECK WEE (PAL's Appraiser Pte Ltd)
5. AMAS ONG (AEON Auto Consultants LLP)	10. ANDY YAP TECK LEE (LCW Appraiser Pte Ltd)

4. Please let us know **within two (2) working days** whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,

(For and on behalf of Mr Nedumaran Muthukrishnan)

Serene Tan (Ms)

M NEDUMARAN & CO

Advocates & Solicitors

Commissioner for Oaths

**Branch Office:**

11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel: 6509-8480 / 6509-8481

Fax: 6509-8482

**Email : [serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)**

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]  
**Sent:** Tuesday, 9 April 2019 1:09 PM  
**To:** Serene Tan <serene.tan@mneduco.com.sg>  
**Cc:** Igene Lim <igene.lim@mneduco.com.sg>; Angie Foo <angie.foo@sg.cntaiping.com>  
**Subject:** RE: PRE-REPAIR SURVEY / OUR REF: TBA

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Dear Angie,

For registration.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Serene Tan [mailto:serene.tan@mneduco.com.sg]  
**Sent:** Tuesday, 9 April, 2019 1:02 PM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Cc:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Igene Lim <igene.lim@mneduco.com.sg>; Irene

Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>; Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Subject: PRE-REPAIR SURVEY**

## **URGENT**

WITHOUT PREJUDICE

Our Ref: MN.IG.B1.1913008.st

Dear Sirs,

Notice of Accident dated **9/4/2019** attached herein.

Thanks & Best Regards,

(For and on behalf of Mr Nedumaran Muthukrishnan)

Serene Tan (Ms)

M NEDUMARAN & CO

Advocates & Solicitors

Commissioner for Oaths

**Branch Office:**

11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel: 6509-8480 / 6509-8481

Fax: 6509-8482

**Email : [serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)**

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



MTE119045115-01 / Trans Eurokars Pte Ltd - Sungei Kadut  
 ENTRY DATE & TIME: 08/04/2019 10:37  
 SUBMITTED BY: Ng Pei Fang

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 08/04/2019 10:37  
 Date Of Accident 06/04/2019 12:15  
 Exact Location Of Accident TAMPINES IKEA CARPARK  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMG7215K  
**Insured/Policyholder**  
 Name Of Registered Owner GOLDEN MOUNT INTERNATIONAL PTE LTD  
 Co Reg No 201300803D  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-92291866  
 Alternative Phone No Office-92291866

### Vehicle Particulars

Manufacturer MAZDA  
 Model MAZDA 3

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number  
 Cover Note Number 3100030771

### Driver

Name of Driver ZHANG JIN  
 NRIC No S8374197Z  
 Date Of Birth 03/03/1983  
 Occupation INDOOR  
 Date Of Driving Pass 13/11/2006  
 Driving Experience 12 YEARS AND 4 MONTHS  
 Gender FEMALE  
 Mobile Number (LOCAL) +65-92291866



Fax Number  
Contact Number  
EMail Address NOEMAIL  
Address 89 YISHUN STREET 81  
#02-11  
Postcode 768449  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - SALES MANAGER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 5  
Passenger 1 Name: : XIE JIAN ZHEN  
Gender: : Female  
Passenger 2 Name: : NG ZHIYANG  
Gender: : Male  
Passenger 3 Name: : LINCHY LU JUNCHEN  
Gender: : Male  
Passenger 4 Name: : YOLINNA LU YIXUAN  
Gender: : Female

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER TO SKETCH PLAN AND STATEMENT

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBC8186E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Sketch Plan**

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I turn right to one direction driving then suddenly the van coming to me from his parking lots. He scratch my car and for I run to stop him, asked his IC & driving licence. He said never bring

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
 6 Raffles Quay #18-00 Singapore 048580  
 Tel (65) 6224 0010 Fax (65) 6224 0030  
 Operating Hours: Monday to Friday, 09.00 – 17.00  
 UEN: S66550020G / GST Reg. No.: M480017735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No: MTE119045115 Vehicle Registration No: SM67215K  
 Name (as shown in NRIC): ZHAN JIN NRIC/FIN/Passport No: S83741972  
 (\*Vehicle Driver/Vehicle Owner) (\*) Please delete as appropriate  
 Address: 89 YIS/UN ST S1 #02-11 Singapore 268449  
 Contact (Tel): - Mobile No.: 92291866  
 Email Address: -  
 Date of Accident: 06 APRIL 2019 Time of Accident: 1215  
 Place of Accident: TAMPINES IKEA CARPARK  
 Insurance Company: MIG

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

To amend the report From OD To TP Claims.

Policyholder / Driver's Signature  
 Date:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:  
 Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	0803D
<b>Vehicle Details</b>	
Vehicle No.:	SMG7215K
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jun 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	P520529069
Chassis No.:	JM6BN22A8J0236571
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,277.00
Original Registration Date:	28 Dec 2018
First Registration Date:	28 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,277.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2028
PARF Rebate Amount:	\$10,707.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,501.00
COE Rebate Amount:	\$24,328.00
<b>Total Rebate Amount:</b>	<b>\$35,035.00</b>

The information contained herein is correct as at 12 Jun 2019

OK



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2019		12 Jun 2019 17:44	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
			<a href="#">Edit Adj Rpt</a>				

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	<b>GOLDEN MOUNT INTERNATIONAL PTE LTD</b> , Co. Reg. No.: 201300803D		
Vehicle Reg. No.:	<b>SMG7215K</b>	Date of Loss:	06/04/2019 12:00 - :59 [3 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM19D201577C02</b>	Policy/Cover Note No.:	DMCVSN30339518000
Vehicle Reg. No. (Insured):	<b>GBC8186E</b>	Policy No. (Claimant):	3100030771
		Excess:	S\$0.00
Repairer:	<b>Bluwel Automotive Service Pte Ltd (HQ)</b> 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Claimant's Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 21/06/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SMG7215K (SNM19D201577C02)**  
**[GBC8186E]**

































TP

**GOLDEN MOUNT INTERNATIONAL PTE LTD**  
**Apr 6 2019 12:00PM**





[-]

**Bluwel Automotive Service Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	08/04/19 10:54	<b>Video - Accident</b> [Linked Accident Report Documents]	Load MP4	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	08/04/19 10:55	<b>Accident Statement</b>	Load HTM	
2	10/04/19 13:09	<b>Addendum Sheet</b>	Load TIF	
3	10/04/19 13:10	<b>Accident Statement Addm. #1</b>	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	08/04/19 10:52	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	08/04/19 10:52	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	08/04/19 10:52	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	08/04/19 10:52	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	08/04/19 10:52	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
2	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
3	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
4	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
5	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
6	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
7	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
8	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
9	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
10	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
11	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
12	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
13	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
14	12/06/19 18:40	<b>Front View</b>	Load JPG	<input checked="" type="checkbox"/>
15	12/06/19 18:43	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
16	12/06/19 18:43	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
17	12/06/19 18:43	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
18	12/06/19 18:43	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
19	12/06/19 18:43	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
20	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	12/06/19 18:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	12/06/19 18:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	12/06/19 18:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	12/06/19 18:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	12/06/19 18:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	12/06/19 18:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	12/06/19 18:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	12/06/19 18:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	12/06/19 18:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	12/06/19 18:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	12/06/19 18:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	12/06/19 18:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	12/06/19 18:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	12/06/19 18:44	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/06/19 17:45	pri contact	 Load PDF	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	08/04/19 10:51	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

## Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	1 per page	<input checked="" type="checkbox"/>
1	08/04/19 10:54	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	08/04/19 10:55	Accident Statement	 Load HTM	
2	10/04/19 13:09	Addendum Sheet	 Load TIF	
3	10/04/19 13:10	Accident Statement Addm. #1	 Load HTM	

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	08/04/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	08/04/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	08/04/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	08/04/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	08/04/19 10:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	08/04/19 10:51	Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CTI19006291/GCD3S2  
**Date:** 03/07/2019

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30339518000  
**Claimant Vehicle No :** SMG7215K **Insured Vehicle No :** GBC8186E  
**Date of Loss:** 06/04/2019 **Nature of Claim:** TP **Claim No:** SNM19D201577C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG7215K**  
 Make & Model: MAZDA 3, 1.5 SEDAN EU6 (A) Engine No: P520529069  
 Reg. Date: 28/12/2018 (Man. Year: 2018) Chassis No: JM6BN22A8J0236571  
 Colour: Blue Odometer: 4282 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16  
 Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm  
 Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 12/06/2019  
 Date Inspected: 11/04/2019 Inspected At: Bluwel Automotive Service Pte Ltd (HQ)  
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56  
 Autobay@Kaki Bukit  
 Singapore 417883  
 Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2019)
<b>Parts:</b>	143	MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMG7215K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >