

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Cheng Boon Sen of CPE Date/Time: 8/4/19 @ 6:05pm.

Estimated Cost: Bill to:

OD (TT) WS / TP RES / OD RES / EVA / INV / MV TCS

To Inspect Vehicle No: YN3561H Insured: GX83014

at Workshop n/a: K. Kim Hin Tel: 64527018

of 160 Sin Ming Drive #02-20

Policy No: Claim No: SNM19D201408C02

Sum Insured: Excess:

Make of Vch: D.O.A. 29/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS 10/4/19

Date/Time: 5:15pm @ 9/4/19 Person Contacted: Joanne Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

YN 3561H - X

GX 83014 - X

11/4 - Sent email to Boon Sen on owner, not willing to total loss

REF: CTI

ASSIGNMENT

From: Date: 10/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN 35614

at Workshop m/s

K. Kim Hin

of 160 Sin Ming Drive #02-20

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 835K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 28 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1422

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

YN 35614

Yr Regn:

12/12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Isuzu NMR85

c.c

2999

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TAA NMR8514C 7101537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

Yoko

R:

1P5185R16 (2)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9 mm

R/Bal.

22 mm

L/Bal.

9 mm

L/Bal.

22 mm

D.O.A.

29/3/19

D.O.I.

10/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2 Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/4 Workshop asking for 11pm 835K, please return Urgent!

Submit uneconomical total loss report

MV: 35000/-
UA: 22024/-
NV: 1876/-

RECEIVED 17 APR 2019

Date/Time, File Pass to?

1) 17/4 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$))

☐ : Preli. Report
☐ : Final Report

Days Of Repair: -

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, \$

) Photos

) Others

TOTAL

220

TL-TP

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 8 April 2019 6:05 PM
To: service@kkimhin.com.sg
Cc: simon@kkimhin.com.sg; Sandra (Gmail); 'assignments'
Subject: RE: Fwd: Accident Involving YN 3561 H and GX 8301 U on 29 March 2019 / our ref: SNM19D201408c02

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: service [mailto:service@kkimhin.com.sg]
Sent: Monday, 8 April, 2019 5:59 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: service@kkimhin.com.sg; simon@kkimhin.com.sg; Sandra (Gmail) <sandrakhong@gmail.com>
Subject: re: Fwd: Accident Involving YN 3561 H and GX 8301 U on 29 March 2019

Dear Officer

Vehicle is in. Please kindly appoint the list of surveyor for us to choose ASAP.

Many thanks.

Best Regards
Sandra
6452 7018
9622 2116
K. Kim Hin Auto Pte Ltd

From: "Sandra Khong" <sandrakhong@gmail.com>
Sent: Monday, April 8, 2019 5:56 PM
To: "k.kim.hin" <service@kkimhin.com.sg>
Subject: Fwd: Accident Involving YN 3561 H and GX 8301 U on 29 March 2019

----- Forwarded message -----

From: **service** <service@kkimhin.com.sg>
Date: Fri, Apr 5, 2019 at 11:14 AM
Subject: Accident Involving YN 3561 H and GX 8301 U on 29 March 2019
To: <claimsdept@sg.cntaiping.com>, <boonsen.chong@sg.cntaiping.com>
Cc: <service@kkimhin.com.sg>, <simon@kkimhin.com.sg>, <survey2@kkimhin.com.sg>, <survey@kkimhin.com.sg>, Sandra (Gmail) <sandrakhong@gmail.com>

Your Ref: GX 8301 U
Our Ref: YN 3561 H

Dear Officer

Good day to you.

Enclosed the GIA report of our insured YN 3561 H who was hit by GX 8301 U on 29 March 2019.

Vehicle has been towed to our workshop.

Please kindly let us have the list of surveyor to choose from and also advise us the liability of the case.

Many thanks,
Sandra
6452 7018
K. Kim Hin Auto Pte Ltd

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Denise Tay (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 11 April 2019 5:20 PM
To: Denise Tay (LKKAUTO)
Cc: SUR
Subject: RE: Fwd: Accident Involving YN 3561 H and GX 8301 U on 29 March 2019 / our ref: SNM19D201408c02

Dear Denise,

As spoken, understand that Insurer has to give goahead to treat case as CTL though claimant wanted to repair (as you are the middle man, so you need Insurer goahead).

Have checked internally and we will treat it as CTL.

Third party claimant can proceed to submit claim accordingly.

Hope this assists.

As for below mentioned of Policy Jacket Terms and Conditions, this will of course not be applicable as this is only for our own policy.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen
Sent: Thursday, 11 April, 2019 4:40 PM
To: 'Denise Tay (LKKAUTO)' <denisetay@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Fwd: Accident Involving YN 3561 H and GX 8301 U on 29 March 2019 / our ref: SNM19D201408c02

Dear Denise,

For this matter, we note that damages is extensive as mentioned by you, and the nett value will therefore be insufficient to repair.

Under the Policy Jacket terms and conditions, in the event of a total loss or where it is no economical to repair the vehicle, we (Insurer) has the option to treat the insured vehicle as total loss.

Hope this assists and clarifies.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/03/2019 18:28
Date Of Accident	29/03/2019 10:30
Exact Location Of Accident	PIE TOWARDS BOON LAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN3561H
Insured/Policyholder	
Name Of Registered Owner	SYSTEMATIC AIRCONDITIONING & REFRIGERATION ENGINEER
Co Reg No	48101200A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64847188

Vehicle Particulars

Manufacturer	ISUZU
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1568015
Cover Note Number	

Driver

Name of Driver	WEE BOON POH
NRIC No	G6668810R
Date Of Birth	13/11/1981
Occupation	INDOOR
Date Of Driving Pass	20/09/2010
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83729993
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NO ADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX8301U
Vehicle Make/Model/Colour	TOYOTA HIACE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	XD4951Z
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

WEE BOON POH

Approximate Age

Injuries Sustain

LEG PAIN

Injured person in which vehicle?

YN3561H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature


Driver's Signature


Reporting Centre Personnel's Signature

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS coming to a stop as Vehicle C brake. Suddenly Vehicle B collided into my rear and pushing me forward to hit Vehicle C. I have some discomfort and will be seeing doctor.

* Repair at other workshop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Date & Time:

Company Chop (if applicable)

Signature



(If driver is not the policyholder)

Date & Time:

Name:

NRIC/FIN No:



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1200A
Vehicle Details	
Vehicle No.:	YN3561H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Apr 2019
Vehicle Make:	ISUZU
Vehicle Model:	NMR85UH5A 3.0 MT TURBO 2WD 2DR 5.0T
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	4JJ11230591
Chassis No.:	JAANMR85HC7101537
Maximum Power Output:	-
Open Market Value:	\$37,286.00
Original Registration Date:	21 Dec 2012
First Registration Date:	21 Dec 2012
Transfer Count:	0
Actual ARF Paid:	\$1,865.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Dec 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$62,201.00
COE Rebate Amount:	\$23,024.00
Total Rebate Amount:	\$23,024.00

The information contained herein is correct as at 07 Apr 2019

OK



AVIVA

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

2018 Mercedes-Benz E-Class E63 S AMG At \$500K.



Very Low Mileage, Immaculate
Condition, Cheapest In The
Market.
Direct Owner StarAd

KA-HUP

HOTLINE: 6741 9997

[VIEW OUR CARS](#)

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

1 vehicles

Isuzu NMR85U

[Advanced Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Isuzu NMR85U	Any	Any	2016	Any	Any	Any	Available



Isuzu NMR85U
Fuel Type: Diesel

\$51,800**\$6,800 /yr****21-Nov-2016****2,999 cc****-****Truck****Available**

Think One Automobile & Trading

Posted: 04-Apr-2019

Tags: 2016 Isuzu NMR85U, 2016 isuzu nmr85u, Isuzu NMR85U, isuzu nmr85u, Isuzu, NMR85U, nmr85u, Used Isuzu

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 ▼ results/page

[Home](#)
[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Isuzu NMR85U, Isuzu NMR85U Singapore, used Isuzu NMR85U Singapore, used Isuzu NMR85U, used vehicles Singapore or even buy used Isuzu NMR85U Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#)
[Careers](#)
[Contact Us](#)
[Sitemap](#)
[Terms of Service](#)
[Privacy Policy](#)
[Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.



ANNOUNCING 88 Motor Trading
as sgCarMart Premium Dealer for the 5th Consecutive Year

88 汽车贸易
MOTOR TRADING


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 10 Years Coe Renewal Toyota Wish 1.8A



2.88% P.A. Low Interest @ GV
Finance... 2 Years Warranty
\$4800 Down Monthly From \$73
GV Credit Pte Ltd [Star Ad](#)



Browse by Category ▾

Sort by Date Posted ▾ 20 results/page ▾

0 vehicles

Isuzu NMR85U

Advanced Search 🔍

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection Isuzu NMR85U Any Any 2012 Any Any Any Available

Sorry, there are no search results for your following query. Please refine your search fields, or try searching for it in our Expired ads.

Basic Search Criteria

Keyword(s) : Isuzu NMR85U

Depreciation : Any

Veh Type : Any

Price Range : -

Eng Cap : -

Availability : Available

Reg Date : 2012

Mileage : -

Category : All Categories

You may also wish to save these search fields to be notified whenever a vehicle is added.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Isuzu NMR85U, Isuzu NMR85U Singapore, used Isuzu NMR85U Singapore, used Isuzu NMR85U, used vehicles Singapore or even buy used Isuzu NMR85U Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Attn : China Insurance Claims Dept
Vehicle Insured : GX 8301 U
Accident Date : 29 -Mar- 2019

Date : 11-Apr-2019

Our Ref : 190181 (CHINA) / Simon

SYSTEMATIC AIRCONDITIONING & REFRIGERATION ENGINEERING
Singapore

Dear Sir,

Vehicle damaged were extensive and our repair region is about \$35K.
Kindly reply back on urgent basis as owner would not like to total loss his vehicle.

Regards
Simon
K.Kim Hin Auto Pte Ltd
6452 7018

TP: CHINA

(1N)

w/o \$ 7/4/19

K. Kim Hin

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 30412

Vehicle Insured : GX 8301 U
Accident Date : 29-Mar-2019

Date : 07-Apr-2019

Our Ref : 190181 (CHINA) / SANDRA

PAGE : 1

SYSTEMATIC AIRCONDITIONING &
Singapore

Not Authorised
LI Long B?

ESTIMATED COST OF REPAIR FOR ISUZU NMR85UH5A 3.0 MT (2012) YN3561H

- | | | |
|--------|--|----------------|
| 1 pc | front bumper | Bu- |
| 2 pcs | front bumper bracket (lh/rh) | R x |
| 1 pc | front bumper lower air guide | Sw x |
| 1 pc | front bumper inner cross member | R x |
| 1 pc | front grille | Mi- |
| 1 pc | front grille seal | Mc- |
| 12 pcs | front grille clips | Mc- |
| 1 pc | front fog lamp (lh/rh) | Sw x |
| 1 pc | front panel - outer | B1- |
| 1 pc | front panel seal | Mc- |
| 1 pc | front panel 'Reward-NM' sticker | Mc- |
| 1 pc | front panel 'ISUZU' emblem | Mc- |
| 1 pc | front panel - inner | B1- |
| 2 pcs | front corner panel (lh/rh) | B1- |
| 4 pcs | front corner panel clips-big | Mc- |
| 2 pcs | front corner panel clips-small | Mc- |
| 2 pcs | front corner panel vertical inner seal (lh/rh) | Di x |
| 1 pc | front corner panel top garnish (lh/rh) | Mi- |
| 1 pc | front windscreen glass | CMA- |
| 1 pc | front windscreen glass moulding-lower | Sw- |
| 1 pc | front windscreen glass moulding-upper | Ad- |
| 1 pc | front windscreen glass moulding-upper inner | Di x |
| 2 pcs | front windscreen pillar inner garnish (lh/rh) | Bu- |
| 2 pcs | headlamp assy (lh/rh) | ds cm NLS mi ✓ |
| 2 pcs | headlamp lower rubber lid | Mi- |

LKK Auto Consultants hence notify the Repairer of the following: Con't Page 2 ...

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : GX 8301 U
Our Ref : 190181

Page : 2
No. : 30412

(lh/rh)
2 pcs front signal lamp (lh/rh) *Brd mi ✓*
1 pc wingmirror stay - RH *mi ✓*
1 pc wingmirror - big RH *mi ✓*
1 pc wingmirror stay - LH *mi ✓*
1 pc wingmirror - big LH *mi ✓*
1 pc wingmirror - round LH *mi ✓*
2 pcs wingmirror stay cap cover (lh/rh) *mi ✓*
1 pc roof top panel *BT ✓*
1 pc roof top panel trim lining *Defor ✓*
2 pcs roof header tray compartment (lh/rh) *Di ✓*
2 pcs roof header tray compartment bracket (lh/rh) *Di ✓*
2 pcs sun visor (lh/rh) *Sm X*
2 pcs sun visor cover (lh/rh) *Sm X*
2 pcs sun visor holder (lh/rh) *?*
2 pcs handle grip front (lh/rh) *Sm X*
1 pc roof top interior lamp *Sm X*
1 pc rear view mirror *mi ✓*
1 pc cabin rear glass rubber *mc ✓*
1 pc roof top reinforcement beam-front *BT ✓*
2 pcs front wiper arm (lh/rh) *BT ✓*
2 pcs front wiper blade (lh/rh) *Gr ✓*
1 pc front wiper linkage (lh) *?*
1 pc front wiper linkage (rh) *?*
1 pc front wiper motor *?*
2 pcs front wiper nozzle cover *di mi Lt*
2 pcs front wiper pivot asm *?*
2 pcs front wiper nozzle washer *di mi Lt*
1 pc wiper washer tank *?*
1 pc wiper washer tank motor *?*
1 pc wiper washer hose *?*
1 pc roof top head lining - front *Di ✓*
1 pc roof top head lining - side (lh/rh) *Di ✓*
5 pcs roof top head lining cushion *?*

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GX 8301 U
Our Ref : 190181

Page : 3
No. : 30412

2 pcs door outer pillar (lh/rh) *BT-*
2 pcs front door (lh/rh) *BT-*
2 pcs front door step garnish (lh/rh) *cl/s c/p*
2 pcs front door hinges (lh/rh) *BT-*
2 pcs front door checker (lh/rh) *BT-*
2 pcs front door glass (lh/rh) *BT-*
2 pcs front door glass channel (lh/rh) *BT-*
2 pcs front door regulator (lh/rh) *BT-*
2 pcs front door regulator motor (lh/rh) *BT-*
2 pcs front door speaker (lh/rh) *?*
2 pcs front door inner trimboard (lh/rh) *BT-*
2 pcs front door weatherstrip (lh/rh) *Ad/L*
2 pcs front door frame weatherstrip (lh/rh) *Return*
2 pcs front door ash tray compartment (lh/rh) *CR*
2 pcs front door arm grip handle (lh/rh) *Sn X*
2 pcs front door outer moulding (lh/rh) *BT-*
2 pcs front door lock (lh/rh) *BT-*
2 pcs front door signal lamp (lh/rh) *Sn X*
2 pcs front door lock catch (lh/rh) *?*
2 pcs front door lock switch (lh/rh) *?*
2 pcs front door arch garnish (lh/rh) *BT-*
2 pcs front door arch garnish seal (lh/rh) *?*
1 pc front door power window switch (LH) *?*
1 pc front door power window switch (RH) *?*
1 pc cabin rear panel *BT-*
2 pcs rear pillar inner lower garnish (lh/rh) *BT-*
2 pcs front door inner pull handle (lh/rh) *?*

Con't Page 4 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GX 8301 U
Our Ref : 190181

Page : 4
No. : 30412

2 pcs air con blower bypass hose ?
1 pc air con liquid pipe ?
1 pc air con discharge pipe ?
1 pc air con suction pipe ?
1 pc heater pipe ?
2 pcs brake pipe ?
1 pc clutch pipe ?
1 pc engine wireharness ?
1 pc engine control module ?
1 pc dashboard front trimming Di-
1 pc dashboard - top 97/47-
1 pc dashboard meter ?
1 pc dashboard meter garnish ?
1 pc dashboard side cover - LH ?
1 pc dashboard reinforcement ?
4 pcs dashboard air con louver ?
1 pc dashboard glove box compart- ?
ment
1 pc n/s dashboard lower garnish ?
1 pc dashboard ignition key lock ?
1 pc radio headset ?
1 pc freezer temperature control
module ?
1 pc dashboard air con control
module ?
1 pc driver's seat back cushion ?
1 pc driver's seat back frame ?
1 pc driver's seat lower frame ?
1 pc driver's seat lower railing ?
1 pc steering box ?
1 pc steering wheel lower cover ?
1 pc steering wheel upper cover ?
1 pc steering column cover ?
1 pc steering column shaft assy ?
1 pc steering lock asm ?
2 pcs front cabin mounting (lh/rh) ?
2 pcs front cabin mounting bracket ?
(lh/rh)
1 pc front cabin torsion bar ?

Con't Page 5 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : GX 8301 U
Our Ref : 190181

Page : 5
No. : 30412

- 1 pc front cabin torsion bar inner shaft ?
- 2 pcs front cabin torsion bar bush ?
- 2 pcs rear cabin mounting (lh/rh) ?
- 2 pcs rear cabin mounting bracket (lh/rh) ?
- 1 pc cabin tilt stay ?
- 1 pc accelerator foot control link ?
- 1 pc cabin rear safety lock ?
- 1 pc cabin rear safety lock linkage ?
- 1 pc cabin rear safety lock lever ?
- 1 pc air intake duct *Not* ?
- 1 pc air duct inner hose ?
- 2 pcs engine mounting (lh/rh) ?
- 1 pc engine mounting ?
- 1 pc radiator assy ?
- 1 pc radiator coolant ?
- 1 pc radiator fan blade ?
- 1 pc radiator fan cowling ?
- 1 pc radiator fan guide ?
- 1 pc inter cooler ?
- 1 pc radiator top hose ?
- 1 pc radiator lower hose ?
- 1 pc hand gear change lever ?
- 1 pc hand gear change lever dust cover ?
- 1 pc hand gear change cable *Not* ?
- 1 pc hand brake pull lever ?
- 1 pc hand brake pull cable ?
- 1 pc clutch foot pedal ?
- 1 pc clutch foot pedal bracket ?
- 1 pc clutch master pump ?
- 1 pc foot brake pedal ?
- 1 pc brake booster pump ?
- 1 pc brake booster pump bracket ?
- 1 pc brake master pump ?
- 1 pc brake reservoir tank ?
- 1 pc brake fluid *Not* ?
- 1 pc diesel fuel tank ?

Con't Page 6 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GX 8301 U
Our Ref : 190181

Page : 6
No. : 30412

- 1 pc front number plate
- 1 pc front windscreen glass sealant
- 1 pc front windscreen glass damping seal
- 1 pc ERP bracket
- 1 pc air con blower
- 1 pc air con cooling coil
- 1 pc heater unit
- 1 pc rear stainless steel frame
- 1 pc n/s rear door
- 1 pc n/s rear door rubber
- 1 pc n/s rear door lock

Handwritten notes:
Mn 40sn 35.00 sn
Mn 40sn 60.00 sn
Mn 20.00 sn ✓
Mn 26.00 sn ✓
1,200.00 sn 7
850.00 sn 7
650.00 sn 7
C/M 5,500.00 sn ✓
Mn 850.00 sn ✓
Mn 250.00 sn ✓
400.00 sn 7

To tow accident vehicle to workshop
by normal towing

100.00 ✓

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

Handwritten: 3200d
3,500.00

To remove and renew front wind-
screen glass and conduct water
leak test.

120.00 ✓

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

120.00 *100d*

To remove and renew front
instrument panel assy, to rewiring
and transfer instrument fittings.

260.00 *24d*

To remove door's fittings

180.00 *12d*

To check and realignment on chassis
member.

2,000.00 7



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : GX 8301 U
Our Ref : 190181

Page : 7
No. : 30412

To remove and renew door glass.
Vacuum and clean up glass-splinter.

80.00 *50%*

To remove front brake booster,
brake master pump and steering
column

180.00 *100%*

To putty and respray on affected
portions.

1,600.00 *150%*

To focus headlamps. To check front
wiring and lighting operation.

50.00 *20%*

Total : S\$18,031.00
=====

Singapore Dollars Eighteen Thousand and Thirty
One Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2019		17 Apr 2019 14:31 Edit Adj Rpt	S\$12,256.00 Edit Estimates	S\$12,256.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SYSTEMATIC AIRCONDITIONING, Co. Reg. No.: 48101200A		
Main Claimant:	SYSTEMATIC AIRCONDITIONING & REFRIGERATION ENGINEER, Co. Reg. No.: 48101200A		
Vehicle Reg. No.:	YN3561H	Date of Loss:	29/03/2019 10:00 - :59 [75 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201408C02	Policy/Cover Note No.:	DMCVSN30842818011
Vehicle Reg. No. (Insured):	GX8301U	Policy No. (Claimant):	P1568015
		Excess:	S\$0.00
Repairer:	K Kim Hin Automotive Pte Ltd () BLK 34 SIN MING DRIVE,, #01-114,SINGAPORE 575708, 575708 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/04/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YN3561H (SNM19D201408C02)
[GX8301U]

TP

SYSTEMATIC AIRCONDITIONING & REFRIGERATION ENGINEE

Mar 29 2019 10:00AM








































[SYSTEMATIC AIRCONDITIONING]

K Kim Hin Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports			1 per page	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	29/03/19 19:35	Accident Statement	Load HTM	
Photos/Images			3 per page	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
2	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
3	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
4	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
5	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
6	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
7	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
8	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
9	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
10	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
11	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
12	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
13	29/03/19 19:34	Accident Photo [Linked Accident Report Documents]	Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/04/19 15:53	General View	Load JPG	
2	17/04/19 15:53	General View	Load JPG	
3	17/04/19 15:53	General View	Load JPG	
4	17/04/19 15:53	General View	Load JPG	
5	17/04/19 15:53	General View	Load JPG	
6	17/04/19 15:53	General View	Load JPG	
7	17/04/19 15:53	General View	Load JPG	
8	17/04/19 15:53	General View	Load JPG	
9	17/04/19 15:53	General View	Load JPG	
10	17/04/19 15:53	General View	Load JPG	
11	17/04/19 15:53	General View	Load JPG	
12	17/04/19 15:53	General View	Load JPG	
13	17/04/19 15:53	General View	Load JPG	
14	17/04/19 15:53	General View	Load JPG	

Assessment Reports			1 per page ▼	✓
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
15	17/04/19 15:53	General View	 Load JPG	✓
16	17/04/19 15:53	General View	 Load JPG	✓
17	17/04/19 15:53	General View	 Load JPG	✓
18	17/04/19 15:53	General View	 Load JPG	✓
19	17/04/19 15:53	General View	 Load JPG	✓
20	17/04/19 15:53	General View	 Load JPG	✓
21	17/04/19 15:53	General View	 Load JPG	✓
22	17/04/19 15:53	General View	 Load JPG	✓
23	17/04/19 15:53	General View	 Load JPG	✓
24	17/04/19 15:53	General View	 Load JPG	✓
25	17/04/19 15:53	General View	 Load JPG	✓
26	17/04/19 15:53	General View	 Load JPG	✓
27	17/04/19 15:53	General View	 Load JPG	✓
28	17/04/19 15:53	General View	 Load JPG	✓
29	17/04/19 15:53	General View	 Load JPG	✓
30	17/04/19 15:53	General View	 Load JPG	✓
31	17/04/19 15:53	General View	 Load JPG	✓
32	17/04/19 15:53	General View	 Load JPG	✓
33	17/04/19 15:53	General View	 Load JPG	✓
34	17/04/19 15:53	General View	 Load JPG	✓
35	17/04/19 15:53	General View	 Load JPG	✓
36	17/04/19 15:53	General View	 Load JPG	✓
37	17/04/19 15:53	General View	 Load JPG	✓
38	17/04/19 15:53	General View	 Load JPG	✓
39	17/04/19 15:53	General View	 Load JPG	✓
40	17/04/19 15:53	General View	 Load JPG	✓
41	17/04/19 15:53	General View	 Load JPG	✓
42	17/04/19 15:53	General View	 Load JPG	✓
43	17/04/19 15:53	General View	 Load JPG	✓
44	17/04/19 15:53	General View	 Load JPG	✓
45	17/04/19 15:53	General View	 Load JPG	✓
46	17/04/19 15:53	General View	 Load JPG	✓
47	17/04/19 15:53	General View	 Load JPG	✓
48	17/04/19 15:53	General View	 Load JPG	✓
49	17/04/19 15:53	General View	 Load JPG	✓
50	17/04/19 15:53	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/04/19 14:32	pri contact	 Load PDF	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	29/03/19 19:33	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/19 10:04	LTA REBATE	 Load PDF	

Linked Accident Report Documents

View View in Browser ▼

Assessment Reports

1 per page ▼



Assessment Reports			1 per page	Thumbnail	Print
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	29/03/19 19:35	Accident Statement	1	Load HTM	
Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
12	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
13	29/03/19 19:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	29/03/19 19:33	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006295/KTD3S2

Date: 06/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30842818011

Claimant Vehicle No: YN3561H Insured Vehicle No: GX8301U

Date of Loss: 29/03/2019 Nature of Claim: TP Claim No: SNM19D201408C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YN3561H

Make & Model: ISUZU NMR85UH5A, 3.0 D (M)

Reg. Date: 21/12/2012 (Man. Year: 2012)

Colour: White

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 4JJ11230591

Chassis No: JAANMR85HC7101537

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85R16 Rear Tyre Size: 195/85R16 (D)

Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 2/2 mm

Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,841.00	6,706.00	3,135.00	31.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,190.00	5,550.00	2,640.00	32.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,031.00	12,256.00	5,775.00	32.03
+ GST 7.00/7.00% (S\$)	1,262.17	857.92	404.25	32.03
Nett Amount (S\$)	19,293.17	13,113.92	6,179.25	32.03

INSPECTION

Date of Assignment: 17/04/2019

Date Inspected: 10/04/2019 Inspected At: K Kim Hin Automotive Pte Ltd
160 SIN MING DRIVE, #02-20
SIN MING AUTOCITY SINGAPORE 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$35,000.00
OMV :	\$37,286.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$62,201.00
COE Rebate (2) :	\$23,024.00
Total Rebate (1) + (2) = :	\$23,024.00

The total amount incurred will be Market Value \$35,000.00 minus Total Rebate \$23,024.00 = \$11,976.00

(EXCLUDE CHECK ITEMS S\$5,100.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Apr 2019)	
Parts:	N/A	ISUZU NMR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN3561H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*20.00 FS
2	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
3	1		*FRONT WINDSCREEN GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS
4	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
5	1		*AIR CON BLOWER	*Check	1,200.00 FS	*- FS
6	1		*AIR CON COOLING COIL	*Check	850.00 FS	*- FS
7	1		*HEATER UNIT	*Check	650.00 FS	*- FS
8	1		*REAR STAINLESS STEEL FRAME	Cracked	5,500.00 FS	*5,500.00 FS
9	1		*N/S REAR DOOR	Bent	850.00 FS	*850.00 FS
10	1		*N/S REAR DOOR RUBBER	Necessary	250.00 FS	*250.00 FS
11	1		*N/S REAR DOOR LOCK	*Check	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	9,841.00 6,706.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY NORMAL TOWING.	New	100.00	100.00
2	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	3,500.00	3,200.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	120.00	120.00
4	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	New	120.00	100.00
5	TO REMOVE AND RENEW FRONT INSTRUMENT PANEL ASSY, TO REWIRING AND TRANSFER INSTRUMENT FITTINGS.	New	260.00	240.00
6	TO REMOVE DOORS FITTINGS.	New	180.00	120.00
7	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER. (*Check)	New	2,000.00	0.00
8	TO REMOVE AND RENEW DOOR GLASS. VACUUM AND CLEAN UP GLASS-SPLINTER.	New	80.00	50.00
9	TO REMOVE FRONT BRAKE BOOSTER, BRAKE MASTER PUMP AND STEERING COLUMN.	New	180.00	100.00
10	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,600.00	1,500.00
11	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	50.00	20.00
Gross Labour Cost (S\$)			8,190.00	5,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >