

ASS. REC. BY:

REF:

CS/INC19006297/Jtd302

Special Instruction:

Surveyor

Anne Kie

ASSIGNMENT (Office)

From (Person):

Anne Koh

of

INC

Date/Time:

9/4/19 @ 9.24am

Estimated Cost:

Bill to:

OD (TP) WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLK 9014B

Insured:

SLC 4150R

at Workshop m/s

World Auto

Tel:

63621776

of

1 krungi loop

Policy No:

Claim No:

MT/1033601-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

23/2/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10.43am @ 9/4/19

Person Contacted:

Jensel

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 9014B-X

SLC 4150R-X

Surveys Huse die

REF: INC

# ASSIGNMENT

From: Date: 9/4/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK9014B  
at Workshop m/s World Auto

of 1 Kranji loop.

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKK9014B Yr Regn: 3 Feb 2017

Type: M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 170519 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU11205897

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/2/19 D.O.I. 9/4/19 1153am

Survey held at World Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirmed L/S \$1100t slays of repair. (Red: 2931.04; 72%)

RECEIVED 30 MAY 2019

Date/Time, File Pass to?

1) 29/5 Typist ☐ : Preli. Report ☒ : Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I.: (\$ 1100t )

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS, \$

) Photos

) Others

TOTAL

290

290

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
						Status
Main	03 Apr 2019		03 Apr 2019 18:25 Assign			New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS									
[Created by insurer]									
Insured:		MELVIN EE KIM WEE (YU JINWEI), ID: S7206095D							
Claimant:		MUHAMMAD HAIKAL BIN ABDUL KADIR, ID: S9440767B							
Vehicle Reg. No.:		SBT2678C							
Claim Type:		TP / SNM19D201430C02							
Vehicle Reg. No. (Insured):		SKQ247K							
Policy No. (Insured):									
Date of Loss:		28/03/2019 23:00 - :59							
Policy/Cover Note No.:		DMPCSN30674518000 (Comprehensive)							
Coverage:		17/10/2018 - 16/10/2019							
Excess:		\$0.00							
Repairer:		RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/04/2019]							
Remarks:		Adj Asg. kindly assign Mr Marcus Chua for SJE. You may contact John Ong / Jin Hai at 6286 6060 / 8811 2101 for arrangement of survey. thank you.							
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?									
No results.									

## Nivitha (LKK Auto)

---

**From:** Annie Koh <annie.koh@income.com.sg>  
**Sent:** Tuesday, 9 April 2019 1:48 PM  
**To:** 'assignments@lkkauto.com'  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Hi LKK,

Please take note of the Olc and claim number for GBE6149R and SLK9014B.

1	FIONA SHEN	MT/0954065-002	GBE6149R	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595		FBB4174X	15/7/17
5	JARED LIU	MT/1033601-002	SLK9014B	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Daniel / 63621776		SLC4150R	25/2/19

Warmest Regards

Annie Koh  
Senior Admin,  
Motor Insurance  
T +65 64307899  
[www.income.com.sg](http://www.income.com.sg)



---

**From:** Annie Koh  
**Sent:** Tuesday, 9 April 2019 10:44 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Re-send

Warmest Regards

Annie Koh  
Senior Admin,  
Motor Insurance  
T +65 64307899  
[www.income.com.sg](http://www.income.com.sg)



## Nivitha (LKK Auto)

---

**From:** Annie Koh <annie.koh@income.com.sg>  
**Sent:** Tuesday, 9 April 2019 2:20 PM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** SUR  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Hi LKK,

Please take note of the OIC and claim number for PA8482U\*\*

4	SERENE LIM	MT/1039440-001	PA8482U	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	Winnie Chai / 9850-9666	14:00- 16:00
---	---------------	----------------	---------	-----------	--	----------------------------	-----------------

Warmest Regards

**Annie Koh**  
Senior Admin,  
Motor Insurance  
T +65 64307899  
[www.income.com.sg](http://www.income.com.sg)



---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Tuesday, 9 April 2019 2:01 PM  
**To:** Annie Koh <annie.koh@income.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Dear Annie,

Thank you for the assignment.

Please be informed that PA8482U (Connect 3) is not in the workshop, repairer arrange on 10/04/2019.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Annie Koh  
**Sent:** Tuesday, 9 April 2019 9:24 AM  
**To:** 'assignments@lkkauto.com' <assignments@lkkauto.com>  
**Cc:** Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>  
**Subject:** RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA
1		PENDING ADVISE	GBE6149R	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595		FB84174X	15/7/17
2	AZHARI	MT/1039198-002	SLC6230E	VERMOGEN ACE PTE LTD	6 BENOI ROAD, SINGAPORE 629904	Pila / 6358 3031		SGY3323J	5/4/19
3	DAVID PHUA	MT/1039006-002	SMC166K	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 6266 0555		SLQ4302X	4/4/19
4		PENDING ADVISE	PA8482U	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	Winnie Chai / 9850-9666	14:00-16:00	FBN5354Z	22/3/19
5		PENDING ADVISE	SLK9014B	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Daniel / 63621776		SLC4150R	25/2/19

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh  
 Senior Admin Assistant, Motor Insurance  
 T +65 6430 7899  
[www.income.com.sg](http://www.income.com.sg)



---

## Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

NTue

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/02/2019 12:23
Date Of Accident	25/02/2019 07:00
Exact Location Of Accident	BLK 157 BISHAN ST 13 CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLK9014B
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	19-MK000194-R00
Cover Note Number	
Driver	
Name of Driver	CHUA HOCK YONG
NRIC No	S1610460D
Date Of Birth	01/09/1963
Occupation	OUTDOOR
Date Of Driving Pass	01/11/1980
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86981335
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO OVERWRITTEN
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC4150R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_



Driver's Signature \_\_\_\_\_  
 [If driver is not the policyholder]  
 Date & Time \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
ID/C/Title No.: \_\_\_\_\_

## Sketch Plan #2

### SKETCH PLAN



A. SLK 9014E  
B. SLK 4150R

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25/02/2019 around 7 AM AT BISHAN ST 13 BIK/157  
Car Park as I was follow this car SLK 4150R behind  
suddenly stop and no signal and reversing into the parking lot  
and my car front was scratch

### DECLARATION




I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NPIC/TIN No:

### Sketch Plan #3



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	4597K
<b>Vehicle Details</b>	
Vehicle No.:	SLK9014B
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4405898
Chassis No.:	RU11205897
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,442.00
Original Registration Date:	03 Feb 2017
First Registration Date:	03 Feb 2017
Transfer Count:	1
Actual ARF Paid:	\$12,019.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Feb 2027
PARF Rebate Amount:	\$9,014.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$39,804.00
<b>Total Rebate Amount:</b>	<b>\$48,818.00</b>

The information contained herein is correct as at 10 Apr 2019

OK

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
Halcyon 2, S'pore 577200  
Tel No. : 6451 3933 Fax No. : 6455 7576  
E-Mail : worldaut@singnet.com.sg  
Website : www.worldauto.com.sg  
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED  
75 BRAS BASAH ROAD NTUC INCOME CENTRE  
189557

Attention : Motor Claim Department  
Contact : 336 3322

Estimate : ES190047

Date : 08/04/2019  
Vehicle Num. : SLK 9014B[LCR]  
Make/Model : HONDA VEZEL  
Chassis/Eng# :  
Accident Date : 25/02/2019  
Claim No. :  
Reference :  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT BUMPER DEF ✓		620.80
2.	1	FRONT BUMPER SIDE RETAINER L/H nux		38.50
3.	1	HEADLAMP ASSY LH nux		1,850.00
4.	1	HEADLAMP TOP BRACKET LH nux		32.00
5.	1	HEADLAMP LOWER BRACKET LH nux		78.00
6.	1	FRONT GRILLE BASE nux		380.00
7.	1	FRONT GRILLE MOULDING LENS SCR ✓		360.00
8.	1	FRONT GRILLE CENTRE LOCK BRACKET nux		42.00
List Total S\$ :				3,401.30
20.00% Discount S\$ :				680.26
				2,721.04

SPECIAL NETT ITEMS :				
1.	1SET	FRONT BUMPER CLIP ncr ✓		30.00
Special Nett Total S\$ :				30.00

LABOUR :			
WIRINGS CHECK AND RECTIFY WHERE NECESSARY			40 180.00
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANELS WHERE NECESSARY AND REPLACE ABOVE PARTS			250 500.00
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS			250 600.00
Labour Total S\$ :			1,280.00

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Total S\$ : 4,031.04  
=====

Hwee Jie - LKK  
9/4/19  
4/5 P/P 3days.

Total - \$1100



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19006297/Jtd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 04-06-2019



ATTN : JARED LIU

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 4150R	Veh. Inspected	SLK 9014B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1033601-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	09/04/2019

#### 2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU11205897	Colour	BLACK
Odometer	170519 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	6 mm
L/H Front Tyre	215/60 R16	GITI	6 mm
R/H Rear Tyre	215/60 R16	GITI	6 mm
L/H Rear Tyre	215/60 R16	GITI	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	25/02/2019	Inspect Date / Time	09/04/2019 ( 11:53 AM )
Survey held at	1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 9014B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DEFORMED	620.80	620.80
1	FRONT BUMPER SIDE RETAINER L/H	NOT NECESSARY	38.50	-
1	HEADLAMP ASSY LH	NOT NECESSARY	1,850.00	-
1	HEADLAMP TOP BRACKET LH	NOT NECESSARY	32.00	-
1	HEADLAMP LOWER BRACKET LH	NOT NECESSARY	78.00	-
1	FRONT GRILLE BASE	NOT NECESSARY	380.00	-
1	FRONT GRILLE MOULDING LENS	SCRATCHED	360.00	360.00
1	FRONT GRILLE CENTRE LOCK BRACKET	NOT NECESSARY	42.00	-
	LESS 20% DISCOUNT		-680.26	-196.16
			2,721.04	784.64
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
			30.00	30.00
	<b><u>LABOUR</u></b>			
	WIRINGS CHECK AND RECTIFY WHERE NECESSARY.		180.00	40.00
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANELS WHERE NECESSARY AND REPLACE ABOVE PARTS.		500.00	250.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS.		600.00	250.00
			1,280.00	540.00
	<b>GRAND TOTAL</b>		<b>4,031.04</b>	<b>1,354.64</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,100.00</b>

Report Ref No. CS/INC19006297/Jtd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.