

27/03/2002

A.S. REC. BY:

REF: CS3/CTI190063151Ecd302

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

meriman

From (Person): Elaine Cheong

of CTI

Date/Time: 9.4.19 16.03pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLN 1762L

Insured: GBE 4976T

at Workshop m/s Han Car Repair

Tel: 62710275

of BLK 1001 Bukit Merah Lane 3 #01-49 Alexandra

Policy No: DMCVSN 16082518022

Claim No: SNM19020151802

Sum Insured:

Excess:

Make of Veh:

D.O.A. 4.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 10.4.19 9.53am

Person Contacted:

David

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SLN 1762L - NBA / CTI 190059831Y

D.O.A - 4/4/2019

GBE 4976T - NBA / CTI 190059831Y

D.O.A - 4/4/2019

Dismantle: 11/4/2019

ASSIGNMENT

PRS

From

Date:

10/04/2019

Veh No:

SLN1762L

Yr Regn:

25/04/17

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Make:

Honda Jazz

C.C.

.1498

To Inspect Vehicle No:

SLN1762L

Colour

Red

A/C: Insured / Std / NI / NA

at Workshop m/s

Han Car Repair

Sp. Reading

15213

T/Radio: Insured / Std / NI / NA

of Blk 1001 Blk Merah Lane 3 #01-49

Insured:

Eng/No:

Policy No.

C/No:

JHMG K58501X 291487

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R16


R:

(Policy Condition)

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

7

mm

R/Bal.

7

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

7

mm

L/Bal.

7

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

4/4/19

D.O.L.

10/4/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Han Car

CA / REV / REP. / 24 HRS

(up)

Des. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair range \$4K-5K
Days 6 days

[Signature]
11/4/2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

6

1)

☐

: Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

Survey Fee:

190

2)

Add Fee:

☐

: Site Insp (\$)

Transportation:

S + RS, \$

☐

: Interview (\$)

Photos

☐

: Tech. Invs (\$)

Others

☐

: Weekend (\$)

TOTAL

Report Format: PRS

Lump Sum / I.B.I.: (\$)

190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2019		09 Apr 2019 16:03 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	HOME SPRAY COATING & PAINTING SERVICE, Co. Reg. No.: 52847976L		[Created by insurer]
Main Claimant:	ADELINE CHEN YEYI, ID: S8170081H		
Vehicle Reg. No.:	SLN1762L	Date of Loss:	04/04/2019 09:00 - :59 [23 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201518C02	Policy/Cover Note No.:	DMCVSN16082518022 (Comprehensive) Coverage: 16/12/2018 - 15/12/2019
Vehicle Reg. No. (Insured):	GBE4976T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Han Car Repairs (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/04/2019]		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0081H
Vehicle Details	
Vehicle No.:	SLN1762L
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B31191099
Chassis No.:	JHMGK5850HX201487
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,058.00
Original Registration Date:	25 Apr 2017
First Registration Date:	25 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$13,058.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2027
PARF Rebate Amount:	\$9,793.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,765.00
COE Rebate Amount:	\$41,613.00
Total Rebate Amount:	\$51,406.00

The information contained herein is correct as at 10 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2019 17:05
Date Of Accident	04/04/2019 09:30
Exact Location Of Accident	SLIP RD OF UPPER SERANGOON RD TO SERANGOON CENTRAL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN1762L
Insured/Policyholder	
Name Of Registered Owner	ADELIN CHEN YEHYI
NRIC No	S8170081H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87286889
Alternative Phone No	OFFICE-62894813

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	TAY SUAN KIMP
NRIC No	S0083611G
Date Of Birth	19/03/1946
Occupation	INDOOR
Date Of Driving Pass	10/05/1969
Driving Experience	49 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87286889
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	16 JALAN GIRANG
Postcode	359187
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE4678T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WONG KWAI CHUEN
NRIC/Passport Number	S0040908A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 04-14-2019




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along slip Road of upper Serangoon Road
Towards Serangoon Central.

I slowed down and stopped to give way to oncoming
traffic.

Vehicle (B) came from behind and hit my car (A)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Apr 2019		09 Apr 2019 16:03 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HOME SPRAY COATING & PAINTING SERVICE , Co. Reg. No.: 52847976L								
Main Claimant:	ADELINE CHEN YEHI , ID: S8170081H								
Vehicle Reg. No.:	SLN1762L	Date of Loss:	04/04/2019 09:00 - :59 [23 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201518C02	Policy/Cover Note No.:	DMCVSN16082518022 (Comprehensive) Coverage: 16/12/2018 - 15/12/2019						
Vehicle Reg. No. (Insured):	GBE4678T	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Han Car Repairs (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 18/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN1762L (SNM19D201518C02)

[GBE4678T]




































TP































ADELINE CHEN YEHI































Apr 4 2019 9:00AM

[HOME SPRAY COATING & PAINTING SERVICE]

Han Car Repairs


Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)							Thumbnail		Print	
1	05/04/19 10:10	Accident Statement							 Load HTM			
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
2	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
3	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
4	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
5	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
6	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
7	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
8	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
9	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
10	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
11	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
12	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
13	10/04/19 16:15	Odometer Reading							 Load JPG		<input checked="" type="checkbox"/>	
14	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
15	10/04/19 16:15	Chassis Number							 Load JPG		<input checked="" type="checkbox"/>	
16	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
17	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
18	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
19	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
20	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
21	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
22	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
23	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
24	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
25	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
26	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
27	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
28	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
29	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
30	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
31	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
32	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
33	10/04/19 16:15	General View							 Load JPG		<input checked="" type="checkbox"/>	
34	10/04/19 16:15	General View							 Load JPG			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/04/19 16:15	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
84	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	11/04/19 19:26	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/04/19 15:57	INSD GBE4678T GIA REPORT	 Load PDF	
2	09/04/19 15:57	PRS EMAIL	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	05/04/19 10:10	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	04/04/19 17:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/04/19 17:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/04/19 17:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/04/19 17:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/04/19 17:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	04/04/19 17:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	05/04/19 10:10	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer	
<small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19006315/ECD3E2

Date: 15/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN16082518022

Claimant Vehicle
No: SLN1762LInsured Vehicle
No: GBE4678T

Date of Loss: 04/04/2019

Nature of Claim: TP

Claim
No: SNM19D201518C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN1762L**

Make & Model: HONDA JAZZ, 1.5 (A)

Reg. Date: 25/04/2017 (Man. Year: 2016)

Colour: Red

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: L15B31191099

Chassis No: JHMGK5850HX201487

Odometer: 15213 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/04/2019

Date Inspected: 10/04/2019 Inspected At:

Han Car Repairs (HQ)
BLK 1001 BUKIT MERAH LANE 3 #01-49
ALEXANDRA VILLAGE
Singapore 159718

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2019)
Parts: 144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN1762L)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >