

ASS. REC. BY:

REF:

cc3/AIG19006342/Avd3n2

ASSIGNMENT

Adrian

merimen

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

1800062578

Claims No.

Sum Insured:

Excess:

800


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

160K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8/8

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMH2528K

Yr Regn:

2018 / May.

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A6

c.c

1798

Colour:

Brown.

A/C:

Insured / Std / NI / NA

Sp. Reading

31699.

T/Radio:

Insured / Std / NI / NA

Eng/No:

7

C/No:

WAUZZZ469JN05145

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size: F:

225/55R17.

R:

225/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

7/4/19

D.O.I.

10/04/19

Survey held at

Premium:

Des. of Damages

Frt

Rear

O/S

N/S

U/C

Rooftop

or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD ALG.

SMH2528K-X

10/4/19

Revert via merimen

11/4/19

Rece approved \$21,787 from Victor by merimen

11/4/19

Informed Nora C/A ex \$800 by email

6/6/19

Final fig \$26,437.68 (Red 20,433.32, 4419) confirmed by email

RECEIVED 21 JUN 2019

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1)

216 - typist

2)

IN

OUT

3)

4)

Basic & Add.

200

5)

6)

S + RS, SI

11

Prel. Report:

Photos

Final Report:

Others

TOTAL

211