

15/5/2019

INS. CASE OWNER:

CC3/CTI1900 6268, 12 j63

LKK:

IDAC:

Surveyor:

Edvin

DOI:

ASSIGNMENT

9/4/19

Date / Time :

01464

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SEB 7934E

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II : \$\$

D.O.A :

9/4/19

Place of Accident :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SHD 7934E



INSRS:

WSP:

Tel :

Liability :

RMKS:

CDGE
W

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☐ ☐
	Release Voucher:	☐ ☐
	Final Repair Bill:	☐ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice	☐ ☐
	LTA / GIA :	☐ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☐ ☐
	LOD	☐ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	\$\$	(days) Reduction:	%
		Confirm by:	
		Email ☐	Call ☐
FINAL SETTLEMENT Date/Time:		Confirm with	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	
Repair Cost:	\$\$	If NO or B 28, Ass. Lia :	
Loss of Rental (LOR):	\$\$	(days)	
Loss of Use (LOU):	\$\$	(\$ x days)	
Loss of Income (LOI):	\$\$	(\$ x days)	
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LO ☐ [Tick only one]
GIA/LTA Search	\$\$		
Medical:	\$\$		
Disbursement:	\$\$	(e.g. Tow/ Independent)	
Legal Cost	\$\$		
Total:	\$\$	Global Sum \$:	
FINAL PAYMENT Date/Time:		Confirm with:	
		Email ☐	Call ☐
Payee 1:	\$\$	Name 1:	
Payee 2: (Strike if N.A.)	\$\$	Name 2:	
Payee 3: (Strike if N.A.)	\$\$	Name 3:	

OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

203 Brasemar Road Singapore 579701

Mainline + 65 6363 8280 Facsimile + 65 6280 8135

Workshops

59 Laying Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 09.04.2019 14:28

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 3913230

JC NO.: 305285874


OMER	REGN NO.: SHD3351B	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
OMER NO. 7010045	MODEL I-40	E.....1/2.....F
ESS 383 SIN MING DRIVE	YR OF MANU. 21.07.2016	DATE/TIME IN 09.04.2019 09:20
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMGU092193	TARGET DATE
(R) 65508755 (O)	COMPLETION DATE/TIME:	
(P)		
OUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 09.04.2019

NATURE: 3P 09.04.19

S/NO LABOR CODE DESCRIPTION



OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHD3351B

LIMITS

Vehicle No.:

SHD3351B

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard