

COMFORTDELGRO ENGINEERING PTE LTD

Date: 09.04.2019

REPAIR ESTIMATE

Time: 14:47:28

Page: 1

China Taiping
CP/PJ

LKK-Kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305285874
 REGN NO : SHD3351B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 21.07.2016
 DATE/TIME IN : 09.04.2019 09:20
 ACCIDENT DATE : 09.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0592-G	FRT DOOR RH	1	2,256.40	20.00	1,805.12	/
0002	04-01-0103-0573-A	FRT FENDER RH	1	566.30	20.00	453.04	/
0003	04-01-0103-2934-A	FRT FENDER SHIELD RH	1	175.90	20.00	140.72	?
0004	04-01-0103-0810-G	ROCKER PANEL GARNISH RH	1	483.30	20.00	386.64	/
0005	04-01-0103-0716-G	FRT DOOR UPR HINGE RH	1	53.40	20.00	42.72	?
0006	04-01-0103-0715-G	FRT DOOR LWR HINGE RH	1	53.40	20.00	42.72	?
0007	04-01-0103-0658-G	FRT WHEEL CAP RH	1	107.10	20.00	85.68	/
0008	T-205 WL-RP26	FRT WESTLAKE TYRE RH	1	216.00	2.00	216.00	X
0009	28-01-0103-0003-A	Frt Door ComfortDelGro RH	1	75.00	0.20	75.00	/

SUB-TOTAL : 3,247.64

JOB NATURE

0000 PB PANEL BEATING
 0001 SP SPRAYPAINT CHARGE

500.00 400
~~800~~ 600

COMFORTDELGRO ENGINEERING PTE LTD

Date: 09.04.2019

REPAIR ESTIMATE

Time: 14:47:28

Page: 2

China Taiping
(P/P)

LKK - Kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305285874
 REGN NO : SHD3351B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 21.07.2016
 DATE/TIME IN : 09.04.2019 09:20
 ACCIDENT DATE : 09.04.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 17-01	CHECK ALL LIGHTING	40.00	X	
0003 20-00	TUFF COAT ON AFFECTED PARTS.	100.00	50	
0004 L	TRANSFER OF DOOR	120.00	50	
0005 L	WHEEL ALIGNMENT	120.00	X	
SUB-TOTAL		: 1,380.00		

TOTAL : 4,627.64

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Kalvin 10/11/19

N

9/4/19

1526

3 P/P

P/P
Before Part photo