

15/5/2019

INS. CASE OWNER:

CC 4/LPC1900

6751, 4166302

LKK:  
IDAC:

Surveyor:

KALVIN

DOI:

## ASSIGNMENT

10/4/19

Date / Time:

01/4/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

S76 6470T

Name of Insured:

SELOKANG SLO POWNUSAMU

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

7/4/19

Is driver the owner?

( YES / NO )

Nature of Accident:

Claim No.:

101/10/19/005/01650

Policy No.:

101/05/0000000000

Make / Model:

TOYOTA

Place of Accident:

MINE UP HASTING KOLISBENTHUM

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC 1105P

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:CODE  
WYINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

SHC 1105P - 10/05/2019/10/05/2019  
S76 6470T - 1

08.06.19

FILE PASS TO TYPST TO PREPARE REPORT.

## STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

## FINALIZATION

Date/Time:

Confirm with:

Confirm by: AMK

Repair Cost:

P/P \$561.30

( 2 )

days) Reduction:

79 %

Email

Call

## FINAL SETTLEMENT

Date/Time: 18-07-19

Confirm with: KAZAN

Email

Call

Final Liability:

100 %

(Agreed / Assessed) BOLA S/N No.:

9

If NO or B 28, Ass. Lia:

Repair Cost:

W/L \$54.09

( 3.5 )

days) x = 125.40

Loss of Rental (LOR):

\$54.09

Loss of Use (LOU):

\$54.09

(\$

x

days)

Loss of Income (LOI):

\$175.00

(\$

50

x 3.5 days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search:

\$7.49

Medical:

\$ -

Disbursement:

\$ -

(e.g. Tow/ Independent)

Legal Cost:

\$ -

Total:

\$1,279.48

Global Sum \$5,100

## FINAL PAYMENT

Date/Time: 18-07-19

Confirm with: KAZAN

Email

Call

Payee 1:

\$1,200.00

Name 1:

COMPUTERELGRO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

\$ -

Name 2:

Payee 3: (Strike if N.A.)

\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 450

COPY SENT  
27/7/19

Surveyor: Kelvin

REF: \_\_\_\_\_

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / ITP / WS / ITP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Vth: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 1105 P Yr Regn: 5ZY, 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / T. / Prime Mover /

Truck / Trailer or

Make: T. J. P. Pius cc 1798

Colour: Blue AJC: Insu 6 / Std / NI / NA

Sp. Reading: 250836 T/Radio: Insu 6 / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: J70KB3F4307561189

Gen. Cond: Good / 6 / Poor / Burnt

Steering: Inor 6 / Jammed / Leaked / Burnt or

Brake: Inor 6 / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / SD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Waller

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 7/4/19 D.O.I. 10/4/19

Survey held at CDHE (Loyang)

Des. of Damages: Frl / Rear / OIS / N/S / UIC / Rooftop or

8/1 Rn

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Lampac  
PIP

RP: 611.30 (RED: 2,243.88 79%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Long Form (B.I.R.)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS \$ \_\_\_\_\_

Photos

Others

TOTAL



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

511 BLAQUE #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/LPC19006351/K1eb3

Date: 11.04.2019

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**


**SHC1105P**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10.04.2019 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,855.18
Revised Estimate Amount	: S\$	758.53
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:  
The vehicle sustained damages at the  
O/S Rear Portion



Comments/Present Status:  
Damages Consistent  
Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

Team: ARC Repair TP(CLS0)1

## JOB CARD

Sales Order:

JC NO: 305285640

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717

(R) 65508755 (O)

(P)

UNIT CARD NO.

REGN NO:

SHC1105P

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)08.04.2019 15:50

DATE/TIME IN

YR OF MANU

05.07.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU303561189

COMPLETION DATE/TIME

## JOB DESCRIPTION


Accident Date: 07.04.2019

NATURE: 3P 07.04.19

S/NO

LABOR CODE

DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHC1105P

JU LONPAC

Vehicle No.:

SHC1105P

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard



Lampal - JH.  
PIP -

COMFORTDELGRO ENGINEERING PTE LTD

**REPAIR ESTIMATE**

VEHICLE NO: SHC 1105P

9/4/2019 16:11

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR BUMPER <i>X repair</i>			\$ 458.60
REAR BUMPER UNDER COVER <i>X su</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>X su</i>			\$ 112.70
REAR BUMPER UNDER SIDE COVER (RH) <i>✓ CR</i>			\$ 232 <i>148.40</i>
REAR BUMPER TOWING COVER <i>X su</i>			\$ 82.70
REAR BUMPER CLIPS <i>X an</i>			\$ 22.00
TAIL LAMP ASSY (UPPER) (LH) <i>X su</i>			\$ 557.90
TAIL LAMP ASSY (LOWER) (RH) <i>X su</i>			\$ 548.40
SUB TOTAL			\$ 2,566.90
LESS 25%			\$ 641.73
DISCOUNTED TOTAL			\$ 1,925.18
LABOUR CHARGE			<i>200</i>
Panel Beating			\$ 400.00
Spray Painting Charge			\$ 400.00 <i>300</i>
Wiring Charge			\$ 50.00 <i>X</i>
Remove/Refix Reverse Sensor			\$ 80.00 <i>X</i>
TOTAL LABOUR			\$ 930.00
ESTIMATE TOTAL			\$ 2,855.18

*Kalvinick*  
*10/4/19 1635h*  
*2 PIP*  
*Attn Repair ph.*

By: [Signature]  
Date: [Blank]  
Acknowledged by Repairer  
[Signature]  
Date: [Blank]

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.04.2019

Time: 09:48:54

Page: 1

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305285640  
REGN NO : SHC1105P  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 05.07.2017  
DATE/TIME IN : 08.04.2019 15:50  
ACCIDENT DATE : 07.04.2019

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-2965-G PRIG4 FILLER-REAR BUMPER 1 148.40 25.00 111.30

SUB-TOTAL : 111.30

## JOB NATURE

0000 PB PANEL BEATING 200.00  
0001 SP SPRAYPAINT CHARGE 300.00

SUB-TOTAL : 500.00

TOTAL : 611.30

AUTHORISED : YES / NO

MVA NAME & SIGNATURE  
DATE :

SURVEYOR NAME & SIGNATURE  
DATE :

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305285640  
Date : 15/04/2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK Fax :  
Attn : KALVIN  
: SHC1105P Date of Accident : 07/04/19


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: LONPAC --- SJS6470T  
###
2. The finalized amount shall be:
 

(a) Spare Parts after List discount		<u>\$111.30</u>
(b) Labour Charges	###	<u>\$500.00</u>
<b>Total for Part-By-Part Repair Cost</b>		<b><u>\$611.30</u></b>
N		
(c) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: <u>20%</u>		
<b>Final Lumpsum Repair cost</b>		

3. Estimated normal period for repairs: 2 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :   
Name : KALVIN  
Date : 15/4/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## Nivitha (LKK Auto)

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Tuesday, 9 April 2019 5:35 PM  
**To:** assignments@lkkauto.com; Admin-D (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** Our Ref: 19/19/19/VP05/021650 [External General]  
**Attachments:** 21650 CDGE.pdf

10am @ 10/4/2019  
vehicle In  
person @ jumeri  
SUR @ Calvin

### Lonpac External - General

Dear Nivitha

Please refer to the attached and arrange survey.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969



Our Ref : 305285640  
Date : 09-04-19  
Time of Fax: 10:30 hrs

Via Fax : 6216-2706  
Your Insured: SJS 6470T  
Date of Acc : 07-04-19

Attn: Motor Claims Department

Lompac

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH C1105 P

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident \_

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our Initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

• Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} jumanibm@cdge.com.sg Fax no. 6546 8156
• Jumanibm Masudin	Tel: 6214 8315 or HP: 9635 5305	
• Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
• Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
• Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	
• Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176	

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

for Vice President  
Crash Repairs & Claims Recovery

## Shu Pei (LKKAuto)

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Thursday, 11 April 2019 5:37 PM  
**To:** Shu Pei (LKKAuto)  
**Cc:** MT\_Claim\_SG; Admin A; Asher Sng (LKKAuto)  
**Subject:** RE: Our Ref: 19/19/19/VP05/021650 [External General]  
**Attachments:** SJS6470T 070419.PDF

### Lonpac External - General


Dear Shu Pei

Please see attached.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

**From:** Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]  
**Sent:** Thursday, 11 April, 2019 5:02 PM  
**To:** ONG LI LI  
**Cc:** MT\_Claim\_SG; Admin A; Asher Sng (LKKAuto)  
**Subject:** RE: Our Ref: 19/19/19/VP05/021650 [External General]

### WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 1105P at M/s ComfortDelGro Engineering Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin-D (LKKAuto)

**Sent:** Wednesday, 10 April 2019 4:10 PM

**To:** 'ONG LI LI' <[llong@lonpac.com](mailto:llong@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Bryan Ang (LKKAuto) <[bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)>

**Subject:** RE: Our Ref: 19/19/19/VP05/021650 [External General]

Dear Li Li,

Noted with thanks.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** ONG LI LI [<mailto:llong@lonpac.com>]

**Sent:** Wednesday, 10 April 2019 4:08 PM

**To:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Bryan Ang (LKKAuto) <[bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)>

**Subject:** RE: Our Ref: 19/19/19/VP05/021650 [External General]

**Lonpac External - General**

Hi Nivitha

Please highlight to your surveyor that our Insured has informed us that initially the taxi company has only requested \$500 to close file and there was hardly any damage to the taxi. There was no damage to our Insured vehicle.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*


**From:** ONG LI LI  
**Sent:** Wednesday, 10 April, 2019 10:20 AM  
**To:** Admin-D (LKKAUTO); assignments  
**Cc:** MT\_Claim\_SG; Admin A  
**Subject:** RE: Our Ref: 19/19/19/VP05/021650 [External General]

### Lonpac External - General

Dear Nivitha

Please forward the attached accident scene photograph taken by our Insured to your claim handler.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

**From:** Admin-D (LKKAUTO) [<mailto:admin-d@lkkauto.com>]  
**Sent:** Wednesday, 10 April, 2019 9:57 AM  
**To:** ONG LI LI; assignments  
**Cc:** MT\_Claim\_SG; Admin A  
**Subject:** RE: Our Ref: 19/19/19/VP05/021650 [External General]

Dear Li Li,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


**From:** ONG LI LI [mailto:[long@lonpac.com](mailto:long@lonpac.com)]  
**Sent:** Tuesday, 9 April 2019 5:35 PM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com); Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** Our Ref: 19/19/19/VP05/021650 [External General]

### Lonpac External - General

Dear Nivitha

Please refer to the attached and arrange survey.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19006351/K1eb3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 24-07-2019



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 6470T	Veh. Inspected	SHC 1105P
Policy No.	Z19VP05022396	Coverage (\$)	0.00
Claim No.	19/19/19/VP05/021650	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	09/04/2019

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU303561189	Colour	BLUE
Odometer	250836	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	07/04/2019	Inspection Date	10/04/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1105P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	552.60	-
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER UNDER SIDE COVER (RH)	CRACKED	232.00	148.40
1	REAR BUMPER TOWING COVER	SERVICEABLE	82.70	-
1	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	TAIL LAMP ASSY (UPPER) (LH)	SERVICEABLE	557.90	-
1	TAIL LAMP ASSY (LOWER) RH	SERVICEABLE	548.40	-
	LESS 25% DISCOUNT		-641.73	-37.10
			1,925.17	111.30
<b>LABOUR</b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	200.00
	SPRAY PAINTING CHARGE.		400.00	300.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	80.00	-
			930.00	500.00
<b>GRAND TOTAL</b>			<b>2,855.17</b>	<b>611.30</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>611.30</b>

Report Ref No. CC4/LPC19006351/K1eb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.